


Asbestos Register

(Hazardous Materials and Risk Assessment)



School : Karningul School (5581)
Region : South Western Sydney
State Electorate : Bankstown
Local Government Area : Bankstown

Initial Survey : Noel Arnold & Associates : 11 - Mar - 2008
Register Issue Date : 23 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/Staff Facilities - 1899 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

Interior**B00A - R0001 - Clerical Office/Workroom**

No Asbestos

B00A - R0002 - Staff Kitchen

No Asbestos

B00A - R0003 - Security Store

No Asbestos

B00A - R0004 - Movement

Wall Linings Internal	Flat AC Sheeting								
	5581/B00A/R0004/Wall Linings Internal/S2								No Asbestos Detected

B00A - R0005 - Access Shower/Toilet

Wall Linings Internal	Flat AC Sheeting								
	5581/B00A/R0004/Wall Linings Internal/S2								No Asbestos Detected

B00A - R0006 - Interview

No Asbestos

B00A - R0007 - Movement

No Asbestos

B00A - R0008 - Staff Room

No Asbestos

B00A - R0009 - Clerical Office

No Asbestos

B00A - R0010 - Movement

No Asbestos

B00A - R0011 - Staff Room

No Asbestos

B00A - R0012 - Principal

No Asbestos

B00A - R0013 - External Movement

Wall Linings Internal	Flat AC Sheeting	25m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	5581/B00A/R0013/Wall Linings Internal/S1					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00A - R0014 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 2002 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00B - R0001 - External Movement**

No Asbestos

B00B - R0002 - Practical Activities - 1hb

No Asbestos

B00B - R0003 - Home Base StoreVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00B - R0004 - Home Base**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00B - R0005 - Withdrawal Space - 2hb**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00B - R0006 - Home Base**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00B - R0007 - Home Base Store**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00B - R0008 - Practical Activities - 1hb**

No Asbestos

B00B - R0009 - Toilets - Girls

No Asbestos

B00B - R0010 - Toilets - Boys

No Asbestos

B00B - R0011 - External Stairs

No Asbestos

B00B - R0012 - General Assistant/Bulk Store

No Asbestos

B00B - R1001 - External Movement

No Asbestos

B00B - R1002 - Practical Activities - 1hb

No Asbestos

B00B - R1003 - Home Base StoreVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00B - R1004 - Home Base**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00B - R1005 - Withdrawal Space - 2hb**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00B - R1006 - Home Base**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00B - R1007 - Home Base Store**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00B - R1008 - Practical Activities - 1hb**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00B - R1009 - External Stairs

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Building Services - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00C - R0001 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017