


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Kurrabee School (5621)
Region : Western Sydney
State Electorate : Londonderry
Local Government Area : Penrith

Initial Survey : Noel Arnold & Associates : 13 - May - 2008
Reviewed By : Parsons Brinckerhoff : 28 - May - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00A - Administration/Staff Facilities - 2007 - Brick/Veneer (Brick/Veneer)**Exterior**

Eaves Linings	Flat AC Sheeting 5621/B00C/Eaves Linings/S3					No Asbestos Detected
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					
Wall Cladding	Compressed AC Sheet 5621/B00A/Wall Cladding/S5					No Asbestos Detected

Interior**B00A - R0002 - Entry Vestibule**

No Asbestos

B00A - R0003 - Interview

No Asbestos

B00A - R0004 - Principal

No Asbestos

B00A - R0005 - Movement

No Asbestos

B00A - R0006 - Clerical Office

No Asbestos

B00A - R0008 - Sick Bay

No Asbestos

B00A - R0009 - Disabled Shower/Toilet

No Asbestos

B00A - R0010 - Security Store

No Asbestos

B00A - R0013 - Staff Room Annexe

No Asbestos

B00A - R0014 - Cleaning Distributed Store

No Asbestos

B00A - R0015 - Staff Toilet

No Asbestos

B00A - R0017 - Staff Room

No Asbestos

B00A - R0018 - Staff Room Annexe

No Asbestos

B00A - R0019 - Staff Toilet

No Asbestos

B00A - R0020 - Access Shower/Toilet

No Asbestos

B00A - R0021 - General Storeroom

No Asbestos

B00A - R0022 - General Storeroom

No Asbestos

B00A - R0023 - Reading Area

No Asbestos

B00A - R0024 - Communications Room

No Asbestos

B00A - R0025 - K.L.A. Store

No Asbestos

B00A - R0026 - Library Office/Workroom

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00A - R0027 - External Movement

No Asbestos

B00A - R0028 - Staff Room Annexe

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning/Pupil Facilities - 2007 - Brick/Block (Brick/Block)**Exterior**

In-fill-panel	Compressed AC Sheet	50m2	North, South, East, West, Lower portion, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	5621/B00B/R0023/In-fill-panel/S2					Chrysotile (white asbestos)
Eaves Linings	Flat AC Sheeting					No Asbestos Detected
	5621/B00B/R0012/Ceiling Structures/Linings/S1					
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					
Wall Cladding	Compressed AC Sheet					No Asbestos Detected
	5621/B00A/Wall Cladding/S5					

Interior**B00B - R0001 - External Movement**

Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	5621/B00B/R0012/Ceiling Structures/Linings/S1					

B00B - R0003 - General Storeroom

No Asbestos

B00B - R0004 - Toilets - Boys/Girls

No Asbestos

B00B - R0005 - Toilets - Boys/Girls

No Asbestos

B00B - R0007 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	5621/B00B/R0012/Ceiling Structures/Linings/S1					

B00B - R0008 - Home Base Store - S

No Asbestos

B00B - R0009 - Practical Activities - S - 1hb

No Asbestos

B00B - R0010 - Home Base - S

No Asbestos

B00B - R0011 - Practical Activities - S - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Special Purpose (Craft Art Science Tas Etc) - 2007 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting 5621/B00C/Eaves Linings/S3					No Asbestos Detected
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					
Wall Cladding	Compressed AC Sheet 5621/B00A/Wall Cladding/S5					No Asbestos Detected

Interior

B00C - R0001 - External Movement

No Asbestos

B00C - R0003 - General Storeroom

No Asbestos

B00C - R0004 - Disabled Shower/Toilet

No Asbestos

B00C - R0005 - Staff Toilet

No Asbestos

B00C - R0006 - General Storeroom

No Asbestos

B00C - R0008 - Home Base - S

No Asbestos

B00C - R0009 - Practical Activities - S - 1hb

No Asbestos

B00C - R0010 - Home Base - S

No Asbestos

B00C - R0011 - Practical Activities - S - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning - 2011 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					
Wall Cladding	Compressed AC Sheet 5621/B00A/Wall Cladding/S5					No Asbestos Detected

Interior

B00D - R0001 - External Movement

No Asbestos

B00D - R0003 - Staff Kitchen

No Asbestos

B00D - R0004 - General Storeroom

No Asbestos

B00D - R0005 - Home Base - S

No Asbestos

B00D - R0006 - Home Base - S

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning - 2013 - Brick/Veneer (Brick/Veneer)**Exterior**

In-fill-panel	Compressed AC Sheet	35m2	North, South, East, West, Lower portion, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	5621/B00B/R0023/In-fill-panel/S2					Chrysotile (white asbestos)
Eaves Linings	Flat AC Sheeting					No Asbestos Detected
	5621/B00B/R0012/Ceiling Structures/Linings/S1					
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00E - R0001 - Practical Activities**

Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	5621/B00B/R0012/Ceiling Structures/Linings/S1					

B00E - R0002 - Home Base

Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	5621/B00B/R0012/Ceiling Structures/Linings/S1					

B00E - R0003 - Cleaning Distributed Store

Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	5621/B00B/R0012/Ceiling Structures/Linings/S1					

B00E - R0004 - Home Base Store

No Asbestos

B00E - R0005 - Withdrawal Space - 1hb

No Asbestos

B00E - R0006 - Breakout Area

Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	5621/B00B/R0012/Ceiling Structures/Linings/S1					

Wall Linings Internal	Flat AC Sheeting	25m2	North, East, West, Lower portion, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
-----------------------	------------------	------	--	--------------------	---------	--------------------

5621/B00B/R0023/In-fill-panel/S2

Chrysotile (white asbestos)**B00E - R0007 - Disabled Toilet**

Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	5621/B00B/R0012/Ceiling Structures/Linings/S1					

B00E - R0008 - Other

No Asbestos

B00E - R0009 - Access Shower/Toilet

No Asbestos

B00E - R0010 - Practical Activities

No Asbestos

B00E - R0011 - Home Base

Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	5621/B00B/R0012/Ceiling Structures/Linings/S1					

B00E - R0012 - Access Shower/Toilet

Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	5621/B00B/R0012/Ceiling Structures/Linings/S1					

B00E - R0013 - Home Base Store

Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	5621/B00B/R0012/Ceiling Structures/Linings/S1					

B00E - R0014 - Withdrawal Space - 1hb

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00E - R0015 - Breakout Area						
No Asbestos						
B00E - R0016 - Laundry - Type 3						
No Asbestos						
B00E - R0017 - Home Base Store						
No Asbestos						
B00E - R0018 - Withdrawal Space - 1hb						
Ceiling Structures/Linings Flat AC Sheeting 5621/B00B/R0012/Ceiling Structures/Linings/S1					No Asbestos Detected	
B00E - R0019 - Breakout Area						
No Asbestos						
B00E - R0020 - Practical Activities						
No Asbestos						
B00E - R0021 - Home Base						
No Asbestos						
B00E - R0022 - Disabled Toilet						
No Asbestos						
B00E - R0023 - Other						
No Asbestos						
B00E - R0024 - Access Shower/Toilet						
No Asbestos						
B00E - R0025 - Practical Activities						
No Asbestos						
B00E - R0026 - Home Base						
No Asbestos						
B00E - R0027 - Home Base Store						
No Asbestos						
B00E - R0028 - Withdrawal Space - 1hb						
No Asbestos						
B00E - R0029 - Breakout Area						
No Asbestos						
B00E - R0030 - Plant						
No Asbestos						
B00E - R0031 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						
B00E - R0032 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						
B00E - R0033 - External Movement						
No Asbestos						
B00E - R0034 - External Movement						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning - 2013 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior**B00F - R0001 - Practical Activities**

No Asbestos

B00F - R0002 - Home BaseVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00F - R0003 - Cleaning Distributed Store**

No Asbestos

B00F - R0004 - Home Base Store

No Asbestos

B00F - R0005 - Withdrawal Space - 1hb

No Asbestos

B00F - R0006 - Breakout Area

No Asbestos

B00F - R0007 - Disabled Toilet

No Asbestos

B00F - R0008 - Other

No Asbestos

B00F - R0009 - Access Shower/Toilet

No Asbestos

B00F - R0010 - Practical ActivitiesVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00F - R0011 - Home Base**

No Asbestos

B00F - R0012 - Access Shower/Toilet

No Asbestos

B00F - R0013 - Home Base Store

No Asbestos

B00F - R0014 - Withdrawal Space - 1hb

No Asbestos

B00F - R0015 - Breakout Area

No Asbestos

B00F - R0016 - Laundry - Type 3

No Asbestos

B00F - R0017 - Home Base Store

No Asbestos

B00F - R0018 - Withdrawal Space - 1hb

No Asbestos

B00F - R0019 - Breakout Area

No Asbestos

B00F - R0020 - Practical Activities

No Asbestos

B00F - R0021 - Home Base

No Asbestos

B00F - R0022 - Disabled Toilet

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00F - R0023 - Other						
No Asbestos						
B00F - R0024 - Access Shower/Toilet						
No Asbestos						
B00F - R0025 - Practical Activities						
No Asbestos						
B00F - R0026 - Home Base						
No Asbestos						
B00F - R0027 - Home Base Store						
No Asbestos						
B00F - R0028 - Withdrawal Space - 1hb						
No Asbestos						
B00F - R0029 - Breakout Area						
No Asbestos						
B00F - R0030 - Plant						
No Asbestos						
B00F - R0031 - Distribution Board				Note: No inspection of live electrical installation.		
No Asbestos						
B00F - R0032 - Distribution Board				Note: No inspection of live electrical installation.		
No Asbestos						
B00F - R0033 - External Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00G - General Learning - 2013 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior**B00G - R0001 - Practical Activities**

No Asbestos

B00G - R0002 - Home Base

No Asbestos

B00G - R0003 - Cleaning Distributed Store

No Asbestos

B00G - R0004 - Home Base Store

No Asbestos

B00G - R0005 - Withdrawal Space - 1hb

No Asbestos

B00G - R0006 - Breakout Area

No Asbestos

B00G - R0007 - Disabled Toilet

No Asbestos

B00G - R0008 - Other

No Asbestos

B00G - R0009 - Access Shower/Toilet

No Asbestos

B00G - R0010 - Practical Activities

No Asbestos

B00G - R0011 - Home Base

No Asbestos

B00G - R0012 - Access Shower/Toilet

No Asbestos

B00G - R0013 - Home Base Store

No Asbestos

B00G - R0014 - Withdrawal Space - 1hb

No Asbestos

B00G - R0015 - Breakout Area

No Asbestos

B00G - R0016 - Laundry - Type 3

No Asbestos

B00G - R0017 - Home Base Store

No Asbestos

B00G - R0018 - Withdrawal Space - 1hb

No Asbestos

B00G - R0019 - Breakout Area

No Asbestos

B00G - R0020 - Practical Activities

No Asbestos

B00G - R0021 - Home Base

No Asbestos

B00G - R0022 - Disabled Toilet

No Asbestos

B00G - R0023 - Other

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
	No Asbestos					
	B00G - R0024 - Access Shower/Toilet					
	No Asbestos					
	B00G - R0025 - Practical Activities					
	No Asbestos					
	B00G - R0026 - Home Base					
	No Asbestos					
	B00G - R0027 - Home Base Store					
	No Asbestos					
	B00G - R0028 - Withdrawal Space - 1hb					
	No Asbestos					
	B00G - R0029 - Breakout Area					
	No Asbestos					
	B00G - R0030 - Plant					
	No Asbestos					
	B00G - R0031 - Distribution Board				Note: No inspection of live electrical installation.	
	No Asbestos					
	B00G - R0032 - Distribution Board				Note: No inspection of live electrical installation.	
	No Asbestos					
	B00G - R0033 - External Movement					
	No Asbestos					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Communal Facilities/Building Services - 2013 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00H - R0001 - Covered Outdoor Learning Area

No Asbestos

B00H - R0002 - Communal Space

No Asbestos

B00H - R0003 - Kitchen - Pre

No Asbestos

B00H - R0004 - Special Programs Room

No Asbestos

B00H - R0005 - Special Programs Store

No Asbestos

B00H - R0006 - P.E. Store

No Asbestos

B00H - R0007 - Chair Storeroom

No Asbestos

B00H - R0008 - Main Switch Board

No Asbestos

B00H - R0009 - General Assistant/Bulk Store

No Asbestos

B00H - R0010 - Sports Store

No Asbestos

B00H - R0011 - Garden Store

No Asbestos

B00H - R0012 - Access Shower/Toilet

No Asbestos

B00H - R0013 - Disabled Toilet

No Asbestos

B00H - R0014 - Cleaning Distributed Store

No Asbestos

B00H - R0017 - Covered Outdoor Learning Area

No Asbestos

B00H - R0018 - Distribution Board

No Asbestos

Note: No inspection of live electrical installation.

B00H - R0019 - External Movement

No Asbestos

B00H - R0020 - External Movement

No Asbestos

B00H - R0021 - External Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - Pupil Facilities/Special Purpose - 2013 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior**B00I - R0001 - Movement**

No Asbestos

B00I - R0002 - Hydrotherapy

No Asbestos

B00I - R0003 - Movement

No Asbestos

B00I - R0004 - Hydrotherapy - Pool

No Asbestos

B00I - R0005 - Sports Store

No Asbestos

B00I - R0006 - Shower/Change

No Asbestos

B00I - R0007 - Disabled Toilet

No Asbestos

B00I - R0008 - Access Shower/Toilet

No Asbestos

B00I - R0009 - Other

No Asbestos

B00I - R0010 - General Storeroom

No Asbestos

B00I - R0011 - Plant

No Asbestos

B00I - R0012 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00I - R0013 - Plant

No Asbestos

B00I - R0014 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Staff Facilities - 2013 - Timber (Timber)**Exterior**

Eaves Linings	Flat AC Sheeting 5621/B00J/Eaves Linings/S4					No Asbestos Detected
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00J - R0001 - Residential Staff Kitchen**

No Asbestos

B00J - R0002 - Movement

No Asbestos

B00J - R0003 - Residential Bedroom

No Asbestos

B00J - R0004 - Teacher Bathroom

No Asbestos

B00J - R0005 - Teacher Bedroom

No Asbestos

B00J - R0006 - Teacher Bedroom

No Asbestos

B00J - R0007 - Movement

No Asbestos

B00J - R0008 - Teacher Bedroom

No Asbestos

B00J - R0009 - Teacher Bedroom

No Asbestos

B00J - R0010 - Movement

No Asbestos

B00J - R0011 - Teacher Bathroom

No Asbestos

B00J - R0012 - Residential Laundry

No Asbestos

B00J - R0013 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017