


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Karonga School (5670)
Region : Northern Sydney
State Electorate : Epping
Local Government Area : Hornsby

Initial Survey : Noel Arnold & Associates : 17 - Jan - 2008
Reviewed By : Parsons Brinckerhoff : 16 - Sep - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/Support Unit - 1982 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids - Raked Ceiling No Asbestos Found

Underfloor Voids - Slab on Ground No Asbestos Found

Interior**B00A - R0002 - Therapy**

No Asbestos

B00A - R0003 - Toilet - S

No Asbestos

B00A - R0004 - Therapy Store

No Asbestos

B00A - R0005 - Interview

No Asbestos

B00A - R0006 - Therapy

No Asbestos

B00A - R0007 - Main Switch Board

Wall Linings Internal	Flat AC Sheeting	60m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	5670/B00A/R0047/Wall Linings Internal/S1				Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	5670/B00A/R0047/Wall Linings Internal/S1				Chrysotile (white asbestos)	

B00A - R0008 - Cleaning Distributed Store

No Asbestos

B00A - R0009 - Movement

No Asbestos

B00A - R0010 - Staff Room

No Asbestos

B00A - R0011 - Movement

No Asbestos

B00A - R0012 - Clerical Office/Workroom

No Asbestos

B00A - R0013 - Movement

No Asbestos

B00A - R0014 - Entry Vestibule

No Asbestos

B00A - R0015 - Security Store

No Asbestos

B00A - R0016 - Clerical Office

No Asbestos

B00A - R0017 - Clerical Office/Workroom

No Asbestos

B00A - R0018 - Community Clinic

No Asbestos

B00A - R0019 - Staff Toilet

No Asbestos

B00A - R0020 - Staff Toilet

No Asbestos

B00A - R0021 - Staff Toilet

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R0022 - General Storeroom						
No Asbestos						
B00A - R0024 - Deputy Principal						
No Asbestos						
B00A - R0025 - Principal						
No Asbestos						
B00A - R0026 - Movement						
No Asbestos						
B00A - R0027 - Movement						
No Asbestos						
B00A - R0028 - Covered Vehicle Area/Porte Cochere						
No Asbestos						
B00A - R0029 - Movement						
No Asbestos						
B00A - R0030 - Sick Bay						
No Asbestos						
B00A - R0031 - Movement						
No Asbestos						
B00A - R0032 - Hall Chair Store						
No Asbestos						
B00A - R0033 - Communal Space						
No Asbestos						
B00A - R0034 - Raised Platform						
No Asbestos						
B00A - R0035 - General Storeroom						
No Asbestos						
B00A - R0036 - Canteen						
No Asbestos						
B00A - R0037 - Canteen Office/Store						
No Asbestos						
B00A - R0038 - Staff Toilet						
No Asbestos						
B00A - R0039 - Movement						
No Asbestos						
B00A - R0040 - Movement						
No Asbestos						
B00A - R0041 - Movement						
No Asbestos						
B00A - R0042 - Movement						
No Asbestos						
B00A - R0043 - General Assistant/Bulk Store						
No Asbestos						
B00A - R0044 - General Assistant/Bulk Store						
No Asbestos						
B00A - R0045 - Distribution Board						
					Note: No inspection of live electrical installation.	
Wall Linings Internal	Flat AC Sheeting	25m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
5670/B00A/R0047/Wall Linings Internal/S1					Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
5670/B00A/R0047/Wall Linings Internal/S1					Chrysotile (white asbestos)	
B00A - R0046 - Cleaning Distributed Store						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00A - R0047 - Distribution Board

Note: No inspection of live electrical installation.

Wall Linings Internal	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
-----------------------	------------------	-----	--------------	--------------------	---------	--------------------

5670/B00A/R0047/Wall Linings Internal/S1

Chrysotile (white asbestos)

Ceiling Structures/Linings	Flat AC Sheeting	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	-----	--------------	--------------------	---------	--------------------

5670/B00A/R0047/Wall Linings Internal/S1

Chrysotile (white asbestos)**B00A - R0048 - Movement**

No Asbestos

B00A - R0049 - Clerical Office

No Asbestos

B00A - R0050 - General Storeroom

No Asbestos

B00A - R0053 - Toilets - Girls

No Asbestos

B00A - R0055 - Movement

No Asbestos

B00A - R0056 - General Storeroom

No Asbestos

B00A - R0057 - K.L.A. Store

No Asbestos

B00A - R0058 - Movement

No Asbestos

B00A - R0059 - Movement

No Asbestos

B00A - R0060 - Movement

No Asbestos

B00A - R0061 - Resource/Toy Space

No Asbestos

B00A - R0062 - Reading Area

No Asbestos

B00A - R0063 - Deputy Principal - Type 1

No Asbestos

B00A - R0064 - Deputy Principal - Type 1

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Staff Facilities - 1982 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids - Raked Ceiling No Asbestos Found

Underfloor Voids - Slab on Ground No Asbestos Found

Interior**B00B - R0001 - Clerical Office**

No Asbestos

B00B - R0002 - Stairs

No Asbestos

B00B - R9001 - Staff Room

No Asbestos

B00B - R9002 - Movement

No Asbestos

B00B - R9003 - Stairs

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Support Unit - 1982 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids - Raked Ceiling No Asbestos Found

Underfloor Voids - Slab on Ground No Asbestos Found

Interior**B00C - R0001 - Toilet - S**

No Asbestos

B00C - R0002 - Toilet - S

No Asbestos

B00C - R0003 - Plant

No Asbestos

B00C - R0004 - Distribution Board

Note: No inspection of live electrical installation.

Wall Linings Internal	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
-----------------------	------------------	-----	--------------	--------------------	---------	--------------------

5670/B00C/R0004/Wall Linings Internal/S2

Chrysotile (white asbestos)

Ceiling Structures/Linings	Flat AC Sheeting	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	-----	--------------	--------------------	---------	--------------------

5670/B00C/R0004/Wall Linings Internal/S2

Chrysotile (white asbestos)

B00C - R0006 - General Storeroom

No Asbestos

B00C - R0007 - Toilet - S

No Asbestos

B00C - R0008 - Movement

No Asbestos

B00C - R0009 - Special Education Support Centre

No Asbestos

B00C - R0010 - Laundry - S

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Support Unit - 1982 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids - Raked Ceiling No Asbestos Found

Interior

B00D - R0001 - Home Base - S

No Asbestos

B00D - R0002 - Toilet - S

No Asbestos

B00D - R0003 - Practical Activities - S - 1hb

No Asbestos

B00D - R0004 - Covered Outdoor Learning Area - S

No Asbestos

B00D - R0005 - Home Base - S

No Asbestos

B00D - R0006 - Covered Outdoor Learning Area - S

No Asbestos

B00D - R0007 - Cleaning Distributed Store

No Asbestos

B00D - R0008 - Toilet - S

No Asbestos

B00D - R0009 - Toilet - S

No Asbestos

B00D - R0010 - Distribution Board

Note: No inspection of live electrical installation.

Wall Linings Internal	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
-----------------------	------------------	-----	--------------	--------------------	---------	--------------------

5670/B00D/R0010/Ceiling Structures/Linings/S3

Chrysotile (white asbestos)

Ceiling Structures/Linings	Flat AC Sheeting	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	-----	--------------	--------------------	---------	--------------------

5670/B00D/R0010/Ceiling Structures/Linings/S3

Chrysotile (white asbestos)

B00D - R0011 - Therapy

No Asbestos

B00D - R0012 - Home Base - S

No Asbestos

B00D - R0013 - Movement

No Asbestos

B00D - R0014 - Practical Activities - S - 1hb

No Asbestos

B00D - R0015 - Toilet - S

No Asbestos

B00D - R0016 - Home Base - S

No Asbestos

B00D - R0017 - Movement

No Asbestos

B00D - R0018 - Movement

No Asbestos

B00D - R0019 - Toilet - S

No Asbestos

B00D - R0020 - Toilet - S

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00D - R0021 - Music Store						
No Asbestos						
B00D - R0022 - Toilet - S						
No Asbestos						
B00D - R0023 - Toilet - S						
No Asbestos						
B00D - R0024 - No Access						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Support Unit - 1985 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids - Raked Ceiling No Asbestos Found

Underfloor Voids - Slab on Ground No Asbestos Found

Interior

B00E - R0003 - Home Base - S

No Asbestos

B00E - R0004 - Movement

No Asbestos

B00E - R0005 - Therapy

No Asbestos

B00E - R0006 - No Access

No Asbestos

B00E - R0007 - Movement

No Asbestos

B00E - R0008 - Movement

No Asbestos

B00E - R0009 - Disabled Toilet

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00P - Pupil Facilities/Communal Facilities - 1976 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids - Raked Ceiling	No Asbestos Found					
Underfloor Voids - Packing to Floor Joists	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	50m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	5670/B00P/Eaves Linings/S12				Chrysotile (white asbestos)	
Eaves Linings	Flat AC Sheeting	50m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	5670/B00P/Eaves Linings/S12				Chrysotile (white asbestos)	

Interior**B00P - R0001 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	5670/B00P/Eaves Linings/S4				Chrysotile (white asbestos)	

B00P - R0002 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	5670/B00P/R0002/Ceiling Structures/Linings/S5				Chrysotile (white asbestos)	

B00P - R0003 - Distribution Board

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	5670/B00P/R0002/Ceiling Structures/Linings/S5				Chrysotile (white asbestos)	

B00P - R0004 - Disabled Toilet

No Asbestos

B00P - R0007 - Hydrotherapy - Pool

Ceiling Structures/Linings	Flat AC Sheeting	250m2	Pitched ceiling - All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	5670/B00P/R0002/Ceiling Structures/Linings/S5				Chrysotile (white asbestos)	

B00P - R0008 - Plant

No Asbestos

B00P - R0009 - Shower/Change

No Asbestos

B00P - R0010 - Toilet - M

No Asbestos

B00P - R9001 - Plant

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00R - General Learning - 2013 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B00R - R0001 - External Movement**

No Asbestos

B00R - R0002 - Practical Activities - 1hb

No Asbestos

B00R - R0003 - Toilets - Boys/Girls

No Asbestos

B00R - R0004 - Home Base Store

No Asbestos

B00R - R0005 - Withdrawal Space - 1hb

No Asbestos

B00R - R0006 - Breakout Area

No Asbestos

B00R - R0007 - Home Base

No Asbestos

B00R - R0008 - Cleaning Distributed Store

No Asbestos

B00R - R0009 - Access Shower/Toilet - Type 2

No Asbestos

B00R - R0010 - Plant

No Asbestos

B00R - R0011 - Home Base Store

No Asbestos

B00R - R0012 - Breakout Area

No Asbestos

B00R - R0013 - Withdrawal Space - 1hb

No Asbestos

B00R - R0014 - Home Base

No Asbestos

B00R - R0015 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00R - R0016 - Practical Activities - 1hb

No Asbestos

B00R - R0017 - Therapy

No Asbestos

B00R - R0018 - Practical Activities - 1hb

No Asbestos

B00R - R0019 - Withdrawal Space - 1hb

No Asbestos

B00R - R0020 - Breakout Area

No Asbestos

B00R - R0021 - Home Base Store

No Asbestos

B00R - R0022 - Home Base

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00R - R0023 - Change - Type 2						
No Asbestos						
B00R - R0024 - Access Shower/Toilet - Type 2						
No Asbestos						
B00R - R0025 - Laundry - P						
No Asbestos						
B00R - R0026 - Access Shower/Toilet - Type 2						
No Asbestos						
B00R - R0027 - Breakout Area						
No Asbestos						
B00R - R0028 - Withdrawal Space - 1hb						
No Asbestos						
B00R - R0029 - Home Base Store						
No Asbestos						
B00R - R0030 - Home Base						
No Asbestos						
B00R - R0031 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						
B00R - R0032 - Practical Activities - 1hb						
No Asbestos						
B00R - R0033 - Plant						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00T - Building Services - 2013 - Metal Shed (Metal Shed)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior

B00T - R0001 - General Assistant/Bulk Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00U - General Learning - 2013 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B00U - R0001 - External Movement**

No Asbestos

B00U - R0002 - Practical Activities/Movement - 1hb

No Asbestos

B00U - R0003 - Home Base

No Asbestos

B00U - R0004 - Breakout Area

No Asbestos

B00U - R0005 - Home Base Store

No Asbestos

B00U - R0006 - Movement

No Asbestos

B00U - R0007 - Access Shower/Toilet/Change

No Asbestos

B00U - R0008 - Access Shower/Toilet/Change

No Asbestos

B00U - R0009 - Home Base Store

No Asbestos

B00U - R0010 - Breakout Area

No Asbestos

B00U - R0011 - Withdrawal Space - 1hb

No Asbestos

B00U - R0012 - Home Base

No Asbestos

B00U - R0013 - Practical Activities/Movement - 1hb

No Asbestos

B00U - R0014 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00U - R0015 - Therapy

No Asbestos

B00U - R0016 - Practical Activities/Movement - 1hb

No Asbestos

B00U - R0017 - Home Base

No Asbestos

B00U - R0018 - Withdrawal Space - 1hb

No Asbestos

B00U - R0019 - Breakout Area

No Asbestos

B00U - R0020 - Home Base Store

No Asbestos

B00U - R0021 - Change - Type 2

No Asbestos

B00U - R0022 - Access Shower/Toilet - Type 2

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00U - R0023 - Cleaning Distributed Store						
No Asbestos						
B00U - R0024 - Access Shower/Toilet - Type 2						
No Asbestos						
B00U - R0025 - Change - Type 2						
No Asbestos						
B00U - R0026 - Breakout Area						
No Asbestos						
B00U - R0027 - Withdrawal Space - 1hb						
No Asbestos						
B00U - R0028 - Home Base Store						
No Asbestos						
B00U - R0029 - Home Base						
No Asbestos						
B00U - R0030 - Practical Activities/Movement - 1hb						
No Asbestos						
B00U - R0031 - General Storeroom						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0PA - Support Unit (M P S) - 2007 - Fibre Cement Clad (Fibre Cement Clad)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B0PA - R0001 - Tutorial Centre**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0PA - R0002 - Seminar/Study

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0PA - R0003 - General Storeroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0PA - R0004 - General Storeroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0PA - R0005 - Tutorial Centre

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0PA - R0006 - Toilets - Boys/Girls

No Asbestos

B0PA - R0007 - Toilet - M

No Asbestos

B0PA - R0008 - Staff Room Annexe

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0PA - R0009 - Staff Kitchen

No Asbestos

B0PA - R0010 - Toilet - M

No Asbestos

B0PA - R0011 - Practical Activities - M - 1hb

No Asbestos

B0PA - R0012 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017