


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Kandeer School (5744)
Region : Riverina
State Electorate : Albury
Local Government Area : Albury

Initial Survey : Noel Arnold & Associates : 12 - Mar - 2008
Register Issue Date : 23 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Other - 2006 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00C - R0001 - Practical Activities

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning - 2010 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00D - R0001 - Home Base

No Asbestos

B00D - R0002 - Home Base Store

No Asbestos

B00D - R0003 - Practical Activities

No Asbestos

B00D - R0004 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Other/Special Purpose - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00E - R0001 - Garage/Carport

No Asbestos

B00E - R0002 - Practical Activities - S - 1hb

No Asbestos

B00E - R0003 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning - 2013 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00F - R0001 - Toilets - Girls**

No Asbestos

B00F - R0002 - Toilets-Unisex

No Asbestos

B00F - R0003 - Movement

No Asbestos

B00F - R0004 - Toilets - Boys

No Asbestos

B00F - R0005 - Craft Room

No Asbestos

B00F - R0006 - Craft Room

No Asbestos

B00F - R0007 - Drinking Facilities

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00G - Administration - 2013 - Steel (Steel)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00G - R0001 - Security Store**

No Asbestos

B00G - R0002 - Staff Room

No Asbestos

B00G - R0003 - Reading Area

No Asbestos

B00G - R0004 - Staff Kitchen

No Asbestos

B00G - R0005 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00G - R0006 - Principal

No Asbestos

B00G - R0007 - Cleaning Distributed Store

No Asbestos

B00G - R0008 - Sick Bay

No Asbestos

B00G - R0009 - Movement

No Asbestos

B00G - R0010 - Movement

No Asbestos

B00G - R0011 - Clerical Office

No Asbestos

B00G - R0012 - Staff Toilet

No Asbestos

B00G - R0013 - Access Shower/Toilet

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - General Learning - 2013 - Steel (Steel)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00H - R0001 - Home Base**

No Asbestos

B00H - R0002 - General Storeroom

No Asbestos

B00H - R0003 - Practical Activities

No Asbestos

B00H - R0004 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - General Learning - 2013 - Steel (Steel)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00I - R0001 - Home Base**

No Asbestos

B00I - R0002 - General Storeroom

No Asbestos

B00I - R0003 - Practical Activities

No Asbestos

B00I - R0004 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - General Learning - 2013 - Steel (Steel)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00J - R0001 - Home Base**

No Asbestos

B00J - R0002 - General Storeroom

No Asbestos

B00J - R0003 - Practical Activities

No Asbestos

B00J - R0004 - Movement

No Asbestos

B00J - R0005 - Practical Activities

No Asbestos

B00J - R0006 - General Storeroom

No Asbestos

B00J - R0007 - Home Base

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Storage - 2013 - Timber Shed (Timber Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00K - R0001 - Garden Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017