

# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Kempsey High School (8123)  
**Region :** North Coast  
**State Electorate :** Oxley  
**Local Government Area :** Kempsey

**Initial Survey :** Noel Arnold & Associates : 01 - May - 2008  
**Reviewed By :** AECOM : 29 - Oct - 2014



# 2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - Administration/General Learning - 1972 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting	100m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - Height Restriction (6-7m)</b>						
Underfloor Voids	No Asbestos Found					
Ceiling Voids - Flat Roof	Non Accessible Area - Generally fixed ceilings to first floor, limited access for inspection to ground floor.					

**Interior****B00A - R0001 - General Storeroom (2.83 m2)**

No Asbestos

**B00A - R0002 - Security Store (16.36 m2)**

No Asbestos

**B00A - R0003 - Leading Teacher (15.64 m2)**

No Asbestos

**B00A - R0004 - Deputy Principal Office (16.3 m2)**

No Asbestos

**B00A - R0005 - Duplicating Workroom (26.39 m2)**

No Asbestos

**B00A - R0006 - Interview/Office - Type 1 (16.52 m2)**

No Asbestos

**B00A - R0007 - Interview/Office - Type 1 (13.05 m2)**

No Asbestos

**B00A - R0008 - Clinic - Boys (12.98 m2)**

No Asbestos

**B00A - R0009 - Toilets-Boys (2.2 m2)**

No Asbestos

**B00A - R0010 - Toilets-Girls (2.33 m2)**

No Asbestos

**B00A - R0011 - Clinic - Girls (13.02 m2)**

No Asbestos

**B00A - R0012 - Distribution Board Cupboard (1.2 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00A - R0013 - Cleaning Store - Distributed (3.88 m2)**

No Asbestos

**B00A - R0014 - External Movement (2.24 m2)**

No Asbestos

**B00A - R0015 - Ancillary Staff (21.99 m2)**

No Asbestos

**B00A - R0018 - Principal Office (19.32 m2)**

No Asbestos

**B00A - R0019 - Public Entry (21.01 m2)**

No Asbestos

**B00A - R0020 - Administration - Clerical (43.37 m2)**

No Asbestos

**B00A - R0021 - Pupil Entry (50.06 m2)**

No Asbestos

**B00A - R0022 - External Movement (10.38 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

**B00A - R0023 - Movement (24.97 m2)**

No Asbestos

**B00A - R0024 - Movement (26.86 m2)**

No Asbestos

**B00A - R0025 - Toilet - Lobby (3.74 m2)**

No Asbestos

**B00A - R0026 - Staff - Toilet (1.62 m2)**

No Asbestos

**B00A - R1001 - General Learning Space (53.73 m2)**

No Asbestos

**B00A - R1002 - General Learning Space (52.88 m2)**

No Asbestos

**B00A - R1003 - Resources Store (12.77 m2)**

No Asbestos

**B00A - R1004 - General Learning Space (40.6 m2)**

No Asbestos

**B00A - R1005 - General Learning Space (53.37 m2)**

No Asbestos

**B00A - R1006 - Interview/Office - Type 1 (26.21 m2)**

No Asbestos

**B00A - R1007 - Staff - Toilet (4.33 m2)**

No Asbestos

**B00A - R1008 - Staff Study (33.85 m2)**

No Asbestos

**B00A - R1009 - Staff - Toilet (4.26 m2)**

No Asbestos

**B00A - R1010 - Movement (68.33 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - General Learning - 1928 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting	100m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - Height Restriction (8-9m)</b>						
Ceiling Voids	Non Accessible Area - Height Restriction (4-5m)					
Underfloor Voids	AC Fragments/Debris	NA	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
8123/B00B/Underfloor Voids/S30					<b>Chrysotile (white asbestos)</b>	
Underfloor Voids	AC Fragments/Debris	NA	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
8123/B00B/Underfloor Voids/S30					<b>Chrysotile (white asbestos)</b>	
Underfloor Voids	Flat AC Sheeting	2m2	Around electrical conduits in southwest corner of void	Minimal Damage (2)	Low (1)	Low Priority (2-3)
8123/B00J/Underfloor Voids/S33					<b>Positive Result(s) , Amosite (brown asbestos)</b>	

**Interior**

**B00B - R0001 - Resources Store (5.01 m2)**

No Asbestos

**B00B - R0002 - Performance Workspace (86.24 m2)**

No Asbestos

**B00B - R0003 - Performing Arts Store (16.24 m2)**

No Asbestos

**B00B - R0004 - Art Learning Space (51 m2)**

No Asbestos

**B00B - R0005 - General Learning Space (51.14 m2)**

No Asbestos

**B00B - R0006 - General Learning Space (45.98 m2)**

No Asbestos

**B00B - R0007 - Cleaning Store - Distributed (5.23 m2)**

No Asbestos

**B00B - R0008 - Movement (22.11 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					
8123/B00B/R0008/Floor Coverings Res/Textile/S1					<b>No Asbestos Detected</b>	

**B00B - R0009 - Resources Store (13.7 m2)**

No Asbestos

**B00B - R0015 - Staff Study (16.78 m2)**

No Asbestos

**B00B - R0016 - Staff - Toilet (3.38 m2)**

Wall Linings Internal	Flat AC Sheeting					
8123/B00B/R0016/Wall Linings Internal/S2					<b>No Asbestos Detected</b>	

**B00B - R0017 - Movement (90.11 m2)**

No Asbestos

**B00B - R0018 - Movement (4.24 m2)**

No Asbestos

**B00B - R0019 - External Movement (3.03 m2)**

No Asbestos

**B00B - R0020 - External Movement (2.38 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

**B00B - R0021 - External Movement (25.61 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	24m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	------	------------	--------------------	---------	--------------------

**Assumed Asbestos - Height Restriction (2-3m)**

**B00B - R0022 - External Movement (4 m2)**

No Asbestos

**B00B - R0023 - Toilets-Boys (3.23 m2)**

Wall Linings Internal	Flat AC Sheeting	8123/B00B/R0023/Wall Linings Internal/S27				No Asbestos Detected
-----------------------	------------------	---	--	--	--	----------------------

Ceiling Structures/Linings	Flat AC Sheeting	8123/B00B/R0023/Ceiling Structures/Linings/S28				No Asbestos Detected
----------------------------	------------------	--	--	--	--	----------------------

**B00B - R0024 - Toilets-Boys (3.23 m2)**

Wall Linings Internal	Flat AC Sheeting	8123/B00B/R0023/Wall Linings Internal/S27				No Asbestos Detected
-----------------------	------------------	---	--	--	--	----------------------

Ceiling Structures/Linings	Flat AC Sheeting	8123/B00B/R0023/Ceiling Structures/Linings/S28				No Asbestos Detected
----------------------------	------------------	--	--	--	--	----------------------

**B00B - R0025 - Toilets-Boys (3.23 m2)**

Wall Linings Internal	Flat AC Sheeting	8123/B00B/R0023/Wall Linings Internal/S27				No Asbestos Detected
-----------------------	------------------	---	--	--	--	----------------------

Ceiling Structures/Linings	Flat AC Sheeting	8123/B00B/R0023/Wall Linings Internal/S27				No Asbestos Detected
----------------------------	------------------	---	--	--	--	----------------------

**B00B - R0026 - Toilets-Boys (3.23 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	8123/B00B/R0023/Ceiling Structures/Linings/S28				No Asbestos Detected
----------------------------	------------------	--	--	--	--	----------------------

Wall Linings Internal	Flat AC Sheeting	8123/B00B/R0023/Wall Linings Internal/S27				No Asbestos Detected
-----------------------	------------------	---	--	--	--	----------------------

**B00B - R0027 - General Learning Space (52.56 m2)**

No Asbestos

**B00B - R0030 - Staff Lounge (5.56 m2)**

No Asbestos

**B00B - R0031 - Staff Kitchen (28.02 m2)**

No Asbestos

**B00B - R0032 - Staff Lounge (35.4 m2)**

No Asbestos

**B00B - R0033 - Staff Kitchen (8.67 m2)**

No Asbestos

**B00B - R0034 - Stairs (8.1 m2)**

No Asbestos

**B00B - R0035 - Stairs (7.64 m2)**

No Asbestos

**B00B - R0036 - Stairs (3.42 m2)**

No Asbestos

**B00B - R1001 - Resources Store (8.97 m2)**

No Asbestos

**B00B - R1002 - Resources Store (8.81 m2)**

No Asbestos

**B00B - R1003 - Computer Learning Space (51.98 m2)**

No Asbestos

**B00B - R1004 - General Learning Space (52.72 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

**B00B - R1005 - General Learning Space (51.76 m2)**

No Asbestos

**B00B - R1006 - Computer Learning Space (51.91 m2)**

No Asbestos

**B00B - R1007 - General Learning Space (47.47 m2)**

No Asbestos

**B00B - R1008 - Staff Study (8.95 m2)**

No Asbestos

**B00B - R1009 - Cleaning Store - Distributed (1.99 m2)**

No Asbestos

**B00B - R1011 - General Learning Space (35.94 m2)**

No Asbestos

**B00B - R1012 - Staff Study (20.86 m2)**

No Asbestos

**B00B - R1013 - Staff Study (21.07 m2)**

No Asbestos

**B00B - R1017 - Movement (32.77 m2)**

No Asbestos

**B00B - R1018 - Movement (6.29 m2)**

No Asbestos

**B00B - R1019 - General Storeroom (14.53 m2)**

No Asbestos

**B00B - R1020 - General Learning Space (51.04 m2)**

No Asbestos

**B00B - R1021 - Movement (93.91 m2)**

No Asbestos

**B00B - R1022 - Stairs (12.41 m2)**

No Asbestos

**B00B - R1023 - Stairs (12.27 m2)**

No Asbestos

**B00B - R9001 - Movement (5.09 m2)**

No Asbestos

**B00B - R9002 - Visual Arts Store (2.86 m2)**

No Asbestos

**B00B - R9003 - Visual Arts Store (10.12 m2)**

No Asbestos

**B00B - R9004 - Visual Arts Store (12.53 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - General Learning - 1956 - Timber (Timber)****Exterior**

Eaves Linings	Flat AC Sheeting	30m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
---------------	------------------	------	------------	--------------------	---------	--------------------

**Assumed Asbestos - Height Restriction (3-4m)**

Underfloor Voids	AC Fragments/Debris 8123/B00C/Underfloor Voids/S29					<b>No Asbestos Detected</b>
------------------	---	--	--	--	--	-----------------------------

Ceiling Voids	Flat AC Sheeting	NA	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8123/B00C/R0010/Ceiling Structures/Linings/S11					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**Interior****B00C - R0001 - Serviced Learning Space (83.92 m2)**

No Asbestos

**B00C - R0002 - Preparation (8.8 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					
	8123/B00C/R0002/Floor Coverings Res/Textile/S13					<b>No Asbestos Detected</b>

**B00C - R0003 - General Learning Space (49.93 m2)**

No Asbestos

**B00C - R0004 - Staff Study (15.48 m2)**

No Asbestos

**B00C - R0005 - Staff - Toilet (4.64 m2)**

No Asbestos

**B00C - R0006 - Cleaning Store - Distributed (2.88 m2)**

No Asbestos

**B00C - R0008 - External Movement (2.16 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8123/B00C/R0010/Ceiling Structures/Linings/S11					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00C - R0009 - General Storeroom (6.35 m2)**

No Asbestos

**B00C - R0010 - External Movement (1.92 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8123/B00C/R0010/Ceiling Structures/Linings/S11					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00C - R0011 - Movement (32.01 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					
	8123/B00C/R0011/Floor Coverings Res/Textile/S12					<b>No Asbestos Detected</b>

**B00C - R0012 - Movement (20.83 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					
	8123/B00C/R0011/Floor Coverings Res/Textile/S12					<b>No Asbestos Detected</b>

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - Science/Art - 1965 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting	40m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
---------------	------------------	------	-------	--------------------	---------	--------------------

**Assumed Asbestos - Height Restriction (6-8m)**

Ceiling Voids	No Asbestos Found					
---------------	-------------------	--	--	--	--	--

Underfloor Voids	Bituminous dampcourse between walls and concrete beams 8123/B00F/Underfloor Voids/S31					<b>No Asbestos Detected</b>
------------------	--	--	--	--	--	-----------------------------

**Interior**

<b>B00F - R0018 - Distribution Board Cupboard (1.24 m2)</b>	Note: No inspection of live electrical installation.
---	--

No Asbestos

<b>B00F - R0020 - Main Switchroom (4.43 m2)</b>
---

No Asbestos

<b>B00F - R0021 - External Movement (1.72 m2)</b>
---

No Asbestos

<b>B00F - R0022 - External Movement (0.97 m2)</b>
---

No Asbestos

<b>B00F - R0024 - Pantry (5.16 m2)</b>
--

Floor Coverings Res/Textile	Vinyl Tiles 8123/B00E/R0012/Floor Coverings Res/Textile/S5					<b>No Asbestos Detected</b>
-----------------------------	---	--	--	--	--	-----------------------------

<b>B00F - R0025 - Laundry (9.49 m2)</b>
---

No Asbestos

<b>B00F - R0026 - Preparation (22.13 m2)</b>
--

No Asbestos

<b>B00F - R0027 - Cleaning Store - Distributed (0.9 m2)</b>
---

No Asbestos

<b>B00F - R0028 - Kitchen - Type 1 (106.32 m2)</b>
--

No Asbestos

<b>B00F - R0029 - Materials Store (19.22 m2)</b>
--

No Asbestos

<b>B00F - R0030 - General Learning Space (59.42 m2)</b>
---

No Asbestos

<b>B00F - R0031 - Handwashing Facilities (2.24 m2)</b>
--

No Asbestos

<b>B00F - R0032 - Staff - Toilet (2.25 m2)</b>
--

No Asbestos

<b>B00F - R0033 - General Learning Space (53.88 m2)</b>
---

No Asbestos

<b>B00F - R0034 - Change (5.18 m2)</b>
--

No Asbestos

<b>B00F - R0035 - Materials Store (8.41 m2)</b>
---

No Asbestos

<b>B00F - R0036 - Movement (5.08 m2)</b>
--

No Asbestos

<b>B00F - R0037 - General Learning Space (62.51 m2)</b>
---

No Asbestos

<b>B00F - R0038 - Wood Technology Bay (105.81 m2)</b>
---



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No						Test Result
No Asbestos						
<b>B00F - R0039 - General Learning Space (59.35 m2)</b>						
No Asbestos						
<b>B00F - R0040 - Movement (194.16 m2)</b>						
No Asbestos						
<b>B00F - R0041 - Materials Store (25.31 m2)</b>						
No Asbestos						
<b>B00F - R0042 - Staff Study (33.87 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	33m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8123/B00F/R0007/Floor Coverings Res/Textile/S21						<b>Chrysotile (white asbestos)</b>
<b>B00F - R0043 - Lift (2.24 m2)</b>						
No Asbestos						
<b>B00F - R0044 - Stairs (2.72 m2)</b>						
No Asbestos						
<b>B00F - R0045 - Stairs (4.67 m2)</b>						
No Asbestos						
<b>B00F - R0046 - Stairs (2.72 m2)</b>						
Recently Modified Space Requires Inspection						
<b>B00F - R1022 - Distribution Board Cupboard (1.06 m2)</b>						
						Note: No inspection of live electrical installation.
No Asbestos						
<b>B00F - R1023 - Distribution Board Cupboard (1.29 m2)</b>						
						Note: No inspection of live electrical installation.
No Asbestos						
<b>B00F - R1025 - Darkroom Space (2.67 m2)</b>						
No Asbestos						
<b>B00F - R1026 - Dark Room (22.22 m2)</b>						
No Asbestos						
<b>B00F - R1027 - General Learning Space (52.28 m2)</b>						
No Asbestos						
<b>B00F - R1028 - Movement (5.11 m2)</b>						
No Asbestos						
<b>B00F - R1029 - Art Learning Space (113.02 m2)</b>						
No Asbestos						
<b>B00F - R1030 - Materials Store (11.28 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
8123/B00H/R0005/Floor Coverings Res/Textile/S14						<b>No Asbestos Detected</b>
<b>B00F - R1031 - Pottery Store (9.71 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	9.7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8123/B00F/R0007/Floor Coverings Res/Textile/S21						<b>Chrysotile (white asbestos)</b>
<b>B00F - R1032 - Kiln Space (9.62 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	9.6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8123/B00F/R0007/Floor Coverings Res/Textile/S21						<b>Chrysotile (white asbestos)</b>
<b>B00F - R1033 - Materials Store (18.73 m2)</b>						
No Asbestos						
<b>B00F - R1034 - General Learning Space - Type 4 (59.35 m2)</b>						
No Asbestos						
<b>B00F - R1035 - Staff Study (26.4 m2)</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
	No Asbestos					
	<b>B00F - R1036 - Seminar/Technology Space (25.08 m2)</b>					
	No Asbestos					
	<b>B00F - R1037 - Music Learning Space (85.57 m2)</b>					
	No Asbestos					
	<b>B00F - R1038 - Music Store (12.78 m2)</b>					
	No Asbestos					
	<b>B00F - R1039 - Music Learning Space (12.8 m2)</b>					
	No Asbestos					
	<b>B00F - R1040 - Multi Media Workshop (105.66 m2)</b>					
	No Asbestos					
	<b>B00F - R1041 - Multi Media Store (20.16 m2)</b>					
	No Asbestos					
	<b>B00F - R1042 - Multi Media Studio (11.18 m2)</b>					
	No Asbestos					
	<b>B00F - R1043 - Cleaning Store - Distributed (1.66 m2)</b>					
	No Asbestos					
	<b>B00F - R1044 - Movement (126.38 m2)</b>					
	No Asbestos					
	<b>B00F - R1045 - Stairs (5.76 m2)</b>					
	No Asbestos					
	<b>B00F - R1046 - Stairs (5.54 m2)</b>					
	No Asbestos					
	<b>B00F - R9002 - Materials Store (8.49 m2)</b>					
	No Asbestos					
	<b>B00F - R9007 - Cleaning Store - Distributed (7.6 m2)</b>					
	No Asbestos					
	<b>B00F - R9010 - General Learning Space (58.33 m2)</b>					
	No Asbestos					
	<b>B00F - R9011 - Metal Technology Bay (105.59 m2)</b>					
	No Asbestos					
	<b>B00F - R9012 - General Learning Space (58.47 m2)</b>					
	No Asbestos					
	<b>B00F - R9013 - Movement (55.76 m2)</b>					
	No Asbestos					
	<b>B00F - R9014 - Materials Store (47.31 m2)</b>					
	No Asbestos					
	<b>B00F - R9015 - Distribution Board Cupboard (0.64 m2)</b>				Note: No inspection of live electrical installation.	
	No Asbestos					
	<b>B00F - R9016 - Movement (5.06 m2)</b>					
	No Asbestos					
	<b>B00F - R9018 - Stairs (5.01 m2)</b>					
	No Asbestos					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - Pupil Facilities - 1930 - Brick/Veneer (Brick/Veneer)****Exterior**

Eaves Linings	Flat AC Sheeting	5m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
---------------	------------------	-----	--------------	--------------------	---------	--------------------

**Assumed Asbestos - Height Restriction (3-4m)**

Underfloor Voids - Slab on Ground	No Asbestos Found
-----------------------------------	-------------------

Ceiling Voids	Non Accessible Area - No access due height (3m) and access hatch nailed shut. Asbestos unlikely.
---------------	--

**Interior****B00G - R0001 - No Access (12.56 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - Multi Purpose Facilities - 1960 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					
Ceiling Voids	No Asbestos Found					

**Interior**

**B00H - M0001 - General Storeroom (18.2 m2)**

No Asbestos

**B00H - R0001 - Staff Kitchen (12.14 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					
	8123/B00H/R0005/Floor Coverings Res/Textile/S14					<b>No Asbestos Detected</b>

Ceiling Structures/Linings	Flat AC Sheeting	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8123/B00H/R0005/Ceiling Structures/Linings/S15					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00H - R0002 - Multi-Purpose Space (408.29 m2)**

No Asbestos

**B00H - R0003 - Stage (113.36 m2)**

No Asbestos

**B00H - R0004 - General Storeroom (3.18 m2)**

No Asbestos

**B00H - R0005 - Chair Store (12.1 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					
	8123/B00H/R0005/Floor Coverings Res/Textile/S14					<b>No Asbestos Detected</b>

Ceiling Structures/Linings	Flat AC Sheeting	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8123/B00H/R0005/Ceiling Structures/Linings/S15					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00H - R0006 - External Movement (42.97 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	43m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8123/B00H/R0005/Ceiling Structures/Linings/S15					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00H - R0007 - External Movement (3.99 m2)**

No Asbestos

**B00H - R0008 - External Movement (4.25 m2)**

No Asbestos

**B00H - R0009 - Stairs (9.17 m2)**

No Asbestos

**B00H - R0010 - Stairs (8.56 m2)**

No Asbestos

**B00H - R0011 - External Movement (14.6 m2)**

No Asbestos

**B00H - R0012 - Toilets-Boys (3.23 m2)**

Ceiling Structures/Linings	Flat AC Sheeting					
	8123/B00H/R0012/Ceiling Structures/Linings/S26					<b>No Asbestos Detected</b>

**B00H - R0013 - Toilets-Boys (3.23 m2)**

Ceiling Structures/Linings	Flat AC Sheeting					
	8123/B00H/R0012/Ceiling Structures/Linings/S26					<b>No Asbestos Detected</b>

**B00H - R0014 - Cleaning Supplies Store (5.6 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Ceiling Structures/Linings	Flat AC Sheeting 8123/B00H/R0012/Ceiling Structures/Linings/S26					No Asbestos Detected
<b>B00H - R0015 - Toilets-Girls (3 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting 8123/B00H/R0012/Ceiling Structures/Linings/S26					No Asbestos Detected
<b>B00H - R0016 - Access Student Shower/Toilet/Change (5.54 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting 8123/B00H/R0012/Ceiling Structures/Linings/S26					No Asbestos Detected
<b>B00H - R0017 - Toilets-Girls (3.3 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting 8123/B00H/R0012/Ceiling Structures/Linings/S26					No Asbestos Detected
<b>B00H - R0018 - Movement (7.05 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting 8123/B00H/R0012/Ceiling Structures/Linings/S26					No Asbestos Detected
<b>B00H - R9001 - Movement (4.01 m2)</b>						
No Asbestos						
<b>B00H - R9002 - Performing Arts Changeroom (25.44 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	26m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8123/B00H/R9008/Ceiling Structures/Linings/S19					Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00H - R9003 - Toilets-Boys (1.48 m2)</b>						
No Asbestos						
<b>B00H - R9004 - Toilets-Boys (1.48 m2)</b>						
No Asbestos						
<b>B00H - R9005 - General Storeroom (17.46 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8123/B00H/R9008/Ceiling Structures/Linings/S19					Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00H - R9006 - General Storeroom (26.59 m2)</b>						
No Asbestos						
<b>B00H - R9007 - General Assistants (16.93 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8123/B00H/R9008/Ceiling Structures/Linings/S19					Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00H - R9008 - General Assistants (28.34 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	29m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8123/B00H/R9008/Ceiling Structures/Linings/S19					Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00H - R9009 - General Storeroom (25.85 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	26m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8123/B00H/R9008/Ceiling Structures/Linings/S19					Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00H - R9010 - External Movement (3.99 m2)</b>						
No Asbestos						
<b>B00H - R9012 - Stairs (4.58 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8123/B00H/R9008/Ceiling Structures/Linings/S19					Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00H - R9013 - Stairs (9.17 m2)</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

**B00H - R9014 - External Movement (11.12 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00I - Building Services - 2000 - Timber Shed (Timber Shed)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00I - R0001 - Sport Equipment Store (36.13 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00J - Multi Purpose Facilities - 1973 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids	Non Accessible Area - No access due fixed ceiling (strammit tiles) and height in areas (up to 7m)					
Underfloor Voids	Fibre Cement Pipe	3Unit	Southeastern section of void	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8123/B00J/Underfloor Voids/S32					<b>Chrysotile (white asbestos)</b>
Underfloor Voids	Fibre Cement Pipe	2Unit	Service conduits running through concrete slab	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8123/B00J/Underfloor Voids/S32					<b>Chrysotile (white asbestos)</b>
Underfloor Voids	Flat AC Sheeting	NA	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	8123/B00B/Underfloor Voids/S30					<b>Chrysotile (white asbestos)</b>
Underfloor Voids	Flat AC sheeting and associated debris	4m2	Around electrical service conduits in southeast and southwest corners of void	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	8123/B00J/Underfloor Voids/S33					<b>Positive Result(s) , Amosite (brown asbestos)</b>

**Interior****B00J - R0001 - General Storeroom (18.83 m2)**

No Asbestos

**B00J - R0002 - Cleaning Store - Distributed (1.01 m2)**

No Asbestos

**B00J - R0003 - Sport Equipment Store (16.94 m2)**

No Asbestos

**B00J - R0004 - Distribution Board Cupboard (0.92 m2)**

Note: No inspection of live electrical installation.

Non Accessible

**B00J - R0005 - Movement (77.12 m2)**Ceiling Structures/Linings Vermiculite  
8123/B00J/R0005/Ceiling Structures/Linings/S9**Limited Samples Taken****Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works****B00J - R0006 - General Storeroom (17.47 m2)**

No Asbestos

**B00J - R0007 - Sport Equipment Store (16.08 m2)**

No Asbestos

**B00J - R0008 - Garden Store Room (5.08 m2)**

No Asbestos

**B00J - R0009 - Movement (48.22 m2)**

No Asbestos

**B00J - R0010 - General Storeroom (10.11 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8123/B00J/R1013/Floor Coverings Res/Textile/S8					<b>Chrysotile (white asbestos)</b>

**B00J - R0011 - Student Canteen (47.55 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	48m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8123/B00J/R1013/Floor Coverings Res/Textile/S8					<b>Chrysotile (white asbestos)</b>

**B00J - R0012 - General Storeroom (6.53 m2)**



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8123/B00J/R1013/Floor Coverings Res/Textile/S8					Chrysotile (white asbestos)	
<b>B00J - R0013 - Cleaning Store - Distributed (0.91 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8123/B00J/R1013/Floor Coverings Res/Textile/S8					Chrysotile (white asbestos)	
<b>B00J - R0014 - Staff - Toilet (3.17 m2)</b>						
No Asbestos						
<b>B00J - R0015 - General Storeroom (6.4 m2)</b>						
No Asbestos						
<b>B00J - R0016 - General Storeroom (3.26 m2)</b>						
No Asbestos						
<b>B00J - R0017 - Cleaning Supplies Store (5.08 m2)</b>						
No Asbestos						
<b>B00J - R0018 - Movement (47.57 m2)</b>						
No Asbestos						
<b>B00J - R0019 - Multi-Purpose Space (310.02 m2)</b>						
No Asbestos						
<b>B00J - R0020 - Stairs (9.24 m2)</b>						
No Asbestos						
<b>B00J - R0021 - Stairs (9.24 m2)</b>						
No Asbestos						
<b>B00J - R0022 - External Movement (28.86 m2)</b>						
No Asbestos						
<b>B00J - R0023 - External Movement (9.95 m2)</b>						
No Asbestos						
<b>B00J - R1001 - Movement (10.8 m2)</b>						
No Asbestos						
<b>B00J - R1007 - Toilets-Boys (14.2 m2)</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8123/B00J/R1007/Partition Walls (Cubicles)/S7					Chrysotile (white asbestos)	
<b>B00J - R1008 - Shower/Change (46.59 m2)</b>						
No Asbestos						
<b>B00J - R1009 - Toilets-Girls (14.04 m2)</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8123/B00J/R1007/Partition Walls (Cubicles)/S7					Chrysotile (white asbestos)	
<b>B00J - R1010 - Shower/Change (46.93 m2)</b>						
No Asbestos						
<b>B00J - R1011 - Movement (4.25 m2)</b>						
No Asbestos						
<b>B00J - R1012 - Staff - Toilet (8.12 m2)</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8123/B00J/R1007/Partition Walls (Cubicles)/S7					Chrysotile (white asbestos)	
<b>B00J - R1013 - Staff Study (6.9 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8123/B00J/R1013/Floor Coverings Res/Textile/S8					Chrysotile (white asbestos)	
<b>B00J - R1014 - Staff Shower (1.54 m2)</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Partition Walls (Cubicles)	Compressed AC Sheet	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)

8123/B00J/R1007/Partition Walls (Cubicles)/S7

Chrysotile (white asbestos)

**B00J - R1015 - Cleaning Store - Distributed (4.04 m2)**

No Asbestos

**B00J - R1016 - Movement (10.82 m2)**

No Asbestos

**B00J - R1017 - Staff Study (18.45 m2)**

No Asbestos

**B00J - R1018 - Movement (60.82 m2)**

No Asbestos

**B00J - R1019 - Stairs (53.4 m2)**

No Asbestos

**B00J - R1020 - Stairs (53.4 m2)**

No Asbestos

**B00J - R1021 - Cleaning Store - Distributed (4.43 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00L - Science/Library - 1972 - Brick/Block (Brick/Block)****Exterior**

Underfloor Voids	Non Accessible Area - Area inaccessible, no designated access point found.
Ceiling Voids	Non Accessible Area - Generally no access due fixed ceilings. Limited inspection through access hatch in LR0001 did not identify asbestos.

**Interior****B00L - M1001 - Careers Advisers Office (19.23 m2)**

No Asbestos

**B00L - M1002 - Study Space (121.02 m2)**

No Asbestos

**B00L - M1003 - Movement (1.46 m2)**

No Asbestos

**B00L - M1004 - Plant Space (31.86 m2)**

No Asbestos

**B00L - M1005 - Stairs (4.08 m2)**

No Asbestos

**B00L - M1006 - Stairs (3.98 m2)**

No Asbestos

**B00L - R0001 - Laboratory L.S. (92.09 m2)**

Ceiling Structures/Linings	Vermiculite 8123/B00J/R0005/Ceiling Structures/Linings/S9	Limited Samples Taken
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>		

**B00L - R0002 - Apparatus Store (14.65 m2)**

No Asbestos

**B00L - R0003 - Distribution Board Cupboard (0.78 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00L - R0004 - Laboratory L.S. (91.99 m2)**

Floor Coverings Res/Textile	Vinyl Tiles 8123/B00C/R0002/Floor Coverings Res/Textile/S13	No Asbestos Detected
Ceiling Structures/Linings	Vermiculite 8123/B00J/R0005/Ceiling Structures/Linings/S9	Limited Samples Taken
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>		

**B00L - R0005 - Preparation (47.95 m2)**

Ceiling Structures/Linings	Vermiculite 8123/B00J/R0005/Ceiling Structures/Linings/S9	Limited Samples Taken
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>		

**B00L - R0006 - Laboratory L.S. (92.1 m2)**

Ceiling Structures/Linings	Vermiculite 8123/B00J/R0005/Ceiling Structures/Linings/S9	Limited Samples Taken
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>		

**B00L - R0007 - Laboratory L.S. (91.98 m2)**

Ceiling Structures/Linings	Vermiculite 8123/B00J/R0005/Ceiling Structures/Linings/S9	Limited Samples Taken
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>		

**B00L - R0008 - Preparation (47.99 m2)**

Ceiling Structures/Linings	Vermiculite 8123/B00J/R0005/Ceiling Structures/Linings/S9	Limited Samples Taken
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>		

**B00L - R0009 - Movement (42.83 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles					
	8123/B00C/R0002/Floor Coverings Res/Textile/S13					No Asbestos Detected
Ceiling Structures/Linings	Vermiculite					
	8123/B00J/R0005/Ceiling Structures/Linings/S9					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00L - R0010 - Movement (29.72 m2)</b>						
No Asbestos						
<b>B00L - R0011 - Cleaning Store - Distributed (4.52 m2)</b>						
No Asbestos						
<b>B00L - R0012 - Main Switchroom (8.8 m2)</b>						
Electrical Backing Board	Resinous Board	1m2	West, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - Electrical Hazard</b>						
<b>B00L - R0013 - Stairs (12.82 m2)</b>						
No Asbestos						
<b>B00L - R0014 - Movement (17.08 m2)</b>						
No Asbestos						
<b>B00L - R0015 - Toilets-Girls (2.84 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting					
	8123/B00B/R0023/Ceiling Structures/Linings/S28					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting					
	8123/B00B/R0023/Wall Linings Internal/S27					No Asbestos Detected
<b>B00L - R0016 - Toilets-Girls (2.84 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting					
	8123/B00B/R0023/Ceiling Structures/Linings/S28					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting					
	8123/B00B/R0023/Wall Linings Internal/S27					No Asbestos Detected
<b>B00L - R0017 - Toilets-Girls (2.84 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting					
	8123/B00B/R0023/Ceiling Structures/Linings/S28					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting					
	8123/B00B/R0023/Wall Linings Internal/S27					No Asbestos Detected
<b>B00L - R0018 - Toilets-Girls (2.84 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting					
	8123/B00B/R0023/Ceiling Structures/Linings/S28					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting					
	8123/B00B/R0023/Wall Linings Internal/S27					No Asbestos Detected
<b>B00L - R0019 - Toilets-Girls (2.87 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting					
	8123/B00B/R0023/Wall Linings Internal/S27					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting					
	8123/B00B/R0023/Wall Linings Internal/S27					No Asbestos Detected
<b>B00L - R0020 - Toilets-Girls (2.81 m2)</b>						
Non Accessible						
<b>B00L - R1001 - Seminar (12.47 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8123/B00J/R0005/Ceiling Structures/Linings/S9					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00L - R1002 - Seminar (12.64 m2)</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite		8123/B00J/R0005/Ceiling Structures/Linings/S9			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00L - R1003 - Distribution Board Cupboard (2.45 m2)</b>						
Note: No inspection of live electrical installation.						
Ceiling Structures/Linings	Vermiculite		8123/B00J/R0005/Ceiling Structures/Linings/S9			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00L - R1004 - Cleaning Store - Distributed (2.76 m2)</b>						
Ceiling Structures/Linings	Vermiculite		8123/B00J/R0005/Ceiling Structures/Linings/S9			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00L - R1005 - Seminar (12.68 m2)</b>						
Ceiling Structures/Linings	Vermiculite		8123/B00J/R0005/Ceiling Structures/Linings/S9			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00L - R1006 - Seminar (12.68 m2)</b>						
Ceiling Structures/Linings	Vermiculite		8123/B00J/R0005/Ceiling Structures/Linings/S9			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00L - R1007 - Seminar (37.24 m2)</b>						
Ceiling Structures/Linings	Vermiculite		8123/B00J/R0005/Ceiling Structures/Linings/S9			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00L - R1008 - Workroom (48.45 m2)</b>						
Ceiling Structures/Linings	Vermiculite		8123/B00J/R0005/Ceiling Structures/Linings/S9			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00L - R1009 - Librarian (11.48 m2)</b>						
Ceiling Structures/Linings	Vermiculite		8123/B00J/R0005/Ceiling Structures/Linings/S9			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00L - R1010 - Toilets-Girls (6.57 m2)</b>						
No Asbestos						
<b>B00L - R1011 - Entry (4.45 m2)</b>						
Ceiling Structures/Linings	Vermiculite		8123/B00J/R0005/Ceiling Structures/Linings/S9			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00L - R1012 - Toilets-Boys (6.57 m2)</b>						
No Asbestos						
<b>B00L - R1013 - Main Area (363.67 m2)</b>						
In-fill-panel	Flat AC Sheeting	10m	Throughout, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	8123/B00L/R1013/In-fill-panel/S22					Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite		8123/B00J/R0005/Ceiling Structures/Linings/S9			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00L - R1014 - Movement (26.75 m2)</b>						
No Asbestos						
<b>B00L - R1015 - Stairs (18.37 m2)</b>						
No Asbestos						
<b>B00L - R1016 - Stairs (0.5 m2)</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Ceiling Structures/Linings Vermiculite  
 8123/B00J/R0005/Ceiling Structures/Linings/S9 **Limited Samples Taken**  
*Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works*

**B00L - R1017 - Stairs (0.5 m2)**

Ceiling Structures/Linings Vermiculite  
 8123/B00J/R0005/Ceiling Structures/Linings/S9 **Limited Samples Taken**  
*Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works*

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00M - Pupil Facilities - 2011 - Brick/Veneer (Brick/Veneer)****Exterior**

No Asbestos

**Interior****B00M - R0001 - Student Canteen (48.32 m2)**

No Asbestos

**B00M - R0002 - Distribution Board Cupboard (0.45 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00M - R0003 - Office/Store (10.89 m2)**

No Asbestos

**B00M - R0004 - Store - Coolroom (7.16 m2)**

No Asbestos

**B00M - R0005 - External Movement (105.42 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

### B00N - Other/Multi Purpose Facilities - 2011 - Brick/Veneer (Brick/Veneer)

#### Exterior

No Asbestos

#### Interior

##### B00N - R0001 - Aboriginal Resource Centre (65.59 m2)

No Asbestos

##### B00N - R0002 - Staff Study (19.45 m2)

No Asbestos

##### B00N - R0003 - Interview/Office - Type 2 (13.58 m2)

No Asbestos

##### B00N - R0004 - Toilets-Unisex (7 m2)

No Asbestos

##### B00N - R0005 - Distribution Board Cupboard (0.93 m2)

Note: No inspection of live electrical installation.

No Asbestos

##### B00N - R0006 - External Movement (16.74 m2)

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B000 - Technological & Applied Studies - 2011 - Brick/Veneer (Brick/Veneer)****Exterior**

No Asbestos

**Interior****B000 - R0001 - Outdoor Workshop (97.04 m2)**

No Asbestos

**B000 - R0002 - Materials Store (36.59 m2)**

No Asbestos

**B000 - R0003 - Handwashing Facilities (9.17 m2)**

No Asbestos

**B000 - R0004 - Dust Extraction Space (8.31 m2)**

No Asbestos

**B000 - R0005 - Distribution Board Cupboard (0.81 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B000 - R0006 - L.P.G. Store (1.56 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00P - Computer Learning/General Learning - 2010 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

**Interior**

**B00P - R0001 - Computer Learning Space (91.9 m2)**

No Asbestos

**B00P - R0002 - Seminar - Type 2 (18.84 m2)**

No Asbestos

**B00P - R0003 - Resource/Project Store (10.1 m2)**

No Asbestos

**B00P - R0004 - Computer Store (9.02 m2)**

No Asbestos

**B00P - R0005 - External Movement (28.77 m2)**

No Asbestos

**B00P - R0006 - Distribution Board Cupboard (0.46 m2)**

Note: No inspection of live electrical installation.

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00Q - Technological & Applied Studies - 2010 - Steel (Steel)**

**Exterior**

No Asbestos

**Interior**

**B00Q - R0001 - General Learning Space (53.17 m2)**

No Asbestos

**B00Q - R0002 - Growing/Breeding (17.24 m2)**

No Asbestos

**B00Q - R0003 - External Movement (28.42 m2)**

No Asbestos

**B00Q - R0004 - External Movement (19.34 m2)**

No Asbestos

**B00Q - R0005 - Materials Store (17.65 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

### B00R - Technological & Applied Studies - 2011 - Brick/Veneer (Brick/Veneer)

#### Exterior

No Asbestos

#### Interior

##### B00R - R0001 - External Movement (10.8 m2)

No Asbestos

##### B00R - R0002 - Food/Research Space (29.39 m2)

No Asbestos

##### B00R - R0003 - Distribution Board Cupboard (0.92 m2)

Note: No inspection of live electrical installation.

No Asbestos

##### B00R - R0004 - General Storeroom (14.98 m2)

No Asbestos

##### B00R - R0005 - Kitchen - Type 2 (94.96 m2)

No Asbestos

##### B00R - R0006 - Pantry (8.13 m2)

No Asbestos

##### B00R - R0007 - Preparation - Materials (18.44 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B0AG - Agricultural Science - 1970 - Brick/Block (Brick/Block)****Exterior**

Wall Cladding	Flat AC Sheeting	40m2	North, South, East, West, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	8123/B0AG/Wall Cladding/S23					<b>Chrysotile (white asbestos)</b>
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

**Interior****B0AG - R0001 - Staff - Toilet (1.95 m2)**

No Asbestos

**B0AG - R0002 - Staff Shower (4.95 m2)**

No Asbestos

**B0AG - R0003 - General Storeroom (9.47 m2)**

No Asbestos

**B0AG - R0004 - Machine Storage (40.39 m2)**

No Asbestos

**B0AG - R0005 - Plant Growing Space (7.83 m2)**

Wall Linings Internal	Flat AC Sheeting	10m2	Throughout, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	8123/B0AG/R0005/Wall Linings Internal/S24					<b>Chrysotile (white asbestos)</b>

**B0AG - R0006 - Agriculture Covered Area (18.02 m2)**

Wall Linings Internal	Flat AC Sheeting	5m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	8123/B0AG/R0005/Wall Linings Internal/S24					<b>Chrysotile (white asbestos)</b>

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

**B0G1 - General Learning - 1948 - Timber (Timber)**

**Exterior**

Eaves Linings	Flat AC Sheeting	20m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8123/B0G1/R0001/Ceiling Structures/Linings/S17			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Underfloor Voids	AC Fragments/Debris	NA	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	8123/B00B/Underfloor Voids/S30			<b>Chrysotile (white asbestos)</b>		
Ceiling Voids	AC Fragments/Debris	NA	Throughout	Some Damage - Unsealed (3)	Medium (2)	Medium Priority (4-5)
	8123/B0G1/R0001/Ceiling Structures/Linings/S17			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**Interior**

**B0G1 - R0001 - General Learning Space (52.42 m2)**

Wall Linings Internal	Flat AC Sheeting	20m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	8123/B0G1/R0001/Wall Linings Internal/S16			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Ceiling Structures/Linings	Flat AC Sheeting	53m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8123/B0G1/R0001/Ceiling Structures/Linings/S17			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B0G1 - R0002 - General Learning Space (52.34 m2)**

Wall Linings Internal	Flat AC Sheeting	20m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	8123/B0G1/R0001/Wall Linings Internal/S16			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Ceiling Structures/Linings	Flat AC Sheeting	53m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8123/B0G1/R0001/Ceiling Structures/Linings/S17			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B0G1 - R0003 - General Learning Space (52.06 m2)**

Wall Linings Internal	Flat AC Sheeting	30m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	8123/B0G1/R0001/Wall Linings Internal/S16			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Ceiling Structures/Linings	Flat AC Sheeting	52m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8123/B0G1/R0001/Ceiling Structures/Linings/S17			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B0G1 - R0004 - Special Learning Space (51.35 m2)**

Wall Linings Internal	Flat AC Sheeting	30m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	8123/B0G1/R0001/Wall Linings Internal/S16			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Ceiling Structures/Linings	Flat AC Sheeting	52m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8123/B0G1/R0001/Ceiling Structures/Linings/S17			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B0G1 - R0005 - External Movement (28.27 m2)**

Ceiling Structures/Linings	Flat AC Sheeting					<b>No Asbestos Detected</b>
	8123/B0G1/R0005/Ceiling Structures/Linings/S18					

**B0G1 - R0006 - Cleaning Store - Distributed (6.99 m2)**

Wall Linings Internal	Flat AC Sheeting	5m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	8123/B0G1/R0001/Wall Linings Internal/S16			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting		8123/B0G1/R0005/Ceiling Structures/Linings/S18			No Asbestos Detected
<b>B0G1 - R0007 - External Movement (28.39 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting		8123/B0G1/R0005/Ceiling Structures/Linings/S18			No Asbestos Detected
<b>B0G1 - R0008 - Resources Store (6.78 m2)</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B0G2 - General Learning - 1948 - Timber (Timber)****Exterior**

Eaves Linings	Flat AC Sheeting	30m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8123/B0G1/R0001/Ceiling Structures/Linings/S17			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Ceiling Voids	Non Accessible Area - No access due fixed ceilings, no designated access point.					
Underfloor Voids - Packing to Floor Joists	Packing					
	8123/B0G2/Underfloor Voids - Packing to Floor Joists/S34			<b>No Asbestos Detected</b>		
Underfloor Voids	AC Fragments/Debris	NA	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	8123/B00B/Underfloor Voids/S30			<b>Chrysotile (white asbestos)</b>		

**Interior****B0G2 - R0001 - General Learning Space (44.19 m2)**

Wall Linings Internal	Flat AC Sheeting	40m2	North, South, East, West, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	8123/B0G1/R0001/Wall Linings Internal/S16			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Ceiling Structures/Linings	Flat AC Sheeting	45m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8123/B0G1/R0001/Ceiling Structures/Linings/S17			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B0G2 - R0002 - General Learning Space (44.2 m2)**

Wall Linings Internal	Flat AC Sheeting	40m2	North, South, East, West, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	8123/B0G1/R0001/Wall Linings Internal/S16			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Ceiling Structures/Linings	Flat AC Sheeting	45m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8123/B0G1/R0001/Ceiling Structures/Linings/S17			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B0G2 - R0004 - General Storeroom (6.54 m2)**

Ceiling Structures/Linings	Flat AC Sheeting					<b>No Asbestos Detected</b>
	8123/B0G1/R0005/Ceiling Structures/Linings/S18					

**B0G2 - R0005 - External Movement (27.88 m2)**

Ceiling Structures/Linings	Flat AC Sheeting					<b>No Asbestos Detected</b>
	8123/B0G1/R0005/Ceiling Structures/Linings/S18					

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**BAG1 - Agricultural Science - 2009 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Slab on Ground      No Asbestos Found

Ceiling Voids      No Asbestos Found

**Interior**

**BAG1 - R0001 - External Movement (33.79 m2)**

No Asbestos

**BAG1 - R0004 - General Storeroom (199.97 m2)**

No Asbestos

**BAG1 - R0005 - Staff Study (12.17 m2)**

No Asbestos

**BAG1 - R0006 - Cleaning Supplies Store (5.98 m2)**

No Asbestos

**BAG1 - R0007 - Movement (20.6 m2)**

No Asbestos

**BAG1 - R0008 - Movement (20.12 m2)**

No Asbestos

**BAG1 - R0009 - Toilets - Boys (3.46 m2)**

No Asbestos

**BAG1 - R0010 - Toilets - Girls (3.46 m2)**

No Asbestos

**BAG1 - R0011 - Staff - Toilet (4.65 m2)**

No Asbestos

**BAG1 - R0012 - Stairs (0.71 m2)**

No Asbestos

**BAG1 - R1001 - Computer Learning Space (37.63 m2)**

No Asbestos

**BAG1 - R1002 - Computer Learning Space (29.26 m2)**

No Asbestos

**BAG1 - R1003 - Movement (2.17 m2)**

No Asbestos

**BAG1 - R1004 - Stairs (4.84 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**BAG2 - Agricultural Science - 2010 - Steel (Steel)**

**Exterior**

No Asbestos

**Interior**

**BAG2 - R0001 - Movement (6.93 m2)**

No Asbestos

**BAG2 - R0002 - Staff Study (10.23 m2)**

No Asbestos

**BAG2 - R0003 - General Learning Space (35.43 m2)**

No Asbestos

**BAG2 - R0004 - Class Tools Storage (34.95 m2)**

No Asbestos

**BAG2 - R0005 - Outdoor Learning Area (47.98 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017