


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Kyogle High School (8189)  
**Region :** North Coast  
**State Electorate :** Lismore  
**Local Government Area :** Kyogle

**Initial Survey :** Noel Arnold & Associates : 11 - Jun - 2008  
**Reviewed By :** Parsons Brinckerhoff : 24 - Feb - 2015



# 2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - Administration - 1955 - Brick/Block (Brick/Block)****Exterior**

Underfloor Voids	Packing	>1m2	Throughout	Some Damage - Unsealed (3)	Medium (2)	Medium Priority (4-5)
	8189/B00A/Underfloor Voids/S11			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Ceiling Voids	No Asbestos Found					

**Interior****B00A - R0001 - Secure Storeroom (17.09 m2)**

No Asbestos

**B00A - R0002 - Interview/Office - Type 1 (13.83 m2)**

No Asbestos

**B00A - R0003 - Administration - Clerical (10.82 m2)**

No Asbestos

**B00A - R0004 - Principal Office (20.52 m2)**

No Asbestos

**B00A - R0005 - Public Entry (20.36 m2)**

No Asbestos

**B00A - R0006 - Interview/Office - Type 1 (9.76 m2)**

No Asbestos

**B00A - R0007 - Administration - Clerical (23.56 m2)**

No Asbestos

**B00A - R0008 - Duplicating Workroom (20.69 m2)**

No Asbestos

**B00A - R0009 - Cleaning Store - Distributed (3.64 m2)**

No Asbestos

**B00A - R0010 - Distribution Board Cupboard (1.32 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00A - R0011 - Deputy Principal Office (16.86 m2)**

No Asbestos

**B00A - R0012 - Commonroom (85.19 m2)**

No Asbestos

**B00A - R0013 - Staff - Toilet (5.2 m2)**

No Asbestos

**B00A - R0014 - Staff - Toilet (5.34 m2)**

No Asbestos

**B00A - R0015 - Movement (64.34 m2)**

No Asbestos

**B00A - R0016 - Clinic - Girls (13.12 m2)**

No Asbestos

**B00A - R0017 - Clinic-Toilets (2.14 m2)**

No Asbestos

**B00A - R0018 - Clinic - Boys (13.15 m2)**

No Asbestos

**B00A - R0019 - Clinic-Toilets (2.14 m2)**

No Asbestos

**B00A - R0020 - Movement (7.24 m2)**

No Asbestos

**B00A - R9001 - General Storeroom (31.96 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

**B00A - R9002 - Cleaning Store - Distributed (6.08 m2)**

No Asbestos

**B00A - R9003 - Movement (21.42 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - Library/Science Learning - 1955 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior****B00B - R0001 - Laboratory L.S. (92.8 m2)**

Ceiling Structures/Linings	Vermiculite					
	8189/B00B/R1008/Ceiling Structures/Linings/S2					Limited Samples Taken
	<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>					
Floor Coverings Res/Textile	Vinyl Tiles	93m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8189/B00B/R0009/Floor Coverings Res/Textile/S8					Chrysotile (white asbestos)

**B00B - R0002 - Preparation (48.68 m2)**

Ceiling Structures/Linings	Vermiculite					
	8189/B00B/R1008/Ceiling Structures/Linings/S2					Limited Samples Taken
	<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>					
Floor Coverings Res/Textile	Vinyl Tiles	49m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8189/B00B/R0009/Floor Coverings Res/Textile/S8					Chrysotile (white asbestos)

**B00B - R0004 - Distribution Board Cupboard (0.47 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00B - R0006 - Movement (2.07 m2)**

No Asbestos

**B00B - R0007 - Laboratory L.S. (92.8 m2)**

Ceiling Structures/Linings	Vermiculite					
	8189/B00B/R1008/Ceiling Structures/Linings/S2					Limited Samples Taken
	<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>					
Floor Coverings Res/Textile	Vinyl Tiles	93m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8189/B00B/R0009/Floor Coverings Res/Textile/S8					Chrysotile (white asbestos)

**B00B - R0008 - Computer Learning Space (59.73 m2)**

Ceiling Structures/Linings	Vermiculite					
	8189/B00B/R1008/Ceiling Structures/Linings/S2					Limited Samples Taken
	<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>					
Floor Coverings Res/Textile	Vinyl Tiles	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8189/B00B/R0009/Floor Coverings Res/Textile/S8					Chrysotile (white asbestos)

**B00B - R0009 - Movement (12.81 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8189/B00B/R0009/Floor Coverings Res/Textile/S8					Chrysotile (white asbestos)

Ceiling Structures/Linings	Vermiculite					
	8189/B00B/R1008/Ceiling Structures/Linings/S2					Limited Samples Taken
	<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>					

**B00B - R0010 - Movement (19.77 m2)**

No Asbestos

**B00B - R0011 - Apparatus Store (7.1 m2)**

Ceiling Structures/Linings	Vermiculite					
	8189/B00B/R1008/Ceiling Structures/Linings/S2					Limited Samples Taken
	<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>					
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8189/B00B/R0009/Floor Coverings Res/Textile/S8					Chrysotile (white asbestos)

**B00B - R0012 - Chemical Store (7.05 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite 8189/B00B/R1008/Ceiling Structures/Linings/S2					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Vinyl Tiles 8189/B00B/R0009/Floor Coverings Res/Textile/S8	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00B - R0013 - Stairs (10.76 m2)</b>						
No Asbestos						
<b>B00B - R0014 - Toilet - Lobby (3.4 m2)</b>						
Decorative Coating	Vermiculite 8189/B00B/R0014/Decorative Coating/S20					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00B - R0015 - Staff - Toilet (1.77 m2)</b>						
Decorative Coating	Vermiculite 8189/B00B/R0015/Decorative Coating/S21					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00B - R1001 - Staff Study (12.92 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8189/B00B/R1008/Ceiling Structures/Linings/S2					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00B - R1002 - Study Space (12.89 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8189/B00B/R1008/Ceiling Structures/Linings/S2					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00B - R1003 - Audio Visual Workroom (12.89 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8189/B00B/R1008/Ceiling Structures/Linings/S2					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00B - R1004 - Duplicating Workroom (12.78 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8189/B00B/R1008/Ceiling Structures/Linings/S2					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00B - R1006 - Distribution Board Cupboard (0.77 m2)</b>						
No Asbestos					Note: No inspection of live electrical installation.	
<b>B00B - R1008 - Main Area (244.72 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8189/B00B/R1008/Ceiling Structures/Linings/S2					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00B - R1010 - Librarian (5.85 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8189/B00B/R1008/Ceiling Structures/Linings/S2					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00B - R1011 - Workroom (18.7 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8189/B00B/R1008/Ceiling Structures/Linings/S2					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00B - R1012 - Movement (19.77 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting 8189/B00B/R1012/Ceiling Structures/Linings/S22	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
<b>B00B - R1013 - Stairs (4.28 m2)</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8189/B00B/R1013/Ceiling Structures/Linings/S23				Chrysotile (white asbestos) , Amosite (brown asbestos)		

**B00B - R1014 - Toilet - Lobby (1.69 m2)**

No Asbestos

**B00B - R1015 - Toilets-Unisex (1.31 m2)**

No Asbestos

**B00B - R1016 - Toilets-Unisex (1.26 m2)**

No Asbestos

**B00B - R1017 - Toilet - Lobby (1.99 m2)**

No Asbestos

**B00B - R1018 - Cleaning Supplies Store (2.48 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - General Learning - 1962 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids	No Asbestos Found					
Underfloor Voids - Packing to Floor Joists	Flat AC Sheeting	>1m2	Throughout	Some Damage - Unsealed (3)	Medium (2)	Medium Priority (4-5)
	8189/B00C/Underfloor Voids - Packing to Floor Joists/S13			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Underfloor Voids	Debris AC Sheeting					No Asbestos Detected
	8189/B00C/Underfloor Voids/S12					

**Interior****B00C - R0001 - Movement (52.37 m2)**

No Asbestos

**B00C - R0002 - General Learning Space (53.22 m2)**

No Asbestos

**B00C - R0003 - General Learning Space (53.15 m2)**

No Asbestos

**B00C - R0004 - Movement (24.93 m2)**

No Asbestos

**B00C - R0005 - Cleaning Store - Distributed (6.72 m2)**

No Asbestos

**B00C - R0008 - Movement (28.94 m2)**

No Asbestos

**B00C - R0009 - Stairs (0.78 m2)**

No Asbestos

**B00C - R0010 - External Movement (12.18 m2)**

No Asbestos

**B00C - R1001 - General Learning Space (53.87 m2)**

No Asbestos

**B00C - R1002 - General Learning Space (53.22 m2)**

No Asbestos

**B00C - R1003 - Leading Teacher (9.43 m2)**

No Asbestos

**B00C - R1004 - Movement (69.32 m2)**

No Asbestos

**B00C - R1005 - Stairs (13.6 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - General Learning - 1955 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids	No Asbestos Found					
Underfloor Voids	Debris (Vinyl Floor Tiles)	1m2	Throughout	Some Damage - Unsealed (3)	Medium (2)	Medium Priority (4-5)
8189/B00D/Underfloor Voids/S14					<b>Chrysotile (white asbestos)</b>	

**Interior****B00D - R0001 - General Learning Space (50.15 m2)**

No Asbestos

**B00D - R0002 - General Learning Space (50.16 m2)**

No Asbestos

**B00D - R0003 - Study Space (17.82 m2)**

No Asbestos

**B00D - R0004 - Staff Study (39.51 m2)**

No Asbestos

**B00D - R0006 - General Learning Space (50.16 m2)**

No Asbestos

**B00D - R0007 - General Learning Space (50.15 m2)**

No Asbestos

**B00D - R0008 - General Learning Space (50.15 m2)**

No Asbestos

**B00D - R0009 - General Learning Space (50.16 m2)**

No Asbestos

**B00D - R0010 - Distribution Board Cupboard (0.93 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00D - R0011 - Resources Store (10.08 m2)**

No Asbestos

**B00D - R0012 - General Storeroom (17.69 m2)**

No Asbestos

**B00D - R0013 - Movement (164.88 m2)**

No Asbestos

**B00D - R0014 - Stairs (18.05 m2)**

No Asbestos

**B00D - R0015 - Stairs (6.07 m2)**

No Asbestos

**B00D - R0016 - Movement (19.85 m2)**

No Asbestos

**B00D - R0017 - Staff - Toilet (9.06 m2)**

No Asbestos

**B00D - R0018 - Toilet - Lobby (2.8 m2)**

No Asbestos

**B00D - R1001 - General Learning Space (50.24 m2)**

No Asbestos

**B00D - R1002 - Preparation (20.3 m2)**

No Asbestos

**B00D - R1003 - Laboratory L.S. (79.6 m2)**

No Asbestos

**B00D - R1004 - General Learning Space (50.24 m2)**



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

**B00D - R1006 - Staff Study (39.76 m2)**

No Asbestos

**B00D - R1007 - Staff Study (21.1 m2)**

No Asbestos

**B00D - R1008 - Computer Learning Space (60 m2)**

No Asbestos

**B00D - R1009 - Resources Store (6.93 m2)**

No Asbestos

**B00D - R1010 - Computer Resource (13.76 m2)**

No Asbestos

**B00D - R1011 - Resources Store (17.2 m2)**

Floor Coverings  
Res/Textile

Vinyl Tiles

8189/B00D/R1011/Floor Coverings Res/Textile/S1

**No Asbestos Detected**

**B00D - R1012 - Movement (170.2 m2)**

No Asbestos

**B00D - R1013 - Resources Store (12.57 m2)**

No Asbestos

**B00D - R1014 - Cleaning Store - Distributed (4.47 m2)**

No Asbestos

**B00D - R1015 - Stairs (13.94 m2)**

No Asbestos

**B00D - R1016 - Stairs (12.89 m2)**

No Asbestos

**B00D - R1017 - Staff - Toilet (9.09 m2)**

No Asbestos

**B00D - R1018 - Toilet - Lobby (2.81 m2)**

No Asbestos

**B00D - R9001 - Movement (15.08 m2)**

No Asbestos

**B00D - R9002 - Stairs (6.66 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - General Learning - 1966 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					
Window Frame Putty	Putty 8189/B00E/Window Frame Putty/S15					<b>No Asbestos Detected</b>

**Interior****B00E - R0001 - Cleaning Store - Distributed (12.88 m2)**

No Asbestos

**B00E - R0002 - Shower/Change (33.74 m2)**

Partition Walls (Cubicles)	Compressed AC Sheet	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8189/B00E/R0002/Partition Walls (Cubicles)/S6						<b>Chrysotile (white asbestos)</b>

**B00E - R0003 - Staff Study (5.26 m2)**

No Asbestos

**B00E - R0004 - Staff Shower (2.68 m2)**

No Asbestos

**B00E - R0005 - Staff Study (5.26 m2)**

No Asbestos

**B00E - R0006 - Staff Shower (2.66 m2)**

No Asbestos

**B00E - R0007 - Sport Equipment Store (15.85 m2)**

No Asbestos

**B00E - R0008 - Sport Equipment Store (19.49 m2)**

No Asbestos

**B00E - R0009 - Cleaning Store - Distributed (7.59 m2)**

No Asbestos

**B00E - R0010 - Shower/Change (34.27 m2)**

Partition Walls (Cubicles)	Compressed AC Sheet	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8189/B00E/R0002/Partition Walls (Cubicles)/S6						<b>Chrysotile (white asbestos)</b>

**B00E - R0011 - Darkroom Space (25.1 m2)**

No Asbestos

**B00E - R0012 - Gymnasium (120.09 m2)**

No Asbestos

**B00E - R0013 - General Storeroom (25.82 m2)**

No Asbestos

**B00E - R0014 - Sport Equipment Store (6.14 m2)**

No Asbestos

**B00E - R0015 - External Movement (124 m2)**

No Asbestos

**B00E - R0016 - Apparatus Store (7.43 m2)**

No Asbestos

**B00E - R0017 - Stairs (2.4 m2)**

No Asbestos

**B00E - R0018 - Stairs (7.59 m2)**

No Asbestos

**B00E - R0019 - External Movement (5.43 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00E - R0020 - Lift (3.21 m2)</b>						
No Asbestos						
<b>B00E - R1001 - General Learning Space (52.55 m2)</b>						
Ceiling Structures/Linings	Vermiculite		8189/B00E/R2012/Ceiling Structures/Linings/S9			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R1002 - Staff Study (12.23 m2)</b>						
Ceiling Structures/Linings	Vermiculite		8189/B00E/R2012/Ceiling Structures/Linings/S9			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R1003 - Staff Study (12.24 m2)</b>						
Ceiling Structures/Linings	Vermiculite		8189/B00E/R2012/Ceiling Structures/Linings/S9			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R1004 - Resources Store (12.74 m2)</b>						
Ceiling Structures/Linings	Vermiculite		8189/B00E/R2012/Ceiling Structures/Linings/S9			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R1005 - Staff Study (12.7 m2)</b>						
Ceiling Structures/Linings	Vermiculite		8189/B00E/R2012/Ceiling Structures/Linings/S9			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Window Putty	Putty		8189/B00E/R1005/Window Putty/S24			No Asbestos Detected
<b>B00E - R1007 - Preparation (28.04 m2)</b>						
Ceiling Structures/Linings	Vermiculite		8189/B00E/R2012/Ceiling Structures/Linings/S9			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R1008 - Preparation (9.63 m2)</b>						
Ceiling Structures/Linings	Vermiculite		8189/B00E/R2012/Ceiling Structures/Linings/S9			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R1009 - Laboratory L.S. (85.83 m2)</b>						
Ceiling Structures/Linings	Vermiculite		8189/B00E/R2012/Ceiling Structures/Linings/S9			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R1010 - Distribution Board Cupboard (0.64 m2)</b>					Note: No inspection of live electrical installation.	
No Asbestos						
<b>B00E - R1013 - External Stairs (6.21 m2)</b>						
No Asbestos						
<b>B00E - R1017 - Art Learning Space (66.53 m2)</b>						
Decorative Coating	Vermiculite		8189/B00E/R1017/Decorative Coating/S25			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R1018 - Store (18.22 m2)</b>						
Decorative Coating	Vermiculite		8189/B00E/R1018/Decorative Coating/S26			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R1019 - External Movement (137.87 m2)</b>						
No Asbestos						
<b>B00E - R1020 - Stairs (5.06 m2)</b>						
No Asbestos						
<b>B00E - R1021 - Stairs (5.06 m2)</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
<b>B00E - R1022 - External Movement (5.19 m2)</b>						
No Asbestos						
<b>B00E - R2001 - Music Learning Space (51.83 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8189/B00E/R2012/Ceiling Structures/Linings/S9					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R2002 - Resources Store (9.17 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8189/B00E/R2012/Ceiling Structures/Linings/S9					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R2003 - Cleaning Store - Distributed (3.09 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8189/B00E/R2012/Ceiling Structures/Linings/S9					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R2004 - Interview/Office - Type 1 (25.91 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8189/B00E/R2012/Ceiling Structures/Linings/S9					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R2005 - Resources Store (6.14 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8189/B00E/R2012/Ceiling Structures/Linings/S9					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R2006 - Staff - Toilet (6.1 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8189/B00E/R2012/Ceiling Structures/Linings/S9					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R2007 - General Learning Space (51.75 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8189/B00E/R2012/Ceiling Structures/Linings/S9					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R2008 - Resources Store (5.49 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8189/B00E/R2012/Ceiling Structures/Linings/S9					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R2009 - Distribution Board Cupboard (0.58 m2)</b>						
					Note: No inspection of live electrical installation.	
No Asbestos						
<b>B00E - R2010 - Art Learning Space (59.29 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8189/B00E/R2012/Ceiling Structures/Linings/S9					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R2011 - Resources Store (6.19 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8189/B00E/R2012/Ceiling Structures/Linings/S9					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R2012 - Art Learning Space (52.56 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8189/B00E/R2012/Ceiling Structures/Linings/S9					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R2013 - Kiln Space (21.23 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8189/B00E/R2012/Ceiling Structures/Linings/S9					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R2014 - External Movement (128.38 m2)</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	129m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
8189/B00E/R2016/Ceiling Structures/Linings/S27				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00E - R2015 - Resources Store (10.95 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
8189/B00E/R2012/Ceiling Structures/Linings/S9				<b>Limited Samples Taken</b>		
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R2016 - Stairs (14.16 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	14m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
8189/B00E/R2016/Ceiling Structures/Linings/S27				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00E - R2017 - Stairs (14.04 m2)</b>						
In-fill-panel	Flat AC Sheeting	4m	East, Lower portion	Poor Condition (4)	Low (1)	Low Priority (2-3)
8189/B00E/R2016/In-fill-panel/S5				<b>Chrysotile (white asbestos)</b>		
Ceiling Structures/Linings	Flat AC Sheeting	14m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
8189/B00E/R2017/Ceiling Structures/Linings/S28				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00E - R2018 - External Movement (5.19 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting					
8189/B00E/R2018/Ceiling Structures/Linings/S37				<b>No Asbestos Detected</b>		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - Multi Purpose Facilities - 1992 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids	No Asbestos Found					
Underfloor Voids	Debris AC Sheeting	1m2	Throughout	Some Damage - Unsealed (3)	Medium (2)	Medium Priority (4-5)
	8189/B00H/Underfloor Voids/S16					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**Interior**

**B00H - R0001 - Pupil Entry (36.68 m2)**

No Asbestos

**B00H - R0002 - Movement (2.68 m2)**

No Asbestos

**B00H - R0003 - Control Room (3.81 m2)**

No Asbestos

**B00H - R0004 - Multi-Purpose Space (245.3 m2)**

No Asbestos

**B00H - R0005 - Toilets-Boys (5.57 m2)**

No Asbestos

**B00H - R0006 - Toilets-Girls (10.77 m2)**

Partition Walls (Cubicles)	Compressed AC Sheet					<b>No Asbestos Detected</b>
	8189/B00H/R0006/Partition Walls (Cubicles)/S3					

**B00H - R0007 - Stage (77.27 m2)**

No Asbestos

**B00H - R0008 - Resources Store (2.85 m2)**

No Asbestos

**B00H - R0009 - Cleaning Store - Distributed (2.29 m2)**

No Asbestos

**B00H - R0011 - Chair Store (23.78 m2)**

No Asbestos

**B00H - R0012 - Movement (18.15 m2)**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00H - R0014 - Movement (9.21 m2)**

No Asbestos

**B00H - R0016 - Ramp (6.09 m2)**

No Asbestos

**B00H - R0017 - Movement (8.5 m2)**

No Asbestos

**B00H - R0018 - Performance Workshop (10.4 m2)**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00H - R0019 - Audio Visual Workroom (7.99 m2)**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00H - R0020 - Seminar Space (18.71 m2)**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00H - R0021 - Seminar Space (23.89 m2)**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00H - R9001 - General Storeroom (54.82 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	<b>Sample No</b>					<b>Test Result</b>

No Asbestos

**B00H - R9002 - Plant Space (11.77 m2)**

No Asbestos

**B00H - R9003 - Ramp (3.09 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00I - Building Services - 2005 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00I - R0001 - Maintenance Bulk Store (5.19 m2)**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

**B00K - Pupil Facilities - 2005 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					
Gable Verge Lining	Flat AC Sheeting	8m2	East and West	Some Damage - Unsealed (3)	Medium (2)	Medium Priority (4-5)
	8189/B00K/Gable Verge Lining/S19					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
Eaves Linings	Flat AC Sheeting	8m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	8189/B00K/Eaves Linings/S17					<b>Chrysotile (white asbestos)</b>
Electrical Backing Board	Resinous Board	1m2	North	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8189/B00K/Electrical Backing Board/S18					<b>Chrysotile (white asbestos)</b>

**Interior****B00K - R0001 - Movement (8.61 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8189/B00K/R0001/Ceiling Structures/Linings/S29					<b>Chrysotile (white asbestos)</b>

**B00K - R0002 - Toilets - Girls (21.88 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8189/B00K/R0002/Ceiling Structures/Linings/S30					<b>Chrysotile (white asbestos)</b>

Partition Walls (Cubicles)	Compressed AC Sheet	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8189/B00K/R0002/Partition Walls (Cubicles)/S31					<b>Chrysotile (white asbestos)</b>

**B00K - R0003 - Cleaning Distributed Store (0.73 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8189/B00K/R0003/Ceiling Structures/Linings/S32					<b>Chrysotile (white asbestos)</b>

**B00K - R0004 - Toilets - Boys (22.72 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8189/B00K/R0004/Ceiling Structures/Linings/S33					<b>Chrysotile (white asbestos)</b>

Partition Walls (Cubicles)	Compressed AC Sheet	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8189/B00K/R0004/Partition Walls (Cubicles)/S34					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00K - R0005 - Movement (8.58 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8189/B00K/R0005/Ceiling Structures/Linings/S35					<b>Chrysotile (white asbestos)</b>

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00L - Pupil Facilities - 2005 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior****B00L - R0003 - Other (5.57 m2)**

No Asbestos

**B00L - R0004 - Other (5.25 m2)**

No Asbestos

**B00L - R0005 - External Movement (11.92 m2)**

No Asbestos

**B00L - R0006 - Other (15.04 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00N - Building Services - 2008 - Metal Shed (Metal Shed)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00N - R0001 - General Assistants (16.6 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B000 - Other - 2013 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

**Interior****B000 - R0001 - External Movement (177.45 m2)**

No Asbestos

**B000 - R0002 - Student Canteen (44.45 m2)**

No Asbestos

**B000 - R0003 - Office/Store (4.69 m2)**

No Asbestos

**B000 - R0004 - Toilets-Girls (24.44 m2)**

No Asbestos

**B000 - R0005 - Toilets-Disabled (5.75 m2)**

No Asbestos

**B000 - R0006 - Toilets-Boys (26.38 m2)**

No Asbestos

**B000 - R0007 - Vending Machines (2.74 m2)**

No Asbestos

**B000 - R0008 - Distribution Board Cupboard (0.99 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B000 - R0009 - Other (8.04 m2)**

No Asbestos

**B000 - R0010 - Toilet - Lobby (3.93 m2)**

No Asbestos

**B000 - R0011 - Handwashing Facilities (8.52 m2)**

No Asbestos

**B000 - R0012 - Toilet - Lobby (4.05 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00P - Technological & Applied Studies - 2013 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

**Interior****B00P - R0001 - General Storeroom (24.16 m2)**

No Asbestos

**B00P - R0002 - Dust Extraction Space (9.21 m2)**

No Asbestos

**B00P - R0003 - L.P.G. Store (3.18 m2)**

No Asbestos

**B00P - R0004 - Plant (1.63 m2)**

No Asbestos

**B00P - R1001 - Wood Technology Bay (126.02 m2)**

No Asbestos

**B00P - R1002 - General Learning Space - Type 9 (59.82 m2)**

No Asbestos

**B00P - R1003 - Staff Study (38.84 m2)**

No Asbestos

**B00P - R1004 - Access Staff Shower/Toilet (8.14 m2)**

No Asbestos

**B00P - R1005 - Main Switch Board Cupboard (8.2 m2)**

No Asbestos

**B00P - R1006 - External Stairs (11.24 m2)**

No Asbestos

**B00P - R1007 - Workshop Area (82.39 m2)**

No Asbestos

**B00P - R1008 - Materials Store (60.55 m2)**

No Asbestos

**B00P - R1009 - Kiln Space (10.31 m2)**

No Asbestos

**B00P - R1010 - Project Store - Type 1 (9.71 m2)**

No Asbestos

**B00P - R1011 - Welding Area (11.89 m2)**

No Asbestos

**B00P - R1012 - Pottery Store (7.43 m2)**

No Asbestos

**B00P - R1013 - Seminar - Type 2 (18.44 m2)**

No Asbestos

**B00P - R1014 - Metal Technology Bay (119.32 m2)**

No Asbestos

**B00P - R1015 - Materials Store (19.17 m2)**

No Asbestos

**B00P - R1016 - External Movement (79.48 m2)**

No Asbestos

**B00P - R1017 - Distribution Board Cupboard (1.19 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00P - R1018 - Distribution Board Cupboard (0.71 m2)**

Note: No inspection of live electrical installation.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
	No Asbestos					
	<b>B00P - R1019 - External Stairs (14.15 m2)</b>					
	No Asbestos					
	<b>B00P - R1020 - Movement (11.93 m2)</b>					
	No Asbestos					
	<b>B00P - R2001 - Kitchen - Type 1 (127.32 m2)</b>					
	No Asbestos					
	<b>B00P - R2002 - Seminar (18.88 m2)</b>					
	No Asbestos					
	<b>B00P - R2003 - Materials Store (18.73 m2)</b>					
	No Asbestos					
	<b>B00P - R2004 - General Learning Space - Type 7 (69.49 m2)</b>					
	No Asbestos					
	<b>B00P - R2005 - General Learning Space - Type 6 (57.82 m2)</b>					
	No Asbestos					
	<b>B00P - R2006 - Preparation - Materials (23.33 m2)</b>					
	No Asbestos					
	<b>B00P - R2007 - Pantry (17.51 m2)</b>					
	No Asbestos					
	<b>B00P - R2008 - Laundry (6.79 m2)</b>					
	No Asbestos					
	<b>B00P - R2009 - Movement (28.58 m2)</b>					
	No Asbestos					
	<b>B00P - R2010 - Food/Research Space (38.13 m2)</b>					
	No Asbestos					
	<b>B00P - R2011 - Materials Store (18.05 m2)</b>					
	No Asbestos					
	<b>B00P - R2012 - Pantry (12.07 m2)</b>					
	No Asbestos					
	<b>B00P - R2013 - Kitchen - Type 2 (123.34 m2)</b>					
	No Asbestos					
	<b>B00P - R2014 - Preparation - Materials (14.64 m2)</b>					
	No Asbestos					
	<b>B00P - R2015 - External Movement (81.77 m2)</b>					
	No Asbestos					
	<b>B00P - R2016 - External Stairs (6.9 m2)</b>					
	No Asbestos					
	<b>B00P - R2017 - External Stairs (14.76 m2)</b>					
	No Asbestos					
	<b>B00P - R2018 - Distribution Board Cupboard (0.57 m2)</b>					Note: No inspection of live electrical installation.
	No Asbestos					
	<b>B00P - R2019 - Distribution Board Cupboard (0.77 m2)</b>					Note: No inspection of live electrical installation.
	No Asbestos					
	<b>B00P - R2020 - Communications Cupboard (2.06 m2)</b>					
	No Asbestos					
	<b>B00P - R2021 - Movement (11.93 m2)</b>					
	No Asbestos					
	<b>B00P - R2022 - External Movement (8.65 m2)</b>					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B0AG - Agricultural Science - 1955 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B0AG - R0001 - Machine Storage (88.8 m2)**

No Asbestos

**B0AG - R0002 - General Storeroom (8.45 m2)**

No Asbestos

**B0AG - R0003 - Machine Storage (20.89 m2)**

No Asbestos

**B0AG - R0004 - General Storeroom (12.4 m2)**

No Asbestos

**B0AG - R0005 - Staff Change (8.39 m2)**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**BAGA - Agricultural Science - 2008 - Metal Shed (Metal Shed)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**BAGA - R0001 - Growing/Breeding (15.1 m2)**

Wall Linings Internal	Flat AC Sheeting	6m2	North and East	Poor Condition - Extensive Damage (4)	High (3)	High Priority (6-8)
	8189/BAGA/R0001/Wall Linings Internal/S36				<b>Chrysotile (white asbestos)</b>	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Build+1 - Added Building**

**Exterior**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Build+2 - Added Building**

**Exterior**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017