

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Kingsgrove High School (8247)
Region : Sydney
State Electorate : Kogarah
Local Government Area : Hurstville

Initial Survey : Noel Arnold & Associates : 30 - Mar - 2008
Reviewed By : Greencap-NAA : 13 - Aug - 2014



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning/Administration - 1960 - Concrete Framed (Concrete Framed)**Exterior**

Wall Cladding	Flat AC Sheeting 8247/B00A/Wall Cladding/S11					No Asbestos Detected
Eaves Linings	Flat AC Sheeting 8247/B00A/Eaves Linings/S36					No Asbestos Detected
Underfloor Voids	No Asbestos Found					
Ceiling Voids	No Asbestos Found					

Interior**B00A - R0001 - Computer Learning Space (37.42 m2)**

No Asbestos

B00A - R0002 - Computer Learning Space (35.82 m2)

No Asbestos

B00A - R0003 - Laboratory L.S. (91.33 m2)

No Asbestos

B00A - R0004 - Preparation (30.16 m2)

No Asbestos

B00A - R0005 - General Storeroom (6.05 m2)

No Asbestos

B00A - R0006 - Distribution Board Cupboard (0.74 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0007 - Tiered Learning Area (51.98 m2)

No Asbestos

B00A - R0008 - Cleaning Supplies Store (7.13 m2)

No Asbestos

B00A - R0009 - Chemical Store (6.23 m2)

No Asbestos

B00A - R0010 - General Storeroom (5.26 m2)

No Asbestos

B00A - R0011 - Movement (137.85 m2)

No Asbestos

B00A - R0012 - Staff - Toilet (3.24 m2)

No Asbestos

B00A - R0013 - External Movement (116.77 m2)

Ceiling Structures/Linings	Flat AC Sheeting	80m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8247/B00A/R9008/Ceiling Structures/Linings/S20					Chrysotile (white asbestos)

B00A - R0015 - Staff Kitchen (11.22 m2)

No Asbestos

B00A - R0016 - General Learning Space (41.12 m2)

No Asbestos

B00A - R0018 - Interview/Office - Type 1 (8.28 m2)

No Asbestos

B00A - R0019 - Principal Office (14.43 m2)

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					No Asbestos Detected
	8247/B00A/R0025/Floor Coverings Res/Textile/S21					

B00A - R0020 - Staff - Toilet (3.82 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Partition Walls (Cubicles)	Compressed AC Sheet					
	8247/B00A/R0027/Partition Walls (Cubicles)/S8					No Asbestos Detected
B00A - R0021 - General Storeroom (3.65 m2)						
No Asbestos						
B00A - R0022 - Movement (12.73 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	8247/B00A/R0025/Floor Coverings Res/Textile/S21					No Asbestos Detected
B00A - R0023 - Distribution Board Cupboard (1.03 m2)						
				Note: No inspection of live electrical installation.		
Wall Linings Internal	Flat AC Sheeting	2m2	South facing	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8247/B00A/R9007/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)
B00A - R0024 - Staff - Toilet (4.98 m2)						
Partition Walls (Cubicles)	Compressed AC Sheet					
	8247/B00A/R0027/Partition Walls (Cubicles)/S8					No Asbestos Detected
B00A - R0025 - Movement (18.82 m2)						
Floor Coverings Res/Textile	Vinyl Sheet					
	8247/B00A/R0025/Floor Coverings Res/Textile/S21					No Asbestos Detected
B00A - R0026 - Cleaning Supplies Store (2.11 m2)						
No Asbestos						
B00A - R0027 - Staff - Toilet (5.04 m2)						
Partition Walls (Cubicles)	Compressed AC Sheet					
	8247/B00A/R0027/Partition Walls (Cubicles)/S8					No Asbestos Detected
B00A - R0028 - Deputy Principal Office (14.3 m2)						
No Asbestos						
B00A - R0029 - Duplicating Workroom (7.56 m2)						
No Asbestos						
B00A - R0030 - Administration - Clerical (6.93 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	8247/B00A/R0025/Floor Coverings Res/Textile/S21					No Asbestos Detected
B00A - R0031 - Administration - Clerical (10.01 m2)						
No Asbestos						
B00A - R0032 - Administration - Clerical (65.56 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8247/B00A/R9008/Ceiling Structures/Linings/S20					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	8247/B00A/R0025/Floor Coverings Res/Textile/S21					No Asbestos Detected
B00A - R0033 - Secure Storeroom (12.95 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	13m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8247/B00A/R9007/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)
B00A - R0034 - Movement (20.11 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	8247/B00A/R0025/Floor Coverings Res/Textile/S21					No Asbestos Detected
B00A - R0035 - Movement (2.42 m2)						
No Asbestos						
B00A - R0036 - General Storeroom (5.26 m2)						
No Asbestos						
B00A - R0037 - Duplicating Workroom (16.42 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No						Test Result
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	8247/B00A/R0025/Floor Coverings Res/Textile/S21					No Asbestos Detected
B00A - R0038 - Pupil Entry (11.82 m2)						
Floor Coverings Res/Textile	Vinyl Tiles					
	8247/B00A/R0038/Floor Coverings Res/Textile/S2					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8247/B00A/R9007/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)
B00A - R0039 - Movement (77.5 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	78m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8247/B00A/R9007/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)
B00A - R0040 - Clinic - Boys (13.61 m2)						
No Asbestos						
B00A - R0041 - Clinic-Toilets (2.23 m2)						
No Asbestos						
B00A - R0042 - Clinic-Waiting (4.66 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8247/B00A/R9007/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)
B00A - R0043 - Staff - Toilet (2.23 m2)						
No Asbestos						
B00A - R0044 - Deputy Principal Office (13.94 m2)						
No Asbestos						
B00A - R0045 - Leading Teacher (16.46 m2)						
No Asbestos						
B00A - R0046 - General Storeroom (5.77 m2)						
No Asbestos						
B00A - R0047 - Apparatus Store (3.11 m2)						
No Asbestos						
B00A - R0048 - General Storeroom (4.06 m2)						
Floor Coverings Res/Textile	Vinyl Tiles					
	8247/B00A/R0025/Floor Coverings Res/Textile/S21					No Asbestos Detected
B00A - R0049 - Staff Study (20.96 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	8247/B00A/R0025/Floor Coverings Res/Textile/S21					No Asbestos Detected
B00A - R0051 - Preparation (19.72 m2)						
No Asbestos						
B00A - R0052 - Apparatus Store (7.88 m2)						
No Asbestos						
B00A - R0053 - Laboratory L.S. (88.33 m2)						
No Asbestos						
B00A - R0056 - Stairs (9.21 m2)						
No Asbestos						
B00A - R0057 - Stairs (5.97 m2)						
No Asbestos						
B00A - R0058 - External Movement (18.94 m2)						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R0059 - Stairs (2.63 m2)						
No Asbestos						
B00A - R0060 - Commonroom (40.18 m2)						
No Asbestos						
B00A - R0061 - Staff Kitchen (11.66 m2)						
No Asbestos						
B00A - R0062 - Commonroom (104.8 m2)						
No Asbestos						
B00A - R0063 - Movement (7.95 m2)						
No Asbestos						
B00A - R0065 - Movement (12.03 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8247/B00A/R9008/Ceiling Structures/Linings/S20					Chrysotile (white asbestos)	
B00A - R0066 - Movement (23.44 m2)						
No Asbestos						
B00A - R0067 - Stairs (2.97 m2)						
No Asbestos						
B00A - R0068 - Stairs (6.58 m2)						
No Asbestos						
B00A - R1001 - General Learning Space (51.9 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
8247/B00A/R0025/Floor Coverings Res/Textile/S21					No Asbestos Detected	
B00A - R1002 - General Learning Space (65.73 m2)						
No Asbestos						
B00A - R1003 - General Storeroom (4.31 m2)						
No Asbestos						
B00A - R1004 - General Storeroom (7.8 m2)						
No Asbestos						
B00A - R1005 - Resources Store (6.07 m2)						
No Asbestos						
B00A - R1006 - Kiln Space (6.04 m2)						
No Asbestos						
B00A - R1007 - Art Learning Space (64.95 m2)						
No Asbestos						
B00A - R1008 - General Learning Space (38.85 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
8247/B00A/R0025/Floor Coverings Res/Textile/S21					No Asbestos Detected	
B00A - R1009 - Staff Study (38.8 m2)						
No Asbestos						
B00A - R1011 - General Storeroom (6.67 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
8247/B00A/R0025/Floor Coverings Res/Textile/S21					No Asbestos Detected	
B00A - R1012 - Cleaning Store - Distributed (3.61 m2)						
Floor Coverings Res/Textile	Vinyl Sheet					
8247/B00A/R1025/Floor Coverings Res/Textile/S4					No Asbestos Detected	
B00A - R1013 - General Learning Space (64.87 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	8247/B00A/R0025/Floor Coverings Res/Textile/S21				No Asbestos Detected	
B00A - R1014 - General Learning Space (52.05 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	8247/B00A/R0025/Floor Coverings Res/Textile/S21				No Asbestos Detected	
B00A - R1015 - General Learning Space (51.77 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	8247/B00A/R0025/Floor Coverings Res/Textile/S21				No Asbestos Detected	
B00A - R1016 - General Learning Space (51.77 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	8247/B00A/R0025/Floor Coverings Res/Textile/S21				No Asbestos Detected	
B00A - R1017 - General Learning Space (52.05 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	8247/B00A/R0025/Floor Coverings Res/Textile/S21				No Asbestos Detected	
B00A - R1018 - Cleaning Store - Distributed (0.72 m2)						
No Asbestos						
B00A - R1019 - Toilets-Girls (10.01 m2)						
No Asbestos						
B00A - R1020 - General Learning Space (52.28 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	8247/B00A/R0025/Floor Coverings Res/Textile/S21				No Asbestos Detected	
B00A - R1021 - General Learning Space (51.91 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	8247/B00A/R0025/Floor Coverings Res/Textile/S21				No Asbestos Detected	
B00A - R1022 - General Learning Space (51.84 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	8247/B00A/R0025/Floor Coverings Res/Textile/S21				No Asbestos Detected	
B00A - R1023 - General Learning Space (51.98 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	8247/B00A/R0025/Floor Coverings Res/Textile/S21				No Asbestos Detected	
B00A - R1024 - General Learning Space (65.27 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	8247/B00A/R0025/Floor Coverings Res/Textile/S21				No Asbestos Detected	
B00A - R1025 - Distribution Board Cupboard (3.56 m2)						
					Note: No inspection of live electrical installation.	
Floor Coverings Res/Textile	Vinyl Sheet					
	8247/B00A/R1025/Floor Coverings Res/Textile/S4				No Asbestos Detected	
Electrical Backing Board	Resinous Board	1Unit	South	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Live						
B00A - R1026 - Staff Study (16.15 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	8247/B00A/R0025/Floor Coverings Res/Textile/S21				No Asbestos Detected	
B00A - R1027 - General Storeroom (6.6 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Wall Linings Internal	Flat AC Sheeting					
	8247/B00A/R0052/Wall Linings Internal/S3					No Asbestos Detected
B00A - R1028 - General Storeroom (14.35 m2)						
No Asbestos						
B00A - R1029 - General Learning Space (49.96 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	8247/B00A/R0025/Floor Coverings Res/Textile/S21					No Asbestos Detected
B00A - R1030 - General Learning Space (51.91 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	8247/B00A/R0025/Floor Coverings Res/Textile/S21					No Asbestos Detected
B00A - R1031 - General Storeroom (14 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	8247/B00A/R0025/Floor Coverings Res/Textile/S21					No Asbestos Detected
B00A - R1032 - General Learning Space (51.26 m2)						
No Asbestos						
B00A - R1033 - Movement (201.06 m2)						
No Asbestos						
B00A - R1035 - Stairs (8.43 m2)						
No Asbestos						
B00A - R1036 - Stairs (8.38 m2)						
No Asbestos						
B00A - R1037 - Stairs (8.45 m2)						
No Asbestos						
B00A - R1038 - Movement (14.31 m2)						
No Asbestos						
B00A - R1041 - Staff Kitchen (3.69 m2)						
No Asbestos						
B00A - R1042 - Commonroom (12.4 m2)						
No Asbestos						
B00A - R9001 - Student Canteen (39.98 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	40m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8247/B00A/R9007/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)
B00A - R9002 - Main Switchroom (3.9 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8247/B00A/R9007/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)
B00A - R9003 - Staff - Toilet (3.9 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8247/B00A/R9007/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)
B00A - R9004 - Cleaning Supplies Store (5.86 m2)						
No Asbestos						
B00A - R9005 - General Assistants (12.1 m2)						
No Asbestos						
B00A - R9006 - Maintenance Bulk Store (76.78 m2)						
No Asbestos						
B00A - R9007 - Movement (156.06 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	10m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
8247/B00A/R9007/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	
B00A - R9008 - Cleaning Supplies Store (6.52 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8247/B00A/R9008/Ceiling Structures/Linings/S20					Chrysotile (white asbestos)	
B00A - R9009 - No Access (6.14 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8247/B00A/R9008/Ceiling Structures/Linings/S20					Chrysotile (white asbestos)	
B00A - R9010 - Stairs (6.21 m2)						
No Asbestos						
B00A - R9011 - External Movement (4.39 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8247/B00A/R9008/Ceiling Structures/Linings/S20					Chrysotile (white asbestos)	
B00A - R9012 - Movement (12.78 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8247/B00A/R9008/Ceiling Structures/Linings/S20					Chrysotile (white asbestos)	
B00A - Room+1 - AR9012						
Ceiling Structures/Linings	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8247/B00A/R9007/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	
B00A - Room+2 - Movement next to AR9012						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8247/B00A/R9007/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	
B00A - Room+3 - Movement- NW Corner						
Ceiling Structures/Linings	Flat AC Sheeting	78m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8247/B00A/R9007/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	
B00A - Room+4 - Added Room						
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8247/B00A/R9008/Ceiling Structures/Linings/S20					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning/Art - 1965 - Concrete Framed (Concrete Framed)**Exterior**

Eaves Linings	Flat AC Sheeting	12m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Height restricted 8m						
Underfloor Voids	No Asbestos Found					
Ceiling Voids	No Asbestos Found					

Interior**B00B - R0001 - Music Learning Space (64.46 m2)**

No Asbestos

B00B - R0002 - Music Store (6.11 m2)

No Asbestos

B00B - R0003 - Pupil Entry (2.96 m2)

No Asbestos

B00B - R0004 - Computer Store (5.76 m2)

No Asbestos

B00B - R0005 - Computer Learning Space (51.91 m2)

No Asbestos

B00B - R0006 - General Storeroom (12.44 m2)

No Asbestos

B00B - R0007 - General Learning Space (52.06 m2)

No Asbestos

B00B - R0009 - General Storeroom (4.26 m2)

No Asbestos

B00B - R0011 - Cleaning Store - Distributed (0.88 m2)

No Asbestos

B00B - R0012 - Main Switchroom (8.33 m2)

Electrical Backing Board	Resinous Board	1Unit	West	Good Condition (1)	Low (1)	Low Priority (2-3)
8247/B00B/R0012/Electrical Backing Board/S23					Chrysotile (white asbestos)	

Flooring	Compressed AC Sheet					No Asbestos Detected
8247/B00B/R0012/Flooring/S24						

B00B - R0013 - General Storeroom (2.96 m2)

No Asbestos

B00B - R0014 - Pantry (10.5 m2)

No Asbestos

B00B - R0015 - Food Technology L.S. (65.05 m2)

No Asbestos

B00B - R0020 - Movement (137.67 m2)

No Asbestos

B00B - R0021 - External Movement (6.15 m2)

No Asbestos

B00B - R0022 - Cleaning Store - Distributed (1.03 m2)

No Asbestos

B00B - R0023 - External Movement (6.13 m2)

No Asbestos

B00B - R0024 - Stairs (14.05 m2)

No Asbestos

B00B - R0025 - External Movement (28.35 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No		Test Result				
No Asbestos						
B00B - R0026 - Stairs (6.8 m2)						
No Asbestos						
B00B - R0029 - Preparation (24.65 m2)						
No Asbestos						
B00B - R0030 - Food Technology L.S. (90.65 m2)						
No Asbestos						
B00B - R0031 - Laundry (0.86 m2)						
No Asbestos						
B00B - R0032 - Commonroom (45.36 m2)						
No Asbestos						
B00B - R1001 - General Learning Space (69.35 m2)						
No Asbestos						
B00B - R1002 - Materials Store (6.07 m2)						
No Asbestos						
B00B - R1003 - General Storeroom (6.94 m2)						
No Asbestos						
B00B - R1004 - Design L.S. (69.55 m2)						
No Asbestos						
B00B - R1005 - General Storeroom (3.53 m2)						
No Asbestos						
B00B - R1006 - General Storeroom (3.3 m2)						
No Asbestos						
B00B - R1007 - Materials Store (6.09 m2)						
No Asbestos						
B00B - R1008 - Design L.S. (69.78 m2)						
No Asbestos						
B00B - R1009 - Cleaning Store - Distributed (3.3 m2)						
No Asbestos						
B00B - R1010 - Distribution Board Cupboard (0.96 m2)						
				Note: No inspection of live electrical installation.		
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8247/B00B/R1010/Ceiling Structures/Linings/S25				Chrysotile (white asbestos) , Amosite (brown asbestos)		
Electrical Backing Board	Resinous Board	1Unit	East	Good Condition (1)	Low (1)	Low Priority (2-3)
8247/B00B/R0012/Electrical Backing Board/S23				Chrysotile (white asbestos)		
B00B - R1012 - Art Learning Space (55.51 m2)						
No Asbestos						
B00B - R1013 - Art Learning Space (56.29 m2)						
No Asbestos						
B00B - R1014 - Staff Study (27.71 m2)						
No Asbestos						
B00B - R1015 - Darkroom Space (11.55 m2)						
No Asbestos						
B00B - R1016 - Kiln Space (12.78 m2)						
No Asbestos						
B00B - R1017 - Art Learning Space (55.73 m2)						
No Asbestos						
B00B - R1018 - Cleaning Store - Distributed (0.84 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00B - R1019 - Movement (131.03 m2)

No Asbestos

B00B - R1020 - Cleaning Store - Distributed (0.87 m2)

No Asbestos

B00B - R1021 - Stairs (14.92 m2)

No Asbestos

B00B - R1022 - Stairs (15.78 m2)

No Asbestos

B00B - R1023 - Commonroom (16.38 m2)

No Asbestos

B00B - R1024 - Staff Kitchen (3.59 m2)

No Asbestos

B00B - R9001 - Toilets-Boys (100.38 m2)

No Asbestos

B00B - R9002 - Staff - Toilet (8.92 m2)

No Asbestos

B00B - R9003 - Movement (13.1 m2)

No Asbestos

B00B - R9004 - Stairs (6.26 m2)

No Asbestos

B00B - R9005 - External Movement (28.35 m2)

No Asbestos

B00B - R9006 - External Movement (3.72 m2)

No Asbestos

B00B - Room+1 - Movement next to BR0001

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8247/B00B/R1010/Ceiling Structures/Linings/S25				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00B - Room+2 - Movement next to BR0007

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8247/B00B/R1010/Ceiling Structures/Linings/S25				Chrysotile (white asbestos) , Amosite (brown asbestos)		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Technological & Applied Studies/Staff Facilities - 1962 - Concrete Framed (Concrete Framed)

Exterior

Eaves Linings	Flat AC Sheeting 8247/B00C/Eaves Linings/S26	50m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
Underfloor Voids	No Asbestos Found					
Ceiling Voids	No Asbestos Found					

Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)

Interior

B00C - R0001 - Staff - Toilet (5.87 m2)

No Asbestos

B00C - R0005 - Materials Technology L.S. (78.45 m2)

No Asbestos

B00C - R0007 - Movement (6.07 m2)

No Asbestos

B00C - R0012 - Materials Technology L.S. (71.81 m2)

No Asbestos

B00C - R0013 - Materials Store (10.21 m2)

No Asbestos

B00C - R0016 - External Movement (8.66 m2)

No Asbestos

B00C - R0017 - External Movement (7.87 m2)

No Asbestos

B00C - R0018 - External Movement (3.91 m2)

No Asbestos

B00C - R0019 - Distribution Board Cupboard (1.19 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0020 - Movement (4.03 m2)

No Asbestos

B00C - R0021 - Staff Kitchen (4.55 m2)

No Asbestos

B00C - R0022 - Commonroom (14.19 m2)

No Asbestos

B00C - R0023 - Project Store - Type 1 (21.5 m2)

No Asbestos

B00C - R0024 - Plant (5.78 m2)

No Asbestos

B00C - R0025 - Plant (4.85 m2)

No Asbestos

B00C - R0026 - Materials Technology L.S. (149.04 m2)

No Asbestos

B00C - R0027 - Movement (8.26 m2)

No Asbestos

B00C - R0028 - Seminar - Type 2 (21.17 m2)

No Asbestos

B00C - R0029 - Metal Technology Bay (10.52 m2)

No Asbestos

B00C - Room+1 - Movement next to CR0015

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8247/B00C/Room+2/Ceiling Structures/Linings/S10					Chrysotile (white asbestos)	
B00C - Room+2 - Movement next to CR0004						
Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8247/B00C/Room+2/Ceiling Structures/Linings/S10					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00D - General Learning/Physical Education - 1965 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	120m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
Assumed Asbestos - High restriction						
debris	Flat AC Sheeting	4m2	under void throughout	Minimal Damage (2)	Medium (2)	Medium Priority (4-5)
8247/B00D/debris/S14				Chrysotile (white asbestos)		
Infill panel	Compressed AC Sheet	176m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8247/B00D/Infill panel/S18				Chrysotile (white asbestos)		
Ceiling Voids	No Asbestos Found					

Interior**B00D - R0001 - Laboratory L.S. (86.29 m2)**

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken	
8247/B00D/R9009/Ceiling Structures/Linings/S6		Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works					

B00D - R0002 - Preparation (28.25 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken	
8247/B00D/R9009/Ceiling Structures/Linings/S6		Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works					

Floor Coverings Res/Textile	Vinyl Tiles	1m2	Variable positions	Minimal Damage (2)	Medium (2)	Medium Priority (4-5)
8247/B00D/R9001/Floor Coverings Res/Textile/S19				Chrysotile (white asbestos)		

B00D - R0003 - Staff Study (9.39 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken	
8247/B00D/R9009/Ceiling Structures/Linings/S6		Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works					

B00D - R0004 - Laboratory L.S. (86.22 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken	
8247/B00D/R9009/Ceiling Structures/Linings/S6		Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works					

B00D - R0005 - General Learning Space (52.48 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken	
8247/B00D/R9009/Ceiling Structures/Linings/S6		Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works					

B00D - R0006 - Staff Study (26.06 m2)

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8247/B00D/R9001/Floor Coverings Res/Textile/S19				Chrysotile (white asbestos)		

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken	
8247/B00D/R9014/Wall Linings Internal/S17		Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works					

B00D - R0007 - General Learning Space (52.63 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken	
8247/B00D/R9009/Ceiling Structures/Linings/S6		Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works					

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8247/B00D/R9001/Floor Coverings Res/Textile/S19				Chrysotile (white asbestos)		

B00D - R0008 - General Learning Space (52.56 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken	
8247/B00D/R9009/Ceiling Structures/Linings/S6		Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8247/B00D/R9001/Floor Coverings Res/Textile/S19	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00D - R0009 - Distribution Board Cupboard (0.82 m2)				Note: No inspection of live electrical installation.		
Floor Coverings Res/Textile	Vinyl Tiles 8247/B00D/R9001/Floor Coverings Res/Textile/S19	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00D - R0010 - General Storeroom (2.7 m2)						
Ceiling Structures/Linings	Vermiculite 8247/B00D/R9009/Ceiling Structures/Linings/S6					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles 8247/B00D/R0010/Floor Coverings Res/Textile/S7	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00D - R0011 - General Storeroom (6.49 m2)						
Ceiling Structures/Linings	Vermiculite 8247/B00D/R9009/Ceiling Structures/Linings/S6					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8247/B00D/R9001/Floor Coverings Res/Textile/S19	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00D - R0012 - General Learning Space (52.41 m2)						
Ceiling Structures/Linings	Vermiculite 8247/B00D/R9009/Ceiling Structures/Linings/S6					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8247/B00D/R9001/Floor Coverings Res/Textile/S19	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00D - R0016 - Movement (152.89 m2)						
Ceiling Structures/Linings	Vermiculite 8247/B00D/R9009/Ceiling Structures/Linings/S6					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles 8247/B00D/R0010/Floor Coverings Res/Textile/S7	10m2	South facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00D - R0017 - General Storeroom (6.33 m2)						
No Asbestos						
B00D - R0019 - Stairs (9.3 m2)						
No Asbestos						
B00D - R0020 - Stairs (4.11 m2)						
No Asbestos						
B00D - R0021 - External Movement (3.15 m2)						
No Asbestos						
B00D - R0022 - External Movement (3.15 m2)						
No Asbestos						
B00D - R0023 - Plant (0.84 m2)						
Ceiling Structures/Linings	Vermiculite 8247/B00E/R0001/Ceiling Structures/Linings/S9					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8247/B00D/R9001/Floor Coverings Res/Textile/S19	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00D - R0024 - General Learning Space (53.17 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Ceiling Structures/Linings	Vermiculite 8247/B00E/R0001/Ceiling Structures/Linings/S9					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8247/B00D/R9001/Floor Coverings Res/Textile/S19	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00D - R0025 - Commonroom (39.18 m2)						
Ceiling Structures/Linings	Vermiculite 8247/B00D/R9009/Ceiling Structures/Linings/S6					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00D - R0026 - Staff Study (17.12 m2)						
Ceiling Structures/Linings	Vermiculite 8247/B00E/R0001/Ceiling Structures/Linings/S9					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8247/B00D/R9001/Floor Coverings Res/Textile/S19	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00D - R0027 - Staff Kitchen (8.68 m2)						
No Asbestos						
B00D - R1002 - General Learning Space (52.56 m2)						
Ceiling Structures/Linings	Vermiculite 8247/B00D/R9009/Ceiling Structures/Linings/S6					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00D - R1003 - Preparation (23.74 m2)						
Ceiling Structures/Linings	Vermiculite 8247/B00D/R9009/Ceiling Structures/Linings/S6					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00D - R1004 - Apparatus Store (7.67 m2)						
Ceiling Structures/Linings	Vermiculite 8247/B00D/R9009/Ceiling Structures/Linings/S6					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00D - R1005 - Laboratory L.S. (86.21 m2)						
Ceiling Structures/Linings	Vermiculite 8247/B00D/R9009/Ceiling Structures/Linings/S6					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00D - R1006 - General Storeroom (3.03 m2)						
Ceiling Structures/Linings	Vermiculite 8247/B00D/R9009/Ceiling Structures/Linings/S6					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8247/B00D/R9001/Floor Coverings Res/Textile/S19	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00D - R1007 - General Storeroom (9.18 m2)						
Ceiling Structures/Linings	Vermiculite 8247/B00D/R9009/Ceiling Structures/Linings/S6					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8247/B00D/R9001/Floor Coverings Res/Textile/S19	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00D - R1008 - General Learning Space (66.28 m2)						
Ceiling Structures/Linings	Vermiculite 8247/B00D/R9009/Ceiling Structures/Linings/S6					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8247/B00D/R9001/Floor Coverings Res/Textile/S19	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00D - R1009 - General Storeroom (21.33 m2)						
Ceiling Structures/Linings	Vermiculite 8247/B00D/R9009/Ceiling Structures/Linings/S6					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8247/B00D/R9001/Floor Coverings Res/Textile/S19	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00D - R1010 - General Learning Space (61.15 m2)						
Ceiling Structures/Linings	Vermiculite 8247/B00D/R9009/Ceiling Structures/Linings/S6					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8247/B00D/R9001/Floor Coverings Res/Textile/S19	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00D - R1011 - General Learning Space (52.56 m2)						
Ceiling Structures/Linings	Vermiculite 8247/B00D/R9009/Ceiling Structures/Linings/S6					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00D - R1012 - Staff Study (12.6 m2)						
Ceiling Structures/Linings	Vermiculite 8247/B00D/R9009/Ceiling Structures/Linings/S6					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00D - R1013 - General Storeroom (6.14 m2)						
Ceiling Structures/Linings	Vermiculite 8247/B00D/R9009/Ceiling Structures/Linings/S6					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles 8247/B00D/R9001/Floor Coverings Res/Textile/S19	50m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00D - R1014 - Cleaning Store - Distributed (0.45 m2)						
Ceiling Structures/Linings	Vermiculite 8247/B00D/R9009/Ceiling Structures/Linings/S6					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00D - R1015 - Distribution Board Cupboard (0.92 m2)						
Ceiling Structures/Linings	Vermiculite 8247/B00D/R9009/Ceiling Structures/Linings/S6					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Fume Cupboard	Flat AC Sheeting	1Unit	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Assumed Asbestos - Sealed unit no access
B00D - R1016 - General Learning Space (52.56 m2)						
Ceiling Structures/Linings	Vermiculite 8247/B00D/R9009/Ceiling Structures/Linings/S6					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vermiculite 8247/B00D/R9001/Floor Coverings Res/Textile/S19	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00D - R1018 - General Learning Space (52.92 m2)						
Ceiling Structures/Linings	Vermiculite 8247/B00D/R9009/Ceiling Structures/Linings/S6					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8247/B00D/R9001/Floor Coverings Res/Textile/S19	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00D - R1019 - Movement (146.39 m2)						
Ceiling Structures/Linings	Vermiculite 8247/B00D/R9009/Ceiling Structures/Linings/S6					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles 8247/B00D/R0010/Floor Coverings Res/Textile/S7	10m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00D - R1020 - Staff - Toilet (6.77 m2)						
No Asbestos						
B00D - R1021 - Stairs (16.59 m2)						
No Asbestos						
B00D - R1022 - Stairs (4.92 m2)						
Ceiling Structures/Linings	Vermiculite 8247/B00D/R9001/Floor Coverings Res/Textile/S19	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00D - R1023 - G.L.S. Store (2.99 m2)						
Ceiling Structures/Linings	Vermiculite 8247/B00E/R0001/Ceiling Structures/Linings/S9					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8247/B00D/R9001/Floor Coverings Res/Textile/S19	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00D - R1024 - G.L.S. Store (9.12 m2)						
Ceiling Structures/Linings	Vermiculite 8247/B00E/R0001/Ceiling Structures/Linings/S9					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8247/B00D/R9001/Floor Coverings Res/Textile/S19	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00D - R1025 - Commonroom (36.14 m2)						
Ceiling Structures/Linings	Vermiculite 8247/B00D/R9009/Ceiling Structures/Linings/S6					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00D - R1026 - Staff Kitchen (2.79 m2)						
Ceiling Structures/Linings	Vermiculite 8247/B00D/R9009/Ceiling Structures/Linings/S6					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00D - R9001 - Staff Shower (9.73 m2)						
Floor Coverings Res/Textile	Vinyl Tiles 8247/B00D/R9001/Floor Coverings Res/Textile/S19	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive 8247/B00D/R9001/Floor Coverings Res/Textile/S34					No Asbestos Detected
B00D - R9002 - Shower/Change (54.78 m2)						
Partition Walls (Cubicles)	Compressed AC Sheet 8247/B00D/R9002/Partition Walls (Cubicles)/S5	20m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00D - R9003 - Shower/Change (54.73 m2)						
No Asbestos						
B00D - R9004 - Staff Shower (9.96 m2)						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00D - R9005 - General Storeroom (9.87 m2)						
No Asbestos						
B00D - R9006 - General Storeroom (6.21 m2)						
Flu pipe	Fibre Cement Pipe	2m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8247/B00D/R9006/Flu pipe/S15					Chrysotile (white asbestos)
Insulation to Pipework	Lagging					No Asbestos Detected
	8247/B00D/R9006/Insulation to Pipework/S16					
B00D - R9007 - Sport Equipment Store (20 m2)						
No Asbestos						
B00D - R9008 - Sport Equipment Store (27.67 m2)						
No Asbestos						
B00D - R9010 - Secure Storeroom (3.75 m2)						
No Asbestos						
B00D - R9011 - External Movement (4.38 m2)						
No Asbestos						
B00D - R9012 - External Movement (4.35 m2)						
No Asbestos						
B00D - R9013 - Stairs (5.62 m2)						
No Asbestos						
B00D - R9014 - Movement (39.89 m2)						
Wall Linings Internal	Vermiculite					Limited Samples Taken
	8247/B00D/R9014/Wall Linings Internal/S17					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8247/B00D/R9014/Wall Linings Internal/S17					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00D - R9015 - Movement (18.04 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8247/B00D/R9014/Wall Linings Internal/S17					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Library - 1984 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	4m2	East facing, West facing, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Height restricted 6m						
Underfloor Voids	No Asbestos Found					
Ceiling Voids	No Asbestos Found					

Interior**B00E - M1001 - Plant (23.92 m2)**

Air Conditioning Unit	Gasket material to heating unit 8247/B00E/M1001/Air Conditioning Unit/S29					No Asbestos Detected
-----------------------	--	--	--	--	--	-----------------------------

B00E - M1002 - Plant (26.5 m2)

Sound proofing tiles	Encapsulated Insulation material within unit 8247/B00E/M1002/Sound proofing tiles/S28					No Asbestos Detected
----------------------	---	--	--	--	--	-----------------------------

B00E - R0001 - Librarian (16.23 m2)

Ceiling Structures/Linings	Vermiculite 8247/B00E/R0001/Ceiling Structures/Linings/S9					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

B00E - R0002 - Staff - Toilet (3.72 m2)

Ceiling Structures/Linings	Vermiculite 8247/B00E/R0001/Ceiling Structures/Linings/S9					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

B00E - R0004 - Staff - Toilet (3.82 m2)

Ceiling Structures/Linings	Vermiculite 8247/B00E/R0001/Ceiling Structures/Linings/S9					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

B00E - R0005 - General Storeroom (4.75 m2)

Ceiling Structures/Linings	Vermiculite 8247/B00E/R0001/Ceiling Structures/Linings/S9					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

B00E - R0006 - Audio Visual Workroom (3.07 m2)

Floor Coverings Res/Textile	Vinyl Tiles 8247/B00E/R0007/Floor Coverings Res/Textile/S27					No Asbestos Detected
--------------------------------	--	--	--	--	--	-----------------------------

B00E - R0007 - Distribution Board Cupboard (1.03 m2)

Note: No inspection of live electrical installation.

Floor Coverings Res/Textile	Vinyl Tiles 8247/B00E/R0007/Floor Coverings Res/Textile/S27					No Asbestos Detected
--------------------------------	--	--	--	--	--	-----------------------------

B00E - R0009 - Audio Visual Workroom (49.21 m2)

Ceiling Structures/Linings	Vermiculite 8247/B00E/R0001/Ceiling Structures/Linings/S9					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

B00E - R0010 - General Storeroom (4.61 m2)

No Asbestos

B00E - R0012 - Movement (49.46 m2)

Ceiling Structures/Linings	Vermiculite 8247/B00E/R0001/Ceiling Structures/Linings/S9					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

B00E - R0013 - Movement (3.43 m2)

No Asbestos

B00E - R0014 - Stairs (3 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
B00E - R0015 - Lift (1.34 m2)						
No Asbestos						
B00E - R0016 - Main Area (207.83 m2)						
Ceiling Structures/Linings	Vermiculite		8247/B00E/R0001/Ceiling Structures/Linings/S9			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R0017 - Tiered Learning Area (8.66 m2)						
No Asbestos						
B00E - R0018 - Senior Study (13.64 m2)						
Ceiling Structures/Linings	Vermiculite		8247/B00E/R0001/Ceiling Structures/Linings/S9			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R0019 - Librarian (38.96 m2)						
Ceiling Structures/Linings	Vermiculite		8247/B00E/R0001/Ceiling Structures/Linings/S9			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R0020 - Library Administration (9.46 m2)						
Ceiling Structures/Linings	Vermiculite		8247/B00E/R0001/Ceiling Structures/Linings/S9			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R0021 - Stairs (1.37 m2)						
No Asbestos						
B00E - R1002 - Cleaning Store - Distributed (1.44 m2)						
Ceiling Structures/Linings	Vermiculite		8247/B00E/R0001/Ceiling Structures/Linings/S9			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles		8247/B00E/R0007/Floor Coverings Res/Textile/S27			No Asbestos Detected
B00E - R1003 - Seminar (16.12 m2)						
Ceiling Structures/Linings	Vermiculite		8247/B00E/R0001/Ceiling Structures/Linings/S9			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R1004 - Seminar (16.52 m2)						
Ceiling Structures/Linings	Vermiculite		8247/B00E/R0001/Ceiling Structures/Linings/S9			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R1005 - Seminar (16.44 m2)						
Ceiling Structures/Linings	Vermiculite		8247/B00E/R0001/Ceiling Structures/Linings/S9			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R1006 - Interview/Office - Type 1 (16.6 m2)						
Ceiling Structures/Linings	Vermiculite		8247/B00E/R0001/Ceiling Structures/Linings/S9			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R1007 - Seminar (16.28 m2)						
Ceiling Structures/Linings	Vermiculite		8247/B00E/R0001/Ceiling Structures/Linings/S9			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R1008 - Distribution Board Cupboard (1.4 m2)						
					Note: No inspection of live electrical installation.	
Ceiling Structures/Linings	Vermiculite		8247/B00E/R0001/Ceiling Structures/Linings/S9			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Floor Coverings Res/Textile	Vinyl Tiles 8247/B00E/R0007/Floor Coverings Res/Textile/S27	No Asbestos Detected
--------------------------------	--	-----------------------------

B00E - R1009 - Schools As Community Centres Program (3 m2)

No Asbestos

B00E - R1010 - Stairs (3 m2)

No Asbestos

B00E - R1011 - Main Area (239.11 m2)

Ceiling Structures/Linings	Vermiculite 8247/B00E/R0001/Ceiling Structures/Linings/S9	Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
----------------------------	--	---

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Multi Purpose Facilities - 1970 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids - Raked Ceiling No Asbestos Found

Interior

B00F - M0001 - Control Room (6.74 m2)

Electrical Backing Board	Resinous Board	2Unit	South	Good Condition (1)	Low (1)	Low Priority (2-3)
8247/B00B/R0012/Electrical Backing Board/S23					Chrysotile (white asbestos)	

B00F - M0002 - Control Room (6.85 m2)

No Asbestos

B00F - R0001 - Stage (96.19 m2)

No Asbestos

B00F - R0002 - Multi-Purpose Space (454.35 m2)

No Asbestos

B00F - R0003 - Toilets-Boys (9.6 m2)

No Asbestos

B00F - R0005 - Toilets-Girls (7.22 m2)

No Asbestos

B00F - R0006 - Public Entry (17.71 m2)

No Asbestos

B00F - R0007 - Distribution Board Cupboard (0.64 m2)

Note: No inspection of live electrical installation.

Door lining	Flat AC Sheeting	2Unit	South	Good Condition (1)	Low (1)	Low Priority (2-3)
8247/B00F/R0007/Door lining/S32					Chrysotile (white asbestos)	

Electrical Backing Board	Resinous Board	1Unit	North	Good Condition (1)	Low (1)	Low Priority (2-3)
--------------------------	----------------	-------	-------	--------------------	---------	--------------------

Assumed Asbestos - Sealed unit & live

B00F - R0008 - Student Canteen (17.23 m2)

Floor Coverings Res/Textile	Vinyl Tiles	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8247/B00F/R0008/Floor Coverings Res/Textile/S33					Chrysotile (white asbestos)	

Floor Coverings Res/Textile	Adhesive					
8247/B00F/R0008/Floor Coverings Res/Textile/S35					No Asbestos Detected	

B00F - R0009 - Movement (4.76 m2)

No Asbestos

B00F - R0010 - External Movement (8.54 m2)

No Asbestos

B00F - R0011 - Movement (4.76 m2)

No Asbestos

B00F - R0012 - Movement (4.72 m2)

No Asbestos

B00F - R0013 - Movement (4.4 m2)

No Asbestos

B00F - R9001 - Toilets-Girls (5.9 m2)

No Asbestos

B00F - R9002 - Chair Store (11.18 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00F - R9003 - Chair Store (11.09 m2)						
No Asbestos						
B00F - R9004 - Toilets-Boys (5.85 m2)						
No Asbestos						
B00F - R9005 - Chair Store (63.85 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Pupil Facilities/Other - 1960 - Concrete Framed (Concrete Framed)**Exterior**

Eaves Linings	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8247/B00G/Eaves Linings/S30					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior**B00G - R0002 - Toilets-Boys (7.79 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8247/B00G/R0002/Ceiling Structures/Linings/S22					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)

B00G - R0003 - Movement (2.16 m2)

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8247/B00G/R0002/Ceiling Structures/Linings/S22					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)

B00G - R0004 - Toilets-Girls (61.18 m2)

No Asbestos

B00G - R0005 - Cleaning Store - Distributed (12.14 m2)

No Asbestos

B00G - Room+1 - GR0005

Ceiling Structures/Linings	Flat AC Sheeting	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8247/B00G/R0002/Ceiling Structures/Linings/S22					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Building Services/Pupil Facilities - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

No Asbestos

Interior

B00H - R0001 - Movement (5.03 m2)

No Asbestos

B00H - R0002 - Lift (2.24 m2)

No Asbestos

B00H - R0003 - External Movement (14.84 m2)

No Asbestos

B00H - R1001 - Movement (5.03 m2)

No Asbestos

B00H - R9001 - Movement (5.39 m2)

No Asbestos

B00H - R9002 - Access Student Shower/Toilet/Change (8.29 m2)

No Asbestos

B00H - R9003 - External Movement (4.07 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - Other - 2010 - Metal Shed (Metal Shed)

Exterior

No Asbestos

Interior

B00I - R0001 - Other (41.22 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Build+1 - Covered Walkway between buildings E,D,A

Exterior

No Asbestos

Interior

Build+1 - Room+1 - Covered Walkway

Ceiling Structures/Linings Flat AC Sheeting
 8247/Build+1/Room+1/Ceiling Structures/Linings/S31

No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017