

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Ku-ring-gai High School (8416)
Region : Northern Sydney
State Electorate : Ku-ring-gai
Local Government Area : Ku-Ring-Gai

Initial Survey : Noel Arnold & Associates : 22 - May - 2008
Reviewed By : Grencap-NAA : 13 - Aug - 2014



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/General Learning/Art - 1965 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids Non Accessible Area
- No access to ceiling void

Underfloor Voids - Slab on Ground No Asbestos Found

Interior**B00A - R0001 - Clinic (8.97 m2)**

Ceiling Structures/Linings Vermiculite
8416/B00A/R0002/Ceiling Structures/Linings/S2 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00A - R0002 - Plant (0.88 m2)

No Asbestos

B00A - R0003 - Art Learning Space (86.2 m2)

Ceiling Structures/Linings Vermiculite
8416/B00A/R0002/Ceiling Structures/Linings/S2 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00A - R0004 - Interview/Meeting (19.13 m2)

Ceiling Structures/Linings Vermiculite
8416/B00A/R0002/Ceiling Structures/Linings/S2 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

Fume Cupboard	Flat AC Sheeting	1Unit	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	8416/B00A/R0004/Fume Cupboard/S4				Chrysotile (white asbestos) , Amosite (brown asbestos)	

Floor Coverings Res/Textile	Vinyl Tiles	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8416/B00A/R0004/Floor Coverings Res/Textile/S5				Chrysotile (white asbestos)	

B00A - R0005 - Resources Store (6.68 m2)

Ceiling Structures/Linings Vermiculite
8416/B00A/R0002/Ceiling Structures/Linings/S2 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

Floor Coverings Res/Textile	Vinyl Tiles	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8416/B00A/R0004/Floor Coverings Res/Textile/S5				Chrysotile (white asbestos)	

B00A - R0007 - General Learning Space (59.1 m2)

Ceiling Structures/Linings Vermiculite
8416/B00A/R0002/Ceiling Structures/Linings/S2 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

Floor Coverings Res/Textile	Vinyl Tiles	59m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8416/B00A/R0004/Floor Coverings Res/Textile/S5				Chrysotile (white asbestos)	

B00A - R0008 - Plant (0.88 m2)

No Asbestos

B00A - R0009 - Public Reception (59.09 m2)

Ceiling Structures/Linings Vermiculite
8416/B00A/R0002/Ceiling Structures/Linings/S2 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00A - R0010 - Administration - Clerical (9.56 m2)

Ceiling Structures/Linings Vermiculite
8416/B00A/R0002/Ceiling Structures/Linings/S2 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00A - R0011 - Staff - Toilet (4.56 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite	8416/B00A/R0002/Ceiling Structures/Linings/S2				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R0012 - Staff - Toilet (4.57 m2)						
Ceiling Structures/Linings	Vermiculite	8416/B00A/R0002/Ceiling Structures/Linings/S2				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R0013 - Movement (7.61 m2)						
Ceiling Structures/Linings	Vermiculite	8416/B00A/R0002/Ceiling Structures/Linings/S2				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R0014 - Principal Office (17.62 m2)						
Ceiling Structures/Linings	Vermiculite	8416/B00A/R0002/Ceiling Structures/Linings/S2				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R0015 - General Storeroom (2.5 m2)						
Ceiling Structures/Linings	Vermiculite	8416/B00A/R0002/Ceiling Structures/Linings/S2				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R0016 - Staff - Toilet (2.82 m2)						
Ceiling Structures/Linings	Vermiculite	8416/B00A/R0002/Ceiling Structures/Linings/S2				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R0017 - Administration - Clerical (52.27 m2)						
Ceiling Structures/Linings	Vermiculite	8416/B00A/R0002/Ceiling Structures/Linings/S2				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R0018 - Staff Kitchen (15.25 m2)						
Ceiling Structures/Linings	Vermiculite	8416/B00A/R0002/Ceiling Structures/Linings/S2				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R0021 - Printing/Photocopying (14.63 m2)						
Ceiling Structures/Linings	Vermiculite	8416/B00A/R0002/Ceiling Structures/Linings/S2				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R0022 - External Movement (311.2 m2)						
Ceiling Structures/Linings	Vermiculite	8416/B00A/R0002/Ceiling Structures/Linings/S2				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Notice board	Flat AC Sheeting	8416/B00A/R0022/Notice board/S3				No Asbestos Detected
B00A - R0023 - External Stairs (5.61 m2)						
No Asbestos						
B00A - R0024 - External Stairs (5.66 m2)						
No Asbestos						
B00A - R0025 - Pupil Entry (17.95 m2)						
Ceiling Structures/Linings	Vermiculite	8416/B00A/R0002/Ceiling Structures/Linings/S2				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R0026 - Lift (2.1 m2)						
No Asbestos						
B00A - R0027 - Movement (6.5 m2)						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R0030 - Access Student Shower/Toilet/Change (8.18 m2)						
No Asbestos						
B00A - R0031 - Other-Vacant (0.59 m2)						
No Asbestos						
B00A - R0032 - External Movement (1.57 m2)						
No Asbestos						
B00A - R0033 - Staff Study (33.19 m2)						
No Asbestos						
B00A - R0034 - Tea Room (4.03 m2)						
Ceiling Structures/Linings	Vermiculite					
	8416/B00A/R0002/Ceiling Structures/Linings/S2					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00A - R0035 - Handwashing Facilities (0.16 m2)						
No Asbestos						
B00A - R0036 - Handwashing Facilities (0.16 m2)						
No Asbestos						
B00A - R0037 - Plant (0.47 m2)						
No Asbestos						
B00A - R0038 - Plant (0.45 m2)						
No Asbestos						
B00A - R1001 - Art Learning Space (65.02 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	65m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8416/B00A/R0004/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite					
	8416/B00A/R0002/Ceiling Structures/Linings/S2					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00A - R1002 - Distribution Board Cupboard (0.88 m2)						
					Note: No inspection of live electrical installation.	
No Asbestos						
B00A - R1003 - General Learning Space (59.32 m2)						
Ceiling Structures/Linings	Vermiculite					
	8416/B00A/R0002/Ceiling Structures/Linings/S2					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
Floor Coverings Res/Textile	Vinyl Tiles	59m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8416/B00A/R0004/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)
B00A - R1004 - General Learning Space (52.8 m2)						
Ceiling Structures/Linings	Vermiculite					
	8416/B00A/R0002/Ceiling Structures/Linings/S2					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
Floor Coverings Res/Textile	Vinyl Tiles	52m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8416/B00A/R0004/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)
B00A - R1005 - General Learning Space (52.87 m2)						
Ceiling Structures/Linings	Vermiculite					
	8416/B00A/R0002/Ceiling Structures/Linings/S2					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
Floor Coverings Res/Textile	Vinyl Tiles	53m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8416/B00A/R0004/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)
B00A - R1006 - Computer Learning Space (59.25 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite 8416/B00A/R0002/Ceiling Structures/Linings/S2					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles 8416/B00A/R0004/Floor Coverings Res/Textile/S5	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00A - R1007 - Distribution Board Cupboard (0.9 m2)				Note: No inspection of live electrical installation.		
No Asbestos						
B00A - R1008 - General Learning Space (40.37 m2)						
Ceiling Structures/Linings	Vermiculite 8416/B00A/R0002/Ceiling Structures/Linings/S2					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles 8416/B00A/R1001/Floor Coverings Res/Textile/S6	40m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00A - R1009 - Staff Study (38.61 m2)						
Ceiling Structures/Linings	Vermiculite 8416/B00A/R0002/Ceiling Structures/Linings/S2					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles 8416/B00A/R1001/Floor Coverings Res/Textile/S6	38m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00A - R1010 - Interview/Meeting (9.65 m2)						
Ceiling Structures/Linings	Vermiculite 8416/B00A/R0002/Ceiling Structures/Linings/S2					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles 8416/B00A/R1001/Floor Coverings Res/Textile/S6	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00A - R1011 - Staff Lounge (61.09 m2)						
Ceiling Structures/Linings	Vermiculite 8416/B00A/R0002/Ceiling Structures/Linings/S2					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles 8416/B00A/R1001/Floor Coverings Res/Textile/S6	62m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00A - R1012 - Office/Store (8.73 m2)						
Ceiling Structures/Linings	Vermiculite 8416/B00A/R0002/Ceiling Structures/Linings/S2					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles 8416/B00A/R1001/Floor Coverings Res/Textile/S6	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00A - R1013 - Staff Kitchen (18.26 m2)						
Ceiling Structures/Linings	Vermiculite 8416/B00A/R0002/Ceiling Structures/Linings/S2					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles 8416/B00A/R1001/Floor Coverings Res/Textile/S6	18m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00A - R1014 - Deputy Principal Office (19.25 m2)						
Ceiling Structures/Linings	Vermiculite 8416/B00A/R0002/Ceiling Structures/Linings/S2					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles	19m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8416/B00A/R0004/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)	
B00A - R1017 - General Learning Space (38.47 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
8416/B00A/R0002/Ceiling Structures/Linings/S2					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
Floor Coverings Res/Textile	Vinyl Tiles	38m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8416/B00A/R0004/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)	
B00A - R1018 - General Learning Space (45.78 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
8416/B00A/R0002/Ceiling Structures/Linings/S2					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
Floor Coverings Res/Textile	Vinyl Tiles	45m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8416/B00A/R0004/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)	
B00A - R1019 - External Movement (139.67 m2)						
No Asbestos						
B00A - R1020 - External Stairs (5.64 m2)						
No Asbestos						
B00A - R1021 - External Stairs (5.61 m2)						
No Asbestos						
B00A - R1022 - Movement (5.45 m2)						
No Asbestos						
B00A - R1023 - External Movement (1.53 m2)						
No Asbestos						
B00A - R1024 - Movement (4.99 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
8416/B00A/R0002/Ceiling Structures/Linings/S2					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
B00A - R1025 - Leading Teacher (13.58 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
8416/B00A/R0002/Ceiling Structures/Linings/S2					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
Floor Coverings Res/Textile	Vinyl Tiles	13m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8416/B00A/R0004/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)	
B00A - R1026 - Handwashing Facilities (0.16 m2)						
No Asbestos						
B00A - R1027 - Handwashing Facilities (0.17 m2)						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Technological & Applied Studies/Music/Art - 1965 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	Non Accessible Area - No access to ceiling void					
Underfloor Voids	No Asbestos Found					

Interior

B00B - R0001 - Distribution Board Cupboard (0.88 m2) Note: No inspection of live electrical installation.

No Asbestos

B00B - R0002 - Resources Store (27.02 m2)

Ceiling Structures/Linings	Vermiculite					
	8416/B00B/R0021/Ceiling Structures/Linings/S7					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

B00B - R0003 - Metal Technology L.S. (92.11 m2)

Ceiling Structures/Linings	Vermiculite					
	8416/B00B/R0021/Ceiling Structures/Linings/S7					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

B00B - R0004 - Welding Area (10.77 m2)

Ceiling Structures/Linings	Vermiculite					
	8416/B00B/R0021/Ceiling Structures/Linings/S7					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

Floor Coverings Res/Textile	Vinyl Tiles	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8416/B00A/R0004/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)

B00B - R0005 - Resources Store (8.74 m2)

Ceiling Structures/Linings	Vermiculite					
	8416/B00B/R0021/Ceiling Structures/Linings/S7					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

Floor Coverings Res/Textile	Vinyl Tiles	11m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8416/B00A/R0004/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)

B00B - R0007 - Performance Workshop (103.16 m2)

Ceiling Structures/Linings	Vermiculite					
	8416/B00B/R0021/Ceiling Structures/Linings/S7					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

B00B - R0008 - Resources Store (22.37 m2)

Ceiling Structures/Linings	Vermiculite					
	8416/B00B/R0021/Ceiling Structures/Linings/S7					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

B00B - R0009 - Staff - Toilet (3.48 m2)

Ceiling Structures/Linings	Vermiculite					
	8416/B00B/R0021/Ceiling Structures/Linings/S7					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

B00B - R0010 - Staff - Toilet (3.33 m2)

Ceiling Structures/Linings	Vermiculite					
	8416/B00B/R0021/Ceiling Structures/Linings/S7					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

B00B - R0011 - General Learning Space (53.9 m2)

Ceiling Structures/Linings	Vermiculite					
	8416/B00B/R0021/Ceiling Structures/Linings/S7					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

B00B - R0012 - Resources Store (3.4 m2)

Ceiling Structures/Linings	Vermiculite					
	8416/B00B/R0021/Ceiling Structures/Linings/S7					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00B - R0013 - Plant (0.88 m2)						
No Asbestos						
B00B - R0014 - Food Technology L.S. (71.98 m2)						
Ceiling Structures/Linings	Vermiculite					
	8416/B00B/R0021/Ceiling Structures/Linings/S7					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	72m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8416/B00B/R1015/Floor Coverings Res/Textile/S8					Chrysotile (white asbestos)
B00B - R0017 - Food Technology L.S. (77.44 m2)						
Ceiling Structures/Linings	Vermiculite					
	8416/B00B/R0021/Ceiling Structures/Linings/S7					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00B - R0021 - External Movement (158.68 m2)						
Ceiling Structures/Linings	Vermiculite					
	8416/B00B/R0021/Ceiling Structures/Linings/S7					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00B - R0022 - External Stairs (5.55 m2)						
No Asbestos						
B00B - R0023 - External Stairs (5.52 m2)						
No Asbestos						
B00B - R0024 - Food/Research Space (45.22 m2)						
Ceiling Structures/Linings	Vermiculite					
	8416/B00B/R0021/Ceiling Structures/Linings/S7					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00B - R0025 - Preparation - Materials (25.68 m2)						
Ceiling Structures/Linings	Vermiculite					
	8416/B00B/R0021/Ceiling Structures/Linings/S7					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00B - R0026 - General Storeroom (20.9 m2)						
Ceiling Structures/Linings	Vermiculite					
	8416/B00B/R0021/Ceiling Structures/Linings/S7					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00B - R0027 - General Storeroom (3 m2)						
Ceiling Structures/Linings	Vermiculite					
	8416/B00B/R0021/Ceiling Structures/Linings/S7					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00B - R0028 - Handwashing Facilities (0.17 m2)						
No Asbestos						
B00B - R1001 - Distribution Board Cupboard (0.88 m2)					Note: No inspection of live electrical installation.	
No Asbestos						
B00B - R1002 - Design/Technology L.S. (66.97 m2)						
Ceiling Structures/Linings	Vermiculite					
	8416/B00B/R0021/Ceiling Structures/Linings/S7					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00B - R1003 - Resources Store (6.32 m2)						
Ceiling Structures/Linings	Vermiculite					
	8416/B00B/R0021/Ceiling Structures/Linings/S7					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00B - R1004 - Resources Store (6.14 m2)						
Ceiling Structures/Linings	Vermiculite					
	8416/B00B/R0021/Ceiling Structures/Linings/S7					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
B00B - R1007 - Wood Technology L.S. (79.57 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	80m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8416/B00A/R0004/Floor Coverings Res/Textile/S5				Chrysotile (white asbestos)	
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8416/B00A/R0002/Ceiling Structures/Linings/S2				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
B00B - R1009 - Materials Store (15.65 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	16m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8416/B00A/R1001/Floor Coverings Res/Textile/S6				Chrysotile (white asbestos)	
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8416/B00B/R0021/Ceiling Structures/Linings/S7				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
B00B - R1010 - Music Learning Space (50.68 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8416/B00B/R0021/Ceiling Structures/Linings/S7				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	50m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8416/B00B/R1015/Floor Coverings Res/Textile/S8				Chrysotile (white asbestos)	
B00B - R1011 - Music Store (13.62 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8416/B00B/R0021/Ceiling Structures/Linings/S7				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
Floor Coverings Res/Textile	Vinyl Tiles	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8416/B00C/R1001/Floor Coverings Res/Textile/S28				Chrysotile (white asbestos)	
B00B - R1012 - Distribution Board Cupboard (0.88 m2)						
				Note: No inspection of live electrical installation.		
No Asbestos						
B00B - R1013 - Music Learning Space (59.25 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8416/B00B/R0021/Ceiling Structures/Linings/S7				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	59m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8416/B00B/R1015/Floor Coverings Res/Textile/S8				Chrysotile (white asbestos)	
B00B - R1014 - Practice/Seminar (26 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8416/B00B/R0021/Ceiling Structures/Linings/S7				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	26m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8416/B00B/R1015/Floor Coverings Res/Textile/S8				Chrysotile (white asbestos)	
B00B - R1017 - Kiln Space (21.28 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8416/B00B/R0021/Ceiling Structures/Linings/S7				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
Floor Coverings Res/Textile	Vinyl Tiles	21m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8416/B00B/R1015/Floor Coverings Res/Textile/S8				Chrysotile (white asbestos)	
B00B - R1018 - Resources Store (10.88 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8416/B00B/R0021/Ceiling Structures/Linings/S7				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Floor Coverings Res/Textile	Vinyl Tiles	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8416/B00B/R1015/Floor Coverings Res/Textile/S8				Chrysotile (white asbestos)		
B00B - R1019 - External Movement (139.72 m2)						
No Asbestos						
B00B - R1020 - External Stairs (5.8 m2)						
No Asbestos						
B00B - R1021 - External Stairs (5.71 m2)						
No Asbestos						
B00B - R1022 - Handwashing Facilities (0.17 m2)						
No Asbestos						
B00B - R1023 - Project Store - Type 1 (8.58 m2)						
No Asbestos						
B00B - R1024 - Dust Extraction Space (6.78 m2)						
No Asbestos						
B00B - R1025 - General Storeroom (4.8 m2)						
Ceiling Structures/Linings	Vermiculite					
8416/B00B/R0021/Ceiling Structures/Linings/S7				Limited Samples Taken		
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8416/B00C/R1001/Floor Coverings Res/Textile/S28				Chrysotile (white asbestos)		
B00B - R1026 - Dust Extraction Space (6.76 m2)						
No Asbestos						
B00B - R1027 - Materials Store (19.5 m2)						
Ceiling Structures/Linings	Vermiculite					
8416/B00C/R0014/Ceiling Structures/Linings/S9				Limited Samples Taken		
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00B - R1028 - Wood Technology L.S. (79.46 m2)						
Ceiling Structures/Linings	Vermiculite					
8416/B00B/R0021/Ceiling Structures/Linings/S7				Limited Samples Taken		
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00B - R1029 - Handwashing Facilities (0.17 m2)						
No Asbestos						
B00B - R1030 - Art Learning Space (65.97 m2)						
Ceiling Structures/Linings	Vermiculite					
8416/B00B/R0021/Ceiling Structures/Linings/S7				Limited Samples Taken		
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
Floor Coverings Res/Textile	Vinyl Tiles	65m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8416/B00B/R1015/Floor Coverings Res/Textile/S8				Chrysotile (white asbestos)		
B00B - R1031 - Staff Study (34.67 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	34m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8416/B00B/R1015/Floor Coverings Res/Textile/S8				Chrysotile (white asbestos)		
Ceiling Structures/Linings	Vermiculite					
8416/B00C/R0014/Ceiling Structures/Linings/S9				Limited Samples Taken		
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00B - R1032 - Tea Room (4.4 m2)						
Ceiling Structures/Linings	Vermiculite					
8416/B00B/R0021/Ceiling Structures/Linings/S7				Limited Samples Taken		
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Pupil Facilities - 1965 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids Non Accessible Area
- Height Restriction

Underfloor Voids - Slab on Ground No Asbestos Found

Interior

B00C - R0001 - Cleaning Supplies Store (7.39 m2)

No Asbestos

B00C - R0006 - Staff - Toilet (2.84 m2)

Ceiling Structures/Linings Vermiculite
8416/B00C/R0014/Ceiling Structures/Linings/S9 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00C - R0007 - Office/Store (12.54 m2)

No Asbestos

B00C - R0008 - General Assistants (20.02 m2)

No Asbestos

B00C - R0009 - General Storeroom (1.74 m2)

No Asbestos

B00C - R0010 - Distribution Board Cupboard (0.35 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0011 - Sport Equipment Store (13.56 m2)

No Asbestos

B00C - R0012 - Cleaning Store - Distributed (1.6 m2)

Ceiling Structures/Linings Vermiculite
8416/B00C/R0014/Ceiling Structures/Linings/S9 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00C - R0013 - Tea Room (5.45 m2)

Ceiling Structures/Linings Vermiculite
8416/B00C/R0014/Ceiling Structures/Linings/S9 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00C - R0015 - Stairs (9.36 m2)

No Asbestos

B00C - R0016 - Stairs (9.37 m2)

No Asbestos

B00C - R0017 - External Movement (52.95 m2)

No Asbestos

B00C - R0018 - Student Canteen (62.52 m2)

No Asbestos

B00C - R0019 - Movement (11.04 m2)

No Asbestos

B00C - R0020 - External Movement (1.53 m2)

No Asbestos

B00C - R0021 - Covered Area (318.16 m2)

No Asbestos

B00C - R0022 - Movement (12.82 m2)

Ceiling Structures/Linings Vermiculite
8416/B00C/R0014/Ceiling Structures/Linings/S9 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00C - R0023 - Movement (19.5 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite					
	8416/B00C/R0014/Ceiling Structures/Linings/S9					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00C - R0024 - Movement (13 m2)						
Ceiling Structures/Linings	Vermiculite					
	8416/B00C/R0014/Ceiling Structures/Linings/S9					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00C - R0025 - External Movement (4.36 m2)						
Ceiling Structures/Linings	Vermiculite					
	8416/B00C/R0014/Ceiling Structures/Linings/S9					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00C - R1001 - Cleaning Store - Distributed (7.24 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8416/B00C/R1001/Floor Coverings Res/Textile/S28					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive					
	8416/B00C/R1001/Floor Coverings Res/Textile/S31					No Asbestos Detected
B00C - R1002 - Toilets-Boys (36.8 m2)						
No Asbestos						
B00C - R1003 - Change (38.48 m2)						
No Asbestos						
B00C - R1004 - Movement (8.85 m2)						
No Asbestos						
B00C - R1005 - General Storeroom (7.45 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8416/B00C/R1001/Floor Coverings Res/Textile/S28					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive					
	8416/B00C/R1001/Floor Coverings Res/Textile/S31					No Asbestos Detected
B00C - R1006 - Toilets-Girls (36.8 m2)						
No Asbestos						
B00C - R1007 - Change (39.06 m2)						
No Asbestos						
B00C - R1008 - Movement (8.92 m2)						
No Asbestos						
B00C - R1009 - Stairs (13.84 m2)						
No Asbestos						
B00C - R1010 - Stairs (13.94 m2)						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Library/Computer Learning/Science Learning - 1965 - Brick/Block (Brick/Block)**Exterior**

Decorative Panels	Compressed AC Sheet	20m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	8416/B00E/Decorative Panels/S23					Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	Non Accessible Area - No access to ceiling void					
Underfloor Voids	No Asbestos Found					

Interior**B00D - R0002 - Librarian (9.6 m2)**

No Asbestos

B00D - R0003 - Communication Space (15.62 m2)

No Asbestos

B00D - R0004 - Office/Store (11.4 m2)

No Asbestos

B00D - R0006 - Main Area (297.3 m2)

No Asbestos

B00D - R0007 - Communication Space (1.04 m2)

Wall Linings Internal	Flat AC Sheeting	4m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	8416/B00D/R0017/Door panel/S13					Chrysotile (white asbestos)

B00D - R0008 - Staff - Toilet (2.79 m2)

No Asbestos

B00D - R0009 - Independent Learning Space (32.44 m2)

Floor Coverings Res/Textile	Vinyl Tiles	33m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8416/B00D/R0009/Floor Coverings Res/Textile/S11					Chrysotile (white asbestos)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8416/B00D/R0025/Ceiling Structures/Linings/S10					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00D - R0010 - General Learning Space (52.51 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8416/B00D/R0025/Ceiling Structures/Linings/S10					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

Floor Coverings Res/Textile	Vinyl Tiles					No Asbestos Detected
	8416/B00D/R1010/Floor Coverings Res/Textile/S15					

B00D - R0011 - Chemical Store (25.89 m2)

No Asbestos

B00D - R0012 - Laboratory L.S. (92.62 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8416/B00D/R0025/Ceiling Structures/Linings/S10					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00D - R0015 - Laboratory L.S. (86.24 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8416/B00D/R0025/Ceiling Structures/Linings/S10					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00D - R0016 - Cleaning Store - Distributed (2.81 m2)

No Asbestos

B00D - R0017 - Plant (1.2 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Door panel	Flat AC Sheeting	2m2	All surfaces	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
	8416/B00D/R0017/Door panel/S13				Chrysotile (white asbestos)	
Debris	Flat AC Sheeting	1m2	All surfaces	Poor Condition (4)	Medium (2)	Medium Priority (4-5)
	8416/B00D/R0017/Door panel/S13				Chrysotile (white asbestos)	
B00D - R0021 - General Storeroom (18.59 m2)						
Ceiling Structures/Linings	Vermiculite				Limited Samples Taken	
	8416/B00D/R0025/Ceiling Structures/Linings/S10				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
B00D - R0023 - Staff Study (25.96 m2)						
Ceiling Structures/Linings	Vermiculite				Limited Samples Taken	
	8416/B00D/R0025/Ceiling Structures/Linings/S10				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
Floor Coverings Res/Textile	Vinyl Tiles				No Asbestos Detected	
	8416/B00D/R1010/Floor Coverings Res/Textile/S15					
B00D - R0024 - Resources Store (6.25 m2)						
Ceiling Structures/Linings	Vermiculite				Limited Samples Taken	
	8416/B00D/R0025/Ceiling Structures/Linings/S10				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
Floor Coverings Res/Textile	Vinyl Tiles	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8416/B00D/R0020/Floor Coverings Res/Textile/S14				Chrysotile (white asbestos)	
B00D - R0025 - Careers Advisers Office (13.47 m2)						
Ceiling Structures/Linings	Vermiculite				Limited Samples Taken	
	8416/B00D/R0025/Ceiling Structures/Linings/S10				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
Floor Coverings Res/Textile	Vinyl Tiles	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8416/B00D/R0020/Floor Coverings Res/Textile/S14				Chrysotile (white asbestos)	
B00D - R0026 - Resources Store (6.57 m2)						
Ceiling Structures/Linings	Vermiculite				Limited Samples Taken	
	8416/B00D/R0025/Ceiling Structures/Linings/S10				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
B00D - R0028 - External Stairs (6.03 m2)						
No Asbestos						
B00D - R0029 - External Stairs (6.71 m2)						
Ceiling Structures/Linings	Vermiculite				Limited Samples Taken	
	8416/B00D/R0025/Ceiling Structures/Linings/S10				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
B00D - R0030 - Staff Study (59.19 m2)						
Ceiling Structures/Linings	Vermiculite				Limited Samples Taken	
	8416/B00D/R0025/Ceiling Structures/Linings/S10				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
Floor Coverings Res/Textile	Vinyl Tiles				No Asbestos Detected	
	8416/B00D/R1010/Floor Coverings Res/Textile/S15					
B00D - R0031 - Staff Kitchen (6.96 m2)						
Ceiling Structures/Linings	Vermiculite				Limited Samples Taken	
	8416/B00D/R0025/Ceiling Structures/Linings/S10				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
Floor Coverings Res/Textile	Vinyl Tiles	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8416/B00D/R0009/Floor Coverings Res/Textile/S11				Chrysotile (white asbestos)	
B00D - R0032 - External Movement (181.27 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite 8416/B00D/R0025/Ceiling Structures/Linings/S10					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00D - R0033 - Movement (5.98 m2)						
No Asbestos						
B00D - R0034 - External Stairs (5.88 m2)						
No Asbestos						
B00D - R0035 - General Learning Space (49.45 m2)						
Ceiling Structures/Linings	Vermiculite 8416/B00D/R0025/Ceiling Structures/Linings/S10					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Vinyl Tiles 8416/B00D/R1010/Floor Coverings Res/Textile/S15					No Asbestos Detected
B00D - R0036 - Handwashing Facilities (2.1 m2)						
Ceiling Structures/Linings	Vermiculite 8416/B00D/R0025/Ceiling Structures/Linings/S10					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Vinyl Tiles 8416/B00D/R0020/Floor Coverings Res/Textile/S14	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <i>Chrysotile (white asbestos)</i>
B00D - R0037 - Resources Store (13.86 m2)						
Ceiling Structures/Linings	Vermiculite 8416/B00D/R0025/Ceiling Structures/Linings/S10					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Vinyl Sheet 8416/B00D/R1010/Floor Coverings Res/Textile/S15					No Asbestos Detected
B00D - R0038 - Preparation - Science (39.23 m2)						
Ceiling Structures/Linings	Vermiculite 8416/B00D/R0025/Ceiling Structures/Linings/S10					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Vinyl Sheet 8416/B00D/R1010/Floor Coverings Res/Textile/S15					No Asbestos Detected
B00D - R0039 - Library Administration (42.11 m2)						
No Asbestos						
B00D - R0040 - Tea Room (5 m2)						
No Asbestos						
B00D - R0041 - Independent Learning Space (11.57 m2)						
No Asbestos						
B00D - R0042 - Independent Learning Space (11.3 m2)						
No Asbestos						
B00D - R0043 - Handwashing Facilities (0.16 m2)						
No Asbestos						
B00D - R1001 - Interview/Office - Type 1 (12.82 m2)						
Ceiling Structures/Linings	Vermiculite 8416/B00D/R0025/Ceiling Structures/Linings/S10					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Vinyl Tiles 8416/B00D/R1010/Floor Coverings Res/Textile/S15					No Asbestos Detected
B00D - R1002 - Resources Store (5.14 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite					
	8416/B00D/R0025/Ceiling Structures/Linings/S10					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R1003 - General Learning Space (53.61 m2)						
Ceiling Structures/Linings	Vermiculite					
	8416/B00D/R0025/Ceiling Structures/Linings/S10					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles					
	8416/B00D/R1010/Floor Coverings Res/Textile/S15					No Asbestos Detected
B00D - R1004 - Distribution Board Cupboard (1.09 m2)					Note: No inspection of live electrical installation.	
Door panel	Flat AC Sheeting	2m2	All surfaces	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
	8416/B00D/R0017/Door panel/S13					Chrysotile (white asbestos)
B00D - R1005 - Staff - Toilet (2.82 m2)						
Ceiling Structures/Linings	Vermiculite					
	8416/B00D/R0025/Ceiling Structures/Linings/S10					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R1006 - General Learning Space (59.01 m2)						
Ceiling Structures/Linings	Vermiculite					
	8416/B00D/R0025/Ceiling Structures/Linings/S10					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles					
	8416/B00D/R1010/Floor Coverings Res/Textile/S15					No Asbestos Detected
B00D - R1007 - General Learning Space (52.07 m2)						
Ceiling Structures/Linings	Vermiculite					
	8416/B00D/R0025/Ceiling Structures/Linings/S10					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles					
	8416/B00D/R1010/Floor Coverings Res/Textile/S15					No Asbestos Detected
B00D - R1008 - General Learning Space (52.37 m2)						
Ceiling Structures/Linings	Vermiculite					
	8416/B00D/R0025/Ceiling Structures/Linings/S10					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles					
	8416/B00D/R1010/Floor Coverings Res/Textile/S15					No Asbestos Detected
B00D - R1009 - Resources Store (6 m2)						
Ceiling Structures/Linings	Vermiculite					
	8416/B00D/R0025/Ceiling Structures/Linings/S10					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R1010 - Resources Store (6.14 m2)						
Ceiling Structures/Linings	Vermiculite					
	8416/B00D/R0025/Ceiling Structures/Linings/S10					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R1011 - Archive Store (6.17 m2)						
Ceiling Structures/Linings	Vermiculite					
	8416/B00D/R0025/Ceiling Structures/Linings/S10					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R1012 - Archive Store (25.82 m2)						
Ceiling Structures/Linings	Vermiculite					
	8416/B00D/R0025/Ceiling Structures/Linings/S10					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00D - R1013 - Archive Store (5.99 m2)						
Ceiling Structures/Linings	Vermiculite					
	8416/B00D/R0025/Ceiling Structures/Linings/S10					Limited Samples Taken
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
B00D - R1014 - Seminar (52 m2)						
Ceiling Structures/Linings	Vermiculite					
	8416/B00D/R0025/Ceiling Structures/Linings/S10					Limited Samples Taken
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
Floor Coverings Res/Textile	Vinyl Tiles					
	8416/B00D/R1010/Floor Coverings Res/Textile/S15					No Asbestos Detected
B00D - R1015 - Seminar (58.51 m2)						
Ceiling Structures/Linings	Vermiculite					
	8416/B00D/R0025/Ceiling Structures/Linings/S10					Limited Samples Taken
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
Floor Coverings Res/Textile	Vinyl Tiles					
	8416/B00D/R1010/Floor Coverings Res/Textile/S15					No Asbestos Detected
B00D - R1016 - General Storeroom (2.79 m2)						
Ceiling Structures/Linings	Vermiculite					
	8416/B00D/R0025/Ceiling Structures/Linings/S10					Limited Samples Taken
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
B00D - R1017 - Distribution Board Cupboard (1.2 m2) Note: No inspection of live electrical installation.						
Door panel	Flat AC Sheeting	1m2	All surfaces	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
	8416/B00D/R0017/Door panel/S13					Chrysotile (white asbestos)
B00D - R1018 - General Learning Space (53.68 m2)						
Ceiling Structures/Linings	Vermiculite					
	8416/B00D/R0025/Ceiling Structures/Linings/S10					Limited Samples Taken
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
Floor Coverings Res/Textile	Vinyl Tiles					
	8416/B00D/R1010/Floor Coverings Res/Textile/S16					No Asbestos Detected
B00D - R1019 - Staff Study (26.11 m2)						
Ceiling Structures/Linings	Vermiculite					
	8416/B00D/R0025/Ceiling Structures/Linings/S10					Limited Samples Taken
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
Floor Coverings Res/Textile	Vinyl Tiles					
	8416/B00D/R1010/Floor Coverings Res/Textile/S15					No Asbestos Detected
B00D - R1020 - Computer Learning Space (72.82 m2)						
Ceiling Structures/Linings	Vermiculite					
	8416/B00D/R0025/Ceiling Structures/Linings/S10					Limited Samples Taken
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
Floor Coverings Res/Textile	Vinyl Tiles					
	8416/B00D/R1010/Floor Coverings Res/Textile/S15					No Asbestos Detected
B00D - R1021 - Computer Store (6.11 m2)						
Ceiling Structures/Linings	Vermiculite					
	8416/B00D/R0025/Ceiling Structures/Linings/S10					Limited Samples Taken
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
Floor Coverings Res/Textile	Vinyl Tiles					
	8416/B00D/R1010/Floor Coverings Res/Textile/S16					No Asbestos Detected
B00D - R1022 - Resources Store (6.16 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite	8416/B00D/R0025/Ceiling Structures/Linings/S10			Limited Samples Taken	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles	8416/B00D/R1010/Floor Coverings Res/Textile/S15			No Asbestos Detected	
B00D - R1023 - General Learning Space (53.9 m2)						
Ceiling Structures/Linings	Vermiculite	8416/B00D/R0025/Ceiling Structures/Linings/S10			Limited Samples Taken	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles	8416/B00D/R1010/Floor Coverings Res/Textile/S15			No Asbestos Detected	
B00D - R1024 - General Learning Space (53.83 m2)						
Ceiling Structures/Linings	Vermiculite	8416/B00D/R0025/Ceiling Structures/Linings/S10			Limited Samples Taken	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles	8416/B00D/R1010/Floor Coverings Res/Textile/S16			No Asbestos Detected	
B00D - R1025 - General Learning Space (52.73 m2)						
Ceiling Structures/Linings	Vermiculite	8416/B00D/R0025/Ceiling Structures/Linings/S10			Limited Samples Taken	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles	8416/B00D/R1010/Floor Coverings Res/Textile/S15			No Asbestos Detected	
B00D - R1026 - General Learning Space (59.02 m2)						
Ceiling Structures/Linings	Vermiculite	8416/B00D/R0025/Ceiling Structures/Linings/S10			Limited Samples Taken	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles	8416/B00D/R1010/Floor Coverings Res/Textile/S15			No Asbestos Detected	
B00D - R1027 - External Movement (175.53 m2)						
Ceiling Structures/Linings	Vermiculite	8416/B00D/R1027/Window Sill/S17			Limited Samples Taken	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Ceiling Structures/Linings	Vermiculite	8416/B00D/R1027/Window Sill/S17			Limited Samples Taken	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Window Sill	Compressed AC Sheet	8416/B00D/R1027/Window Sill/S17			No Asbestos Detected	
Window Sill	Compressed AC Sheet	8416/B00D/R1027/Window Sill/S17			No Asbestos Detected	
B00D - R1028 - External Stairs (6.03 m2)						
Ceiling Structures/Linings	Vermiculite	8416/B00D/R0025/Ceiling Structures/Linings/S10			Limited Samples Taken	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R1029 - External Stairs (5.99 m2)						
No Asbestos						
B00D - R1030 - External Stairs (19.29 m2)						
No Asbestos						
B00D - R1031 - Handwashing Facilities (0.16 m2)						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning/Science Learning - 1965 - Brick/Block (Brick/Block)

Exterior

Decorative Panels	Compressed AC Sheet	20m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	8416/B00E/Decorative Panels/S23				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Voids	Non Accessible Area - No access to ceiling void					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00E - R0001 - General Learning Space (65.34 m2)

Ceiling Structures/Linings	Vermiculite					
	8416/B00E/R0021/Ceiling Structures/Linings/S20					Limited Samples Taken
	Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works					

B00E - R0002 - Plant (0.89 m2)

No Asbestos

B00E - R0003 - Laboratory L.S. (98.09 m2)

Floor Coverings Res/Textile	Vinyl Tiles	100m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8416/B00D/R0009/Floor Coverings Res/Textile/S11					Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite					
	8416/B00D/R0025/Ceiling Structures/Linings/S10					Limited Samples Taken
	Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works					

B00E - R0006 - Laboratory L.S. (84.64 m2)

Floor Coverings Res/Textile	Vinyl Tiles	87m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8416/B00D/R0009/Floor Coverings Res/Textile/S11					Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite					
	8416/B00D/R0025/Ceiling Structures/Linings/S10					Limited Samples Taken
	Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works					

B00E - R0007 - Plant (0.91 m2)

No Asbestos

B00E - R0008 - Laboratory L.S. (79.82 m2)

Ceiling Structures/Linings	Vermiculite					
	8416/B00E/R0021/Ceiling Structures/Linings/S20					Limited Samples Taken
	Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works					

B00E - R0009 - Resources Store (24.26 m2)

Ceiling Structures/Linings	Vermiculite					
	8416/B00E/R0021/Ceiling Structures/Linings/S20					Limited Samples Taken
	Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works					

B00E - R0010 - Apparatus Storage (8.24 m2)

Ceiling Structures/Linings	Vermiculite					
	8416/B00E/R0021/Ceiling Structures/Linings/S20					Limited Samples Taken
	Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works					

B00E - R0011 - Resources Store (11.11 m2)

Floor Coverings Res/Textile	Vinyl Tiles					
	8416/B00D/R1010/Floor Coverings Res/Textile/S16					No Asbestos Detected
Ceiling Structures/Linings	Vermiculite					
	8416/B00D/R0025/Ceiling Structures/Linings/S10					Limited Samples Taken
	Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works					

B00E - R0012 - Deputy Principal Office (15.06 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite 8416/B00E/R0021/Ceiling Structures/Linings/S20					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00E - R0013 - Toilets-Disabled (4.81 m2)						
Ceiling Structures/Linings	Vermiculite 8416/B00E/R0021/Ceiling Structures/Linings/S20					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00E - R0014 - Cleaning Store - Distributed (3.41 m2)						
Ceiling Structures/Linings	Vermiculite 8416/B00E/R0021/Ceiling Structures/Linings/S20					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00E - R0015 - Plant (4.83 m2)						
Ceiling Structures/Linings	Vermiculite 8416/B00E/R0021/Ceiling Structures/Linings/S20					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00E - R0016 - Staff - Toilet (4.73 m2)						
Ceiling Structures/Linings	Vermiculite 8416/B00E/R0021/Ceiling Structures/Linings/S20					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00E - R0017 - Toilets-Girls (35.91 m2)						
Partition Walls (Cubicles)	Flat AC Sheeting	36m2	All surfaces	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
	8416/B00E/R0018/Partition Walls (Cubicles)/S21					
Ceiling Structures/Linings	Vermiculite 8416/B00D/R0025/Ceiling Structures/Linings/S10					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00E - R0018 - Toilets-Boys (28.86 m2)						
Partition Walls (Cubicles)	Flat AC Sheeting	29m2	All surfaces	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
	8416/B00E/R0018/Partition Walls (Cubicles)/S21					
Ceiling Structures/Linings	Vermiculite 8416/B00D/R0025/Ceiling Structures/Linings/S10					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00E - R0019 - Plant (4.83 m2)						
Ceiling Structures/Linings	Vermiculite 8416/B00E/R0021/Ceiling Structures/Linings/S20					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00E - R0020 - General Learning Space (59.4 m2)						
Ceiling Structures/Linings	Vermiculite 8416/B00E/R0021/Ceiling Structures/Linings/S20					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00E - R0021 - External Movement (159.27 m2)						
Ceiling Structures/Linings	Vermiculite 8416/B00E/R0021/Ceiling Structures/Linings/S20					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00E - R0022 - External Stairs (5.51 m2)						
Ceiling Structures/Linings	Vermiculite 8416/B00E/R0021/Ceiling Structures/Linings/S20					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00E - R0023 - External Stairs (5.51 m2)						
No Asbestos						
B00E - R0024 - Preparation - Science (39.16 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite 8416/B00E/R0021/Ceiling Structures/Linings/S20					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00E - R0025 - Handwashing Facilities (0.16 m2)						
No Asbestos						
B00E - R0026 - Handwashing Facilities (0.16 m2)						
No Asbestos						
B00E - R1001 - General Learning Space (65.58 m2)						
Ceiling Structures/Linings	Vermiculite 8416/B00E/R0021/Ceiling Structures/Linings/S20					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles 8416/B00E/R1010/Floor Coverings Res/Textile/S22	65m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00E - R1002 - Distribution Board Cupboard (0.91 m2)					Note: No inspection of live electrical installation.	
No Asbestos						
B00E - R1003 - Computer Learning Space (59.47 m2)						
Ceiling Structures/Linings	Vermiculite 8416/B00E/R0021/Ceiling Structures/Linings/S20					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles 8416/B00E/R1010/Floor Coverings Res/Textile/S22	59m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00E - R1004 - General Learning Space (53.02 m2)						
Ceiling Structures/Linings	Vermiculite 8416/B00E/R0021/Ceiling Structures/Linings/S20					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles 8416/B00E/R1010/Floor Coverings Res/Textile/S22	53m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00E - R1005 - General Learning Space (52.87 m2)						
Ceiling Structures/Linings	Vermiculite 8416/B00E/R0021/Ceiling Structures/Linings/S20					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles 8416/B00E/R1010/Floor Coverings Res/Textile/S22	52m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00E - R1006 - General Learning Space (59.39 m2)						
Ceiling Structures/Linings	Vermiculite 8416/B00E/R0021/Ceiling Structures/Linings/S20					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles 8416/B00E/R1010/Floor Coverings Res/Textile/S22	59m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00E - R1007 - Distribution Board Cupboard (0.88 m2)					Note: No inspection of live electrical installation.	
No Asbestos						
B00E - R1009 - Resources Store (5.21 m2)						
Ceiling Structures/Linings	Vermiculite 8416/B00E/R0021/Ceiling Structures/Linings/S20					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles 8416/B00E/R1010/Floor Coverings Res/Textile/S22	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite	5m2	All surfaces	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
8416/B00E/R1010/Floor Coverings Res/Textile/S22					Chrysotile (white asbestos)	
B00E - R1010 - Resources Store (13 m2)						
Ceiling Structures/Linings	Vermiculite	14m2	All surfaces	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
8416/B00E/R1010/Floor Coverings Res/Textile/S22					Chrysotile (white asbestos)	
Ceiling Structures/Linings	Vermiculite	14m2	All surfaces	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
8416/B00E/R1010/Floor Coverings Res/Textile/S22					Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8416/B00E/R1010/Floor Coverings Res/Textile/S22					Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8416/B00E/R1010/Floor Coverings Res/Textile/S22					Chrysotile (white asbestos)	
B00E - R1011 - General Learning Space (59.41 m2)						
Ceiling Structures/Linings	Vermiculite					
8416/B00E/R0021/Ceiling Structures/Linings/S20					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
Floor Coverings Res/Textile	Vinyl Tiles	59m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8416/B00E/R1010/Floor Coverings Res/Textile/S22					Chrysotile (white asbestos)	
B00E - R1012 - Movement Studio (106.04 m2)						
Ceiling Structures/Linings	Vermiculite					
8416/B00E/R0021/Ceiling Structures/Linings/S20					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
Floor Coverings Res/Textile	Vinyl Tiles	105m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8416/B00E/R1010/Floor Coverings Res/Textile/S22					Chrysotile (white asbestos)	
B00E - R1013 - General Learning Space (59.25 m2)						
Ceiling Structures/Linings	Vermiculite					
8416/B00E/R0021/Ceiling Structures/Linings/S20					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
Floor Coverings Res/Textile	Vinyl Tiles	58m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8416/B00E/R1010/Floor Coverings Res/Textile/S22					Chrysotile (white asbestos)	
B00E - R1014 - External Movement (146.93 m2)						
Ceiling Structures/Linings	Vermiculite					
8416/B00E/R0021/Ceiling Structures/Linings/S20					Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00E - R1015 - External Stairs (5.69 m2)						
No Asbestos						
B00E - R1016 - External Stairs (5.67 m2)						
No Asbestos						
B00E - R1017 - Handwashing Facilities (0.16 m2)						
No Asbestos						
B00E - R1018 - Handwashing Facilities (0.16 m2)						
No Asbestos						
B00E - R1019 - Staff Study (50.15 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	50m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8416/B00E/R1010/Floor Coverings Res/Textile/S22					Chrysotile (white asbestos)	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Ceiling Structures/Linings Vermiculite
 8416/B00E/R0021/Ceiling Structures/Linings/S20 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00E - R1020 - Tea Room (3.54 m2)

Ceiling Structures/Linings Vermiculite
 8416/B00E/R0021/Ceiling Structures/Linings/S20 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Art - 1925 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8416/B00F/R0009/Ceiling Structures/Linings/S18				Chrysotile (white asbestos)	
Underfloor Voids	No Asbestos Found					
Ceiling Voids	Non Accessible Area - No access to ceiling void					

Interior

B00F - R0001 - Toilets-Girls (4.04 m2)

No Asbestos

B00F - R0002 - Materials Store (10.18 m2)

No Asbestos

B00F - R0003 - Cleaning Store - Distributed (2.96 m2)

No Asbestos

B00F - R0004 - Photographic Studio (21.69 m2)

No Asbestos

B00F - R0005 - Dark Room (22.3 m2)

No Asbestos

B00F - R0007 - Workshop (32.95 m2)

No Asbestos

B00F - R0009 - External Movement (3.52 m2)

Ceiling Structures/Linings	Flat AC Sheeting	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8416/B00F/R0009/Ceiling Structures/Linings/S18				Chrysotile (white asbestos)	

B00F - R0010 - External Movement (12.34 m2)

No Asbestos

B00F - R0011 - Covered Area (42.75 m2)

No Asbestos

B00F - R0012 - Movement (2.64 m2)

No Asbestos

B00F - R0013 - General Storeroom (14.2 m2)

No Asbestos

B00F - R0014 - Resources Store (4.42 m2)

No Asbestos

B00F - R0015 - Handwashing Facilities (4.42 m2)

No Asbestos

B00F - R0016 - Movement (4.15 m2)

No Asbestos

B00F - R0017 - Darkroom Space (1.04 m2)

No Asbestos

B00F - R0018 - Movement (7.2 m2)

No Asbestos

B00F - R0019 - Resources Store (0.53 m2)

No Asbestos

B00F - R0020 - External Movement (0.94 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Performance Learning - 1925 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found					
Underfloor Voids	AC Fragments/Debris	2m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
8416/B00G/Underfloor Voids/S30					Chrysotile (white asbestos)	

Interior

B00G - R0001 - External Movement (6.86 m2)

No Asbestos

B00G - R0002 - Performance Workshop (70.08 m2)

No Asbestos

B00G - R0003 - General Storeroom (12.61 m2)

No Asbestos

B00G - R0004 - General Storeroom (5.21 m2)

No Asbestos

B00G - R0005 - Performance Workspace (40.14 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Multi Purpose Facilities - 1971 - Concrete (Concrete)

Exterior

Eaves Linings	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8416/B00F/R0009/Ceiling Structures/Linings/S18				Chrysotile (white asbestos)	
Underfloor Voids	No Asbestos Found					
Ceiling Voids	No Asbestos Found					

Interior

B00H - M0001 - Control Room (21.31 m2)

No Asbestos

B00H - R0002 - Chair Store (14.34 m2)

No Asbestos

B00H - R0004 - General Storeroom (10.07 m2)

Ceiling Structures/Linings	Flat AC Sheeting	10m2	All surfaces	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
	8416/B00H/R0004/Ceiling Structures/Linings/S19				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00H - R0005 - Staff Kitchen (19.07 m2)

Floor Coverings Res/Textile	Vinyl Tiles	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8416/B00H/R0005/Floor Coverings Res/Textile/S25				Chrysotile (white asbestos)	

B00H - R0006 - Control Room (29.29 m2)

No Asbestos

B00H - R0007 - Sport Equipment Store (53.11 m2)

No Asbestos

B00H - R0008 - General Storeroom (9.73 m2)

No Asbestos

B00H - R0009 - Cleaning Store - Distributed (2.49 m2)

No Asbestos

B00H - R0010 - Chair Store (40.91 m2)

No Asbestos

B00H - R0011 - Distribution Board Cupboard (1.45 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00H - R0013 - Movement (2.02 m2)

No Asbestos

B00H - R0014 - Stage (70.74 m2)

No Asbestos

B00H - R0015 - Movement (1.96 m2)

No Asbestos

B00H - R0017 - Multi-Purpose Space (580.95 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8416/B00H/R0017/Ceiling Structures/Linings/S26				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	

B00H - R0018 - External Movement (15.89 m2)

No Asbestos

B00H - R0019 - External Movement (14.35 m2)

No Asbestos

B00H - R0020 - External Movement (9.17 m2)

No Asbestos

B00H - R0021 - External Movement (8.89 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00H - R0022 - Toilet - Lobby (1.92 m2)

No Asbestos

B00H - R0023 - Change (27.75 m2)

No Asbestos

B00H - R0024 - Toilet - Lobby (1.8 m2)

No Asbestos

B00H - R0025 - Change (28.65 m2)

No Asbestos

B00H - R0026 - Toilet - Lobby (3.2 m2)

Air Conditioning Unit	Textile	3m2	Central	Good Condition (1)	Low (1)	Low Priority (2-3)
-----------------------	---------	-----	---------	--------------------	---------	--------------------

8416/B00H/R0026/Air Conditioning Unit/S29

Chrysotile (white asbestos)

B00H - R0027 - Toilets-Boys (9.37 m2)

No Asbestos

B00H - R0028 - Toilet - Lobby (2.66 m2)

No Asbestos

B00H - R0029 - Toilets-Girls (9.52 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - Student Services/Other-D.E.C. Admin - 1952 - Brick/Block (Brick/Block)**Exterior**

Awnings	Flat AC Sheeting	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8416/B00I/R0004/Ceiling Structures/Linings/S1				Chrysotile (white asbestos)	
Eaves Linings	Flat AC Sheeting	35m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8416/B00I/R0004/Ceiling Structures/Linings/S1				Chrysotile (white asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00I - R0001 - Uniform Shop (18.94 m2)**

No Asbestos

B00I - R0002 - Uniform Shop (10.61 m2)

No Asbestos

B00I - R0004 - External Movement (16.36 m2)

New Exterior	Flat AC Sheeting	15m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8416/B00F/R0009/Ceiling Structures/Linings/S18				Chrysotile (white asbestos)	

B00I - R0005 - Other - D.E.T. Admin (15.55 m2)

No Asbestos

B00I - R0006 - Other - D.E.T. Admin (2.14 m2)

No Asbestos

B00I - R0007 - Other - D.E.T. Admin (3.66 m2)

No Asbestos

B00I - R0008 - Other - D.E.T. Admin (11.03 m2)

No Asbestos

B00I - R0009 - Movement (4.13 m2)

No Asbestos

B00I - R0010 - Uniform Shop (12.47 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Storage - 2011 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00K - R0001 - Machine Storage (29.76 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Other - 2012 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00L - R0001 - Other (64.16 m2)

No Asbestos

B00L - R0002 - External Movement (40.59 m2)

No Asbestos

B00L - R0003 - External Movement (32.72 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - Building Services - 1964 - Concrete (Concrete)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00M - R0001 - Cleaning Store - Distributed (7.59 m2)

No Asbestos

B00M - R0002 - Main Switchroom (5.11 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017