


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Kellyville High School (8477)
Region : Western Sydney
State Electorate : Castle Hill
Local Government Area : The Hills

Initial Survey : Noel Arnold & Associates : 23 - May - 2008
Register Issue Date : 24 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00A - Multi Purpose Facilities - 2003 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00A - R0001 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0002 - Office/Store

No Asbestos

B00A - R0003 - Vending Machines

No Asbestos

B00A - R0004 - Student Canteen

No Asbestos

B00A - R0005 - Gymnasium

No Asbestos

B00A - R0006 - Cleaning Store - Distributed

No Asbestos

B00A - R0007 - Main Switchroom

No Asbestos

B00A - R0008 - Gymnasium

No Asbestos

B00A - R0009 - Movement

No Asbestos

B00A - R0010 - First Aid

No Asbestos

B00A - R0011 - Sport Equipment Store

No Asbestos

B00A - R0012 - Control RoomVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00A - R0013 - Chair Store**

No Asbestos

B00A - R0014 - Large Equipment Store

No Asbestos

B00A - R0015 - Bulk Store

No Asbestos

B00A - R0016 - Cleaning Supplies Store

No Asbestos

B00A - R0017 - Movement Studio

No Asbestos

B00A - R0018 - Access Staff Shower/Toilet

No Asbestos

B00A - R0019 - Staff Shower

No Asbestos

B00A - R0020 - Movement Studio Store

No Asbestos

B00A - R0021 - Toilets-Boys

No Asbestos

B00A - R0022 - Toilets-Girls

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R0023 - Change						
No Asbestos						
B00A - R0024 - Movement						
No Asbestos						
B00A - R0025 - Distribution Board Cupboard				Note: No inspection of live electrical installation.		
No Asbestos						
B00A - R0026 - Change						
No Asbestos						
B00A - R0027 - Movement						
No Asbestos						
B00A - R0028 - Stage						
No Asbestos						
B00A - R0029 - Movement						
No Asbestos						
B00A - R9001 - Outdoor Equipment Store						
No Asbestos						
B00A - R9002 - Garden Store Room						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Administration/General Learning - 2003 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00B - R0001 - General Learning Space - Type 3

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0002 - General Learning Space - Type 3

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0003 - Chemical Store

No Asbestos

B00B - R0004 - Cleaning Store - Distributed

No Asbestos

B00B - R0005 - Apparatus Storage

No Asbestos

B00B - R0006 - Apparatus Storage

No Asbestos

B00B - R0007 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00B - R0008 - General Learning Space - Type 3

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0009 - General Learning Space - Type 3

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0010 - General Learning Space - Type 3

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0011 - General Learning Space - Type 3

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0012 - Science Laboratory

No Asbestos

B00B - R0013 - Science Laboratory

No Asbestos

B00B - R0014 - Preparation - Science

No Asbestos

B00B - R0015 - Science Laboratory

No Asbestos

B00B - R0016 - Seminar - Type 2

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0017 - Seminar

No Asbestos

B00B - R0018 - Movement

No Asbestos

B00B - R0019 - Stairs

No Asbestos

B00B - R0020 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00B - R0021 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
B00B - R1002 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B00B - R1003 - Cleaning Store - Distributed						
No Asbestos						
B00B - R1019 - General Learning Space - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00B - R1020 - Movement						
No Asbestos						
B00B - R1023 - General Learning Space - Type 6						
No Asbestos						
B00B - R1024 - General Learning Space - Type 7						
No Asbestos						
B00B - R1025 - Seminar - Type 2						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00B - R1026 - Laundry						
No Asbestos						
B00B - R1027 - General Learning Space - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00B - R1028 - General Learning Space - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00B - R1029 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B00B - R1030 - Performance Store						
No Asbestos						
B00B - R1031 - Practice/Seminar						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00B - R1032 - Performance Workshop						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00B - R1033 - Materials Store - Type 1						
No Asbestos						
B00B - R1034 - Pantry						
No Asbestos						
B00B - R1035 - Preparation - Materials						
No Asbestos						
B00B - R1040 - Toilets-Girls						
No Asbestos						
B00B - R1041 - Toilets-Boys						
No Asbestos						
B00B - R1042 - Stairs						
No Asbestos						
B00B - R1043 - Food Technology L.S.						
No Asbestos						
B00B - R1044 - Food Technology L.S.						
No Asbestos						
B00B - R1045 - Food/Research Space						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - R1046 - Pantry

No Asbestos

B00B - R1047 - Pantry

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Administration/General Learning - 2003 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00C - R0001 - Interview/Office - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0002 - Deputy Principal Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0003 - Administration - Executive

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0004 - Principal Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0005 - Security Store

No Asbestos

B00C - R0006 - Staff - Toilet

No Asbestos

B00C - R0007 - Staff - Toilet

No Asbestos

B00C - R0008 - Visitors Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0009 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0010 - Interview/Meeting

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0011 - Cleaning Store - Distributed

No Asbestos

B00C - R0012 - Public Reception

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0013 - Tea Room

No Asbestos

B00C - R0014 - Administration - Clerical

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0015 - Interview/Office - Type 2

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0016 - Clinic - Boys

No Asbestos

B00C - R0017 - Access Staff Shower/Toilet

No Asbestos

B00C - R0018 - Student Reception

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0019 - Clinic - Girls

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00C - R0020 - Distribution Board Cupboard				Note: No inspection of live electrical installation.		
No Asbestos						
B00C - R0021 - Interview/Office - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00C - R0022 - Movement						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00C - R0023 - Interview/Meeting						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00C - R0024 - Movement						
No Asbestos						
B00C - R0025 - Stairs						
No Asbestos						
B00C - R0026 - Stairs						
No Asbestos						
B00C - R1025 - General Learning Space - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00C - R1026 - General Learning Space - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00C - R1027 - Seminar - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00C - R1028 - General Learning Space - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00C - R1029 - General Learning Space - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00C - R1030 - General Learning Space - Type 2						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00C - R1032 - General Learning Space - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00C - R1035 - Movement						
No Asbestos						
B00C - R1036 - Distribution Board Cupboard				Note: No inspection of live electrical installation.		
No Asbestos						
B00C - R1037 - Stairs						
No Asbestos						
B00C - R1038 - Stairs						
No Asbestos						
B00C - R1039 - Movement						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00C - R1040 - General Storeroom						
No Asbestos						
B00C - R1041 - General Storeroom						
No Asbestos						
B00C - R1042 - Movement						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

B00C - R1043 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning - 2003 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00D - R0001 - General Learning Space - Type 1**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0002 - Practical Activity Area

No Asbestos

B00D - R0003 - General Learning Space - Type 2

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0004 - Movement

No Asbestos

B00D - R0005 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0006 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0007 - Seminar - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0008 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0009 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0010 - Store

No Asbestos

B00D - R0011 - Cleaning Store - Distributed

No Asbestos

B00D - R0012 - Store

No Asbestos

B00D - R0013 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0014 - Shared Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0015 - Movement

No Asbestos

B00D - R0016 - Stairs

No Asbestos

B00D - R1004 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00D - R1009 - Practical Activity Area

No Asbestos

B00D - R1010 - Movement

No Asbestos

B00D - R1011 - Stairs

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00D - R1012 - Shared Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R1013 - General Learning Space - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R1014 - Movement						
No Asbestos						
B00D - R1015 - General Learning Space - Type 2						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R1016 - General Learning Space - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R1017 - General Learning Space - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R1018 - Seminar - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R1019 - General Learning Space - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R1020 - General Learning Space - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R1021 - Store						
No Asbestos						
B00D - R1022 - Cleaning Store - Distributed						
No Asbestos						
B00D - R1023 - Store						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning/Library - 2003 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00E - R0001 - General Learning Space - Type 2

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0002 - Shared Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0003 - Special Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0004 - Staff Study

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0005 - Toilets-Disabled

No Asbestos

B00E - R0006 - Toilets-Disabled

No Asbestos

B00E - R0007 - Toilets-Boys

No Asbestos

B00E - R0008 - Student Laundry - Type 2

No Asbestos

B00E - R0009 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0010 - Toilets-Girls

No Asbestos

B00E - R0011 - G.L.S. Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0012 - Special Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0013 - Special Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0014 - Seminar - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0015 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0016 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0017 - G.L.S. Store

No Asbestos

B00E - R0018 - Cleaning Store - Distributed

No Asbestos

B00E - R0019 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0020 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
B00E - R0021 - Stairs						
No Asbestos						
B00E - R0022 - Movement						
No Asbestos						
B00E - R0023 - Movement						
No Asbestos						
B00E - R1017 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B00E - R1018 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B00E - R1019 - Movement						
No Asbestos						
B00E - R1020 - Stairs						
No Asbestos						
B00E - R1021 - Seminar - Type 3						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00E - R1022 - Seminar - Type 3						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00E - R1023 - Seminar - Type 3						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00E - R1024 - Careers Advisers Office						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00E - R1025 - Main Area						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00E - R1026 - Computer Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00E - R1027 - Movement						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00E - R1028 - Computer Store						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00E - R1029 - Staff - Toilet						
No Asbestos						
B00E - R1030 - Toilets-Disabled						
No Asbestos						
B00E - R1031 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00E - R1032 - Movement						
No Asbestos						
B00E - R1033 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00E - R1034 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00E - R1035 - Communication Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00E - R1036 - System Administrators Office						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00E - R1037 - Library Administration						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Staff Facilities/General Learning - 2003 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00F - R0001 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00F - R0002 - Shared Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00F - R0003 - General Learning Space - Type 2

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00F - R0004 - Movement

No Asbestos

B00F - R0005 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00F - R0006 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00F - R0007 - Seminar - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00F - R0008 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00F - R0009 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00F - R0010 - G.L.S. Store

No Asbestos

B00F - R0011 - Cleaning Store - Distributed

No Asbestos

B00F - R0012 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0013 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0014 - Practical Activity Area

No Asbestos

B00F - R0015 - Stairs

No Asbestos

B00F - R1010 - Movement

No Asbestos

B00F - R1011 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00F - R1012 - Movement

No Asbestos

B00F - R1013 - Stairs

No Asbestos

B00F - R1014 - Interview/Meeting

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No						Test Result
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1015 - Interview/Meeting						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1016 - Preparation/Printing						
No Asbestos						
B00F - R1017 - Distribution Board Cupboard						Note: No inspection of live electrical installation.
No Asbestos						
B00F - R1018 - Access Staff Shower/Toilet						
No Asbestos						
B00F - R1019 - Cleaning Store - Distributed						
No Asbestos						
B00F - R1020 - Staff - Toilet						
No Asbestos						
B00F - R1021 - Staff - Toilet						
No Asbestos						
B00F - R1022 - Staff - Toilet						
No Asbestos						
B00F - R1023 - Staff - Toilet						
No Asbestos						
B00F - R1024 - Interview/Meeting						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1025 - Interview/Meeting						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1026 - Staff Study						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1027 - Staff Lounge						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1028 - Staff Study						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Performing Arts/Technological & Applied Studies - 2003 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00G - R0001 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00G - R0002 - Dust Extraction Space

No Asbestos

B00G - R0003 - Project Store - Type 1

No Asbestos

B00G - R0004 - Materials Workshop - Type 3

No Asbestos

B00G - R0005 - Seminar - Type 1

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0006 - Fitness Store

No Asbestos

B00G - R0007 - Fitness Laboratory

No Asbestos

B00G - R0008 - Change

No Asbestos

B00G - R0009 - Change

No Asbestos

B00G - R0010 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0011 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0012 - Visual Arts Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0013 - General Learning Space - Type 9

No Asbestos

B00G - R0014 - General Learning Space - Type 5

No Asbestos

B00G - R0015 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00G - R0016 - Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Technological & Applied Studies - 2003 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00H - R0001 - Distribution Board Cupboard	Note: No inspection of live electrical installation.
No Asbestos	
B00H - R0002 - Dust Extraction Space	
No Asbestos	
B00H - R0003 - Project Store - Type 1	
No Asbestos	
B00H - R0004 - Materials Workshop - Type 2	
No Asbestos	
B00H - R0005 - Materials Store - Type 2	
No Asbestos	
B00H - R0006 - Visual Arts Workshop	
No Asbestos	
B00H - R0007 - Cleaning Store - Distributed	
No Asbestos	
B00H - R0008 - Distribution Board Cupboard	Note: No inspection of live electrical installation.
No Asbestos	
B00H - R0009 - Dark Room	
No Asbestos	
B00H - R0010 - General Learning Space - Type 5	
No Asbestos	
B00H - R0011 - General Learning Space - Type 4	
No Asbestos	
B00H - R0012 - Visual Arts Store	
No Asbestos	
B00H - R0013 - Project Store - Type 1	
No Asbestos	
B00H - R0014 - General Learning Space - Type 9	
No Asbestos	
B00H - R0015 - General Learning Space - Type 8	
No Asbestos	
B00H - R0016 - Outdoor Workshop	
No Asbestos	
B00H - R0017 - L.P.G. Store	
No Asbestos	
B00H - R0018 - Welding/Hot Metals Area	
No Asbestos	
B00H - R0019 - Pottery Store	
No Asbestos	
B00H - R0020 - Kiln Space	
No Asbestos	
B00H - R0021 - Welding/Hot Metals Area	
No Asbestos	
B00H - R0022 - Movement	
No Asbestos	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - Mechanical Services - 2003 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00I - R0001 - Movement

No Asbestos

B00I - R0002 - Lift

No Asbestos

B00I - R0003 - Plant

No Asbestos

B00I - R0004 - Movement

No Asbestos

B00I - R0005 - Stairs

No Asbestos

B00I - R1001 - Lift

No Asbestos

B00I - R1002 - Movement

No Asbestos

B00I - R1003 - Movement

No Asbestos

B00I - R1004 - Stairs

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

NS 200 - D10810 - Art Learning Space/Workshop/Bulk Store : Placement Date - 29/01/2008

Exterior

No Asbestos Found.

Interior

R1 - Art Learning Space

No Asbestos Found.

R2 - Workshop

No Asbestos Found.

R3 - Bulk Store

No Asbestos Found.

NS 200 - D11651 - Art Learning Space/Workshop/Bulk Store : Placement Date - 12/02/2007

Exterior

No Asbestos Found.

Interior

R1 - Art Learning Space

No Asbestos Found.

R2 - Workshop

No Asbestos Found.

R3 - Bulk Store

No Asbestos Found.

NS 110 - D13825 - Learning Unit - Single Secondary/Secure : Placement Date - 7/02/2007

Exterior

No Asbestos Found.

Interior

R1 - General Learning Space

No Asbestos Found.

R2 - Entry

No Asbestos Found.

R3 - Secure Storeroom

No Asbestos Found.

NS 110 - D14379 - Learning Unit - Single Secondary/Secure : Placement Date - 7/02/2007

Exterior

No Asbestos Found.

Interior

R1 - General Learning Space

No Asbestos Found.

R2 - Entry

No Asbestos Found.

R3 - Secure Storeroom

No Asbestos Found.

NS 111 - D16325 - Learning Unit - Double Secondary/Secure : Placement Date - 28/01/2008

Exterior

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Interior						
R1 - General Learning Space						
No Asbestos Found.						
R2 - General Learning Space						
No Asbestos Found.						
R3 - Entry						
No Asbestos Found.						
R4 - Secure Storeroom						
No Asbestos Found.						
R5 - Secure Storeroom						
No Asbestos Found.						
R6 - Entry						
No Asbestos Found.						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017