

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Kincumber High School (8585)
Region : Hunter/Central Coast
State Electorate : Terrigal
Local Government Area : Gosford

Initial Survey : Noel Arnold & Associates : 15 - Apr - 2008
Register Issue Date : 24 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration - 1989 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00A - R0001 - Ancillary Staff**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0002 - Staff - Toilet

No Asbestos

B00A - R0003 - Deputy Principal Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0004 - Principal Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0005 - Administration - Executive

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0006 - Leading Teacher

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0007 - Clinic - Girls

No Asbestos

B00A - R0008 - Toilets-Girls

No Asbestos

B00A - R0009 - Toilets-Boys

No Asbestos

B00A - R0010 - Clinic - Boys

No Asbestos

B00A - R0011 - Deputy Principal Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0012 - Administration - Clerical

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0013 - Secure Storeroom

No Asbestos

B00A - R0015 - Cleaning Store - Distributed

No Asbestos

B00A - R0018 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0019 - Student Canteen

No Asbestos

B00A - R0020 - Office/Store

No Asbestos

B00A - R0021 - Toilets-Disabled

No Asbestos

B00A - R0023 - General Assistants

No Asbestos

B00A - R0026 - Printing/Photocopying

No Asbestos

B00A - R0027 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0028 - External Movement

No Asbestos

B00A - R0029 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Technological & Applied Studies - 1989 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00B - M0001 - General Storeroom**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - M0002 - Stairs

No Asbestos

B00B - R0001 - Metal Technology L.S.

No Asbestos

B00B - R0002 - Welding Area

No Asbestos

B00B - R0003 - Resources Store

No Asbestos

B00B - R0004 - Movement

No Asbestos

B00B - R0005 - Resources Store

No Asbestos

B00B - R0006 - Wood Technology L.S.

No Asbestos

B00B - R0007 - Dust Extraction Space

No Asbestos

B00B - R0008 - Wood Technology L.S.

No Asbestos

B00B - R0009 - Wood Technology Bay

No Asbestos

B00B - R0010 - Staff Study

No Asbestos

B00B - R0011 - Design L.S.

No Asbestos

B00B - R0012 - Design L.S.

No Asbestos

B00B - R0013 - System Administrators Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0014 - L.P.G. Store

No Asbestos

B00B - R0015 - Materials Technology L.S.

No Asbestos

B00B - R0016 - Resources Store

No Asbestos

B00B - R0019 - Cleaning Store - Distributed

No Asbestos

B00B - R0020 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00B - R0021 - Metal Technology Bay

No Asbestos

B00B - R0024 - Cleaning Supplies Store

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00B - R0025 - General Storeroom						
No Asbestos						
B00B - R0026 - Toilets-Boys						
No Asbestos						
B00B - R0027 - Toilets-Girls						
No Asbestos						
B00B - R0028 - Staff - Toilet						
No Asbestos						
B00B - R0029 - Metal Technology L.S.						
No Asbestos						
B00B - R0030 - Movement						
No Asbestos						
B00B - R0031 - Stairs						
No Asbestos						
B00B - R0032 - External Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Art - 1989 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00C - R0001 - Art Learning Space**

No Asbestos

B00C - R0002 - Resources Store

No Asbestos

B00C - R0003 - Cleaning Store - Distributed

No Asbestos

B00C - R0004 - Computer Learning SpaceVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00C - R0005 - Resources Store**

No Asbestos

B00C - R0006 - Staff StudyVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00C - R0007 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0008 - Art Learning Space

No Asbestos

B00C - R0010 - Kiln Space

No Asbestos

B00C - R0012 - Art Learning Space

No Asbestos

B00C - R0013 - Outdoor Learning Area

No Asbestos

B00C - R0014 - Movement

No Asbestos

B00C - R0015 - External Movement

No Asbestos

B00C - R0016 - Pottery Store

No Asbestos

B00C - R0017 - Computer Learning Space

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Technological & Applied Studies - 1989 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00D - R0001 - Food Technology L.S.

No Asbestos

B00D - R0002 - Computer Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0003 - Resources Store

No Asbestos

B00D - R0004 - Cleaning Store - Distributed

No Asbestos

B00D - R0005 - Design/Technology L.S.

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0006 - Interview/Office - Type 1

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0007 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0008 - Laundry

No Asbestos

B00D - R0009 - Staff Study

No Asbestos

B00D - R0010 - Food Technology L.S.

No Asbestos

B00D - R0011 - Resources Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0012 - Preparation - Materials

No Asbestos

B00D - R0013 - Movement

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0014 - External Movement

No Asbestos

B00D - R0015 - External Movement

No Asbestos

B00D - R0016 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Science Learning - 1989 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00E - R0001 - Laboratory L.S.

No Asbestos

B00E - R0002 - Resources Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0003 - Laboratory L.S.

No Asbestos

B00E - R0004 - Laboratory L.S.

No Asbestos

B00E - R0005 - Staff Study

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0006 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0007 - Laboratory L.S.

No Asbestos

B00E - R0008 - Laboratory L.S.

No Asbestos

B00E - R0009 - Movement

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0010 - Preparation - Science

No Asbestos

B00E - R0011 - Apparatus Storage

No Asbestos

B00E - R0012 - Cleaning Store - Distributed

No Asbestos

B00E - R0013 - Chemical Store

No Asbestos

B00E - R0015 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning/Library/Support Unit - 1989 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00F - R0004 - Seminar/Study

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00F - R0005 - Audio Visual Workroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00F - R0006 - Library Administration

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00F - R0007 - Librarian

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00F - R0008 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0009 - Toilets-Girls

No Asbestos

B00F - R0010 - Staff - Toilet

No Asbestos

B00F - R0013 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00F - R0014 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00F - R0015 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00F - R0016 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00F - R0017 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00F - R0018 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00F - R0019 - Cleaning Store - Distributed

No Asbestos

B00F - R0020 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00F - R0021 - Staff Study

No Asbestos

B00F - R0022 - Staff - Toilet

No Asbestos

B00F - R0023 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0024 - Other

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R0025 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R0026 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R0027 - Resources Store						
No Asbestos						
B00F - R0028 - Leading Teacher						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R0030 - System Administrators Office						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R0031 - Photographic Studio						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R0032 - Staff Study						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R0033 - Computer Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R0034 - Computer Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R0035 - Computer Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R0036 - Resources Store						
No Asbestos						
B00F - R0037 - Interview/Office - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R0038 - Careers Advisers Office						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R0039 - Computer Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R0040 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R0041 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R0043 - Distribution Board Cupboard						
No Asbestos					Note: No inspection of live electrical installation.	
B00F - R0044 - Staff - Toilet						
No Asbestos						
B00F - R0045 - Special Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R0046 - Special Learning Space						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R0047 - Cleaning Store - Distributed						
No Asbestos						
B00F - R0048 - Special Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R0049 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R0050 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R0051 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R0052 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R0053 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R0054 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R0055 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R0056 - Toilets-Boys						
No Asbestos						
B00F - R0057 - Toilets-Girls						
No Asbestos						
B00F - R0058 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B00F - R0059 - Toilets-Disabled						
No Asbestos						
B00F - R0060 - Tiered Learning Area						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R0061 - Performing Arts Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R0062 - Interview/Office - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R0063 - Interview/Office - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R0064 - Resources Store						
No Asbestos						
B00F - R0067 - Interview/Office - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R0068 - Study Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00F - R0069 - Staff Study						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00F - R0070 - Resources Store						
No Asbestos						
B00F - R0071 - Plant						
No Asbestos						
B00F - R0072 - External Movement						
No Asbestos						
B00F - R0073 - External Movement						
No Asbestos						
B00F - R0074 - External Movement						
No Asbestos						
B00F - R0075 - External Movement						
No Asbestos						
B00F - R0076 - External Movement						
No Asbestos						
B00F - R0077 - External Movement						
No Asbestos						
B00F - R0078 - External Movement						
No Asbestos						
B00F - R0079 - Outdoor Learning Area						
No Asbestos						
B00F - R0081 - External Movement						
No Asbestos						
B00F - R0082 - Main Entry						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00F - R0083 - Main Area						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00F - R0084 - Seminar						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00F - R0085 - Commonroom						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00F - R0086 - Tea Room						
No Asbestos						
B00F - R0087 - Resources Store						
No Asbestos						
B00F - R0088 - Darkroom Space						
No Asbestos						
B00F - R0089 - Dark Room						
No Asbestos						
B00F - R0090 - General Storeroom						
No Asbestos						
B00F - R0091 - Computer Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00F - R0092 - Staff Kitchen						
No Asbestos						
B00F - R0093 - Staff Lounge						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0094 - External Movement

No Asbestos

B00F - R0095 - Staff Study

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0096 - Movement

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0097 - Stairs

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Music - 1989 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00G - R0001 - Cleaning Store - Distributed

No Asbestos

B00G - R0002 - Music Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0003 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00G - R0004 - Music Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0005 - Computer Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0006 - Music Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0007 - Music Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0008 - Staff Study

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0010 - External Movement

No Asbestos

B00G - R0011 - Toilets-Boys

No Asbestos

B00G - R0012 - Movement

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0013 - Handwashing Facilities

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Multi Purpose Facilities - 1989 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00H - R0003 - Cleaning Store - Distributed

No Asbestos

B00H - R0005 - Control Room

No Asbestos

B00H - R0006 - Sport Equipment Store

No Asbestos

B00H - R0007 - Staff Study

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R0008 - General Storeroom

No Asbestos

B00H - R0010 - Plant

No Asbestos

B00H - R0011 - General Storeroom

No Asbestos

B00H - R0012 - General Storeroom

No Asbestos

B00H - R0014 - Plant

No Asbestos

B00H - R0015 - Movement

No Asbestos

B00H - R0016 - Movement

No Asbestos

B00H - R0018 - Multi-Purpose Space

No Asbestos

B00H - R0019 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00H - R0020 - Main Switchroom

No Asbestos

B00H - R0021 - External Movement

No Asbestos

B00H - R0022 - Staff Study

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R0023 - Garden Store Room

No Asbestos

B00H - R0025 - External Movement

No Asbestos

B00H - R0026 - External Movement

No Asbestos

B00H - R0027 - External Movement

No Asbestos

B00H - R0029 - Toilet - Lobby

No Asbestos

B00H - R0030 - Toilets-Boys

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00H - R0031 - Toilet - Lobby						
No Asbestos						
B00H - R0032 - Toilets-Girls						
No Asbestos						
B00H - R0033 - Toilet - Lobby						
No Asbestos						
B00H - R0034 - Chair Store						
No Asbestos						
B00H - R0035 - Other-Community Use						
No Asbestos						
B00H - R0036 - Plant						
No Asbestos						
B00H - R0037 - Change						
No Asbestos						
B00H - R0038 - Change						
No Asbestos						
B00H - R0039 - Plant						
No Asbestos						
B00H - R0040 - Stage						
No Asbestos						
B00H - R0041 - External Movement						
No Asbestos						
B00H - R0042 - External Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - Agricultural Science - 1989 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00I - R0001 - Animal Space

No Asbestos

B00I - R0002 - General Storeroom

No Asbestos

B00I - R0003 - General Learning Space

No Asbestos

B00I - R0004 - Machine Storage

No Asbestos

B00I - R0005 - General Storeroom

No Asbestos

B00I - R0006 - Movement

No Asbestos

B00I - R0008 - Shower

No Asbestos

B00I - R0009 - External Movement

No Asbestos

B00I - R0010 - Toilet - Lobby

No Asbestos

B00I - R0011 - Staff - Toilet

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Building Services - 1989 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00J - R0001 - Plant

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0II - Agricultural Science - 2010 - Greenhouse (Greenhouse)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B0II - R0001 - Growing/Breeding

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 600 - D11104 - Learning Unit - Small : Placement Date - 13/04/2002

Exterior

Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	8.64 m2

Interior

R1 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	50 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

OS 601 - D11322 - Learning Unit - Standard/Withdrawal : Placement Date - 9/02/1998

Exterior

Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2
---------	---------------	------------------	-------

OS 601 - D13046 - Learning Unit - Standard/Withdrawal : Placement Date - 8/04/1997

Exterior

Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2
---------	---------------	------------------	-------

NS 200 - D13178 - Art Learning Space/Workshop/Bulk Store : Placement Date - 30/06/1995

Exterior

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Interior						
R1 - Art Learning Space						
No Asbestos Found.						
R2 - Workshop						
No Asbestos Found.						
R3 - Bulk Store						
No Asbestos Found.						
NS 220 - D13191 - Science Learning/Preparation Space : Placement Date - 30/06/1995						
Exterior						
No Asbestos Found.						
Interior						
R1 - Laboratory L.S.						
No Asbestos Found.						
R2 - Preparation						
No Asbestos Found.						
R3 - Entry						
No Asbestos Found.						
OS 700 - D13216 - Art Learning Space/Workshop/Store : Placement Date - 30/06/1995						
Exterior						
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				17.28 m2
Interior						
R1 - Entry						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
R2 - Art Learning Space						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				91 m2
R3 - Store						
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2
OS 600 - D14217 - Learning Unit - Small : Placement Date - 16/01/1996						
Exterior						
Eave Lining	Flat AC Sheet	Assumed Asbestos				8.64 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Interior						
R1 - General Learning Space						
End wall panel	Flat AC Sheet	Assumed Asbestos				50 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
NS 120 - D15108 - Learning Unit - Single Primary H/Cap PAA : Placement Date - 3/10/2007						
Exterior						
No Asbestos Found.						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Interior

R1 - Home Base-I.O.

No Asbestos Found.

R2 - Toilets-Disabled

No Asbestos Found.

R3 - Home Base Store-I.O.

No Asbestos Found.

R4 - Practical Activity Area

No Asbestos Found.

R5 - Entry

No Asbestos Found.

NS 110 - D16079 - Learning Unit - Single Secondary/Secure : Placement Date - 30/06/1995

Exterior

No Asbestos Found.

Interior

R1 - General Learning Space

No Asbestos Found.

R2 - Entry

No Asbestos Found.

R3 - Secure Storeroom

No Asbestos Found.

OS 600 - D16367 - Learning Unit - Small : Placement Date - 19/02/1996

Exterior

Eave Lining	Flat AC Sheet	Assumed Asbestos	8.64 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2

Interior

R1 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	50 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

OS 522 - D18178 - Staff Study : Placement Date - 19/02/2007

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Staff Room

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017