

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Leeville Public School (1740)
Region : North Coast
State Electorate : Clarence
Local Government Area : Richmond Valley

Initial Survey : Noel Arnold & Associates : 10 - Jun - 2008
Reviewed By : Parsons Brinckerhoff : 28 - Feb - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning - 1990 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior

B00A - R0001 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0002 - Home Base Store

No Asbestos

B00A - R0003 - General Storeroom

No Asbestos

B00A - R0004 - Practical Activities - 1hb

No Asbestos

B00A - R0005 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0006 - External Movement

No Asbestos

B00A - R0007 - External Movement

No Asbestos

B00A - R0008 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0009 - Practical Activities - 1hb

No Asbestos

B00A - R0010 - Cleaning Distributed Store

No Asbestos

B00A - R0011 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0012 - Home Base Store

No Asbestos

B00A - R0013 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0015 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Pupil Facilities - 1951 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting 1740/B00B/Eaves Linings/S4				No Asbestos Detected	
Downpipes	Fibre Cement Pipe 1740/B00B/Downpipes/S2	4m	West	Good Condition (1)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Void	Flat AC Sheeting 1740/B00B/Ceiling Void/S6				No Asbestos Detected	

Interior

B00B - R0005 - Toilets - Boys

No Asbestos

B00B - R0006 - Toilets - Girls

No Asbestos

B00B - R0007 - Staff Toilet

No Asbestos

B00B - R0008 - Disabled Shower/Toilet

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Administration - 1951 - Timber (Timber)

Exterior

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior

B00C - R0001 - Staff Room

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Pupil Facilities - 1951 - Timber (Timber)

Exterior

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior

B00D - R0003 - Canteen

No Asbestos

B00D - R0004 - Canteen Covered Area

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Building Services - 1988 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior

B00E - R0001 - Sports Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Administration - 1951 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting 1740/B00F/Eaves Linings/S5					No Asbestos Detected
Ceiling Void	No Asbestos Found					
Underfloor Void	No Asbestos Found					

Interior

B00F - R0006 - Personal Effects Storage

Floor Coverings Res/Textile	Vinyl Tiles 1740/B00D/R0002/Floor Coverings Res/Textile/S1					No Asbestos Detected
--------------------------------	---	--	--	--	--	----------------------

B00F - R0008 - Home Base Store

No Asbestos

B00F - R0009 - Entry Vestibule

No Asbestos

B00F - R0010 - Clerical Office

No Asbestos

B00F - R0011 - Sick Bay

No Asbestos

B00F - R0012 - Principal

No Asbestos

B00F - R0013 - Practical Activities - 1hb

No Asbestos

B00F - R0014 - Home Base

No Asbestos

B00F - R0016 - Drinking Facilities

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Communal Facilities - 2008 - Steel (Steel)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior

B00G - R0001 - Covered Outdoor Learning Area

No Asbestos

B00G - R0002 - General Storeroom

No Asbestos

B00G - R0003 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Administration/Library - 2010 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior

B00H - R0001 - External Movement

No Asbestos

B00H - R0002 - Clerical Office

No Asbestos

B00H - R0003 - Staff Toilet

No Asbestos

B00H - R0004 - Sick Bay

No Asbestos

B00H - R0005 - Security Store

No Asbestos

B00H - R0006 - Disabled Shower/Toilet

No Asbestos

B00H - R0007 - Entry Vestibule

No Asbestos

B00H - R0008 - Staff Room

No Asbestos

B00H - R0009 - Staff Kitchen

No Asbestos

B00H - R0010 - Cleaning Distributed Store

No Asbestos

B00H - R0011 - Principal

No Asbestos

B00H - R0012 - Reading Area

No Asbestos

B00H - R0013 - Communications Room

No Asbestos

B00H - R0014 - K.L.A. Store

No Asbestos

B00H - R0015 - Clerical Office/Workroom

No Asbestos

B00H - R0016 - Distribution Board

No Asbestos

Note: No inspection of live electrical installation.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017