


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Lismore Public School (1780)  
**Region :** North Coast  
**State Electorate :** Lismore  
**Local Government Area :** Lismore

**Initial Survey :** Noel Arnold & Associates : 12 - Jun - 2008  
**Reviewed By :** Parsons Brinckerhoff : 31 - Oct - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - General Learning - 1942 - Brick/Block (Brick/Block)****Exterior**

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

**Interior****B00A - R0001 - Movement (1.49 m2)**

No Asbestos

**B00A - R0002 - Home Base (47.03 m2)**

No Asbestos

**B00A - R0003 - Home Base (47.01 m2)**

No Asbestos

**B00A - R0004 - Home Base (46.96 m2)**

No Asbestos

**B00A - R0005 - Staff Room Annexe (16.55 m2)**

No Asbestos

**B00A - R0006 - Staff Toilet (4.46 m2)**

No Asbestos

**B00A - R0007 - General Storeroom (4.32 m2)**

No Asbestos

**B00A - R0008 - Movement (1.27 m2)**

No Asbestos

**B00A - R0009 - Practical Activities - 1hb (72.09 m2)**

Floor Coverings Res/Textile	Vinyl Tiles
	1780/B00A/R0009/Floor Coverings Res/Textile/S8

**No Asbestos Detected****B00A - R0010 - Staff Room Annexe (16.39 m2)**

No Asbestos

**B00A - R0011 - Cleaning Distributed Store (4.92 m2)**

No Asbestos

**B00A - R0012 - Movement (5.19 m2)**

Floor Coverings Res/Textile	Vinyl Tiles
	1780/B00A/R0009/Floor Coverings Res/Textile/S8

**No Asbestos Detected****B00A - R0013 - Movement (2.02 m2)**

No Asbestos

**B00A - R0014 - Movement (3.12 m2)**

Floor Coverings Res/Textile	Vinyl Tiles
	1780/B00A/R0009/Floor Coverings Res/Textile/S8

**No Asbestos Detected****B00A - R0015 - Stairs (6.55 m2)**

Floor Coverings Res/Textile	Vinyl Tiles
	1780/B00A/R0009/Floor Coverings Res/Textile/S8

**No Asbestos Detected****B00A - R0016 - Movement (10.99 m2)**

No Asbestos

**B00A - R1001 - Home Base (47.64 m2)**

No Asbestos

**B00A - R1002 - Home Base (47.99 m2)**

No Asbestos

**B00A - R1003 - Home Base (47.93 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

**B00A - R1004 - Staff Room Annexe (18.75 m2)**

No Asbestos

**B00A - R1005 - General Storeroom (5.01 m2)**

No Asbestos

**B00A - R1006 - Practical Activities - 1hb (4.54 m2)**

No Asbestos

**B00A - R1007 - Practical Activities - 1hb (65.64 m2)**

No Asbestos

**B00A - R1008 - Movement (16.93 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					
		1780/B00A/R0009/Floor Coverings Res/Textile/S8				<b>No Asbestos Detected</b>

**B00A - R1009 - Movement (4.6 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					
		1780/B00A/R0009/Floor Coverings Res/Textile/S8				<b>No Asbestos Detected</b>

**B00A - R1010 - Stairs (10.79 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					
		1780/B00A/R0009/Floor Coverings Res/Textile/S8				<b>No Asbestos Detected</b>

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - General Learning - 1942 - Brick/Block (Brick/Block)****Exterior**

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

**Interior****B00B - R0001 - Movement (1.47 m2)**

No Asbestos

**B00B - R0002 - Special Programs Room (16.15 m2)**

No Asbestos

**B00B - R0003 - Movement (29.12 m2)**

No Asbestos

**B00B - R0004 - Main Switch Board (3.65 m2)**

Floor Coverings Res/Textile	Vinyl Tiles								
	1780/B00C/R0008/Floor Coverings Res/Textile/S6								<b>No Asbestos Detected</b>
Electrical Mounting Board	Flat AC Sheeting	1Unit	South	Good Condition (1)	Low (1)	Low Priority (2-3)			
	1780/B00B/R0004/Electrical Mounting Board/S21								<b>Chrysotile (white asbestos)</b>

**B00B - R0005 - Staff Toilet (4.97 m2)**

No Asbestos

**B00B - R0006 - Staff Room Annexe (16.73 m2)**

No Asbestos

**B00B - R0007 - General Storeroom (5.08 m2)**

No Asbestos

**B00B - R0008 - Practical Activities - 1hb (34.57 m2)**

No Asbestos

**B00B - R0009 - Home Base (46.37 m2)**

No Asbestos

**B00B - R0010 - Home Base (46.85 m2)**

No Asbestos

**B00B - R0011 - Home Base (46.83 m2)**

No Asbestos

**B00B - R0012 - Movement (12.8 m2)**

No Asbestos

**B00B - R0013 - Movement (3.14 m2)**

No Asbestos

**B00B - R0014 - Movement (2.03 m2)**

No Asbestos

**B00B - R0015 - Movement (4.42 m2)**

No Asbestos

**B00B - R0016 - Stairs (6.85 m2)**

Floor Coverings Res/Textile	Vinyl Tiles								
	1780/B00C/R0008/Floor Coverings Res/Textile/S6								<b>No Asbestos Detected</b>

**B00B - R0017 - Stairs (17.19 m2)**

Floor Coverings Res/Textile	Vinyl Tiles								
	1780/B00C/R0008/Floor Coverings Res/Textile/S6								<b>No Asbestos Detected</b>

**B00B - R1001 - Movement (4.59 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles					
	1780/B00C/R0008/Floor Coverings Res/Textile/S6					<b>No Asbestos Detected</b>
<b>B00B - R1002 - Practical Activities - 1hb (66.56 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	1780/B00C/R0008/Floor Coverings Res/Textile/S6					<b>No Asbestos Detected</b>
<b>B00B - R1003 - General Storeroom (3.98 m2)</b>						
No Asbestos						
<b>B00B - R1004 - Staff Toilet (5.52 m2)</b>						
No Asbestos						
<b>B00B - R1005 - Interview (18.57 m2)</b>						
No Asbestos						
<b>B00B - R1006 - Home Base (47.84 m2)</b>						
No Asbestos						
<b>B00B - R1007 - Home Base (47.92 m2)</b>						
No Asbestos						
<b>B00B - R1008 - Home Base (47.96 m2)</b>						
No Asbestos						
<b>B00B - R1009 - Movement (4.65 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	1780/B00C/R0008/Floor Coverings Res/Textile/S6					<b>No Asbestos Detected</b>
<b>B00B - R1010 - General Storeroom (6.27 m2)</b>						
No Asbestos						
<b>B00B - R1011 - Movement (17.04 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	1780/B00C/R0008/Floor Coverings Res/Textile/S6					<b>No Asbestos Detected</b>
<b>B00B - R1012 - Stairs (11.44 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	1780/B00C/R0008/Floor Coverings Res/Textile/S6					<b>No Asbestos Detected</b>
<b>B00B - R1013 - Stairs (14.42 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	1780/B00C/R0008/Floor Coverings Res/Textile/S6					<b>No Asbestos Detected</b>
<b>B00B - R9001 - Cleaning Supplies (7.33 m2)</b>						
No Asbestos						
<b>B00B - R9002 - Movement (3.21 m2)</b>						
No Asbestos						
<b>B00B - R9003 - Stairs (4.64 m2)</b>						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - General Learning - 1942 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting	16m2	North, West, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	1780/B00C/Eaves Linings/S10					<b>Chrysotile (white asbestos)</b>
Ceiling Void	No Asbestos Found					
Underfloor Void	No Asbestos Found					

**Interior****B00C - R0001 - Clerical Office/Workroom (13.02 m2)**

No Asbestos

**B00C - R0002 - Toilets - Boys/Girls (2.79 m2)**

No Asbestos

**B00C - R0003 - General Storeroom (1.44 m2)**

No Asbestos

**B00C - R0005 - Duplicating Workroom (19.54 m2)**

No Asbestos

**B00C - R0006 - General Storeroom (1.17 m2)**

No Asbestos

**B00C - R0007 - General Storeroom (0.64 m2)**

No Asbestos

**B00C - R0008 - Movement (8.46 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					
	1780/B00C/R0008/Floor Coverings Res/Textile/S6					<b>No Asbestos Detected</b>

**B00C - R0009 - Practical Activities - 1hb (63.93 m2)**

No Asbestos

**B00C - R0010 - Home Base (46.89 m2)**

No Asbestos

**B00C - R0011 - Home Base (46.91 m2)**

No Asbestos

**B00C - R0012 - Home Base (46.86 m2)**

No Asbestos

**B00C - R0014 - Movement (14.74 m2)**

No Asbestos

**B00C - R0015 - Home Base (46.9 m2)**

No Asbestos

**B00C - R0019 - Movement (7.49 m2)**

No Asbestos

**B00C - R0023 - Movement (2.24 m2)**

No Asbestos

**B00C - R0024 - Movement (2.34 m2)**

No Asbestos

**B00C - R0025 - Movement (2.15 m2)**

No Asbestos

**B00C - R0026 - Staff Toilet (1.94 m2)**

No Asbestos

**B00C - R0027 - Toilet - Lobby (2.8 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00C - R0028 - Withdrawal Space - 1hb (24.01 m2)</b>						
No Asbestos						
<b>B00C - R0029 - Interview (10 m2)</b>						
No Asbestos						
<b>B00C - R0030 - Interview (11.23 m2)</b>						
No Asbestos						
<b>B00C - R0031 - Movement (4.61 m2)</b>						
No Asbestos						
<b>B00C - R0032 - General Storeroom (12.45 m2)</b>						
No Asbestos						
<b>B00C - R0033 - Home Base (38 m2)</b>						
No Asbestos						
<b>B00C - R0034 - Practical Activities/Movement - 1hb (23.49 m2)</b>						
No Asbestos						
<b>B00C - R0035 - Toilets - Boys/Girls - Pre (3.29 m2)</b>						
No Asbestos						
<b>B00C - R0036 - Access Shower/Toilet (8.27 m2)</b>						
No Asbestos						
<b>B00C - R9001 - General Storeroom (16.66 m2)</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - General Learning - 1942 - Brick/Block (Brick/Block)****Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Void No Asbestos Found

**Interior****B00D - R0001 - Staff Toilet (5.57 m2)**

No Asbestos

**B00D - R0002 - General Storeroom (2.1 m2)**

No Asbestos

**B00D - R0003 - General Storeroom (19.75 m2)**

No Asbestos

**B00D - R0004 - Movement (63.29 m2)**

No Asbestos

**B00D - R0005 - Toilets - Boys/Girls (3.12 m2)**

Ceiling Structures/Linings Flat AC Sheeting  
1780/B00D/R0009/Ceiling Structures/Linings/S5 **No Asbestos Detected**

**B00D - R0006 - Practical Activities - 1hb (16.23 m2)**

Floor Coverings Res/Textile Vinyl Tiles 16m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)  
1780/B00D/R1003/Floor Coverings Res/Textile/S2 **Chrysotile (white asbestos)**

Ceiling Structures/Linings Flat AC Sheeting  
1780/B00D/R0009/Ceiling Structures/Linings/S5 **No Asbestos Detected**

**B00D - R0007 - Home Base (84.79 m2)**

Ceiling Structures/Linings Flat AC Sheeting  
1780/B00D/R0009/Ceiling Structures/Linings/S5 **No Asbestos Detected**

**B00D - R0008 - Home Base (85.1 m2)**

Ceiling Structures/Linings Flat AC Sheeting  
1780/B00D/R0009/Ceiling Structures/Linings/S5 **No Asbestos Detected**

**B00D - R0009 - Practical Activities - 1hb (16.52 m2)**

Floor Coverings Res/Textile Vinyl Tiles 16m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)  
1780/B00D/R1003/Floor Coverings Res/Textile/S2 **Chrysotile (white asbestos)**

Ceiling Structures/Linings Flat AC Sheeting  
1780/B00D/R0009/Ceiling Structures/Linings/S5 **No Asbestos Detected**

**B00D - R0010 - Toilets - Boys/Girls (3.05 m2)**

Ceiling Structures/Linings Flat AC Sheeting  
1780/B00D/R0009/Ceiling Structures/Linings/S5 **No Asbestos Detected**

**B00D - R0011 - Cleaning Supplies (6.74 m2)**

No Asbestos

**B00D - R0012 - General Storeroom (20.02 m2)**

No Asbestos

**B00D - R0013 - General Storeroom (1.03 m2)**

No Asbestos

**B00D - R0014 - Stairs (1.52 m2)**

No Asbestos

**B00D - R0015 - Stairs (1.49 m2)**

No Asbestos

**B00D - R1001 - Movement (90.2 m2)**



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	90m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1780/B00D/R1001/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	
<b>B00D - R1002 - Home Base (51.88 m2)</b>						
No Asbestos						
<b>B00D - R1003 - Home Base Store (6.83 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1780/B00D/R1003/Floor Coverings Res/Textile/S2					Chrysotile (white asbestos)	
<b>B00D - R1004 - Practical Activities - 1hb (21.29 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1780/B00D/R1003/Floor Coverings Res/Textile/S2					Chrysotile (white asbestos)	
<b>B00D - R1005 - Home Base (53.16 m2)</b>						
No Asbestos						
<b>B00D - R1006 - Home Base (53.55 m2)</b>						
No Asbestos						
<b>B00D - R1007 - Practical Activities - 1hb (21.2 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1780/B00D/R1003/Floor Coverings Res/Textile/S2					Chrysotile (white asbestos)	
<b>B00D - R1008 - Staff Toilet (5.74 m2)</b>						
No Asbestos						
<b>B00D - R1009 - Cleaning Distributed Store (2.08 m2)</b>						
No Asbestos						
<b>B00D - R1010 - Distribution Board (1.02 m2)</b>						
				Note: No inspection of live electrical installation.		
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1780/B00D/R1010/Ceiling Structures/Linings/S4					Chrysotile (white asbestos)	
<b>B00D - R1011 - Withdrawal Space - 1hb (7.02 m2)</b>						
No Asbestos						
<b>B00D - R1012 - Stairs (6.61 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1780/B00D/R1001/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	
<b>B00D - R1013 - Stairs (6.61 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1780/B00D/R1001/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00E - Communal Facilities - 1942 - Brick/Block (Brick/Block)****Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Void No Asbestos Found

**Interior****B00E - R0001 - Movement (170.76 m2)**

No Asbestos

**B00E - R0002 - Disabled Toilet (4.33 m2)**

No Asbestos

**B00E - R0003 - Communal Space (192.57 m2)**

No Asbestos

**B00E - R0004 - Toilets - Boys (16.87 m2)**

No Asbestos

**B00E - R0005 - Toilets - Girls (37.87 m2)**

No Asbestos

**B00E - R0006 - Staff Toilet (2.03 m2)**

No Asbestos

**B00E - R0007 - Cleaning Supplies (7.12 m2)**

No Asbestos

**B00E - R0008 - Cleaning Distributed Store (2.79 m2)**

No Asbestos

**B00E - R0009 - Movement (1.65 m2)**

No Asbestos

**B00E - R0010 - Sports Store (20.73 m2)**

No Asbestos

**B00E - R0011 - Plant (0.67 m2)**

No Asbestos

**B00E - R0012 - Out Of School Hours Care Centre (16.7 m2)**

No Asbestos

**B00E - R0013 - Kiln Room (6.89 m2)**

No Asbestos

**B00E - R0014 - Hall Chair Store (9.44 m2)**

No Asbestos

**B00E - R0015 - Raised Platform (52.02 m2)**

No Asbestos

**B00E - R0016 - Plant (0.9 m2)**

No Asbestos

**B00E - R0017 - Movement (1.88 m2)**

No Asbestos

**B00E - R0018 - Sports Store (2.5 m2)**

No Asbestos

**B00E - R0019 - Canteen (41.32 m2)**

No Asbestos

**B00E - R0020 - Canteen Office/Store (4.57 m2)**

No Asbestos

**B00E - R0021 - Canteen Office/Store (5.39 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00E - R0022 - Distribution Board (0.75 m2)				Note: No inspection of live electrical installation.		

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - Support Unit - 1942 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting	36m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1780/B00G/Eaves Linings/S11					<b>Chrysotile (white asbestos)</b>
Ceiling Void	No Asbestos Found					
Underfloor Void	No Asbestos Found					
Gable Verge Lining	Flat AC Sheeting	10m2	East & West	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	1780/B00G/Gable Verge Lining/S13					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**Interior****B00G - R0001 - Home Base - P (48.42 m2)**

No Asbestos

**B00G - R0002 - Home Base Store - P (1.96 m2)**

No Asbestos

**B00G - R0004 - Movement (53.84 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	49m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1780/B00G/R0004/Ceiling Structures/Linings/S15					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
Infill panels under windows	Flat AC Sheeting	8m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	1780/B00G/R0004/Infill panels under windows/S17					<b>Chrysotile (white asbestos)</b>
Infill panels to windows	Putty					<b>No Asbestos Detected</b>
	1780/B00G/R0004/Infill panels to windows/S18					

**B00G - R0005 - Home Base - P (43.71 m2)**

No Asbestos

**B00G - R0007 - Home Base Store - P (6.28 m2)**

No Asbestos

**B00G - R0008 - Distribution Board (1.07 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00G - R0011 - Cleaning Distributed Store (3.7 m2)**

No Asbestos

**B00G - R0012 - Home Base Store - P (3.72 m2)**

No Asbestos

**B00G - R0014 - Covered Vehicle Area/Porte Cochere (78 m2)**

No Asbestos

**B00G - R0016 - Access Shower/Toilet (6.64 m2)**

No Asbestos

**B00G - R0019 - Practical Activities - 1hb (10.69 m2)**

No Asbestos

**B00G - R0020 - Movement (4.21 m2)**

No Asbestos

**B00G - R0021 - Toilets - Boys/Girls (1.71 m2)**

Wall Linings Internal	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1780/B00G/R0021/Wall Linings Internal/S16					<b>Chrysotile (white asbestos)</b>

**B00G - R0022 - Toilet - Lobby (1.78 m2)**

Wall Linings Internal	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1780/B00G/R0021/Wall Linings Internal/S16					<b>Chrysotile (white asbestos)</b>

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00G - R0023 - Toilet - Lobby (1.79 m2)</b>						
Wall Linings Internal	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1780/B00G/R0021/Wall Linings Internal/S16					<b>Chrysotile (white asbestos)</b>	
<b>B00G - R0024 - Toilets - Boys/Girls (1.7 m2)</b>						
Wall Linings Internal	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1780/B00G/R0021/Wall Linings Internal/S16					<b>Chrysotile (white asbestos)</b>	
<b>B00G - R0025 - Home Base/Practical Activities (43.92 m2)</b>						
Recently Modified Space	Requires Inspection					
<b>B00G - R0026 - Movement (12.98 m2)</b>						
Recently Modified Space	Requires Inspection					
<b>B00G - R0027 - Movement (5.44 m2)</b>						
Recently Modified Space	Requires Inspection					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00H - Administration/Library - 1974 - Brick/Block (Brick/Block)</b>						
<b>Exterior</b>						
Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Void	No Asbestos Found					
<b>Interior</b>						
<b>B00H - R0001 - Duplicating Workroom (18.88 m2)</b>						
Ceiling Structures/Linings	Vermiculite 1780/B00H/R0017/Ceiling Structures/Linings/S9					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00H - R0002 - Movement (29.19 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles 1780/B00G/R0009/Floor Coverings Res/Textile/S7	29m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <i>Chrysotile (white asbestos)</i>
Ceiling Structures/Linings	Vermiculite 1780/B00H/R0017/Ceiling Structures/Linings/S9					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00H - R0003 - Staff Toilet (5.94 m2)</b>						
Ceiling Structures/Linings	Vermiculite 1780/B00H/R0017/Ceiling Structures/Linings/S9					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00H - R0005 - Deputy Principal (12.31 m2)</b>						
Ceiling Structures/Linings	Vermiculite 1780/B00H/R0017/Ceiling Structures/Linings/S9					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00H - R0006 - Clerical Office (12.96 m2)</b>						
Ceiling Structures/Linings	Vermiculite 1780/B00H/R0017/Ceiling Structures/Linings/S9					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00H - R0007 - Entry Vestibule (13.43 m2)</b>						
Ceiling Structures/Linings	Vermiculite 1780/B00H/R0017/Ceiling Structures/Linings/S9					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00H - R0008 - Movement (156.12 m2)</b>						
No Asbestos						
<b>B00H - R0009 - Clerical Office (13 m2)</b>						
Ceiling Structures/Linings	Vermiculite 1780/B00H/R0017/Ceiling Structures/Linings/S9					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00H - R0010 - Sick Bay (5.94 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles 1780/B00G/R0009/Floor Coverings Res/Textile/S7	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <i>Chrysotile (white asbestos)</i>
Ceiling Structures/Linings	Vermiculite 1780/B00H/R0017/Ceiling Structures/Linings/S9					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00H - R0011 - Distribution Board (5.59 m2)</b>						
Note: No inspection of live electrical installation.						
Ceiling Structures/Linings	Vermiculite 1780/B00H/R0017/Ceiling Structures/Linings/S9					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00H - R0012 - Staff Toilet (3.39 m2)</b>						
Ceiling Structures/Linings	Vermiculite 1780/B00H/R0017/Ceiling Structures/Linings/S9					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00H - R0013 - Principal (16.51 m2)</b>						
Ceiling Structures/Linings	Vermiculite		1780/B00H/R0017/Ceiling Structures/Linings/S9			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00H - R0014 - General Storeroom (3.81 m2)</b>						
Ceiling Structures/Linings	Vermiculite		1780/B00H/R0017/Ceiling Structures/Linings/S9			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00H - R0015 - Cleaning Distributed Store (3.62 m2)</b>						
Ceiling Structures/Linings	Vermiculite		1780/B00H/R0017/Ceiling Structures/Linings/S9			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00H - R0016 - General Storeroom (6 m2)</b>						
Ceiling Structures/Linings	Vermiculite		1780/B00H/R0017/Ceiling Structures/Linings/S9			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00H - R0017 - Staff Room (99.09 m2)</b>						
Ceiling Structures/Linings	Vermiculite		1780/B00H/R0017/Ceiling Structures/Linings/S9			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00H - R0018 - Staff Room (32.6 m2)</b>						
Ceiling Structures/Linings	Vermiculite		1780/B00H/R0017/Ceiling Structures/Linings/S9			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00H - R0020 - Cleaning Distributed Store (0.81 m2)</b>						
Ceiling Structures/Linings	Vermiculite		1780/B00H/R0017/Ceiling Structures/Linings/S9			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00H - R0022 - Staff Room Annexe (19.14 m2)</b>						
Ceiling Structures/Linings	Vermiculite		1780/B00H/R0017/Ceiling Structures/Linings/S9			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00H - R0023 - Stairs (8.75 m2)</b>						
No Asbestos						
<b>B00H - R0024 - Toilet - Lobby (4.09 m2)</b>						
Ceiling Structures/Linings	Vermiculite		1780/B00H/R0025/Ceiling Structures/Linings/S20			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00H - R0025 - Staff Toilet (2.27 m2)</b>						
Ceiling Structures/Linings	Vermiculite		1780/B00H/R0025/Ceiling Structures/Linings/S20			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00H - R0026 - Toilet - Lobby (3.62 m2)</b>						
Ceiling Structures/Linings	Vermiculite		1780/B00H/R0025/Ceiling Structures/Linings/S20			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00H - R0027 - Staff Toilet (1.4 m2)</b>						
Ceiling Structures/Linings	Vermiculite		1780/B00H/R0025/Ceiling Structures/Linings/S20			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00H - R0028 - Toilet - Lobby (3.53 m2)</b>						
Ceiling Structures/Linings	Vermiculite		1780/B00H/R0025/Ceiling Structures/Linings/S20			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00H - R0029 - Staff Toilet (2.3 m2)</b>						
Ceiling Structures/Linings	Vermiculite		1780/B00H/R0025/Ceiling Structures/Linings/S20			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00H - R1001 - Movement (22.92 m2)</b>						
No Asbestos						
<b>B00H - R1002 - Reading Area (269.75 m2)</b>						
No Asbestos						
<b>B00H - R1003 - Library Office/Workroom (6.43 m2)</b>						
No Asbestos						
<b>B00H - R1004 - Library Office/Workroom (18.43 m2)</b>						
No Asbestos						
<b>B00H - R1006 - Cleaning Distributed Store (0.97 m2)</b>						
No Asbestos						
<b>B00H - R1008 - Seminar/Study (12.13 m2)</b>						
No Asbestos						
<b>B00H - R1009 - Communications Room (12.89 m2)</b>						
No Asbestos						
<b>B00H - R1010 - Movement (31.45 m2)</b>						
No Asbestos						
<b>B00H - R1011 - Distribution Board (0.97 m2)</b>						
No Asbestos					Note: No inspection of live electrical installation.	
<b>B00H - R1012 - Stairs (4.12 m2)</b>						
No Asbestos						
<b>B00H - R1013 - Toilet - Lobby (3.65 m2)</b>						
No Asbestos						
<b>B00H - R1014 - Staff Toilet (1.41 m2)</b>						
No Asbestos						
<b>B00H - R1015 - Toilet - Lobby (3.48 m2)</b>						
No Asbestos						
<b>B00H - R1016 - Staff Toilet (2.32 m2)</b>						
No Asbestos						

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00J - Pupil Facilities - 1942 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Flat Roof	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1780/B00J/Eaves Linings/S12					<b>Chrysotile (white asbestos)</b>

**Interior**

**B00J - R0001 - Toilets - Girls (25.2 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	26m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1780/B00J/R0001/Ceiling Structures/Linings/S14					<b>Chrysotile (white asbestos)</b>

**B00J - R0002 - Staff Toilet (1.62 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1780/B00J/R0001/Ceiling Structures/Linings/S14					<b>Chrysotile (white asbestos)</b>

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00K - Pupil Facilities - 2011 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Slab on Ground      No Asbestos Found

Ceiling Voids      No Asbestos Found

**Interior**

**B00K - R0001 - Garden Store (20.53 m2)**

No Asbestos

**B00K - R0002 - General Assistant/Bulk Store (25.39 m2)**

No Asbestos

**B00K - R0003 - Sports Store (20.53 m2)**

No Asbestos

**B00K - R0004 - Toilets - Girls (22.83 m2)**

No Asbestos

**B00K - R0005 - Toilets - Boys (16.37 m2)**

No Asbestos

**B00K - R0006 - Access Shower/Toilet/Change (5.8 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00L - Pupil Facilities - 2011 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Slab on Ground      No Asbestos Found

Ceiling Voids      No Asbestos Found

**Interior**

**B00L - R0001 - Garden Store (20.53 m2)**

No Asbestos

**B00L - R0002 - General Assistant/Bulk Store (25.39 m2)**

No Asbestos

**B00L - R0003 - Sports Store (20.53 m2)**

No Asbestos

**B00L - R0004 - Toilets - Girls (22.83 m2)**

No Asbestos

**B00L - R0005 - Toilets - Boys (16.37 m2)**

No Asbestos

**B00L - R0006 - Access Shower/Toilet/Change (5.8 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017