


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Ladysmith Public School (2353)
Region : Riverina
State Electorate : Wagga Wagga
Local Government Area : Wagga Wagga

Initial Survey : Noel Arnold & Associates : 01 - May - 2008
Reviewed By : Parsons Brinckerhoff : 07 - Feb - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/General Learning - 1917 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	6m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2353/B00A/Eaves Linings/S1				Chrysotile (white asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Packing to Floor Joists	Packing	NA	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	2353/B00A/Underfloor Voids - Packing to Floor Joists/S4				Chrysotile (white asbestos)	

Interior

B00A - R0001 - Principal

No Asbestos

B00A - R0002 - Home Base

No Asbestos

B00A - R0003 - General Storeroom

Floor Coverings Res/Textile	Vinyl Sheet					
	2353/B00A/R0003/Floor Coverings Res/Textile/S2				No Asbestos Detected	

B00A - R0004 - Sports Store

Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2353/B00A/R0004/Ceiling Structures/Linings/S5				Chrysotile (white asbestos)	

B00A - R0005 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2353/B00A/R0004/Ceiling Structures/Linings/S5				Chrysotile (white asbestos)	

B00A - R0006 - Duplicating Workroom

No Asbestos

B00A - R0007 - Movement

No Asbestos

B00A - R0008 - Clerical Office

No Asbestos

B00A - R0009 - Entry Vestibule

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 1926 - Timber (Timber)

Exterior

Ceiling Voids	No Asbestos Found					
Underfloor Voids - Packing to Floor Joists	Packing	NA	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
2353/B00A/Underfloor Voids - Packing to Floor Joists/S4					Chrysotile (white asbestos)	

Interior

B00B - R0001 - Practical Activities - 1hb

No Asbestos

B00B - R0002 - Home Base

No Asbestos

B00B - R0003 - Craft Store

No Asbestos

B00B - R0004 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Administration - 1950 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	6m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	2353/B00C/Eaves Linings/S6				Chrysotile (white asbestos)	
Entry Steps	Flat AC Sheeting				No Asbestos Detected	
	2353/B00C/Entry Steps/S3					
Underfloor Voids - Packing to Floor Joists	Packing	NA	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	2353/B00A/Underfloor Voids - Packing to Floor Joists/S4				Chrysotile (white asbestos)	
Ceiling Voids	No Asbestos Found					

Interior

B00C - R0001 - Staff Room

No Asbestos

B00C - R0003 - External Movement

No Asbestos

B00C - R0004 - Disabled Toilet

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Special Purpose - 1950 - Timber (Timber)

Exterior

Underfloor Voids - Packing to Floor Joists	Packing	NA	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	2353/B00A/Underfloor Voids - Packing to Floor Joists/S4				Chrysotile (white asbestos)	
Ceiling Voids	No Asbestos Found					

Interior

B00D - R0001 - External Movement

No Asbestos

B00D - R0003 - General Storeroom

No Asbestos

B00D - R0004 - Toilet - Lobby

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Pupil Facilities/Building Services - 1972 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2353/B00A/Eaves Linings/S1					Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior**B00E - R0001 - Toilets - Girls**

Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2353/B00E/R0001/Ceiling Structures/Linings/S7					Chrysotile (white asbestos)

B00E - R0002 - Cleaning Supplies

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2353/B00E/R0001/Ceiling Structures/Linings/S7					Chrysotile (white asbestos)

B00E - R0003 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2353/B00E/R0001/Ceiling Structures/Linings/S7					Chrysotile (white asbestos)

B00E - R0004 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2353/B00E/R0001/Ceiling Structures/Linings/S7					Chrysotile (white asbestos)

B00E - R0005 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2353/B00E/R0001/Ceiling Structures/Linings/S7					Chrysotile (white asbestos)

B00E - R0006 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2353/B00E/R0001/Ceiling Structures/Linings/S7					Chrysotile (white asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Building Services - 2008 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00F - R0001 - Garden Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Other-Vacant - 2008 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00G - R0001 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Library - 2010 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00H - R0001 - Reading Area

No Asbestos

B00H - R0002 - K.L.A. Store

No Asbestos

B00H - R0003 - Practical Activities

No Asbestos

B00H - R0004 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017