


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Laguna Public School (2356)  
**Region :** Hunter/Central Coast  
**State Electorate :** Cessnock  
**Local Government Area :** Cessnock

**Initial Survey :** Noel Arnold & Associates : 15 - May - 2008  
**Register Issue Date :** 22 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - Library - 1881 - Sandstone (Sandstone)**

**Exterior**

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

**Interior**

**B00A - R0001 - Entry Vestibule**

Floor Coverings Res/Textile	Vinyl Tiles	
	2356/B00A/R0001/Floor Coverings Res/Textile/S2	<b>No Asbestos Detected</b>

**B00A - R0002 - General Storeroom**

No Asbestos

**B00A - R0003 - Reading Area**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - Communal Facilities - 2000 - Timber Shed (Timber Shed)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00B - R0001 - Sports Store**

Ceiling Structures/Linings	Flat AC Sheeting 2356/B00B/R0001/Ceiling Structures/Linings/S1	<b>No Asbestos Detected</b>
----------------------------	---	-----------------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - General Learning/Special Purpose Learning - 2011 - Steel (Steel)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00C - R0001 - External Movement**

No Asbestos

**B00C - R0002 - Special Programs Room**

No Asbestos

**B00C - R0003 - Home Base**

No Asbestos

**B00C - R0004 - Home Base Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Storage - 2010 - Metal Shed (Metal Shed)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00D - R0001 - General Storeroom**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

## Demountables

### Demountable details as per the AMS records as of 15 Feb 2017.

#### OS 505 - D10237 - Admin Staff/Principal/Secure Store : Placement Date - 30/09/2004

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

#### Exterior

No Asbestos Found.

#### Interior

##### R1 - Entry

No Asbestos Found.

##### R2 - Principal

No Asbestos Found.

##### R3 - Staff Room

No Asbestos Found.

##### R4 - Security Store

No Asbestos Found.

##### R5 - Clerical Office

No Asbestos Found.

#### OS 842 - D13292 - Country Toilet - Relta - Boys/Girls : Placement Date - 11/10/2004

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

#### Exterior

No Asbestos Found.

#### Interior

##### R1 - Toilets-Girls

No Asbestos Found.

##### R2 - Staff Toilet

No Asbestos Found.

##### R3 - Toilets-Boys

No Asbestos Found.

##### R4 - Staff Toilet

No Asbestos Found.

#### OS 602 - D15144 - Learning Unit - Standard With P.A.A. : Placement Date - 12/03/2014

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

#### Exterior

No Asbestos Found.

#### Interior

##### R1 - Learning space/withdrawal/entry

No Asbestos Found.

##### R2 - Home Base Store

No Asbestos Found.

#### OS 602 - D15865 - Learning Unit - Standard With P.A.A. : Placement Date - 15/10/2004

#### Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
Ceiling	Flat AC Sheet	Assumed Asbestos				70 m2
<b>R2 - Home Base Store</b>						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				3 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017