


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Lake Wyangan Public School (2363)
Region : Riverina
State Electorate : Murray
Local Government Area : Griffith

Initial Survey : Noel Arnold & Associates : 13 - May - 2008
Register Issue Date : 22 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/General Learning - 1964 - Timber (Timber)

Exterior

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

Interior

B00A - R0001 - Movement

No Asbestos

B00A - R0002 - Staff Room

No Asbestos

B00A - R0003 - Home Base Store

No Asbestos

B00A - R0004 - Home Base

Wall Linings Internal	Flat AC Sheeting	4m2	Behind Heater	Good Condition (1)	Low (1)	Low Priority (2-3)
2363/B00A/R0004/Wall lining behind heater/S1				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00A - R0005 - Handwashing Facilities

No Asbestos

B00A - R0006 - Home Base

No Asbestos

B00A - R0007 - Home Base Store

No Asbestos

B00A - R0008 - Principal

No Asbestos

B00A - R0009 - General Storeroom

No Asbestos

B00A - R0010 - Clerical Office/Workroom

No Asbestos

B00A - R0011 - Staff Toilet

No Asbestos

B00A - R0012 - Entry Vestibule

No Asbestos

B00A - R0013 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Library - 1935 - Timber (Timber)

Exterior

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

Interior

B00B - R0001 - General Storeroom

Flooring	Compressed AC Sheet 2363/B00B/R0001/Floor Coverings Res/Textile/S3					No Asbestos Detected
----------	---	--	--	--	--	-----------------------------

B00B - R0002 - Special Programs Room

No Asbestos

B00B - R0003 - Movement

Wall Linings Internal	Flat AC Sheeting	10m2	North facing, East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	2363/B00B/R0003/Wall Linings Internal/S2					Chrysotile (white asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning - 1940 - Timber (Timber)

Exterior

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

Interior

B00C - R0001 - Home Base

No Asbestos

B00C - R0002 - General Storeroom

No Asbestos

B00C - R0003 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Pupil Facilities - 1926 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	2m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	2363/B00E/Eaves Linings/S4					Chrysotile (white asbestos)
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

Interior

B00E - R0002 - Toilets - Girls

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Pupil Facilities - 1999 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00H - R0001 - Toilets - Girls

No Asbestos

B00H - R0002 - Movement

No Asbestos

B00H - R0003 - Disabled Toilet

No Asbestos

B00H - R0004 - Toilets - Boys

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B001 - Building Services - 2008 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B001 - R0001 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Building Services - 2008 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00J - R0001 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Building Services - 2008 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00K - R0001 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Library - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00L - R0001 - Library Office/Workroom

No Asbestos

B00L - R0002 - K.L.A. Store

No Asbestos

B00L - R0003 - Communications Room

No Asbestos

B00L - R0004 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00L - R0005 - Reading Area

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - Building Services - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00M - R0001 - Garage/Carport

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D10927 - Learning Unit - Standard With P.A.A. : Placement Date - 23/02/2012

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 810 - D11198 - FSU/Shelter/Stores : Placement Date - 7/09/2016

Exterior

No Asbestos Found.

Interior

R1 - Canteen

No Asbestos Found.

R2 - Covered Area

No Asbestos Found.

R3 - Store

No Asbestos Found.

R4 - Sports Store

No Asbestos Found.

R5 - Garden Store

No Asbestos Found.

R6 - Change Room

No Asbestos Found.

R7 - Store

No Asbestos Found.

OS 602 - D13450 - Learning Unit - Standard With P.A.A. : Placement Date - 7/03/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 500 - D18106 - Admin - Library : Placement Date - 8/02/2005

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	20.16 m2

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Interior						
R1 - Entry						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				13 m2
R2 - Principal						
Ceiling	Flat AC Sheet	Assumed Asbestos				18 m2
R3 - Staff Room/Kitchen						
Ceiling	Flat AC Sheet	Assumed Asbestos				19 m2
R4 - Clerical Office						
Ceiling	Flat AC Sheet	Assumed Asbestos				18 m2
R5 - Library						
Ceiling	Flat AC Sheet	Assumed Asbestos				54 m2
R6 - Storeroom						
Ceiling	Flat AC Sheet	Assumed Asbestos				0 m2
R7 - Staff Toilet						
Toilet partitions	Compressed AC Sheet	Assumed Asbestos				6 m2
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				4 m2
R8 - Entry to toilet						
Ceiling	Flat AC Sheet	Assumed Asbestos				0 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017