

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Lambton Public School (2366)
Region : Hunter/Central Coast
State Electorate : Wallsend
Local Government Area : Newcastle

Initial Survey : Noel Arnold & Associates : 11 - Mar - 2008
Reviewed By : AECOM : 25 - Jun - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/Staff Facilities - 1966 - Brick/Block (Brick/Block)**Exterior**

In-fill panels below windows	Flat AC Sheeting 2366/B00A/In-fill panels below windows/S16	52m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Eaves Linings	Flat AC Sheeting 2366/B00A/Eaves Linings/S19					No Asbestos Detected
Gable verge linings	Flat AC Sheeting 2366/B00A/Gable verge linings/S20					No Asbestos Detected
Ceiling Voids	Non Accessible Area - need to access test					
Underfloor Voids	No Asbestos Found					

Interior**B00A - R0001 - Clerical Office**

No Asbestos

B00A - R0002 - Movement

No Asbestos

B00A - R0003 - Sick Bay

No Asbestos

B00A - R0004 - Deputy Principal

No Asbestos

B00A - R0005 - General Storeroom

Floor Coverings Res/Textile	Vinyl Tiles 2366/B00A/R0010/Floor Coverings Res/Textile/S17	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
-----------------------------	--	-----	--------------	--------------------	---------	--

B00A - R0006 - Cleaning Distributed Store

Floor Coverings Res/Textile	Vinyl Tiles 2366/B00A/R0010/Floor Coverings Res/Textile/S17	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
-----------------------------	--	-----	--------------	--------------------	---------	--

B00A - R0007 - Movement

Floor Coverings Res/Textile	Vinyl Tiles 2366/B00A/R0010/Floor Coverings Res/Textile/S17	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
-----------------------------	--	-----	--------------	--------------------	---------	--

B00A - R0008 - Staff Toilet

Floor Coverings Res/Textile	Vinyl Tiles 2366/B00A/R0010/Floor Coverings Res/Textile/S17	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
-----------------------------	--	-----	--------------	--------------------	---------	--

B00A - R0009 - Movement

Floor Coverings Res/Textile	Vinyl Tiles 2366/B00A/R0010/Floor Coverings Res/Textile/S17	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
-----------------------------	--	-----	--------------	--------------------	---------	--

B00A - R0010 - Distribution Board

Note: No inspection of live electrical installation.

Floor Coverings Res/Textile	Vinyl Tiles 2366/B00A/R0010/Floor Coverings Res/Textile/S17	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Electrical Mounting Board	Resinous Board	1Unit	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)

Assumed Asbestos - Electrical Hazard**B00A - R0011 - Clerical Office**

No Asbestos

B00A - R0012 - Duplicating Workroom

No Asbestos

B00A - R0013 - Movement

No Asbestos

B00A - R0014 - Entry Vestibule

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00A - R0015 - Movement

No Asbestos

B00A - R0016 - Principal

No Asbestos

B00A - R0017 - Staff Toilet

Floor Coverings Res/Textile	Vinyl Tiles	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2366/B00A/R0010/Floor Coverings Res/Textile/S17					Chrysotile (white asbestos)	

B00A - R0018 - Staff Toilet

Floor Coverings Res/Textile	Vinyl Tiles	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2366/B00A/R0010/Floor Coverings Res/Textile/S17					Chrysotile (white asbestos)	

B00A - R0019 - Movement

Floor Coverings Res/Textile	Vinyl Tiles	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2366/B00A/R0010/Floor Coverings Res/Textile/S17					Chrysotile (white asbestos)	

B00A - R0020 - Staff Room

Floor Coverings Res/Textile	Vinyl Tiles	10m2	South facing	Minimal Damage (2)	Low (1)	Low Priority (2-3)
2366/B00A/R0010/Floor Coverings Res/Textile/S17					Chrysotile (white asbestos)	

B00A - R0021 - Access Shower/Toilet

No Asbestos

B00A - R9001 - Movement

No Asbestos

B00A - R9002 - General Assistant/Bulk Store

No Asbestos

B00A - R9003 - Garden Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning/Pupil Facilities - 1890 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	50m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2366/B00B/R0005/Ceiling Structures/Linings/S21				Chrysotile (white asbestos)	
Ceiling Voids	Non Accessible Area - Height Restriction - manhole too high located in boys toilet					
Underfloor Voids	Non Accessible Area - Area inaccessible no underfloor entrance found					

Interior**B00B - R0001 - Movement**

No Asbestos

B00B - R0002 - Home Base

No Asbestos

B00B - R0003 - Home Base

No Asbestos

B00B - R0004 - Home Base

No Asbestos

B00B - R0005 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	6.2m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	2366/B00B/R0005/Ceiling Structures/Linings/S21				Chrysotile (white asbestos)	

B00B - R0006 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2366/B00B/R0006/Partition Walls (Cubicles)/S6				Chrysotile (white asbestos)	

Ceiling Structures/Linings	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2366/B00B/R0005/Ceiling Structures/Linings/S21				Chrysotile (white asbestos)	

B00B - R0007 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2366/B00B/R0006/Partition Walls (Cubicles)/S6				Chrysotile (white asbestos)	

Ceiling Structures/Linings	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2366/B00B/R0005/Ceiling Structures/Linings/S21				Chrysotile (white asbestos)	

B00B - R0008 - Movement

No Asbestos

B00B - R0009 - General Storeroom

No Asbestos

B00B - R0010 - Withdrawal Space - 2hb

No Asbestos

B00B - R0011 - General Storeroom

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning/Communal Facilities - 1876 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	Non Accessible Area - Height Restriction manholes too high to get to
Underfloor Voids	No Asbestos Found

Interior

B00C - R0001 - General Storeroom

Floor Coverings Res/Textile	Vinyl Tiles					
	2366/B00C/R0001/Floor Coverings Res/Textile/S13					No Asbestos Detected

B00C - R0002 - Home Base

No Asbestos

B00C - R0003 - Movement

No Asbestos

B00C - R0004 - Home Base

No Asbestos

B00C - R0005 - Home Base

Chalk Board	Flat AC Sheeting	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2366/B00C/R0005/Chalk Board/S14					Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	56m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Height Restriction ceiling too high to					

B00C - R0006 - Communal Space

Ceiling Structures/Linings	Flat AC Sheeting	115m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2366/B00C/R0007/Ceiling Structures/Linings/S26					Chrysotile (white asbestos)
Chalk Board	Flat AC Sheeting	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2366/B00C/R0005/Chalk Board/S14					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles	28m2	North facing, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	2366/B00C/R0006/Floor Coverings Res/Textile/S15					Chrysotile (white asbestos)

B00C - R0007 - Raised Platform

Ceiling Structures/Linings	Flat AC Sheeting	23m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2366/B00C/R0007/Ceiling Structures/Linings/S26					Chrysotile (white asbestos)

B00C - R0008 - General Storeroom

No Asbestos

B00C - R0009 - General Storeroom

No Asbestos

B00C - R0010 - Movement

No Asbestos

B00C - R0011 - General Storeroom

No Asbestos

B00C - R0012 - Movement

No Asbestos

B00C - R9001 - General Storeroom

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Administration - 1950 - Brick/Veneer (Brick/Veneer)**Exterior**

Eaves Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2366/B00D/R0002/Ceiling Structures/Linings/S22			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Voids	Non Accessible Area - Area inaccessible no manhoolee found					
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					

Interior**B00D - R0001 - General Storeroom**

Wall Linings Internal	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2366/B00D/R0001/Wall Linings Internal/S18			Chrysotile (white asbestos)		
Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2366/B00D/R0002/Ceiling Structures/Linings/S22			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00D - R0002 - General Storeroom

Wall Linings Internal	Flat AC Sheeting	60m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2366/B00D/R0001/Wall Linings Internal/S18			Chrysotile (white asbestos)		
Ceiling Structures/Linings	Flat AC Sheeting	26m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2366/B00D/R0002/Ceiling Structures/Linings/S22			Chrysotile (white asbestos) , Amosite (brown asbestos)		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Pupil Facilities - 1966 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	8m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	2366/B00E/R0003/Ceiling Structures/Linings/S25				Chrysotile (white asbestos)	
Ceiling Voids	Non Accessible Area - Area inaccessible no manhole found					
Underfloor Voids	Non Accessible Area - Area inaccessible no void hatch found					

Interior**B00E - R0001 - Staff Toilet**

Ceiling Structures/Linings	Flat AC Sheeting	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2366/B00E/R0003/Ceiling Structures/Linings/S25				Chrysotile (white asbestos)	
In-fill panel	Flat AC Sheeting 2366/B00E/R0001/Wall Linings Internal/S2 No Asbestos Detected					

B00E - R0002 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting	35m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2366/B00E/R0003/Ceiling Structures/Linings/S25				Chrysotile (white asbestos)	
Partition Walls (Cubicles)	No Asbestos Found					

B00E - R0004 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting	28m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2366/B00E/R0003/Ceiling Structures/Linings/S25				Chrysotile (white asbestos)	
Partition Walls (Cubicles)	Compressed AC Sheet	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2366/B00E/R0004/Partition Walls (Cubicles)/S1				Chrysotile (white asbestos)	

B00E - R0005 - External Movement

Recently Modified Space	Requires Inspection					
-------------------------	---------------------	--	--	--	--	--

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning/Pupil Facilities - 1958 - Brick/Block (Brick/Block)**Exterior**

Gable verge linings	Flat AC Sheeting 2366/B00A/Gable verge linings/S20					No Asbestos Detected
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					

Interior**B00F - R0001 - Movement**

No Asbestos

B00F - R0002 - Personal Effects Storage

Floor Coverings Res/Textile	Vinyl Tiles 2366/B00F/R0007/Floor Coverings Res/Textile/S4	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)

B00F - R0003 - Home Base Store

Floor Coverings Res/Textile	Vinyl Tiles 2366/B00F/R0007/Floor Coverings Res/Textile/S4	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)

B00F - R0004 - Home Base

No Asbestos

B00F - R0005 - Home Base

No Asbestos

B00F - R0006 - Home Base Store

Floor Coverings Res/Textile	Vinyl Tiles 2366/B00F/R0007/Floor Coverings Res/Textile/S4	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)

B00F - R0007 - Personal Effects Storage

Floor Coverings Res/Textile	Vinyl Tiles 2366/B00F/R0007/Floor Coverings Res/Textile/S4	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)

B00F - R0008 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting 2366/B00B/R0005/Ceiling Structures/Linings/S21	27m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)

Partition Walls (Cubicles)	Compressed AC Sheet 2366/B00F/R0008/Partition Walls (Cubicles)/S3	30m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)

B00F - R0009 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting 2366/B00B/R0005/Ceiling Structures/Linings/S21	27m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)

Partition Walls (Cubicles)	Compressed AC Sheet 2366/B00F/R0008/Partition Walls (Cubicles)/S3	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning/Special Purpose Learning - 1912 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	30m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2366/B00G/Eaves Linings/S5					Chrysotile (white asbestos)
Ceiling Voids	Non Accessible Area - Height Restriction manhole too high GR0003					
Underfloor Voids	Non Accessible Area - Area inaccessible underfloor caged in					

Interior

B00G - R0001 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	27m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2366/B00G/Eaves Linings/S5					Chrysotile (white asbestos)

B00G - R0002 - Home Base

No Asbestos

B00G - R0003 - Home Base

No Asbestos

B00G - R0004 - Craft Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00H - General Learning - 1912 - Timber (Timber)						
Exterior						
Eaves Linings	Flat AC Sheeting	30m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2366/B00H/Eaves Linings/S10					Chrysotile (white asbestos)
Wall Cladding	Flat AC Sheeting					No Asbestos Detected
	2366/B00H/Wall Cladding/S11					
Ceiling Voids	Non Accessible Area					
	- Area inaccessible no manholee found					
Underfloor Voids	Non Accessible Area					
	- Area inaccessible					
Interior						
B00H - R0001 - General Storeroom						
Ceiling Structures/Linings	Flat AC Sheeting	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2366/B00H/Eaves Linings/S10					Chrysotile (white asbestos)
B00H - R0002 - Home Base						
Ceiling Structures/Linings	Flat AC Sheeting	53m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2366/B00H/Eaves Linings/S10					Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	120m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2366/B00H/R0004/Wall Linings Internal/S12					Chrysotile (white asbestos)
B00H - R0003 - Home Base						
Ceiling Structures/Linings	Flat AC Sheeting	53m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2366/B00H/Eaves Linings/S10					Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	120m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2366/B00H/R0004/Wall Linings Internal/S12					Chrysotile (white asbestos)
B00H - R0005 - General Storeroom						
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	2366/B00H/R0006/Ceiling Structures/Linings/S23					Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	2366/B00H/R0006/Wall Linings Internal/S24					
B00H - R0006 - Practical Activities - 2hb						
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2366/B00H/R0006/Ceiling Structures/Linings/S23					Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	2366/B00H/R0006/Wall Linings Internal/S24					
B00H - R0007 - Practical Activities - 1hb						
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2366/B00H/R0006/Ceiling Structures/Linings/S23					Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	2366/B00H/R0006/Wall Linings Internal/S24					
B00H - R0008 - External Movement						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B001 - Library - 1982 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	Non Accessible Area - Area inaccessible no manhole found
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

Interior

B001 - R0001 - Movement

No Asbestos

B001 - R0002 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2366/B001/R0002/Partition Walls (Cubicles)/S8					Chrysotile (white asbestos)	

B001 - R0003 - Distribution Board

Note: No inspection of live electrical installation.

Wall Linings Internal	Flat AC Sheeting	4m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
2366/B001/R0003/Wall Linings Internal/S7					Chrysotile (white asbestos)	

B001 - R0004 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2366/B001/R0002/Partition Walls (Cubicles)/S8					Chrysotile (white asbestos)	

B001 - R0005 - Library Office/Workroom

No Asbestos

B001 - R0006 - K.L.A. Store

No Asbestos

B001 - R0007 - Reading Area

No Asbestos

B001 - R0008 - Special Programs Room

No Asbestos

B001 - R0009 - Plant

No Asbestos

B001 - R0010 - Special Programs Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Communal Facilities - 1966 - Timber (Timber)

Exterior

Wall Cladding	Flat AC Sheeting 2366/B00J/Wall Cladding/S9					No Asbestos Detected
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Ceiling Voids	No Asbestos Found					

Interior

B00J - R0001 - Sports Store

No Asbestos

B00J - R0002 - Covered Outdoor Learning Area

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Pupil Facilities - 1966 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting 2366/B00A/Eaves Linings/S19					No Asbestos Detected
Gable verge lining	Flat AC Sheeting 2366/B00A/Gable verge linings/S20					No Asbestos Detected
Ceiling Voids	Non Accessible Area - Area inaccessible					
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					

Interior

B00K - R0001 - Movement

No Asbestos

B00K - R0002 - Canteen Office/Store

No Asbestos

B00K - R0003 - Canteen Office/Store

No Asbestos

B00K - R0004 - Canteen

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00L - Communal Facilities/Pupil Facilities - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	Non Accessible Area - Height Restriction
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

Interior

B00L - R0001 - Covered Outdoor Learning Area

No Asbestos

B00L - R0003 - Access Shower/Toilet

No Asbestos

B00L - R0004 - Main Switch Board

No Asbestos

B00L - R0005 - Communal Space

No Asbestos

B00L - R0006 - Cleaning Distributed Store

No Asbestos

B00L - R0007 - General Storeroom

No Asbestos

B00L - R0008 - Toilet - Lobby

No Asbestos

B00L - R0009 - Toilets - Boys

No Asbestos

B00L - R0010 - Sound Cupboard

No Asbestos

B00L - R0011 - Toilet - Lobby

No Asbestos

B00L - R0012 - Toilets - Girls

No Asbestos

B00L - R0013 - P.E. Store

No Asbestos

B00L - R0014 - Communal/Performance Store

No Asbestos

B00L - R0015 - Hall Chair Store

No Asbestos

B00L - R0016 - Movement

No Asbestos

B00L - R0017 - Raised Platform

No Asbestos

B00L - R0018 - Ramp

No Asbestos

B00L - R0019 - Movement

No Asbestos

B00L - R0020 - External Movement

No Asbestos

B00L - R0021 - Canteen

No Asbestos

B00L - R0022 - Canteen Office/Store

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D10243 - Learning Unit - Standard With P.A.A. : Placement Date - 10/02/2012

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 601 - D10254 - Learning Unit - Standard/Withdrawal : Placement Date - 25/02/2002

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2
---------	---------------	------------------	-------

OS 602 - D11080 - Learning Unit - Standard With P.A.A. : Placement Date - 12/01/2011

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017