

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Lane Cove Public School (2368)
Region : Northern Sydney
State Electorate : Lane Cove
Local Government Area : Lane Cove

Initial Survey : Noel Arnold & Associates : 28 - Mar - 2008
Reviewed By : Grencap-NAA : 24 - Jun - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B001 - General Learning - 1920 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids	Non Accessible Area - Confined space.					
Ceiling Voids	Non Accessible Area - Unsafe to enter - Obstructions					

Interior

B001 - R0001 - General Storeroom (4.78 m2)

No Asbestos

B001 - R0004 - Movement (4.58 m2)

No Asbestos

B001 - R0005 - General Storeroom (8.19 m2)

Floor Coverings Res/Textile	Vinyl Tiles	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2368/B001/R0005/Floor Coverings Res/Textile/S13				Chrysotile (white asbestos)	

Floor Coverings Res/Textile	Adhesive					
	2368/B001/R0005/Floor Coverings Res/Textile/S31				No Asbestos Detected	

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	8.19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2368/B001/R0005/Floor Coverings Res/Textile/S32				Chrysotile (white asbestos)	

Floor Coverings Res/Textile	Adhesive					
	2368/B001/R0005/Floor Coverings Res/Textile/S33				No Asbestos Detected	

B001 - R0006 - Toilets - Boys/Girls (3.84 m2)

No Asbestos

B001 - R0007 - Movement (14.02 m2)

No Asbestos

B001 - R0008 - Practical Activities - 1hb (12.17 m2)

Floor Coverings Res/Textile	Vinyl Sheet					
	2368/B004/R1011/Floor Coverings Res/Textile/S26				No Asbestos Detected	

Floor Coverings Res/Textile	Olive vinyl tile under blue sheet	12.17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2368/B001/R0005/Floor Coverings Res/Textile/S32				Chrysotile (white asbestos)	

Floor Coverings Res/Textile	Adhesive under olive tile under blue sheet					
	2368/B001/R0005/Floor Coverings Res/Textile/S33				No Asbestos Detected	

B001 - R0009 - Home Base (47.38 m2)

Floor Coverings Res/Textile	Olive tile under carpet	47.38m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2368/B001/R0005/Floor Coverings Res/Textile/S32				Chrysotile (white asbestos)	

Floor Coverings Res/Textile	Adhesive under olive tile under carpet					
	2368/B001/R0005/Floor Coverings Res/Textile/S33				No Asbestos Detected	

B001 - R0010 - Home Base (66.29 m2)

Floor Coverings Res/Textile	Olive tile under carpet	66.29m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2368/B001/R0005/Floor Coverings Res/Textile/S32				Chrysotile (white asbestos)	

Floor Coverings Res/Textile	Adhesive under Olive tile under carpet					
	2368/B001/R0005/Floor Coverings Res/Textile/S33				No Asbestos Detected	

B001 - R0011 - Movement (2.33 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B001 - R0012 - Withdrawal Space - 2hb (13.75 m2)						
No Asbestos						
B001 - R0013 - Home Base Store (4.31 m2)						
No Asbestos						
B001 - R0014 - Home Base (66.29 m2)						
Wall Linings Internal	Vinyl Tiles	1m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	2368/B001/R0014/Wall Linings Internal/S15					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Olive tile under carpet	66.29m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2368/B001/R0005/Floor Coverings Res/Textile/S32					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive under olive tile under carpet					No Asbestos Detected
	2368/B001/R0005/Floor Coverings Res/Textile/S33					
B001 - R0015 - Home Base (47.38 m2)						
Floor Coverings Res/Textile	Olive tile under carpet	47.38m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2368/B001/R0005/Floor Coverings Res/Textile/S32					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive under olive tile under carpet					No Asbestos Detected
	2368/B001/R0005/Floor Coverings Res/Textile/S33					
B001 - R0016 - Practical Activities - 1hb (11.35 m2)						
Floor Coverings Res/Textile	Vinyl Sheet					No Asbestos Detected
	2368/B004/R1011/Floor Coverings Res/Textile/S26					
Floor Coverings Res/Textile	Olive tile under blue sheet	11.35m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2368/B001/R0005/Floor Coverings Res/Textile/S32					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive under olive tile under blue sheet					No Asbestos Detected
	2368/B001/R0005/Floor Coverings Res/Textile/S33					
B001 - R0017 - Staff Toilet (4.39 m2)						
No Asbestos						
B001 - R0018 - Home Base Store (7.74 m2)						
No Asbestos						
B001 - R0019 - Movement (5.45 m2)						
No Asbestos						
B001 - R0020 - Personal Effects Storage (12.37 m2)						
No Asbestos						
B001 - R0021 - Cleaning Distributed Store (3.19 m2)						
No Asbestos						
B001 - R0022 - Plant (25.04 m2)						
No Asbestos						
B001 - R0023 - Movement (2.72 m2)						
No Asbestos						
B001 - R0024 - Movement (12.11 m2)						
No Asbestos						
B001 - R0025 - Stairs (10.31 m2)						
No Asbestos						
B001 - R0026 - Stairs (11.42 m2)						
No Asbestos						
B001 - R1001 - Personal Effects Storage (8.6 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles					
	2368/B001/R0005/Floor Coverings Res/Textile/S31					No Asbestos Detected
Floor Coverings Res/Textile	Adhesive					
	2368/B001/R0005/Floor Coverings Res/Textile/S33					No Asbestos Detected
B001 - R1002 - General Storeroom (5.12 m2)						
No Asbestos						
B001 - R1003 - Toilets - Boys/Girls (3.45 m2)						
No Asbestos						
B001 - R1004 - Movement (16.5 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2368/B001/R0005/Floor Coverings Res/Textile/S32					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive					
	2368/B001/R0005/Floor Coverings Res/Textile/S33					No Asbestos Detected
B001 - R1005 - Home Base (48.67 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	2368/B001/R0005/Floor Coverings Res/Textile/S33					No Asbestos Detected
B001 - R1006 - Home Base (67.95 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	70m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2368/B001/R0005/Floor Coverings Res/Textile/S32					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive					
	2368/B001/R0005/Floor Coverings Res/Textile/S33					No Asbestos Detected
B001 - R1007 - Home Base (67.94 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	70m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2368/B001/R0005/Floor Coverings Res/Textile/S32					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive					
	2368/B001/R0005/Floor Coverings Res/Textile/S33					No Asbestos Detected
B001 - R1008 - Withdrawal Space - 1hb (21.78 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2368/B001/R0005/Floor Coverings Res/Textile/S32					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive					
	2368/B001/R0005/Floor Coverings Res/Textile/S33					No Asbestos Detected
B001 - R1009 - Home Base (48.67 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	49m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2368/B001/R0005/Floor Coverings Res/Textile/S32					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive					
	2368/B001/R0005/Floor Coverings Res/Textile/S33					No Asbestos Detected
B001 - R1010 - Movement (9.36 m2)						
No Asbestos						
B001 - R1011 - Plant (8.88 m2)						
No Asbestos						
B001 - R1012 - Plant (4.53 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
2368/B001/R1012/Ceiling Structures/Linings/S14				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B001 - R1013 - Personal Effects Storage (12.62 m2)

No Asbestos

B001 - R1014 - Movement (5.08 m2)

No Asbestos

B001 - R1015 - Stairs (10.04 m2)

No Asbestos

B001 - R1016 - Stairs (11.72 m2)

No Asbestos

B001 - R9001 - General Storeroom (4.4 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B002 - General Learning - 1935 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	Non Accessible Area - Height Restriction
Underfloor Voids	Non Accessible Area - Area inaccessible

Interior

B002 - R0002 - Staff Toilet (2.32 m2)

No Asbestos

B002 - R0003 - Handwashing Facilities (2.3 m2)

No Asbestos

B002 - R0005 - Kiln Room (1.8 m2)

Floor Coverings Res/Textile	Vinyl Sheet					
		2368/B002/R0006/Floor Coverings Res/Textile/S37				No Asbestos Detected

B002 - R0006 - Special Programs Room (74.94 m2)

Floor Coverings Res/Textile	Vinyl Sheet					
		2368/B002/R0006/Floor Coverings Res/Textile/S37				No Asbestos Detected

B002 - R0007 - Movement (2.72 m2)

No Asbestos

B002 - R0008 - Special Programs Room (12.8 m2)

No Asbestos

B002 - R0009 - Cleaning Distributed Store (2.21 m2)

Floor Coverings Res/Textile	Vinyl Sheet					
		2368/B002/R0006/Floor Coverings Res/Textile/S37				No Asbestos Detected

B002 - R0010 - General Storeroom (12.33 m2)

Floor Coverings Res/Textile	Vinyl Tiles	13m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
		2368/B001/R0005/Floor Coverings Res/Textile/S13				Chrysotile (white asbestos)

Floor Coverings Res/Textile	Adhesive					
		2368/B001/R0005/Floor Coverings Res/Textile/S31				No Asbestos Detected

B002 - R0011 - Staff Toilet (4.83 m2)

No Asbestos

B002 - R0012 - Movement (3.14 m2)

No Asbestos

B002 - R0013 - Personal Effects Storage (22.15 m2)

Electrical Backing Board	Resinous Board	1Unit	North	Good Condition (1)	Low (1)	Low Priority (2-3)
						Assumed Asbestos - Electrical Hazard

B002 - R0014 - Movement (3.46 m2)

No Asbestos

B002 - R0015 - Staff Room Annexe (17.41 m2)

No Asbestos

B002 - R0016 - Home Base (47.31 m2)

No Asbestos

B002 - R0017 - Movement (17.82 m2)

No Asbestos

B002 - R0018 - Home Base (47.31 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B002 - R0019 - Movement (16.04 m2)						
No Asbestos						
B002 - R0020 - Home Base (47.31 m2)						
No Asbestos						
B002 - R0021 - Movement (14.22 m2)						
No Asbestos						
B002 - R0022 - Withdrawal Space - 1hb (19.24 m2)						
No Asbestos						
B002 - R0023 - Stairs (8.28 m2)						
No Asbestos						
B002 - R0024 - Stairs (3.96 m2)						
No Asbestos						
B002 - R0025 - Garden Store (11.65 m2)						
No Asbestos						
B002 - R0026 - Stairs (19.9 m2)						
No Asbestos						
B002 - R0027 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	100m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	2368/B00B/R0014/Ceiling Structures/Linings/S22					Chrysotile (white asbestos)
gable ends - packer	Flat AC Sheeting	10m	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	2368/B00B/Gable Ends/S36					Chrysotile (white asbestos)
B002 - R1001 - Toilets - Boys/Girls (3.53 m2)						
No Asbestos						
B002 - R1002 - Home Base Store (5.62 m2)						
No Asbestos						
B002 - R1003 - Movement (7.97 m2)						
No Asbestos						
B002 - R1004 - Practical Activities - 1hb (17.12 m2)						
Floor Coverings Res/Textile	Vinyl Sheet					
	2368/B002/R0006/Floor Coverings Res/Textile/S37					No Asbestos Detected
B002 - R1005 - Home Base (49.24 m2)						
No Asbestos						
B002 - R1006 - Practical Activities - 1hb (14.77 m2)						
Floor Coverings Res/Textile	Vinyl Sheet					
	2368/B002/R0006/Floor Coverings Res/Textile/S37					No Asbestos Detected
B002 - R1007 - Home Base (49.42 m2)						
No Asbestos						
B002 - R1008 - Practical Activities - 1hb (13.35 m2)						
Floor Coverings Res/Textile	Vinyl Sheet					
	2368/B002/R0006/Floor Coverings Res/Textile/S37					No Asbestos Detected
B002 - R1009 - Home Base (49.42 m2)						
No Asbestos						
B002 - R1010 - General Storeroom (4.03 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	2368/B001/R1012/Ceiling Structures/Linings/S14					Chrysotile (white asbestos) , Amosite (brown asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B002 - R1011 - Movement (7.9 m2)						
No Asbestos						
B002 - R1012 - Movement (21.94 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	22m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
2368/B002/R1012/Ceiling Structures/Linings/S38					Chrysotile (white asbestos)	
B002 - R1013 - Stairs (17.58 m2)						
No Asbestos						
B002 - R1014 - Stairs (11.98 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B003 - General Learning - 1983 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	60m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	2368/B008/Eaves Linings/S20				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Gable Ends	Flat AC Sheeting	10m2	North and South elevations	Good Condition (1)	Low (1)	Low Priority (2-3)
	2368/B003/Gable Ends/S40				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Underfloor Voids	No Asbestos Found					
Ceiling Voids	Non Accessible Area - obstructed ceiling hatch					

Interior**B003 - R0001 - Home Base (57.88 m2)**

No Asbestos

B003 - R0002 - Home Base Store (4.9 m2)

No Asbestos

B003 - R0003 - Personal Effects Storage (7.52 m2)

No Asbestos

B003 - R0004 - Movement (6.21 m2)

Floor Coverings Res/Textile	Vinyl Sheet					
	2368/B003/R0004/Floor Coverings Res/Textile/S34				No Asbestos Detected	

B003 - R0005 - Movement (1.57 m2)

Ceiling Structures/Linings	Flat AC Sheeting	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2368/B005/R0007/Ceiling Structures/Linings/S12				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B003 - R0006 - Home Base Store (4.9 m2)

No Asbestos

B003 - R0007 - Home Base (57.88 m2)

Floor Coverings Res/Textile	Vinyl Sheet					
	2368/B003/R0004/Floor Coverings Res/Textile/S34				No Asbestos Detected	

B003 - R0008 - Special Programs Room (32.34 m2)

Floor Coverings Res/Textile	Vinyl Sheet					
	2368/B003/R0004/Floor Coverings Res/Textile/S34				No Asbestos Detected	

B003 - R0009 - Cleaning Distributed Store (1.7 m2)

Floor Coverings Res/Textile	Vinyl Tiles	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2368/B003/R0009/Floor Coverings Res/Textile/S16				Chrysotile (white asbestos)	

Floor Coverings Res/Textile	Adhesive					
	2368/B003/R0010/Floor Coverings Res/Textile/S35				No Asbestos Detected	

B003 - R0010 - Home Base Store (10.18 m2)

Floor Coverings Res/Textile	Vinyl Tiles	11m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2368/B003/R0009/Floor Coverings Res/Textile/S16				Chrysotile (white asbestos)	

Floor Coverings Res/Textile	Adhesive					
	2368/B003/R0010/Floor Coverings Res/Textile/S35				No Asbestos Detected	

B003 - R0011 - Movement (15.8 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Sheet					
	2368/B003/R0004/Floor Coverings Res/Textile/S34					No Asbestos Detected
Electrical Backing Board	Resinous Board	1Unit	West	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Electrical Hazard						
B003 - R0012 - Staff Toilet (3.19 m2)						
No Asbestos						
B003 - R0013 - Movement (1.68 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2368/B005/R0007/Ceiling Structures/Linings/S12					Chrysotile (white asbestos) , Amosite (brown asbestos)
B003 - R0014 - Staff Toilet (3.22 m2)						
No Asbestos						
B003 - R0015 - Home Base (57.88 m2)						
No Asbestos						
B003 - R0017 - Personal Effects Storage (7.53 m2)						
No Asbestos						
B003 - R0018 - Movement (6.21 m2)						
Floor Coverings Res/Textile	Vinyl Sheet					
	2368/B003/R0004/Floor Coverings Res/Textile/S34					No Asbestos Detected
B003 - R0019 - Movement (1.57 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2368/B005/R0007/Ceiling Structures/Linings/S12					Chrysotile (white asbestos) , Amosite (brown asbestos)
B003 - R0021 - Home Base (57.88 m2)						
Floor Coverings Res/Textile	Vinyl Sheet					
	2368/B003/R0004/Floor Coverings Res/Textile/S34					No Asbestos Detected
B003 - R0025 - Movement (1.5 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2368/B005/R0007/Ceiling Structures/Linings/S12					Chrysotile (white asbestos) , Amosite (brown asbestos)
B003 - R0026 - Practical Activities - 2hb (9.66 m2)						
Floor Coverings Res/Textile	Vinyl Sheet					
	2368/B003/R0004/Floor Coverings Res/Textile/S34					No Asbestos Detected
B003 - R0027 - Uniform Shop (27.03 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	2368/B003/R0010/Floor Coverings Res/Textile/S35					No Asbestos Detected
B003 - R0028 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	50m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	2368/B002/R1012/Ceiling Structures/Linings/S38					Chrysotile (white asbestos)
B003 - R9001 - Toilets - Boys (15.04 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	16m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	2368/B003/R9001/Ceiling Structures/Linings/S17					Chrysotile (white asbestos) , Amosite (brown asbestos)
B003 - R9002 - Sports Store (27.29 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Ceiling Structures/Linings	Flat AC Sheeting	28m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)
2368/B003/R9001/Ceiling Structures/Linings/S17				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B003 - R9003 - Garden Store (11.44 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2368/B003/R9001/Ceiling Structures/Linings/S17				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B003 - R9004 - Cleaning Supplies (7.56 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2368/B003/R9001/Ceiling Structures/Linings/S17				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B003 - R9005 - General Assistant/Bulk Store (7.14 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2368/B003/R9001/Ceiling Structures/Linings/S17				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B003 - R9006 - Garden Store (13.99 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2368/B003/R9001/Ceiling Structures/Linings/S17				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B003 - R9007 - P.E. Store (13.98 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2368/B003/R9001/Ceiling Structures/Linings/S17				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B003 - R9008 - Garden Store (14.19 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2368/B003/R9001/Ceiling Structures/Linings/S17				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B003 - R9009 - Cleaning Distributed Store (3.85 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2368/B003/R9001/Ceiling Structures/Linings/S17				Chrysotile (white asbestos) , Amosite (brown asbestos)		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B004 - General Learning - 1935 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	Non Accessible Area - No manhole.
Underfloor Voids	Non Accessible Area - Confined space.

Interior**B004 - R0001 - Handwashing Facilities (12.62 m2)**

No Asbestos

B004 - R0002 - General Storeroom (2.07 m2)

No Asbestos

B004 - R0003 - Movement (5.24 m2)

No Asbestos

B004 - R0004 - General Storeroom (14.08 m2)

No Asbestos

B004 - R0005 - Craft Store (2.84 m2)

No Asbestos

B004 - R0007 - Movement (5.4 m2)

No Asbestos

B004 - R0008 - Cleaning Distributed Store (2.13 m2)

No Asbestos

B004 - R0009 - Movement (4.37 m2)

No Asbestos

B004 - R0010 - Staff Toilet (3.56 m2)

No Asbestos

B004 - R0011 - Staff Toilet (3.55 m2)

No Asbestos

B004 - R0012 - Home Base (67.98 m2)

No Asbestos

B004 - R0013 - Home Base (47.89 m2)

Chalk Board	Compressed AC Sheet	8m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
2368/B004/R0013/Chalk Board/S7					Chrysotile (white asbestos)	

Floor Coverings Res/Textile	Pink-beige coloured vinyl tiles under carpe	47.89m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2368/B005/R0002/Floor Coverings Res/Textile/S9					Chrysotile (white asbestos)	

B004 - R0014 - Home Base (47.89 m2)

Chalk Board	Compressed AC Sheet	10m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
2368/B004/R0013/Chalk Board/S7					Chrysotile (white asbestos)	

Floor Coverings Res/Textile	Pink-beige coloured vinyl tiles under carpe	47.89m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2368/B005/R0002/Floor Coverings Res/Textile/S9					Chrysotile (white asbestos)	

B004 - R0015 - Home Base (48.35 m2)

Floor Coverings Res/Textile	Pink-beige coloured vinyl tiles under carpe	48.35m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2368/B005/R0002/Floor Coverings Res/Textile/S9					Chrysotile (white asbestos)	

B004 - R0016 - Movement (3.34 m2)

No Asbestos

B004 - R0017 - Movement (55.94 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Electrical Mounting Board	Resinous Membrane	1Unit	South end west wall	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Equipment live.						
B004 - R0018 - Stairs (7.21 m2)						
No Asbestos						
B004 - R0019 - Stairs (7.37 m2)						
No Asbestos						
B004 - R0020 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	100m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	2368/B001/R1012/Ceiling Structures/Linings/S14			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Gable ends - packer	Flat AC Sheeting	10m	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	2368/B00B/Gable Ends/S36			Chrysotile (white asbestos)		
B004 - R1001 - Staff Toilet (4.48 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2368/B004/R1001/Floor Coverings Res/Textile/S8			Chrysotile (white asbestos)		
Floor Coverings Res/Textile	Adhesive for S8					
	2368/B004/R1001/Floor Coverings Res/Textile/S27			No Asbestos Detected		
B004 - R1002 - Personal Effects Storage (7.93 m2)						
No Asbestos						
B004 - R1003 - Staff Room Annexe (20.51 m2)						
No Asbestos						
B004 - R1004 - General Storeroom (8.44 m2)						
No Asbestos						
B004 - R1005 - Movement (8.66 m2)						
No Asbestos						
B004 - R1006 - Practical Activities - 1hb (6.05 m2)						
Floor Coverings Res/Textile	Blue-red mottled vinyl					
	2368/B004/R1011/Floor Coverings Res/Textile/S26			No Asbestos Detected		
B004 - R1007 - Home Base (49.64 m2)						
Chalk Board	Compressed AC Sheet	2m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	2368/B004/R0013/Chalk Board/S7			Chrysotile (white asbestos)		
Floor Coverings Res/Textile	Green-beige vinyl tile under carpet	49.64m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2368/B004/R1009/Floor Coverings Res/Textile/S28			Chrysotile (white asbestos)		
Floor Coverings Res/Textile	Adhesive under green-beige under carpet					
	2368/B004/R1009/Floor Coverings Res/Textile/S29			No Asbestos Detected		
B004 - R1008 - Home Base (48.91 m2)						
Chalk Board	Compressed AC Sheet	8m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	2368/B004/R0013/Chalk Board/S7			Chrysotile (white asbestos)		
Floor Coverings Res/Textile	Green-beige vinyl tile under carpet	48.91m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2368/B004/R1009/Floor Coverings Res/Textile/S28			Chrysotile (white asbestos)		
Floor Coverings Res/Textile	Adhesive under green-beige under carpet					
	2368/B004/R1009/Floor Coverings Res/Textile/S29			No Asbestos Detected		
B004 - R1009 - Home Base (48.91 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Chalk Board	Compressed AC Sheet	6m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	2368/B004/R0013/Chalk Board/S7					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Green-beige vinyl tile under carpet	48.91m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2368/B004/R1009/Floor Coverings Res/Textile/S28					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive under green-beige under carpet					No Asbestos Detected
	2368/B004/R1009/Floor Coverings Res/Textile/S29					
B004 - R1010 - Home Base (48.91 m2)						
Chalk Board	Compressed AC Sheet	10m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	2368/B004/R0013/Chalk Board/S7					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive under green-beige under carpet					No Asbestos Detected
	2368/B004/R1009/Floor Coverings Res/Textile/S29					
Floor Coverings Res/Textile	Green-beige vinyl tile under carpet	48.91m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2368/B004/R1009/Floor Coverings Res/Textile/S28					Chrysotile (white asbestos)
B004 - R1011 - Movement (73.79 m2)						
Floor Coverings Res/Textile	Blue-red mottled vinyl					No Asbestos Detected
	2368/B004/R1011/Floor Coverings Res/Textile/S26					
B004 - R1012 - Stairs (10.61 m2)						
No Asbestos						
B004 - R1013 - Stairs (10.82 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B005 - General Learning - 1923 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	40m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	2368/B008/Eaves Linings/S20				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Gable Verge Lining	Flat AC Sheeting	20m	East & West	Good Condition (1)	Low (1)	Low Priority (2-3)
					Assumed Asbestos - Inaccessible.	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Non Accessible Area - Area inaccessible					

Interior**B005 - R0001 - Home Base (55.03 m2)**

Floor Coverings Res/Textile	Pink-beige coloured vinyl tiles under carpe	55m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2368/B005/R0002/Floor Coverings Res/Textile/S9				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive under pink-beige tile					
	2368/B005/R9003/Floor Coverings Res/Textile/S25				No Asbestos Detected	

B005 - R0002 - Home Base Store (7.91 m2)

Floor Coverings Res/Textile	Vinyl Tiles	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2368/B005/R0002/Floor Coverings Res/Textile/S9				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive under pink-beige tile					
	2368/B005/R9003/Floor Coverings Res/Textile/S25				No Asbestos Detected	

B005 - R0003 - Personal Effects Storage (7.91 m2)

Floor Coverings Res/Textile	Vinyl Sheet					
	2368/B005/R0005/Floor Coverings Res/Textile/S23				No Asbestos Detected	

B005 - R0004 - General Storeroom (9.57 m2)

No Asbestos

B005 - R0005 - Practical Activities - 1hb (27.01 m2)

Wall Linings Internal	Flat AC Sheeting	3m2	near switch board	Good Condition (1)	Low (1)	Low Priority (2-3)
	2368/B005/R0005/Wall Linings Internal/S10				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Vinyl Sheet					
	2368/B005/R0005/Floor Coverings Res/Textile/S23				No Asbestos Detected	

B005 - R0006 - Toilets - Boys/Girls (3.37 m2)

Wall Linings Internal	Flat AC Sheeting	8m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	2368/B005/R0006/Wall Linings Internal/S11				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B005 - R0007 - Movement (1.16 m2)

Ceiling Structures/Linings	Flat AC Sheeting	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2368/B005/R0007/Ceiling Structures/Linings/S12				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Infil over door	Flat AC Sheeting	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2368/B005/R0007/Ceiling Structures/Linings/S12				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B005 - R0008 - Home Base (84.36 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B005 - R0009 - Home Base (56.34 m2)						
No Asbestos						
B005 - R0010 - General Storeroom (6.05 m2)						
No Asbestos						
B005 - R0011 - Personal Effects Storage (3.2 m2)						
No Asbestos						
B005 - R0012 - Movement (2.67 m2)						
No Asbestos						
B005 - R0013 - Movement (1.25 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2368/B005/R0007/Ceiling Structures/Linings/S12			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Infil over door	Flat AC Sheeting	0.5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2368/B005/R0007/Ceiling Structures/Linings/S12			Chrysotile (white asbestos) , Amosite (brown asbestos)		
B005 - R9001 - Home Base (55.18 m2)						
Ceiling Structures/Linings	Vermiculite					
	2368/B005/R9001/Ceiling Structures/Linings/S24			Limited Samples Taken		
	Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works					
Floor Coverings Res/Textile	Pink-beige vinyl tile under carpet	55.18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2368/B005/R0002/Floor Coverings Res/Textile/S9			Chrysotile (white asbestos)		
B005 - R9002 - Home Base Store (4.66 m2)						
Ceiling Structures/Linings	Vermiculite					
	2368/B005/R9001/Ceiling Structures/Linings/S24			Limited Samples Taken		
	Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works					
Floor Coverings Res/Textile	Vinyl Tiles	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2368/B005/R0002/Floor Coverings Res/Textile/S9			Chrysotile (white asbestos)		
B005 - R9003 - Personal Effects Storage (6.97 m2)						
Ceiling Structures/Linings	Vermiculite					
	2368/B005/R9001/Ceiling Structures/Linings/S24			Limited Samples Taken		
	Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works					
Floor Coverings Res/Textile	Vinyl Tiles	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2368/B005/R0002/Floor Coverings Res/Textile/S9			Chrysotile (white asbestos)		
Floor Coverings Res/Textile	Adhesive under pink-beige tile					
	2368/B005/R9003/Floor Coverings Res/Textile/S25			No Asbestos Detected		
B005 - R9004 - Movement (1.26 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2368/B005/R0007/Ceiling Structures/Linings/S12			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Infil over door	Flat AC Sheeting	0.5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	2368/B005/R0007/Ceiling Structures/Linings/S12			Chrysotile (white asbestos) , Amosite (brown asbestos)		

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B006 - General Learning - 1891 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	Non Accessible Area - Height Restriction					
Underfloor Voids	Non Accessible Area - Area inaccessible					
Eaves Linings	Flat AC Sheeting	10m2	East & west	Good Condition (1)	Low (1)	Low Priority (2-3)

Assumed Asbestos - Height Restriction

Interior

B006 - R0001 - Movement (35.8 m2)

No Asbestos

B006 - R0002 - Home Base (46.71 m2)

No Asbestos

B006 - R0003 - Practical Activities - 1hb (45.54 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B008 - Pupil Facilities - 1935 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	4m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	2368/B008/Eaves Linings/S20				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B008 - R0003 - Handwashing Facilities (13.45 m2)

No Asbestos

B008 - R0004 - Cleaning Supplies (12.01 m2)

No Asbestos

B008 - R0005 - Handwashing Facilities (13.44 m2)

No Asbestos

B008 - R0008 - Toilets - Boys (25.33 m2)

No Asbestos

B008 - R0009 - Toilets - Girls (42.92 m2)

No Asbestos

B008 - R0010 - External Movement (24.99 m2)

No Asbestos

B008 - R0011 - External Movement (17.25 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/General Learning - 1935 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting 2368/B00A/Eaves Linings/S6	50m2	Upper and lower eaves	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Gable Ends	Flat AC Sheeting 2368/B00B/Gable Ends/S36	10m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Underfloor Voids	Non Accessible Area - Area inaccessible					
Ceiling Voids - Raked Ceiling	Non Accessible Area - Height Restriction - Restricted Access - Raked Ceilings					

Interior

B00A - R0001 - Movement (15.57 m2)

No Asbestos

B00A - R0002 - Deputy Principal (13.3 m2)

No Asbestos

B00A - R0003 - Principal (21.17 m2)

No Asbestos

B00A - R0004 - Deputy Principal (12.07 m2)

No Asbestos

B00A - R0005 - Staff Toilet (5.38 m2)

Partition Walls (Cubicles)	Compressed AC Sheet 2368/B00A/R0005/Partition Walls (Cubicles)/S1	2m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	--	-----	--------------------	--------------------	---------	--

B00A - R0006 - Distribution Board (1.04 m2)

Note: No inspection of live electrical installation.

Electrical Backing Board	Resinous Board	1Unit	to wall	Good Condition (1)	Low (1)	Low Priority (2-3) Assumed Asbestos - Electrical Hazard
--------------------------	----------------	-------	---------	--------------------	---------	---

B00A - R0007 - Staff Toilet (5.38 m2)

Partition Walls (Cubicles)	Compressed AC Sheet 2368/B00A/R0005/Partition Walls (Cubicles)/S1	2m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	--	-----	--------------------	--------------------	---------	--

Ceiling Structures/Linings	Flat AC Sheeting 2368/B00A/R0007/Ceiling Structures/Linings/S2	1m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	---	-----	--------------------	--------------------	---------	--

B00A - R0008 - Staff Room Annexe (11.59 m2)

Floor Coverings Res/Textile	Vinyl Sheet 2368/B004/R1011/Floor Coverings Res/Textile/S26					No Asbestos Detected
-----------------------------	--	--	--	--	--	-----------------------------

B00A - R0009 - Staff Room (70.69 m2)

No Asbestos

B00A - R0010 - Cleaning Distributed Store (1.36 m2)

No Asbestos

B00A - R0011 - Security Store (21.76 m2)

No Asbestos

B00A - R0012 - Duplicating Workroom (32 m2)

Floor Coverings Res/Textile	Vinyl Sheet 2368/B002/R0006/Floor Coverings Res/Textile/S37					No Asbestos Detected
-----------------------------	--	--	--	--	--	-----------------------------

B00A - R0013 - Security Store (32.73 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles	33m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2368/B001/R0005/Floor Coverings Res/Textile/S13					Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive					
2368/B001/R0005/Floor Coverings Res/Textile/S31					No Asbestos Detected	
B00A - R0014 - Sick Bay (13.94 m2)						
No Asbestos						
B00A - R0015 - Clerical Office (15.2 m2)						
No Asbestos						
B00A - R0016 - Entry Vestibule (52.45 m2)						
No Asbestos						
B00A - R0017 - Movement (25.9 m2)						
No Asbestos						
B00A - R0018 - Movement (23.39 m2)						
No Asbestos						
B00A - R0019 - General Storeroom (4.25 m2)						
Infill panels	Flat AC Sheeting	4m2	Above shutter door	Good Condition (1)	Low (1)	Low Priority (2-3)
2368/B00A/R0021/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	
B00A - R0020 - Movement (3.36 m2)						
No Asbestos						
B00A - R0021 - Movement (40.72 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	41m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2368/B00A/R0021/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	
B00A - R0022 - Movement (9.67 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2368/B00A/R0021/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	
Gable ends - packer	Flat AC Sheeting	5m	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
2368/B00B/Gable Ends/S36					Chrysotile (white asbestos)	
B00A - R0023 - Stairs (10.97 m2)						
No Asbestos						
B00A - R1001 - Communications Room (13.57 m2)						
No Asbestos						
B00A - R1002 - Library Office/Workroom (8.98 m2)						
No Asbestos						
B00A - R1003 - Library Office/Workroom (21.44 m2)						
No Asbestos						
B00A - R1004 - Seminar/Study (11.97 m2)						
No Asbestos						
B00A - R1005 - Seminar/Study (15.26 m2)						
No Asbestos						
B00A - R1006 - Movement (8.68 m2)						
No Asbestos						
B00A - R1007 - Cleaning Distributed Store (0.37 m2)						
No Asbestos						
B00A - R1008 - Toilets - Girls (4.07 m2)						
No Asbestos						
B00A - R1009 - Movement (0.94 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00A - R1010 - Distribution Board (0.68 m2) Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
2368/B00A/R1010/Ceiling Structures/Linings/S39					Chrysotile (white asbestos)	

B00A - R1011 - Toilets - Boys (4.67 m2)

Ceiling Structures/Linings	Flat AC Sheeting	0.5m2	Loft hatch	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
2368/B00A/R1011/Ceiling Structures/Linings/S4					Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00A - R1012 - Reading Area (261.36 m2)

No Asbestos

B00A - R1013 - Movement (45.55 m2)

No Asbestos

B00A - R1014 - Movement (49.8 m2)

Ceiling Structures/Linings	Flat AC Sheeting	50m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2368/B00A/R1014/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)	

B00A - R1015 - Stairs (14.79 m2)

Ceiling Structures/Linings	Flat AC Sheeting	15m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
2368/B00A/R1014/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Communal Facilities - 1935 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids - Raked Ceiling	Non Accessible Area - Restricted Access - Raked Ceilings					
Gable Ends	Flat AC Sheeting 2368/B00B/Gable Ends/S36	10m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Ceiling Voids - Raked Ceiling	Non Accessible Area - Height Restriction - Restricted Access - Raked Ceilings					
Underfloor Voids	Non Accessible Area - Area inaccessible					

Interior**B00B - R0001 - Movement (194.7 m2)**

Ceiling Structures/Linings	Flat AC Sheeting 2368/B00A/R0021/Ceiling Structures/Linings/S3	200m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	---	-------	--------------	--------------------	---------	--

B00B - R0002 - Canteen (41.51 m2)

No Asbestos

B00B - R0003 - Canteen Office/Store (4.73 m2)

No Asbestos

B00B - R0004 - Staff Toilet (3.5 m2)

No Asbestos

B00B - R0005 - Canteen Office/Store (4.84 m2)

No Asbestos

B00B - R0006 - Distribution Board (0.97 m2)

Note: No inspection of live electrical installation.

Electrical Backing Board	Resinous Board	1Unit	to wall	Good Condition (1)	Low (1)	Low Priority (2-3) Assumed Asbestos - Electrical Hazard
--------------------------	----------------	-------	---------	--------------------	---------	---

B00B - R0007 - Hall Chair Store (11.28 m2)

Cementitious Flooring panel	Compressed AC Sheet 2368/B00B/R0007/Cementitious Flooring panel/S21	1m2	South facing	Minimal Damage (2)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
-----------------------------	--	-----	--------------	--------------------	---------	--

B00B - R0008 - Plant (3.56 m2)

No Asbestos

B00B - R0009 - Raised Platform (71.25 m2)

No Asbestos

B00B - R0010 - Music Store (6.94 m2)

No Asbestos

B00B - R0011 - P.E. Store (11.25 m2)

No Asbestos

B00B - R0012 - Communal Space (256.73 m2)

No Asbestos

B00B - R0013 - Toilets - Girls (9.74 m2)

Partition Walls (Cubicles)	Compressed AC Sheet 2368/B00A/R0005/Partition Walls (Cubicles)/S1	2m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	--	-----	--------------------	--------------------	---------	--

B00B - R0014 - Cleaning Distributed Store (1.42 m2)

Ceiling Structures/Linings	Flat AC Sheeting 2368/B00B/R0014/Ceiling Structures/Linings/S22	1m2	All surfaces	Some Damage / Unsealed (3)	Low (1)	Medium Priority (4-5) Chrysotile (white asbestos)
----------------------------	--	-----	--------------	----------------------------	---------	---

B00B - R0015 - Toilets - Boys (9.74 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Partition Walls (Cubicles)	Compressed AC Sheet	2m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
2368/B00A/R0005/Partition Walls (Cubicles)/S1					Chrysotile (white asbestos)	
B00B - R0016 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	100m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
2368/B002/R1012/Ceiling Structures/Linings/S38					Chrysotile (white asbestos)	
Gable ends - packer	Flat AC Sheeting	10m	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
2368/B00B/Gable Ends/S36					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00C - General Learning - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00C - R0001 - Home Base (59.24 m2)	No Asbestos
B00C - R0002 - Home Base (61.03 m2)	No Asbestos
B00C - R0003 - Home Base (60.86 m2)	No Asbestos
B00C - R0004 - Practical Activities - 1hb (20.76 m2)	No Asbestos
B00C - R0005 - Withdrawal Space - 1hb (5.13 m2)	No Asbestos
B00C - R0006 - Home Base Store (9.06 m2)	No Asbestos
B00C - R0007 - Practical Activities - 1hb (19.93 m2)	No Asbestos
B00C - R0008 - Home Base Store (5.45 m2)	No Asbestos
B00C - R0009 - Withdrawal Space - 2hb (11.6 m2)	No Asbestos
B00C - R0010 - Practical Activities - 1hb (19.21 m2)	No Asbestos
B00C - R0011 - Home Base Store (5.51 m2)	No Asbestos
B00C - R0012 - General Storeroom (5.66 m2)	No Asbestos
B00C - R0013 - General Storeroom (4.6 m2)	No Asbestos
B00C - R0014 - External Movement (73.6 m2)	No Asbestos
B00C - R0015 - External Stairs (12.51 m2)	No Asbestos
B00C - R0016 - External Stairs (13.81 m2)	No Asbestos
B00C - R1001 - Home Base (59.14 m2)	No Asbestos
B00C - R1002 - Home Base (61.06 m2)	No Asbestos
B00C - R1003 - Home Base (60.68 m2)	No Asbestos
B00C - R1004 - Practical Activities - 1hb (20.31 m2)	No Asbestos
B00C - R1005 - Withdrawal Space - 1hb (9.04 m2)	No Asbestos
B00C - R1006 - Home Base Store (5.08 m2)	No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00C - R1007 - Practical Activities - 1hb (18.78 m2)

No Asbestos

B00C - R1008 - Home Base Store (5.52 m2)

No Asbestos

B00C - R1009 - Withdrawal Space - 2hb (11.56 m2)

No Asbestos

B00C - R1010 - Practical Activities - 1hb (18.91 m2)

No Asbestos

B00C - R1011 - Home Base Store (5.47 m2)

No Asbestos

B00C - R1012 - External Movement (69.99 m2)

No Asbestos

B00C - R1013 - External Stairs (19.13 m2)

No Asbestos

B00C - R1014 - External Stairs (20.34 m2)

No Asbestos

B00C - R9001 - General Storeroom (121.13 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017