


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Larnook Public School (2375)
Region : North Coast
State Electorate : Lismore
Local Government Area : Lismore

Initial Survey : Noel Arnold & Associates : 10 - Jun - 2008
Reviewed By : Greencap-NAA : 14 - Apr - 2016



2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00A - General Learning - 1975 - Timber (Timber)

Exterior

| | |
|-----------------------------------|--|
| Underfloor Voids - Slab on Ground | Non Accessible Area - Area inaccessible |
| Ceiling Voids | Non Accessible Area - Area inaccessible no access point |

Interior

B00A - R0001 - Practical Activities - 1hb

No Asbestos

B00A - R0002 - Home Base Store

No Asbestos

B00A - R0003 - Home Base

No Asbestos

B00A - R0004 - Movement

| | | |
|----------------------------|---|-----------------------------|
| Ceiling Structures/Linings | Flat AC Sheeting 2375/B00A/R0004/Ceiling Structures/Linings/S4 | No Asbestos Detected |
|----------------------------|---|-----------------------------|

B00A - R0005 - Withdrawal Space - 1hb

No Asbestos

B00A - R0006 - Movement

| | | |
|----------------------------|---|-----------------------------|
| Ceiling Structures/Linings | Flat AC Sheeting 2375/B00A/R0004/Ceiling Structures/Linings/S4 | No Asbestos Detected |
|----------------------------|---|-----------------------------|

B00A - R0007 - Home Base

No Asbestos

B00A - R0008 - Home Base Store

No Asbestos

B00A - R0009 - Practical Activities - 1hb

No Asbestos

B00A - R0010 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0011 - Movement

| | | |
|----------------------------|---|-----------------------------|
| Ceiling Structures/Linings | Flat AC Sheeting 2375/B00A/R0004/Ceiling Structures/Linings/S4 | No Asbestos Detected |
|----------------------------|---|-----------------------------|

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00B - Building Services - 1922 - Timber (Timber)

Exterior

| | | | | | | |
|------------------|-------------------------------|-----|--------------------|---|----------|---------------------|
| Ceiling Voids | No Asbestos Found | | | | | |
| Underfloor Voids | AC Fragments/Debris | 2m2 | Variable positions | Some Damage - Unsealed (3) | High (3) | High Priority (6-8) |
| | 2375/B00B/Underfloor Voids/S6 | | | Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos) | | |

Interior

B00B - R0001 - Shelter

| | | | | | | |
|-----------------------|--|-----|------|------------------------------------|---------|--------------------|
| Wall Linings Internal | Flat AC Sheeting | 8m2 | West | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 2375/B00B/R0001/Wall Linings Internal/S5 | | | Chrysotile (white asbestos) | | |

B00B - R0002 - P.E. Store

| | | | | | | |
|-----------------------|--|------|------------|------------------------------------|---------|--------------------|
| Wall Linings Internal | Flat AC Sheeting | 46m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 2375/B00B/R0001/Wall Linings Internal/S5 | | | Chrysotile (white asbestos) | | |

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|---------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| | Sample No | | | | | Test Result |

B00C - Administration - 1922 - Timber (Timber)

Exterior

| | |
|------------------|--|
| Ceiling Voids | Non Accessible Area - Area inaccessible height 4m |
| Underfloor Voids | No Asbestos Found |

Interior

B00C - R0001 - Clerical Office

No Asbestos

B00C - R0002 - Duplicating Workroom

No Asbestos

B00C - R0003 - Principal

No Asbestos

B00C - R0004 - General Storeroom

No Asbestos

B00C - R0005 - Staff Room

No Asbestos

B00C - R0006 - Movement

No Asbestos

B00C - R0007 - Movement

No Asbestos

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00D - Pupil Facilities - 1975 - Brick/Block (Brick/Block)**Exterior**

| | | | | | | |
|-----------------------------------|---|------|-------------|--------------------|---------|---|
| Underfloor Voids - Slab on Ground | Non Accessible Area - Area inaccessible | | | | | |
| Eaves Linings | Low density board 2375/B00D/Eaves Linings/S2 | 16m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos) |
| Downpipes | Fibre Cement Pipe 2375/B00D/Downpipes/S1 | 4m | North, West | Good Condition (1) | Low (1) | Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos) |
| Ceiling Voids | No Asbestos Found | | | | | |

Interior**B00D - R0001 - Toilets - Boys**

| | | | | | | |
|----------------------------|--|-----|------------|--------------------|---------|---|
| Ceiling Structures/Linings | Low density board 2375/B00D/R0002/Ceiling Structures/Linings/S3 | 8m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos) |
|----------------------------|--|-----|------------|--------------------|---------|---|

B00D - R0002 - Staff Toilet

| | | | | | | |
|----------------------------|--|-----|------------|--------------------|---------|---|
| Ceiling Structures/Linings | Low density board 2375/B00D/R0002/Ceiling Structures/Linings/S3 | 6m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos) |
|----------------------------|--|-----|------------|--------------------|---------|---|

B00D - R0003 - Toilets - Girls

| | | | | | | |
|----------------------------|--|-----|------------|--------------------|---------|---|
| Ceiling Structures/Linings | Low density board 2375/B00D/R0002/Ceiling Structures/Linings/S3 | 6m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos) |
|----------------------------|--|-----|------------|--------------------|---------|---|

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00E - Building Services - 1984 - Metal Shed (Metal Shed)

Exterior

| | |
|---------------------------|-------------------|
| Ceiling Voids - Flat Roof | No Asbestos Found |
| Underfloor Voids | No Asbestos Found |

Interior

B00E - R0001 - General Storeroom

No Asbestos

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00F - Building Services - 2004 - Metal Shed (Metal Shed)

Exterior

Underfloor Voids - Slab on Ground Non Accessible Area
 - Area inaccessible

Ceiling Voids No Asbestos Found

Interior

B00F - R0001 - General Assistant/Bulk Store

No Asbestos

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00G - Library - 2010 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

| | | | | | | |
|------------------|--|--|--|--|--|-----------------------------|
| Ceiling Voids | No Asbestos Found | | | | | |
| Underfloor Voids | No Asbestos Found | | | | | |
| Wall Cladding | Flat AC Sheeting 2375/B00G/Wall Cladding/S8 | | | | | No Asbestos Detected |

Interior

B00G - R0001 - Reading Area

No Asbestos

B00G - R0002 - K.L.A. Store

No Asbestos

B00G - R0003 - Practical Activities

No Asbestos

B00G - R0004 - External Movement

| | | | | | | |
|----------|--|--|--|--|--|-----------------------------|
| Flooring | Compressed AC Sheet 2375/B00G/R0004/Flooring/S7 | | | | | No Asbestos Detected |
|----------|--|--|--|--|--|-----------------------------|

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 842 - D13453 - Country Toilet - Relta - Boys/Girls : Placement Date - 30/06/1995

Exterior

| | | | | | | |
|-------------|---------------------|------------------|--|--|--|---------|
| Step Treads | Compressed AC Sheet | Assumed Asbestos | | | | 1.08 m2 |
| Landing | Compressed AC Sheet | Assumed Asbestos | | | | 1.2 m2 |
| Eave Lining | Flat AC Sheet | Assumed Asbestos | | | | 2.88 m2 |

Interior

R1 - Toilets-Girls

| | | | | | | |
|-------------------|---------------------|------------------|--|--|--|-------|
| Toilet partitions | Compressed AC Sheet | Assumed Asbestos | | | | 4 m2 |
| End wall panel | Flat AC Sheet | Assumed Asbestos | | | | 18 m2 |
| Ceiling | Flat AC Sheet | Assumed Asbestos | | | | 5 m2 |

R2 - Staff Toilet

| | | | | | | |
|----------------|---------------|------------------|--|--|--|-------|
| End wall panel | Flat AC Sheet | Assumed Asbestos | | | | 18 m2 |
| Ceiling | Flat AC Sheet | Assumed Asbestos | | | | 4 m2 |

R3 - Toilets-Boys

| | | | | | | |
|-------------------|---------------------|------------------|--|--|--|------|
| Toilet partitions | Compressed AC Sheet | Assumed Asbestos | | | | 6 m2 |
| Ceiling | Flat AC Sheet | Assumed Asbestos | | | | 5 m2 |

R4 - Staff Toilet

| | | | | | | |
|---------|---------------|------------------|--|--|--|------|
| Ceiling | Flat AC Sheet | Assumed Asbestos | | | | 4 m2 |
|---------|---------------|------------------|--|--|--|------|

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017