

# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Lawrence Public School (2379)  
**Region :** North Coast  
**State Electorate :** Clarence  
**Local Government Area :** Clarence Valley

**Initial Survey :** Noel Arnold & Associates : 26 - May - 2008  
**Reviewed By :** Parsons Brinckerhoff : 31 - Oct - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - General Learning/Administration - 1968 - Brick/Block (Brick/Block)**

**Exterior**

In-fill-panel	Compressed AC Sheet 2379/B00A/In-fill-panel/S13					<b>No Asbestos Detected</b>
Eaves Linings	Flat AC Sheeting 2379/B00A/Eaves Linings/S8					<b>No Asbestos Detected</b>
Eaves Linings	Flat AC Sheeting 2379/B00A/R0018/Ceiling Structures/Linings/S2	30m2	North, West	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
Gable Verge Lining	Flat AC Sheeting 2379/B00A/Gable Verge Lining/S9					<b>No Asbestos Detected</b>
Infill Panels above windows	Flat AC Sheeting 2379/B00A/Infill Panels above windows/S10					<b>No Asbestos Detected</b>
Ceiling Void	No Asbestos Found					
Underfloor Void	No Asbestos Found					
Flue Pipe	Fibre Cement Pipe 2379/B00A/Flue Pipe/S15	2m	North	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5) <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**Interior**

**B00A - R0002 - Principal**

No Asbestos

**B00A - R0004 - Home Base**

No Asbestos

**B00A - R0005 - Home Base Store**

No Asbestos

**B00A - R0006 - General Storeroom**

No Asbestos

**B00A - R0007 - Home Base Store**

No Asbestos

**B00A - R0008 - Home Base**

No Asbestos

**B00A - R0009 - Reading Area**

No Asbestos

**B00A - R0010 - Staff Room**

Floor Coverings Res/Textile	Vinyl Tiles 2379/B00A/R0010/Floor Coverings Res/Textile/S6					<b>No Asbestos Detected</b>
-----------------------------	---	--	--	--	--	-----------------------------

**B00A - R0011 - General Storeroom**

Ceiling Structures/Linings	Flat AC Sheeting 2379/B00A/R0018/Ceiling Structures/Linings/S2	17m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
----------------------------	---	------	------------	--------------------	---------	---

**B00A - R0013 - Cleaning Distributed Store**

No Asbestos

**B00A - R0014 - Staff Toilet**

No Asbestos

**B00A - R0015 - Toilets - Boys**

Partition Walls (Cubicles)	Compressed AC Sheet 2379/B00A/R0015/Partition Walls (Cubicles)/S1	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
----------------------------	--	-----	------------	--------------------	---------	---

**B00A - R0016 - Staff Toilet**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

No Asbestos

**B00A - R0017 - Toilets - Girls**

Partition Walls (Cubicles)	Compressed AC Sheet	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2379/B00A/R0015/Partition Walls (Cubicles)/S1				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00A - R0019 - Clerical Office**

No Asbestos

**B00A - R0020 - Sick Bay**

No Asbestos

**B00A - R0021 - Movement**

No Asbestos

**B00A - R0023 - Interview**

No Asbestos

**B00A - R0024 - External Movement**

Ceiling Structures/Linings	Flat AC Sheeting					
2379/B00A/R0024/Ceiling Structures/Linings/S12				<b>No Asbestos Detected</b>		

**B00A - R0025 - Staff Toilet**

Wall Linings Internal	Flat AC Sheeting					
2379/B00A/R0025/Wall Linings Internal/S5				<b>No Asbestos Detected</b>		

**B00A - R0026 - External Movement**

Ceiling Structures/Linings	Flat AC Sheeting	66m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
2379/B00A/R0018/Ceiling Structures/Linings/S2				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

In-fill-panel	Flat AC Sheeting	17m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
2379/B00A/R0026/In-fill-panel/S14				<b>Chrysotile (white asbestos)</b>		

Infill Panels above windows	Flat AC Sheeting					
2379/B00A/Infill Panels above windows/S10				<b>No Asbestos Detected</b>		

**B00A - R0027 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
2379/B00A/R0018/Ceiling Structures/Linings/S2				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00A - R0028 - Movement**

No Asbestos

**B00A - R0029 - External Movement**

Ceiling Structures/Linings	Flat AC Sheeting					
2379/B00A/R0029/Ceiling Structures/Linings/S11				<b>No Asbestos Detected</b>		



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - Pupil Facilities - 1975 - Steel (Steel)**

**Exterior**

Ceiling Voids - Flat Roof	No Asbestos Found
Underfloor Void	No Asbestos Found

**Interior**

**B00B - R0001 - Canteen**

Floor Coverings Res/Textile	Vinyl Tiles	2379/B00B/R0001/Floor Coverings Res/Textile/S3	<b>No Asbestos Detected</b>
-----------------------------	-------------	--	-----------------------------

Floor Coverings Res/Textile	Vinyl Tiles	2379/B00B/R0002/Floor Coverings Res/Textile/S4	<b>No Asbestos Detected</b>
-----------------------------	-------------	--	-----------------------------

**B00B - R0002 - External Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - Shed - 1997 - Metal Shed (Metal Shed)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

**Interior**

**B00C - R0001 - General Assistant/Bulk Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Shed - 1997 - Timber Shed (Timber Shed)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found					
Wall Cladding	Flat AC Sheeting 2379/B00D/Wall Cladding/S7					<b>No Asbestos Detected</b>
Ceiling Voids	No Asbestos Found					

**Interior**

**B00D - R0001 - Sports Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - Communal Facilities - 2008 - Metal Shed (Metal Shed)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

**Interior**

**B00E - R0001 - Sports Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - General Learning - 2010 - Fibre Cement Clad (Fibre Cement Clad)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

**Interior**

**B00F - R0001 - External Movement**

No Asbestos

**B00F - R0002 - Practical Activities/Movement - 1hb**

No Asbestos

**B00F - R0003 - Home Base Store**

No Asbestos

**B00F - R0004 - Home Base**

No Asbestos

**B00F - R0005 - Withdrawal Space - 2hb**

No Asbestos

**B00F - R0006 - Home Base**

No Asbestos

**B00F - R0007 - Home Base Store**

No Asbestos

**B00F - R0008 - Practical Activities/Movement - 1hb**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - Storage - 2014 - Metal Shed (Metal Shed)**

**Exterior**

Underfloor Voids - Slab on Ground      No Asbestos Found

Ceiling Voids      No Asbestos Found

**Interior**

**B00G - R0001 - General Storeroom**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017