


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Lightning Ridge Central School (2395)
Region : Western NSW
State Electorate : Barwon
Local Government Area : Walgett

Initial Survey : Noel Arnold & Associates : 13 - May - 2008
Reviewed By : Parsons Brinckerhoff : 01 - Nov - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning - 1967 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	15m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2395/B00A/R0001/Ceiling Structures/Linings/S2				Chrysotile (white asbestos)	
Eaves Linings	Flat AC Sheeting	20m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2395/B00A/Eaves Linings/S10				Chrysotile (white asbestos)	
Infill panels under windows	Flat AC Sheeting	12m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2395/B00A/Infill panels under windows/S21				Chrysotile (white asbestos)	
Infill panels to windows	Putty					No Asbestos Detected
	2395/B00A/Infill panels to windows/S25					

Interior**B00A - R0001 - External Movement**

In-fill-panel	Flat AC Sheeting	8m	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2395/B00A/R0001/In-fill-panel/S1				Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	43m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2395/B00A/R0001/Ceiling Structures/Linings/S2				Chrysotile (white asbestos)	

B00A - R0002 - Movement

No Asbestos

B00A - R0003 - Home Base Store

No Asbestos

B00A - R0004 - Practical Activities - 1hb

No Asbestos

B00A - R0005 - Home Base

No Asbestos

B00A - R0006 - Home Base

No Asbestos

B00A - R0007 - Practical Activities - 1hb

Floor Coverings Res/Textile	Vinyl Tiles					No Asbestos Detected
	2395/B00A/R0007/Floor Coverings Res/Textile/S26					

B00A - R0008 - Home Base Store

Non Accessible

Ceiling Void	No Asbestos Found					
--------------	-------------------	--	--	--	--	--

B00A - R0009 - Movement

No Asbestos

B00A - R0010 - General Storeroom

No Asbestos

B00A - R0011 - Interview

No Asbestos

B00A - R0012 - Plant

Boxing to Pipework	Flat AC Sheeting					No Asbestos Detected
	2395/B00A/R0012/Boxing to Pipework/S20					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Support Unit - 1911 - Timber (Timber)

Exterior

Underfloor Voids	AC Fragments/Debris	1m2	Variable positions	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5)
	2395/B00B/Underfloor Voids/S12					Chrysotile (white asbestos)
Ceiling Void	Non Accessible Area - No Access - Ceiling > 5 meters & access not possible because situated near windows					

Interior

B00B - R0001 - External Movement

No Asbestos

B00B - R0002 - Home Base - M

No Asbestos

B00B - R0003 - Staff Room Annexe

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning/Pupil Facilities - 1986 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Void No Asbestos Found

Interior**B00C - R0001 - External Movement**

Ceiling Structures/Linings Flat AC Sheeting 387m2 Throughout Minimal Damage (2) Low (1) Low Priority (2-3)
2395/B00C/R0001/Ceiling Structures/Linings/S6 **Chrysotile (white asbestos)**

In-fill-panel Flat AC Sheeting 10m Throughout Good Condition (1) Low (1) Low Priority (2-3)
2395/B00C/R0001/In-fill-panel/S7 **Chrysotile (white asbestos)**

B00C - R0002 - Toilets - Boys

Ceiling Structures/Linings Flat AC Sheeting 11m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)
2395/B00C/R0001/Ceiling Structures/Linings/S6 **Chrysotile (white asbestos)**

Partition Walls (Cubicles) Compressed AC Sheet 4m2 East Good Condition (1) Low (1) Low Priority (2-3)
2395/B00C/R0002/Partition Walls (Cubicles)/S23 **Chrysotile (white asbestos)**

Ceiling Structures/Linings Flat AC Sheeting 11m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)
2395/B00C/R0002/Ceiling Structures/Linings/S15 **Chrysotile (white asbestos)**

B00C - R0003 - Practical Activities - 1hb

No Asbestos

B00C - R0004 - Toilets - Boys/Girls

No Asbestos

B00C - R0005 - Home Base

No Asbestos

B00C - R0006 - Home Base

No Asbestos

B00C - R0007 - Practical Activities - 1hb

No Asbestos

B00C - R0008 - Staff Kitchen

Floor Coverings Res/Textile Vinyl Tiles 27m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)
2395/B00C/R0009/Floor Coverings Res/Textile/S9 **Chrysotile (white asbestos)**

B00C - R0009 - General Storeroom

Floor Coverings Res/Textile Vinyl Tiles 22m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)
2395/B00C/R0009/Floor Coverings Res/Textile/S9 **Chrysotile (white asbestos)**

B00C - R0010 - Staff Toilet

Infill panels under windows Flat AC Sheeting
2395/B00C/R0010/Infill panels under windows/S19 **No Asbestos Detected**

B00C - R0011 - Staff Toilet

Ceiling Structures/Linings Flat AC Sheeting 5m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)
2395/B00C/R0011/Ceiling Structures/Linings/S14 **Chrysotile (white asbestos)**

Infill Panel on wall Flat AC Sheeting 1m2 North Some Damage - Unsealed (3) Low (1) Medium Priority (4-5)
2395/B00C/R0011/Infill Panel on wall/S22 **Chrysotile (white asbestos)**

B00C - R0012 - Toilets - Girls

Ceiling Structures/Linings Flat AC Sheeting 6m2 West Good Condition (1) Low (1) Low Priority (2-3)
2395/B00C/R0001/Ceiling Structures/Linings/S6 **Chrysotile (white asbestos)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Partition Walls (Cubicles)	Compressed AC Sheet	6m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
2395/B00C/R0002/Partition Walls (Cubicles)/S23					Chrysotile (white asbestos)	
B00C - R0013 - General Storeroom						
No Asbestos						
B00C - R0014 - Cleaning Distributed Store						
Ceiling Structures/Linings	Flat AC Sheeting					
2395/B00C/R0014/Ceiling Structures/Linings/S16					No Asbestos Detected	
B00C - R0015 - Sports Store						
No Asbestos						
B00C - R0016 - Distribution Board						
					Note: No inspection of live electrical installation.	
Ceiling Structures/Linings	Flat AC Sheeting					
2395/B00C/R0016/Ceiling Structures/Linings/S13					No Asbestos Detected	
B00C - R0017 - Movement						
No Asbestos						
B00C - R0018 - Seminar/Study						
No Asbestos						
B00C - R0019 - General Storeroom						
No Asbestos						
B00C - R0020 - General Storeroom						
No Asbestos						
B00C - R0021 - Staff Toilet						
Incinerette	Encapsulated Insulation material within unit	1Unit(s)	East	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Encapsulated material within unit						
B00C - R0022 - Communal Space						
No Asbestos						
B00C - R0023 - Raised Platform						
No Asbestos						
B00C - R0024 - General Storeroom						
No Asbestos						
B00C - R0025 - General Storeroom						
No Asbestos						
B00C - R0026 - Plant						
Wall Linings Internal	Flat AC Sheeting					
2395/B00C/R0026/Wall Linings Internal/S18					No Asbestos Detected	
B00C - R0027 - Cleaning Supplies						
No Asbestos						
B00C - R0028 - Cleaning Distributed Store						
Ceiling Structures/Linings	Flat AC Sheeting					
2395/B00C/R0014/Ceiling Structures/Linings/S16					No Asbestos Detected	



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning - 1986 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Void	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00D - R0001 - Home Base Store

No Asbestos

B00D - R0002 - Home Base

No Asbestos

B00D - R0003 - Practical Activities - 1hb

No Asbestos

B00D - R0004 - Outdoor Learning Area

No Asbestos

B00D - R0005 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting					
	2395/B00D/R0005/Ceiling Structures/Linings/S5					No Asbestos Detected

B00D - R0006 - Practical Activities - 1hb

No Asbestos

B00D - R0007 - Home Base

No Asbestos

B00D - R0008 - Home Base Store

No Asbestos

B00D - R0009 - Outdoor Learning Area

No Asbestos

B00D - R0010 - Withdrawal Space - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning - 1986 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00E - R0001 - Home Base Store

No Asbestos

B00E - R0002 - Home Base

No Asbestos

B00E - R0003 - Practical Activities - 1hb

No Asbestos

B00E - R0004 - Outdoor Learning Area

No Asbestos

B00E - R0005 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting 2395/B00E/R0005/Ceiling Structures/Linings/S4	No Asbestos Detected
----------------------------	---	-----------------------------

B00E - R0006 - Practical Activities - 1hb

No Asbestos

B00E - R0007 - Home Base

No Asbestos

B00E - R0008 - Home Base Store

No Asbestos

B00E - R0009 - Outdoor Learning Area

No Asbestos

B00E - R0010 - Withdrawal Space - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning - 1986 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids	No Asbestos Found
Ceiling Void	No Asbestos Found

Interior

B00F - R0001 - Home Base Store

No Asbestos

B00F - R0002 - Home Base

No Asbestos

B00F - R0003 - Practical Activities - 1hb

No Asbestos

B00F - R0004 - Outdoor Learning Area

No Asbestos

B00F - R0005 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting					
	2395/B00F/R0005/Ceiling Structures/Linings/S3					No Asbestos Detected

B00F - R0006 - Practical Activities - 1hb

No Asbestos

B00F - R0007 - Home Base

No Asbestos

B00F - R0008 - Home Base Store

No Asbestos

B00F - R0009 - Outdoor Learning Area

No Asbestos

B00F - R0010 - Withdrawal Space - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Pupil Facilities - 1970 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Flat Roof	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2395/B00A/R0001/Ceiling Structures/Linings/S2				Chrysotile (white asbestos)	
Eaves Linings	Flat AC Sheeting	12m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	2395/B00G/Eaves Linings/S11				Chrysotile (white asbestos) , Amosite (brown asbestos)	

Interior

B00G - R0001 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting	43m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2395/B00G/R0001/Ceiling Structures/Linings/S17				Chrysotile (white asbestos)	
Partition Walls (Cubicles)	Compressed AC Sheet					No Asbestos Detected
	2395/B00G/R0001/Partition Walls (Cubicles)/S24					

B00G - R0002 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting	44m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2395/B00G/R0001/Ceiling Structures/Linings/S17				Chrysotile (white asbestos)	
Partition Walls (Cubicles)	Compressed AC Sheet					No Asbestos Detected
	2395/B00G/R0001/Partition Walls (Cubicles)/S24					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - Agricultural Science - 2000 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00I - R0001 - Class Tools Storage

No Asbestos

B00I - R0002 - Agriculture Covered Area

No Asbestos

B00I - R0003 - Plant Space

No Asbestos

B00I - R0004 - No Access

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Administration - 2000 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00J - R0001 - Interview

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00J - R0002 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00J - R0003 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00J - R0004 - Clerical Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00J - R0005 - Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00J - R0006 - Staff Toilet

No Asbestos

B00J - R0007 - Staff Toilet

No Asbestos

B00J - R0008 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00J - R0009 - Interview

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00J - R0010 - Interview

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00J - R0011 - Canteen Office/Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00J - R0012 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00J - R0013 - Communications Cupboard

No Asbestos

B00J - R0014 - Staff Kitchen

No Asbestos

B00J - R0015 - Community Clinic

No Asbestos

B00J - R0016 - Toilets - Girls

No Asbestos

B00J - R0017 - Toilets - Boys

No Asbestos

B00J - R0018 - Community Clinic

No Asbestos

B00J - R0019 - Duplicating Workroom

No Asbestos

B00J - R0020 - Security Store

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00J - R0021 - Cleaning Distributed Store

No Asbestos

B00J - R0022 - External Movement

No Asbestos

B00J - R0023 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Technological & Applied Studies - 2000 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B00K - R0001 - External Movement**

No Asbestos

B00K - R0002 - Outdoor Workshop

No Asbestos

B00K - R0003 - Welding/Hot Metals Area

No Asbestos

B00K - R0004 - Kiln Room

No Asbestos

B00K - R0005 - Communications Cupboard

No Asbestos

B00K - R0006 - Materials Store

No Asbestos

B00K - R0007 - Plant

No Asbestos

B00K - R0008 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00K - R0009 - L.P.G. Store

No Asbestos

B00K - R0010 - External Movement

No Asbestos

B00K - R0011 - Materials Workshop - Type 2

No Asbestos

B00K - R0012 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00K - R0013 - General Learning Space

No Asbestos

B00K - R0014 - Plant

No Asbestos

B00K - R0015 - Cleaning Distributed Store

No Asbestos

B00K - R0016 - Laundry

No Asbestos

B00K - R0017 - Resource/Project Store

No Asbestos

B00K - R0018 - Materials Store

No Asbestos

B00K - R0019 - Pantry

No Asbestos

B00K - R0020 - Preparation

No Asbestos

B00K - R0021 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00K - R0022 - Materials Workshop - Type 2

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00K - R0023 - General Learning Space

No Asbestos

B00K - R0024 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00K - R0025 - Plant

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Library - 2004 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B00L - R0001 - Entry**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00L - R0002 - Computer Resource

No Asbestos

B00L - R0003 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00L - R0004 - System Administrators Office

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00L - R0005 - Careers Advisers Office

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00L - R0006 - Movement

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00L - R0007 - Staff Toilet

No Asbestos

B00L - R0008 - Disabled Toilet

No Asbestos

B00L - R0009 - Seminar

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00L - R0010 - Seminar

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00L - R0011 - Audio Visual Workroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00L - R0012 - General Storeroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00L - R0013 - General Storeroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00L - R0014 - Computer Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00L - R0015 - Computer Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00L - R0016 - Workroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00L - R0017 - External Movement

No Asbestos

B00L - R0018 - Main Area

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - Staff Facilities - 2004 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00M - R0001 - Staff Study

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00M - R0002 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00M - R0003 - Security Store

No Asbestos

B00M - R0004 - Cleaning Distributed Store

No Asbestos

B00M - R0005 - Disabled Toilet

No Asbestos

B00M - R0006 - Staff Toilet

No Asbestos

B00M - R0007 - Staff Toilet

No Asbestos

B00M - R0008 - Staff Toilet

No Asbestos

B00M - R0009 - Interview

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00M - R0010 - Interview

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00M - R0011 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00M - R0012 - Duplicating Workroom

No Asbestos

B00M - R0013 - Staff Study

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00M - R0014 - Commonroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00M - R0015 - External Movement

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00N - Multi Purpose Facilities - 2004 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00N - R0001 - Community Clinic

No Asbestos

B00N - R0002 - Sports Store

No Asbestos

B00N - R0003 - Shower/Change

No Asbestos

B00N - R0004 - Movement

No Asbestos

B00N - R0005 - Movement

No Asbestos

B00N - R0006 - Shower/Change

No Asbestos

B00N - R0007 - Shower/Change

No Asbestos

B00N - R0008 - Staff Change

No Asbestos

B00N - R0009 - Hall Chair Store

No Asbestos

B00N - R0010 - Sports Store

No Asbestos

B00N - R0011 - Hall Chair Store

No Asbestos

B00N - R0012 - Multi-Purpose Space

No Asbestos

B00N - R0013 - Plant

No Asbestos

B00N - R0014 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00N - R0015 - General Storeroom

No Asbestos

B00N - R0016 - External Movement

No Asbestos

B00N - R0017 - External Movement

No Asbestos

B00N - R0018 - External Movement

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B000 - Pupil Facilities - 2004 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B000 - R0001 - Canteen

No Asbestos

B000 - R0002 - Canteen Office/Store

No Asbestos

B000 - R0003 - Canteen

No Asbestos

B000 - R0004 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00P - Pupil Facilities - 2004 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00P - R0001 - Toilets - Girls

No Asbestos

B00P - R0002 - Toilets - Boys

No Asbestos

B00P - R0003 - Cleaning Distributed Store

No Asbestos

B00P - R0004 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00P - R0005 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00Q - Science/Art - 2004 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00Q - R0001 - Garden Store

No Asbestos

B00Q - R0002 - Cleaning Supplies

No Asbestos

B00Q - R0003 - Bulk Store

No Asbestos

B00Q - R0004 - Resources Store

No Asbestos

B00Q - R0005 - Cleaning Distributed Store

No Asbestos

B00Q - R0006 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00Q - R0007 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00Q - R0008 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00Q - R0009 - Visual Arts Workshop

No Asbestos

B00Q - R0010 - Dark Room

No Asbestos

B00Q - R0011 - Preparation

No Asbestos

B00Q - R0012 - Movement

No Asbestos

B00Q - R0013 - Apparatus Store

No Asbestos

B00Q - R0014 - Botany/Zoology

No Asbestos

B00Q - R0015 - Chemical Store

No Asbestos

B00Q - R0016 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00Q - R0017 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00Q - R0018 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00Q - R0019 - Science Laboratory

No Asbestos

B00Q - R0020 - External Movement

No Asbestos

B00Q - R0021 - External Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00R - General Learning - 2009 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00R - R0001 - External Movement

No Asbestos

B00R - R0002 - Practical Activities - 1hb

No Asbestos

B00R - R0003 - Home Base Store

No Asbestos

B00R - R0004 - Home Base

No Asbestos

B00R - R0005 - Withdrawal Space - 2hb

No Asbestos

B00R - R0006 - Home Base

No Asbestos

B00R - R0007 - Home Base Store

No Asbestos

B00R - R0008 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00S - General Learning - 2009 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00S - R0001 - External Movement

No Asbestos

B00S - R0002 - Practical Activities - 1hb

No Asbestos

B00S - R0003 - Home Base Store

No Asbestos

B00S - R0004 - Home Base

No Asbestos

B00S - R0005 - Withdrawal Space - 2hb

No Asbestos

B00S - R0006 - Home Base

No Asbestos

B00S - R0007 - Home Base Store

No Asbestos

B00S - R0008 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00T - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00T - R0001 - External Movement

No Asbestos

B00T - R0002 - Seminar - Type 2

No Asbestos

B00T - R0003 - Resources Store

No Asbestos

B00T - R0004 - Computer Store

No Asbestos

B00T - R0005 - Computer Learning Space

No Asbestos

B00T - R0006 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00U - Administration - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00U - R0001 - Toilets-Boys

No Asbestos

B00U - R0002 - Toilets-Girls

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 601 - D10739 - Learning Unit - Standard/Withdrawal : Placement Date - 30/06/1995

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2
---------	---------------	------------------	-------

OS 601 - D10742 - Learning Unit - Standard/Withdrawal : Placement Date - 30/06/1995

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2
---------	---------------	------------------	-------

OS 601 - D10999 - Learning Unit - Standard/Withdrawal : Placement Date - 25/02/1999

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2
---------	---------------	------------------	-------

OS 601 - D12844 - Learning Unit - Standard/Withdrawal : Placement Date - 5/02/1997

Exterior

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Interior						
R1 - Entry						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
R2 - General Learning Space						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
R3 - Store						
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017