


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Lithgow Public School (2410)
Region : Western NSW
State Electorate : Bathurst
Local Government Area : Lithgow

Initial Survey : Noel Arnold & Associates : 27 - May - 2008
Reviewed By : Grencap-NAA : 17 - Apr - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/Library - 1928 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	120m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2410/B00B/Eaves Linings/S2					Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	Non Accessible Area - Height Restriction					
Underfloor Voids	No Asbestos Found					

Interior

B00A - R0001 - Movement

No Asbestos

B00A - R0002 - Cleaning Distributed Store

No Asbestos

B00A - R0003 - Movement

No Asbestos

B00A - R0005 - Movement

No Asbestos

B00A - R0006 - Home Base

No Asbestos

B00A - R0007 - Home Base

No Asbestos

B00A - R0009 - Seminar/Study

No Asbestos

B00A - R0010 - Seminar/Study

No Asbestos

B00A - R0011 - Library Office/Workroom

No Asbestos

B00A - R0012 - Reading Area

No Asbestos

B00A - R0013 - K.L.A. Store

No Asbestos

B00A - R0014 - Movement

No Asbestos

B00A - R0015 - Movement

No Asbestos

B00A - R0016 - Movement

No Asbestos

B00A - R0017 - Movement

No Asbestos

B00A - R0018 - Entry Vestibule

No Asbestos

B00A - R0022 - Deputy Principal

Floor Coverings Res/Textile	Vinyl Sheet					
	2410/B00A/R0022/Floor Coverings Res/Textile/S11					No Asbestos Detected

Floor Coverings Res/Textile	backing to back of vinyl sheet					
	2410/B00A/R0022/Floor Coverings Res/Textile/S12					No Asbestos Detected

B00A - R0023 - Duplicating Workroom

No Asbestos

B00A - R0024 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	2410/B00A/R0022/Floor Coverings Res/Textile/S11				No Asbestos Detected	
Floor Coverings Res/Textile	backing to back of vinyl sheet					
	2410/B00A/R0022/Floor Coverings Res/Textile/S12				No Asbestos Detected	
Wall Linings Internal	Flat AC Sheeting	20m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	2410/B00A/R1001/Wall Linings Internal/S1				Chrysotile (white asbestos)	
B00A - R0025 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2410/B00A/R0025/Ceiling Structures/Linings/S13				Chrysotile (white asbestos)	
B00A - R0026 - Movement						
No Asbestos						
B00A - R0027 - Stairs						
No Asbestos						
B00A - R0028 - Stairs						
No Asbestos						
B00A - R0029 - Stairs						
No Asbestos						
B00A - R0030 - General Assistant/Bulk Store						
Wall Linings Internal	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2410/B00A/R1001/Wall Linings Internal/S1				Chrysotile (white asbestos)	
B00A - R0031 - Principal						
Wall Linings Internal	Flat AC Sheeting	20m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2410/B00A/R1001/Wall Linings Internal/S1				Chrysotile (white asbestos)	
B00A - R0032 - Other						
No Asbestos						
B00A - R0033 - Sick Bay						
No Asbestos						
B00A - R0034 - Movement						
No Asbestos						
B00A - R0035 - Clerical Office						
No Asbestos						
B00A - R1001 - Staff Toilet						
Wall Linings Internal	Flat AC Sheeting	4m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2410/B00A/R1001/Wall Linings Internal/S1				Chrysotile (white asbestos)	
B00A - R1003 - Movement						
No Asbestos						
B00A - R1004 - Home Base						
No Asbestos						
B00A - R1005 - Home Base						
No Asbestos						
B00A - R1006 - Home Base						
No Asbestos						
B00A - R1007 - Home Base						
No Asbestos						
B00A - R1008 - Home Base						
No Asbestos						
B00A - R1009 - Movement						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00A - R1011 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting	4m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
-----------------------	------------------	-----	------	--------------------	---------	--------------------

2410/B00A/R1001/Wall Linings Internal/S1

Chrysotile (white asbestos)

B00A - R1012 - Movement

Wall Linings Internal	Flat AC Sheeting	2m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
-----------------------	------------------	-----	-------	--------------------	---------	--------------------

2410/B00A/R1001/Wall Linings Internal/S1

Chrysotile (white asbestos)

B00A - R1013 - Cleaning Distributed Store

Wall Linings Internal	Flat AC Sheeting	2m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
-----------------------	------------------	-----	-------	--------------------	---------	--------------------

2410/B00A/R1001/Wall Linings Internal/S1

Chrysotile (white asbestos)

B00A - R1014 - General Storeroom

No Asbestos

B00A - R1015 - Communal Space

No Asbestos

B00A - R1016 - Raised Platform

No Asbestos

B00A - R1017 - Staff Room Annexe

No Asbestos

B00A - R1018 - Movement

Wall Linings Internal	Flat AC Sheeting	4m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
-----------------------	------------------	-----	------	--------------------	---------	--------------------

2410/B00A/R1001/Wall Linings Internal/S1

Chrysotile (white asbestos)

B00A - R1019 - Stairs

No Asbestos

B00A - R1020 - Stairs

No Asbestos

B00A - R9001 - General Storeroom

No Asbestos

B00A - R9002 - Stairs

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Support Unit - 1879 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	10m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2410/B00B/Eaves Linings/S2					Chrysotile (white asbestos) , Amosite (brown asbestos)
Electrical Backing Board	Resinous Board	1Unit	West	Good Condition (1)	Low (1)	Low Priority (2-3)
						Assumed Asbestos - Electrical Hazard
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Non Accessible Area - Area inaccessible					

Interior

B00B - R0001 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2410/B00B/R0001/Ceiling Structures/Linings/S3					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00B - R0002 - Withdrawal Space - 1hb

No Asbestos

B00B - R0003 - Home Base - E

No Asbestos

B00B - R0004 - Practical Activities - E

No Asbestos

B00B - R0010 - Staff Toilet

No Asbestos

B00B - R0011 - Toilet - P

No Asbestos

B00B - R0012 - Home Base - P

No Asbestos

B00B - R0013 - Practical Activities - E

No Asbestos

B00B - R0014 - Staff Room Annexe

No Asbestos

B00B - R0015 - General Storeroom


No Asbestos

B00B - R0016 - Movement

No Asbestos

B00B - R0017 - Movement

Electrical Backing Board	Resinous Board	1Unit	East	Good Condition (1)	Low (1)	Low Priority (2-3)
						Assumed Asbestos - Electrical Hazard



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Pupil Facilities - 1975 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2410/B00C/Eaves Linings/S4					Chrysotile (white asbestos)
Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00C - R0001 - Drinking Facilities

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2410/B00C/Eaves Linings/S4					Chrysotile (white asbestos)

B00C - R0002 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting	33m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2410/B00B/Eaves Linings/S2					Chrysotile (white asbestos) , Amosite (brown asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet	15m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2410/B00C/R0002/Partition Walls (Cubicles)/S5					Chrysotile (white asbestos)

B00C - R0003 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2410/B00C/R0002/Partition Walls (Cubicles)/S5					Chrysotile (white asbestos)
Incinerette	Encapsulated Insulation material within unit	1Unit(s)	East	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - sealed unit					
Ceiling Structures/Linings	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2410/B00C/Eaves Linings/S4					Chrysotile (white asbestos)

B00C - R0004 - Drinking Facilities

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2410/B00C/Eaves Linings/S4					Chrysotile (white asbestos)

B00C - R0005 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2410/B00C/Eaves Linings/S4					Chrysotile (white asbestos)
Incinerette	Encapsulated Insulation material within unit	1Unit(s)	East	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - sealed unit					

B00C - R0006 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2410/B00C/Eaves Linings/S4					Chrysotile (white asbestos)

B00C - R0007 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2410/B00C/Eaves Linings/S4					Chrysotile (white asbestos)

B00C - R0008 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2410/B00C/Eaves Linings/S4					Chrysotile (white asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning/Support Unit - 1884 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Non Accessible Area - Area inaccessible

Interior

B00D - R0001 - Cleaning Distributed Store

No Asbestos

B00D - R0002 - Movement

No Asbestos

B00D - R0003 - Sports Store

No Asbestos

B00D - R0004 - Home Base

No Asbestos

B00D - R0005 - Home Base

No Asbestos

B00D - R0006 - Home Base

No Asbestos

B00D - R0007 - Home Base - M

No Asbestos

B00D - R0009 - Toilet - S

No Asbestos

B00D - R0010 - Home Base Store - M

No Asbestos

B00D - R0011 - Movement

No Asbestos

B00D - R0012 - Staff Room Annexe

No Asbestos

B00D - R0014 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	97m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	------	------------	--------------------	---------	--------------------

2410/B00B/R0001/Ceiling Structures/Linings/S3

Chrysotile (white asbestos) , Amosite (brown asbestos)

B00D - R0015 - Movement

No Asbestos

B00D - R0016 - Stairs

No Asbestos

B00D - R0017 - Stairs

No Asbestos

B00D - R0018 - Practical Activities - S - 1hb

No Asbestos

B00D - R0019 - Home Base - S

No Asbestos

B00D - R1001 - Movement

No Asbestos

B00D - R1002 - Staff Room Annexe

No Asbestos

B00D - R1003 - Home Base

No Asbestos

B00D - R1004 - Home Base

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00D - R1005 - Home Base						
No Asbestos						
B00D - R1006 - Home Base						
No Asbestos						
B00D - R1007 - General Storeroom						
No Asbestos						
B00D - R1008 - Home Base						
No Asbestos						
B00D - R1010 - Movement						
No Asbestos						
B00D - R1011 - Staff Room Annexe						
No Asbestos						
B00D - R1012 - Staff Room Annexe						
No Asbestos						
B00D - R1013 - Movement						
No Asbestos						
B00D - R1014 - Stairs						
No Asbestos						
B00D - R1015 - Stairs						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Building Services - 1950 - Brick/Veneer (Brick/Veneer)

Exterior

Wall Cladding	Flat AC Sheeting 2410/B00E/Wall Cladding/S6					No Asbestos Detected
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00E - R0001 - Movement

No Asbestos

B00E - R0002 - General Storeroom

No Asbestos

B00E - R0003 - Garden Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Communal Facilities/Pupil Facilities - 1909 - Brick/Block (Brick/Block)

Exterior

Electrical Backing Board	Resinous Board	1m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
--------------------------	----------------	-----	-------	--------------------	---------	--------------------

Assumed Asbestos - Electrical Hazard

Ceiling Voids	No Asbestos Found					
Underfloor Voids	Non Accessible Area - Area inaccessible					

Interior

B00F - M0001 - General Assistant/Bulk Store

No Asbestos

B00F - M0002 - Movement

No Asbestos

B00F - M0003 - Stairs

No Asbestos

B00F - M0004 - Stairs

No Asbestos

B00F - R0001 - Canteen

No Asbestos

B00F - R0002 - Staff Toilet

No Asbestos

B00F - R0003 - Canteen Office/Store

No Asbestos

B00F - R0004 - Movement

No Asbestos

B00F - R0005 - Movement

No Asbestos

B00F - R0006 - General Storeroom

No Asbestos

B00F - R0007 - Cleaning Supplies

No Asbestos

B00F - R0008 - Special Programs Room

No Asbestos

B00F - R0009 - Special Programs Room

No Asbestos

B00F - R0010 - Craft Store

No Asbestos

B00F - R0011 - Practical Activities - 1hb

No Asbestos

B00F - R0012 - Movement

No Asbestos

B00F - R0013 - Cleaning Distributed Store

No Asbestos

B00F - R0014 - Communal Space

No Asbestos

B00F - R0015 - Movement

No Asbestos

B00F - R0016 - Movement

Ceiling Structures/Linings	Flat AC Sheeting				
	2410/B00F/R0016/Ceiling Structures/Linings/S7				

No Asbestos Detected

B00F - R0017 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00F - R0018 - Stairs

No Asbestos

B00F - R0019 - Stairs

No Asbestos

B00F - R1001 - Other-Community Use

Floor Coverings Vinyl Sheet
Res/Textile

2410/B00F/R1001/Floor Coverings Res/Textile/S8

No Asbestos Detected

B00F - R1002 - Staff Toilet

No Asbestos

B00F - R1003 - Movement

Floor Coverings Vinyl Sheet
Res/Textile

2410/B00F/R1001/Floor Coverings Res/Textile/S8

No Asbestos Detected

B00F - R1005 - Cleaning Distributed Store

No Asbestos

B00F - R1006 - Staff Room

No Asbestos

B00F - R1007 - Stairs

No Asbestos

B00F - R1008 - Stairs

No Asbestos

B00F - R1009 - Home Base/Practical Activities

No Asbestos

B00F - R1010 - Home Base/Practical Activities

No Asbestos

B00F - R1011 - Home Base/Practical Activities

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00G - Pupil Facilities - 1975 - Brick/Block (Brick/Block)						
Exterior						
Eaves Linings	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2410/B00C/Eaves Linings/S4					Chrysotile (white asbestos)
Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Interior						
B00G - R0001 - Drinking Facilities						
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2410/B00G/R0001/Ceiling Structures/Linings/S9					Chrysotile (white asbestos)
B00G - R0002 - Toilets - Boys						
Ceiling Structures/Linings	Flat AC Sheeting	33m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2410/B00G/R0001/Ceiling Structures/Linings/S9					Chrysotile (white asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet	15m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2410/B00C/R0002/Partition Walls (Cubicles)/S5					Chrysotile (white asbestos)
B00G - R0003 - Staff Toilet						
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2410/B00G/R0001/Ceiling Structures/Linings/S9					Chrysotile (white asbestos)
B00G - R0004 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2410/B00G/R0001/Ceiling Structures/Linings/S9					Chrysotile (white asbestos)
B00G - R0005 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2410/B00G/R0001/Ceiling Structures/Linings/S9					Chrysotile (white asbestos)
B00G - R0006 - Cleaning Distributed Store						
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2410/B00G/R0001/Ceiling Structures/Linings/S9					Chrysotile (white asbestos)
B00G - R0007 - Toilets - Girls						
Partition Walls (Cubicles)	Compressed AC Sheet	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2410/B00C/R0002/Partition Walls (Cubicles)/S5					Chrysotile (white asbestos)
Incinerette	Encapsulated Insulation material within unit	1Unit(s)	East	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - sealed unit					
Ceiling Structures/Linings	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2410/B00G/R0001/Ceiling Structures/Linings/S9					Chrysotile (white asbestos)
B00G - R0008 - Drinking Facilities						
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2410/B00G/R0001/Ceiling Structures/Linings/S9					Chrysotile (white asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Pupil Facilities - 1975 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2410/B00C/Eaves Linings/S4					Chrysotile (white asbestos)
Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00H - R0001 - Drinking Facilities

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2410/B00G/R0001/Ceiling Structures/Linings/S9					Chrysotile (white asbestos)

B00H - R0002 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2410/B00G/R0001/Ceiling Structures/Linings/S9					Chrysotile (white asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet	40m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2410/B00C/R0002/Partition Walls (Cubicles)/S5					Chrysotile (white asbestos)

B00H - R0003 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2410/B00G/R0001/Ceiling Structures/Linings/S9					Chrysotile (white asbestos)

B00H - R0004 - General Storeroom

No Asbestos

B00H - R0005 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2410/B00G/R0001/Ceiling Structures/Linings/S9					Chrysotile (white asbestos)

B00H - R0006 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2410/B00G/R0001/Ceiling Structures/Linings/S9					Chrysotile (white asbestos)

B00H - R0007 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2410/B00G/R0001/Ceiling Structures/Linings/S9					Chrysotile (white asbestos)
Incinerette	Encapsulated Insulation material within unit	1Unit(s)	East	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - sealed unit					

B00H - R0008 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting	42m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2410/B00G/R0001/Ceiling Structures/Linings/S9					Chrysotile (white asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet	30m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2410/B00C/R0002/Partition Walls (Cubicles)/S5					Chrysotile (white asbestos)

B00H - R0009 - Drinking Facilities

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2410/B00G/R0001/Ceiling Structures/Linings/S9					Chrysotile (white asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - General Learning - 1916 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found					
Underfloor Voids	Non Accessible Area - Area inaccessible					

Interior

B00I - R0001 - Movement

No Asbestos

B00I - R0002 - General Storeroom

No Asbestos

B00I - R0003 - General Storeroom

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	10m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
2410/B00I/R0020/Floor Coverings Res/Textile/S15						Chrysotile (white asbestos)

Floor Coverings Res/Textile	Adhesive					
2410/B00I/R0020/Floor Coverings Res/Textile/S16						No Asbestos Detected

B00I - R0004 - Movement

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	4m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
2410/B00I/R0020/Floor Coverings Res/Textile/S15						Chrysotile (white asbestos)

Floor Coverings Res/Textile	Adhesive					
2410/B00I/R0020/Floor Coverings Res/Textile/S16						No Asbestos Detected

B00I - R0006 - General Storeroom

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	16m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
2410/B00I/R0020/Floor Coverings Res/Textile/S15						Chrysotile (white asbestos)

Floor Coverings Res/Textile	Adhesive					
2410/B00I/R0020/Floor Coverings Res/Textile/S16						No Asbestos Detected

B00I - R0007 - Staff Toilet

No Asbestos

B00I - R0008 - Sick Bay

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
2410/B00I/R0020/Floor Coverings Res/Textile/S16						No Asbestos Detected

Floor Coverings Res/Textile	Adhesive					
2410/B00I/R0020/Floor Coverings Res/Textile/S16						No Asbestos Detected

B00I - R0009 - Clerical Office/Workroom

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	14m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
2410/B00I/R0020/Floor Coverings Res/Textile/S15						Chrysotile (white asbestos)

Floor Coverings Res/Textile	Adhesive					
2410/B00I/R0020/Floor Coverings Res/Textile/S16						No Asbestos Detected

B00I - R0010 - Home Base

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	46m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
2410/B00I/R0020/Floor Coverings Res/Textile/S15						Chrysotile (white asbestos)

Floor Coverings Res/Textile	Adhesive					
2410/B00I/R0020/Floor Coverings Res/Textile/S16						No Asbestos Detected

Chalk Board	Flat AC Sheeting	10m2	surround	Good Condition (1)	Low (1)	Low Priority (2-3)
2410/B00I/R0010/Chalk Board/S17						Chrysotile (white asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00I - R0011 - Staff Room Annexe						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 2410/B00I/R0020/Floor Coverings Res/Textile/S15	16m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive 2410/B00I/R0020/Floor Coverings Res/Textile/S16					No Asbestos Detected
B00I - R0012 - Home Base						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 2410/B00I/R0020/Floor Coverings Res/Textile/S15	63m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive 2410/B00I/R0020/Floor Coverings Res/Textile/S16					No Asbestos Detected
Chalk Board	Flat AC Sheeting 2410/B00I/R0010/Chalk Board/S17	10m2	surround	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00I - R0013 - General Storeroom						
No Asbestos						
B00I - R0014 - General Storeroom						
No Asbestos						
B00I - R0015 - Movement						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 2410/B00I/R0020/Floor Coverings Res/Textile/S15	19m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive 2410/B00I/R0020/Floor Coverings Res/Textile/S16					No Asbestos Detected
B00I - R0017 - Home Base						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 2410/B00I/R0020/Floor Coverings Res/Textile/S15	45m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive 2410/B00I/R0020/Floor Coverings Res/Textile/S16					No Asbestos Detected
Chalk Board	Flat AC Sheeting 2410/B00I/R0010/Chalk Board/S17	11m2	surround	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00I - R0018 - Home Base						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 2410/B00I/R0020/Floor Coverings Res/Textile/S15	45m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive 2410/B00I/R0020/Floor Coverings Res/Textile/S16					No Asbestos Detected
Chalk Board	Flat AC Sheeting 2410/B00I/R0010/Chalk Board/S17	10m2	surround	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00I - R0019 - Movement						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 2410/B00I/R0020/Floor Coverings Res/Textile/S15	68m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive 2410/B00I/R0020/Floor Coverings Res/Textile/S16					No Asbestos Detected
B00I - R0020 - Movement						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 2410/B00I/R0020/Floor Coverings Res/Textile/S15	5m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Adhesive					
	2410/B001/R0020/Floor Coverings Res/Textile/S16					No Asbestos Detected
B001 - R0021 - Stairs						
No Asbestos						
B001 - R0022 - Stairs						
No Asbestos						
B001 - R1001 - Movement						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	18m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	2410/B001/R0020/Floor Coverings Res/Textile/S15					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive					
	2410/B001/R0020/Floor Coverings Res/Textile/S16					No Asbestos Detected
B001 - R1002 - Home Base						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	47m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	2410/B001/R0020/Floor Coverings Res/Textile/S15					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive					
	2410/B001/R0020/Floor Coverings Res/Textile/S16					No Asbestos Detected
Chalk Board	Flat AC Sheeting	10m2	surround	Good Condition (1)	Low (1)	Low Priority (2-3)
	2410/B001/R0010/Chalk Board/S17					Chrysotile (white asbestos)
B001 - R1003 - Home Base						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	47m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	2410/B001/R0020/Floor Coverings Res/Textile/S15					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive					
	2410/B001/R0020/Floor Coverings Res/Textile/S16					No Asbestos Detected
Chalk Board	Flat AC Sheeting	10m2	surround	Good Condition (1)	Low (1)	Low Priority (2-3)
	2410/B001/R0010/Chalk Board/S17					Chrysotile (white asbestos)
B001 - R1004 - Staff Room						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	17m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	2410/B001/R0020/Floor Coverings Res/Textile/S15					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive					
	2410/B001/R0020/Floor Coverings Res/Textile/S16					No Asbestos Detected
B001 - R1005 - Home Base						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	61m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	2410/B001/R0020/Floor Coverings Res/Textile/S15					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive					
	2410/B001/R0020/Floor Coverings Res/Textile/S16					No Asbestos Detected
Chalk Board	Flat AC Sheeting	10m2	surround	Good Condition (1)	Low (1)	Low Priority (2-3)
	2410/B001/R0010/Chalk Board/S17					Chrysotile (white asbestos)
B001 - R1007 - Withdrawal Space - 1hb						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	7m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	2410/B001/R0020/Floor Coverings Res/Textile/S15					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive	7m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	2410/B001/R0020/Floor Coverings Res/Textile/S15					Chrysotile (white asbestos)
B001 - R1008 - Home Base						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 2410/B001/R0020/Floor Coverings Res/Textile/S15	47m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive 2410/B001/R0020/Floor Coverings Res/Textile/S16					No Asbestos Detected
Chalk Board	Flat AC Sheeting 2410/B001/R0010/Chalk Board/S17	10m2	surround	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B001 - R1009 - Home Base						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 2410/B001/R0020/Floor Coverings Res/Textile/S15	47m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive 2410/B001/R0020/Floor Coverings Res/Textile/S16					No Asbestos Detected
Chalk Board	Flat AC Sheeting 2410/B001/R0010/Chalk Board/S17	10m2	surround	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B001 - R1010 - Movement						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 2410/B001/R0020/Floor Coverings Res/Textile/S15	78m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive 2410/B001/R0020/Floor Coverings Res/Textile/S16					No Asbestos Detected
B001 - R1011 - Stairs						
No Asbestos						
B001 - R1012 - Stairs						
No Asbestos						
B001 - Room+1 - Covered Walkway From Building I to H						
Ceiling Structures/Linings	Flat AC Sheeting 2410/B001/Room+1/Ceiling Structures/Linings/S14	40m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B001 - Room+2 - Movement adjacent to walkway						
Ceiling Structures/Linings	Flat AC Sheeting 2410/B001/Room+1/Ceiling Structures/Linings/S14	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting 2410/B001/Room+2/Wall Linings Internal/S18	4m2	South	Minimal Damage (2)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Crocidolite (blue asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Storage - 1916 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting 2410/B00F/R0016/Ceiling Structures/Linings/S7	No Asbestos Detected				
Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00J - R0001 - Movement

No Asbestos

B00J - R0002 - Sports Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Communal Facilities - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00K - R0001 - Communal Space

No Asbestos

B00K - R0002 - Raised Platform

No Asbestos

B00K - R0003 - Movement

No Asbestos

B00K - R0004 - Covered Outdoor Learning Area

No Asbestos

B00K - R0005 - Ramp

No Asbestos

B00K - R0006 - Movement

No Asbestos

B00K - R0007 - Hall Chair Store

No Asbestos

B00K - R0008 - Communal/Performance Store

No Asbestos

B00K - R0009 - P.E. Store

No Asbestos

B00K - R0010 - Toilets - Girls

No Asbestos

B00K - R0011 - Movement

No Asbestos

B00K - R0012 - Toilets - Boys

No Asbestos

B00K - R0013 - Movement

No Asbestos

B00K - R0014 - Sound Cupboard

No Asbestos

B00K - R0015 - Cleaning Distributed Store

No Asbestos

B00K - R0016 - Other

No Asbestos

B00K - R0017 - Main Switch Board Cupboard

No Asbestos

B00K - R0018 - Access Shower/Toilet/Change

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

Available Asbestos Related Electronic Files

2410_ASB_261112_AMP.pdf

* Note : Refer to AMS for details of the attachment(s).

2017