


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Londonderry Public School (2421)  
**Region :** Western Sydney  
**State Electorate :** Londonderry  
**Local Government Area :** Penrith

**Initial Survey :** Noel Arnold & Associates : 22 - Apr - 2008  
**Reviewed By :** Grencap-NAA : 10 - Jun - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - Pupil Facilities/Administration - 1966 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting 2421/B00A/Eaves Linings/S10					<b>No Asbestos Detected</b>
Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible					
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					

**Interior****B00A - R0001 - Toilets - Boys**

Partition Walls (Cubicles)	Compressed AC Sheet 2421/B00A/R0001/Partition Walls (Cubicles)/S8					<b>No Asbestos Detected</b>
----------------------------	--	--	--	--	--	-----------------------------

**B00A - R0002 - Security Store**

No Asbestos

**B00A - R0003 - Toilets - Girls**

Partition Walls (Cubicles)	Compressed AC Sheet 2421/B00A/R0001/Partition Walls (Cubicles)/S8					<b>No Asbestos Detected</b>
----------------------------	--	--	--	--	--	-----------------------------

**B00A - R0004 - General Storeroom**

No Asbestos

**B00A - R0005 - Disabled Toilet**

Ceiling Structures/Linings	Flat AC Sheeting 2421/B00A/Eaves Linings/S10					<b>No Asbestos Detected</b>
----------------------------	---	--	--	--	--	-----------------------------

**B00A - R0007 - External Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - General Learning/Pupil Facilities - 1966 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting	60m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	2421/B00B/Eaves Linings/S16					<b>Chrysotile (white asbestos)</b>
Gable Verge Lining	Flat AC Sheeting	20m2	East & West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2421/B00B/Gable Verge Lining/S15					<b>Chrysotile (white asbestos)</b>
In-fill-panel	Compressed AC Sheet	25m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2421/B00B/In-fill-panel/S12					<b>Chrysotile (white asbestos)</b>
Underfloor Voids - Slab on Ground	Non Accessible Area					
	- Area inaccessible					

**Interior****B00B - R0001 - Staff Toilet**

No Asbestos

**B00B - R0002 - Canteen Office/Store**

No Asbestos

**B00B - R0003 - Canteen Office/Store**

No Asbestos

**B00B - R0004 - Canteen**

No Asbestos

**B00B - R0005 - Movement**

No Asbestos

**B00B - R0006 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	88m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2421/B00B/R0017/Wall Linings Internal/S5					<b>Chrysotile (white asbestos)</b>

**B00B - R0007 - Practical Activities - 1hb**

No Asbestos

**B00B - R0008 - Home Base**

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	80m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2421/B00G/R0006/Floor Coverings Res/Textile/S4					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive	80m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2421/B00B/R0008/Floor Coverings Res/Textile/S11					<b>Chrysotile (white asbestos)</b>

**B00B - R0009 - Toilets - Boys/Girls**

No Asbestos

**B00B - R0010 - Home Base**

Floor Coverings Res/Textile	Vinyl Tiles	83m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2421/B00G/R0006/Floor Coverings Res/Textile/S4					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive	83m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2421/B00B/R0008/Floor Coverings Res/Textile/S11					<b>Chrysotile (white asbestos)</b>

**B00B - R0011 - Practical Activities - 1hb**

No Asbestos

**B00B - R0012 - Toilets - Boys/Girls**

No Asbestos

**B00B - R0013 - Practical Activities - 1hb**

No Asbestos

**B00B - R0014 - Home Base**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 2421/B00G/R0006/Floor Coverings Res/Textile/S4	53m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos)</b>	
Floor Coverings Res/Textile	Adhesive 2421/B00B/R0008/Floor Coverings Res/Textile/S11	53m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos)</b>	
<b>B00B - R0015 - Movement</b>						
Floor Coverings Res/Textile	Vinyl Tiles 2421/B00G/R0006/Floor Coverings Res/Textile/S4	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos)</b>	
Floor Coverings Res/Textile	Adhesive 2421/B00B/R0008/Floor Coverings Res/Textile/S11	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos)</b>	
<b>B00B - R0016 - Home Base Store</b>						
Floor Coverings Res/Textile	Vinyl Tiles 2421/B00G/R0006/Floor Coverings Res/Textile/S4	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos)</b>	
Floor Coverings Res/Textile	Adhesive 2421/B00B/R0008/Floor Coverings Res/Textile/S11	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos)</b>	
<b>B00B - R0017 - Staff Room Annexe</b>						
Floor Coverings Res/Textile	Vinyl Tiles 2421/B00G/R0006/Floor Coverings Res/Textile/S4	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos)</b>	
Wall Linings Internal	Flat AC Sheeting 2421/B00B/R0017/Wall Linings Internal/S5	10m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos)</b>	
Floor Coverings Res/Textile	Adhesive 2421/B00B/R0008/Floor Coverings Res/Textile/S11	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos)</b>	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - General Learning/Administration - 1951 - Timber (Timber)****Exterior**

Eaves Linings	Flat AC Sheeting	30m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2421/B00C/R0003/Wall Linings Internal/S2					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
Underfloor Voids	No Asbestos Found					
Ceiling Voids	No Asbestos Found					

**Interior****B00C - R0001 - External Movement**

Ceiling Structures/Linings	Flat AC Sheeting	42m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2421/B00C/R0003/Wall Linings Internal/S2					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00C - R0002 - Community Clinic**

Floor Coverings Res/Textile	Vinyl Sheet					
	2421/B00C/R0004/Floor Coverings Res/Textile/S22					<b>No Asbestos Detected</b>

**B00C - R0003 - Home Base**

Wall Linings Internal	Flat AC Sheeting	2m2	East, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	2421/B00C/R0003/Wall Linings Internal/S2					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00C - R0004 - Community Clinic**

Floor Coverings Res/Textile	Vinyl Sheet					
	2421/B00C/R0004/Floor Coverings Res/Textile/S22					<b>No Asbestos Detected</b>

**B00C - R0005 - Home Base**

Wall Linings Internal	Flat AC Sheeting	2m2	South, West, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	2421/B00C/R0003/Wall Linings Internal/S2					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00C - R0006 - General Storeroom**

No Asbestos

**B00C - R0007 - General Storeroom**

No Asbestos

**B00C - R0008 - General Storeroom**

Floor Coverings Res/Textile	Vinyl Tiles	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2421/B00C/R0008/Floor Coverings Res/Textile/S9					<b>Chrysotile (white asbestos)</b>

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Communal Facilities - 1932 - Timber Shed (Timber Shed)**

**Exterior**

Eaves Linings	Flat AC Sheeting 2421/B00D/Wall Cladding/S1					<b>No Asbestos Detected</b>
Wall Cladding	Flat AC Sheeting 2421/B00D/Wall Cladding/S1					<b>No Asbestos Detected</b>
Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible					
Underfloor Voids	No Asbestos Found					

**Interior**

**B00D - R0001 - Sports Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - General Learning - 1932 - Timber (Timber)**

**Exterior**

Wall Cladding	Flat AC Sheeting 2421/B00F/Wall Cladding/S19					<b>No Asbestos Detected</b>
Underfloor Voids	No Asbestos Found					
Ceiling Voids	Non Accessible Area - Area inaccessible					

**Interior**

**B00E - R0001 - External Movement**

No Asbestos

**B00E - R0002 - General Storeroom**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - General Learning - 1936 - Timber (Timber)**

**Exterior**

Wall Cladding	Flat AC Sheeting 2421/B00F/Wall Cladding/S19					<b>No Asbestos Detected</b>
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior**

**B00F - R0001 - External Movement**

No Asbestos

**B00F - R0002 - Home Base**

Wall Linings Internal	Flat AC Sheeting 2421/B00F/R0002/Wall Linings Internal/S7	16m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 2421/B00F/R0002/Floor Coverings Res/Textile/S20	63m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive 2421/B00F/R0002/Floor Coverings Res/Textile/S21					<b>No Asbestos Detected</b>

**B00F - R0003 - Home Base Store**

No Asbestos

**B00F - R0004 - Home Base Store**

Wall Linings Internal	Compressed AC Sheet 2421/B00F/R0004/Wall Linings Internal/S6	1m2	North, West	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
-----------------------	---	-----	-------------	--------------------	---------	---

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - General Learning/Administration - 1966 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting	60m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2421/B00G/Eaves Linings/S18				Chrysotile (white asbestos)	
Gable Verge Lining	Flat AC Sheeting	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2421/B00G/Eaves Linings/S18				Chrysotile (white asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior**

**B00G - R0001 - External Movement**

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2421/B00G/R0001/Ceiling Structures/Linings/S13				Chrysotile (white asbestos)	

**B00G - R0002 - Staff Toilet**

No Asbestos

**B00G - R0003 - Staff Toilet**

No Asbestos

**B00G - R0004 - Staff Room**

No Asbestos

**B00G - R0005 - Movement**

No Asbestos

**B00G - R0006 - Practical Activities - 1hb**

Floor Coverings Res/Textile	Vinyl Tiles	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2421/B00G/R0006/Floor Coverings Res/Textile/S4				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2421/B00B/R0008/Floor Coverings Res/Textile/S11				Chrysotile (white asbestos)	

**B00G - R0007 - Home Base**

No Asbestos

**B00G - R0008 - External Movement**

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2421/B00G/R0001/Ceiling Structures/Linings/S13				Chrysotile (white asbestos)	

**B00G - R0009 - Movement**

No Asbestos

**B00G - R0010 - Home Base Store**

No Asbestos

**B00G - R0011 - Home Base Store**

No Asbestos

**B00G - R0012 - Home Base**

No Asbestos

**B00G - R0013 - Home Base**

No Asbestos

**B00G - R0014 - External Movement**

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2421/B00G/R0001/Ceiling Structures/Linings/S13				Chrysotile (white asbestos)	

**B00G - R0015 - Movement**

No Asbestos

**B00G - R0016 - Personal Effects Storage**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Wall Linings Internal	Flat AC Sheeting 2421/B00G/R0021/Wall Linings Internal/S3					No Asbestos Detected
Ceiling Hatch	Flat AC Sheeting 2421/B00G/R0016/Ceiling Hatch/S17					No Asbestos Detected
<b>B00G - R0017 - Home Base Store</b>						
No Asbestos						
<b>B00G - R0018 - Security Store</b>						
No Asbestos						
<b>B00G - R0019 - Interview</b>						
No Asbestos						
<b>B00G - R0020 - Distribution Board</b>				Note: No inspection of live electrical installation.		
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2421/B00G/R0020/Ceiling Structures/Linings/S14					Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2421/B00G/R0020/Ceiling Structures/Linings/S14					Chrysotile (white asbestos)
<b>B00G - R0021 - Interview</b>						
Wall Linings Internal	Flat AC Sheeting 2421/B00G/R0021/Wall Linings Internal/S3					No Asbestos Detected
Floor Coverings Res/Textile	Adhesive	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2421/B00B/R0008/Floor Coverings Res/Textile/S11					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2421/B00G/R0006/Floor Coverings Res/Textile/S4					Chrysotile (white asbestos)
<b>B00G - R0022 - Ramp</b>						
No Asbestos						
<b>B00G - R0023 - External Movement</b>						
No Asbestos						
<b>B00G - R0024 - Shelter</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - Building Services - 1932 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting 2421/B00H/Eaves Linings/S23					<b>No Asbestos Detected</b>
Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					

**Interior**

**B00H - R0001 - Garden Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00I - Administration/Library - 2010 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

**Interior****B00I - R0001 - Reading Area**

No Asbestos

**B00I - R0002 - K.L.A. Store**

No Asbestos

**B00I - R0003 - Communications Room**

No Asbestos

**B00I - R0004 - Library Office/Workroom**

No Asbestos

**B00I - R0005 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00I - R0006 - Cleaning Distributed Store**

No Asbestos

**B00I - R0007 - Security Store**

No Asbestos

**B00I - R0008 - Staff Toilet**

No Asbestos

**B00I - R0009 - Staff Toilet**

No Asbestos

**B00I - R0010 - Principal**

No Asbestos

**B00I - R0011 - Interview**

No Asbestos

**B00I - R0012 - Movement**

No Asbestos

**B00I - R0013 - Deputy Principal - Type 1**

No Asbestos

**B00I - R0014 - Staff Room**

No Asbestos

**B00I - R0015 - Sick Bay - Shower/Toilet**

No Asbestos

**B00I - R0016 - Sick Bay**

No Asbestos

**B00I - R0017 - Clerical Office/Workroom**

No Asbestos

**B00I - R0018 - Entry Vestibule**

No Asbestos

**B00I - R0019 - External Movement**

No Asbestos

**B00I - R0020 - External Movement**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00J - Communal Facilities - 2011 - Steel (Steel)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

**Interior****B00J - R0001 - External Movement**

No Asbestos

**B00J - R0002 - Staff Kitchen**

No Asbestos

**B00J - R0003 - Toilets - Girls**

No Asbestos

**B00J - R0004 - Toilet - Lobby**

No Asbestos

**B00J - R0005 - Disabled Toilet**

No Asbestos

**B00J - R0006 - Toilets - Boys**

No Asbestos

**B00J - R0007 - Toilet - Lobby**

No Asbestos

**B00J - R0008 - General Storeroom**

No Asbestos

**B00J - R0009 - Cleaning Distributed Store**

No Asbestos

**B00J - R0010 - General Storeroom**

No Asbestos

**B00J - R0011 - Chair Storeroom**

No Asbestos

**B00J - R0012 - General Storeroom**

No Asbestos

**B00J - R0013 - Communal Space**

No Asbestos

**B00J - R0014 - Raised Platform**

No Asbestos

**B00J - R0015 - Movement**

No Asbestos

**B00J - R0016 - Other-Vacant**

No Asbestos

**B00J - R0017 - Movement**

No Asbestos

**B00J - R0018 - Other-Vacant**

No Asbestos

**B00J - R0019 - Chair Storeroom**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017