

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning - 1976 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	40m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	3796/B00A/Eaves Linings/S1					Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	18m	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	3796/B00A/Eaves Linings/S1					Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00A - R0001 - External Movement (10.42 m2)

Ceiling Structures/Linings	Flat AC Sheeting	11m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3796/B00A/Eaves Linings/S1					Chrysotile (white asbestos)

B00A - R0010 - External Movement (23.37 m2)

Ceiling Structures/Linings	Flat AC Sheeting	24m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3796/B00A/Eaves Linings/S1					Chrysotile (white asbestos)

B00A - R0011 - Home Base (71.3 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	3796/B00A/R0006/Ceiling Structures/Linings/S2					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00A - R0012 - Distribution Board (10.02 m2)

Note: No inspection of live electrical installation.

Electrical Backing Board	Resinous Board	1Unit	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						Assumed Asbestos - Live electrical board

B00A - R0013 - External Movement (3.3 m2)

Ceiling Structures/Linings	Compressed AC Sheet					No Asbestos Detected
	3796/B00A/R0006/Ceiling Structures/Linings/S2					

B00A - R0014 - Home Base (56.42 m2)

No Asbestos

B00A - R0015 - Home Base Store (3.37 m2)

No Asbestos

B00A - R0016 - Home Base Store (10.33 m2)

No Asbestos

B00A - R0017 - Withdrawal Space - 2hb (9.93 m2)

No Asbestos

B00A - R0018 - Practical Activities - 2hb (6.67 m2)

No Asbestos

B00A - R0019 - Home Base (56.43 m2)

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Administration/Staff Facilities - 1974 - Brick/Block (Brick/Block)**Exterior**

Gable Verge Lining	Flat AC Sheeting 3796/B00A/Eaves Linings/S1	20m	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Eaves Linings	Flat AC Sheeting 3796/B00A/Eaves Linings/S1	18m2	East facing	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior**B00B - R0001 - Interview (12.02 m2)**

No Asbestos

B00B - R0002 - Movement (13.91 m2)

No Asbestos

B00B - R0003 - Entry Vestibule (19.7 m2)

No Asbestos

B00B - R0004 - Principal (20.74 m2)

No Asbestos

B00B - R0005 - Deputy Principal (12.15 m2)

No Asbestos

B00B - R0006 - Staff Room Annexe (12.18 m2)

No Asbestos

B00B - R0007 - Staff Room (74.17 m2)

No Asbestos

B00B - R0008 - Movement (26.23 m2)

No Asbestos

B00B - R0009 - Duplicating Workroom (12.18 m2)

No Asbestos

B00B - R0010 - Staff Toilet (4.44 m2)

No Asbestos

B00B - R0011 - Staff Toilet (3.87 m2)

No Asbestos

B00B - R0012 - Distribution Board (1.51 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00B - R0013 - Toilets - Boys/Girls (3.02 m2)

Partition Walls (Cubicles)	Compressed AC Sheet 3796/B00J/R0019/Partition Walls (Cubicles)/S5	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	----------------------------------------------------------------------	-----	--------------	--------------------	---------	----------------------------------------------------------

B00B - R0014 - Movement (27.34 m2)

No Asbestos

B00B - R0015 - Staff Toilet (3.01 m2)

Partition Walls (Cubicles)	Compressed AC Sheet 3796/B00J/R0019/Partition Walls (Cubicles)/S5	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	----------------------------------------------------------------------	-----	--------------	--------------------	---------	----------------------------------------------------------

B00B - R0016 - Cleaning Distributed Store (2.67 m2)

No Asbestos

B00B - R0017 - Sick Bay (7.93 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00B - R0018 - Clerical Office/Workroom (11.69 m2)						
No Asbestos						
B00B - R0019 - Duplicating Workroom (12.61 m2)						
No Asbestos						
B00B - R0020 - Distribution Board (2.19 m2)				Note: No inspection of live electrical installation.		
No Asbestos						
B00B - R0021 - General Storeroom (12.32 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Library - 1974 - Brick/Veneer (Brick/Veneer)

Exterior

Gable Verge Lining	Flat AC Sheeting 3796/B00A/Eaves Linings/S1	20m	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Eaves Linings	Flat AC Sheeting 3796/B00A/Eaves Linings/S1	18m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Ceiling Voids - Raked Ceiling	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00C - R0001 - Communications Room (23.65 m2)

No Asbestos

B00C - R0002 - Distribution Board (0.63 m2)

Note: No inspection of live electrical installation.

Non Accessible

B00C - R0003 - Reading Area (255.83 m2)

No Asbestos

B00C - R0004 - Seminar/Study (13.64 m2)

No Asbestos

B00C - R0005 - K.L.A. Store (13.54 m2)

No Asbestos

B00C - R0006 - Library Office/Workroom (8.47 m2)

No Asbestos

B00C - R0007 - Library Office/Workroom (13.46 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning - 1979 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting 3796/B00A/Eaves Linings/S1	50m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting 3796/B00A/Eaves Linings/S1	18m	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00D - R0001 - Home Base (57.22 m2)

No Asbestos

B00D - R0016 - Withdrawal Space - 1hb (20.27 m2)

No Asbestos

B00D - R0017 - Movement (4.13 m2)

No Asbestos

B00D - R0018 - External Movement (2.71 m2)

Ceiling Structures/Linings	Flat AC Sheeting 3796/B00E/R0001/Ceiling Structures/Linings/S6	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Structures/Linings	Flat AC Sheeting 3796/B00E/R0001/Ceiling Structures/Linings/S6	2.71m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)

B00D - R0019 - Home Base Store (9.36 m2)

No Asbestos

B00D - R0020 - Withdrawal Space - 2hb (10.22 m2)

No Asbestos

B00D - R0021 - Practical Activities - 2hb (7.58 m2)

No Asbestos

B00D - R0022 - Home Base (57.06 m2)

No Asbestos

B00D - R0023 - External Movement (11.98 m2)

Ceiling Structures/Linings	Compressed AC Sheet 3796/B00E/R0001/Ceiling Structures/Linings/S6	11.98m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
----------------------------	----------------------------------------------------------------------	---------	------------	--------------------	---------	-------------------------------------------------------------------------------------

B00D - R0024 - External Movement (11.78 m2)

Ceiling Structures/Linings	Corrugated AC Sheeting 3796/B00E/R0001/Ceiling Structures/Linings/S6	11.78m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
----------------------------	-------------------------------------------------------------------------	---------	------------	--------------------	---------	-------------------------------------------------------------------------------------

B00D - R0025 - Home Base (56.97 m2)

No Asbestos

B00D - R0026 - Home Base Store (9.13 m2)

No Asbestos

B00D - R0027 - Withdrawal Space - 2hb (9.73 m2)

No Asbestos

B00D - R0028 - Practical Activities - 2hb (8.18 m2)

No Asbestos

B00D - R0029 - Home Base (56.03 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00D - R0030 - Home Base Store (4.14 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning - 1955 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting 3796/B00A/Eaves Linings/S1	18m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting 3796/B00A/Eaves Linings/S1	18m	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00E - R0001 - External Movement (9.06 m2)

Ceiling Structures/Linings	Flat AC Sheeting 3796/B00E/R0001/Ceiling Structures/Linings/S6	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
----------------------------	-------------------------------------------------------------------	------	--------------	--------------------	---------	-------------------------------------------------------------------------------------

B00E - R0002 - Cleaning Distributed Store (2.89 m2)

No Asbestos

B00E - R0009 - External Movement (60.56 m2)

No Asbestos

B00E - R0010 - External Movement (1.47 m2)

Ceiling Structures/Linings	Flat AC Sheeting 3796/B00E/R0001/Ceiling Structures/Linings/S6	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
----------------------------	-------------------------------------------------------------------	-----	--------------	--------------------	---------	-------------------------------------------------------------------------------------

B00E - R0022 - Home Base (55.5 m2)

Ceiling Structures/Linings	Vermiculite	56m2	All surfaces	Friable Asbestos (5)	Low (1)	Low Priority (2-3) Assumed Asbestos - Unable to safely sample
----------------------------	-------------	------	--------------	----------------------	---------	-------------------------------------------------------------------------

B00E - R0023 - Practical Activities - 1hb (13.51 m2)

Floor Coverings Res/Textile	Vinyl Tiles 3796/B00E/R0004/Floor Coverings Res/Textile/S7					No Asbestos Detected
Ceiling Structures/Linings	Vermiculite	14m2	All surfaces	Friable Asbestos (5)	Low (1)	Low Priority (2-3) Assumed Asbestos - Unable to safely sample

B00E - R0024 - Outdoor Learning Area (38.64 m2)

No Asbestos

B00E - R0025 - Practical Activities - 1hb (23.4 m2)

No Asbestos

B00E - R0026 - Home Base Store (4.81 m2)

No Asbestos

B00E - R0027 - Withdrawal Space - 1hb (8.51 m2)

No Asbestos

B00E - R0028 - Home Base (58.36 m2)

No Asbestos

B00E - R0029 - Home Base (50.6 m2)

No Asbestos

B00E - R0030 - Home Base Store (4.53 m2)

No Asbestos

B00E - R0031 - Withdrawal Space - 1hb (7.42 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00E - R0032 - Practical Activities - 1hb (25.72 m2)						
No Asbestos						
B00E - R0033 - External Movement (11.65 m2)						
No Asbestos						
B00E - R0034 - Practical Activities - 1hb (16.38 m2)						
No Asbestos						
B00E - R0035 - Home Base (75.4 m2)						
No Asbestos						
B00E - R0036 - Home Base Store (7.7 m2)						
No Asbestos						
B00E - R0037 - Withdrawal Space - 2hb (9.36 m2)						
No Asbestos						
B00E - R0038 - Practical Activities/Movement - 2hb (9.57 m2)						
No Asbestos						
B00E - R0039 - Home Base (56.47 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Pupil Facilities - 1976 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00F - R0001 - Drinking Facilities (8.45 m2)

No Asbestos

B00F - R0002 - Toilets - Boys (39.39 m2)

No Asbestos

B00F - R0003 - Cleaning Distributed Store (1.57 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Pupil Facilities - 1976 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00G - R0003 - Drinking Facilities (8.42 m2)

No Asbestos

B00G - R0004 - Toilets - Girls (41.28 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Other-After School Care/Community Use - 1976 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	40m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	3796/B00H/R0009/Ceiling Structures/Linings/S8					Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00H - R0001 - Cleaning Distributed Store (4.6 m2)

Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3796/B00H/R0009/Ceiling Structures/Linings/S8					Chrysotile (white asbestos)

B00H - R0002 - General Storeroom (9.26 m2)

No Asbestos

B00H - R0003 - General Storeroom (13.18 m2)

No Asbestos

B00H - R0004 - Movement (3.2 m2)

No Asbestos

B00H - R0005 - Out Of School Hours Care Centre (53.36 m2)

Floor Coverings Res/Textile	Vinyl Tiles					
	3796/B00H/R0005/Floor Coverings Res/Textile/S9					No Asbestos Detected

B00H - R0006 - Out Of School Hours Care Centre (53.15 m2)

No Asbestos

B00H - R0007 - General Storeroom (53.51 m2)

No Asbestos

B00H - R0008 - Sports Store (52.42 m2)

No Asbestos

B00H - R0009 - External Movement (72.08 m2)

Ceiling Structures/Linings	Flat AC Sheeting	73m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3796/B00H/R0009/Ceiling Structures/Linings/S8					Chrysotile (white asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B001 - General Learning/Communal Facilities - 1974 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	60m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	3796/B00A/Eaves Linings/S1					Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	20m	North facing, South facing, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	3796/B00I/R0013/Ceiling Structures/Linings/S10					Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B001 - R0001 - Cleaning Supplies (11.56 m2)

Ceiling Structures/Linings	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3796/B00I/R0013/Ceiling Structures/Linings/S10					Chrysotile (white asbestos) , Amosite (brown asbestos)

B001 - R0002 - Interview (12.32 m2)

Ceiling Structures/Linings	Flat AC Sheeting	13m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3796/B00I/R0013/Ceiling Structures/Linings/S10					Chrysotile (white asbestos) , Amosite (brown asbestos)

B001 - R0003 - Movement (52.45 m2)

Ceiling Structures/Linings	Flat AC Sheeting	10m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	3796/B00I/R0013/Ceiling Structures/Linings/S10					Chrysotile (white asbestos) , Amosite (brown asbestos)

B001 - R0004 - Practical Activities - 1hb (11.68 m2)

Ceiling Structures/Linings	Vermiculite	12m2	All surfaces	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
						Assumed Asbestos - Unable to sample safely

B001 - R0005 - Home Base (57.64 m2)

Ceiling Structures/Linings	Vermiculite	58m2	All surfaces	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
						Assumed Asbestos - Unable to sample safely

B001 - R0006 - Home Base (57.45 m2)

Ceiling Structures/Linings	Vermiculite	58m2	All surfaces	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
						Assumed Asbestos - Unable to sample safely

B001 - R0007 - Practical Activities - 1hb (11.68 m2)

Ceiling Structures/Linings	Vermiculite	12m2	All surfaces	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
						Assumed Asbestos - Unable to sample safely

B001 - R0008 - Distribution Board (0.44 m2)

No Asbestos Note: No inspection of live electrical installation.

B001 - R0009 - Cleaning Distributed Store (7.09 m2)

Ceiling Structures/Linings	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3796/B00I/R0013/Ceiling Structures/Linings/S10					Chrysotile (white asbestos) , Amosite (brown asbestos)

B001 - R0010 - External Movement (31.02 m2)

Ceiling Structures/Linings	Flat AC Sheeting	32m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3796/B00I/R0013/Ceiling Structures/Linings/S10					Chrysotile (white asbestos) , Amosite (brown asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
B00I - R0011 - Movement (17.48 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	18m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3796/B00I/R0013/Ceiling Structures/Linings/S10				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00I - R0012 - Craft Store (73.21 m2)						
No Asbestos						
B00I - R0013 - External Movement (34.22 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	35m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3796/B00I/R0013/Ceiling Structures/Linings/S10				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00I - R0014 - Toilets - Girls (33.87 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	34m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3796/B00I/R0013/Ceiling Structures/Linings/S10				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00I - R0015 - Toilets - Boys (35.15 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	36m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3796/B00I/R0013/Ceiling Structures/Linings/S10				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00I - R0016 - External Movement (41.45 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	42m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3796/B00I/R0013/Ceiling Structures/Linings/S10				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00I - R0017 - Raised Platform (35.34 m2)						
No Asbestos						
B00I - R0018 - Hall Chair Store (4.47 m2)						
No Asbestos						
B00I - R0019 - General Storeroom (4.18 m2)						
No Asbestos						
B00I - R0020 - Communal Space (246.81 m2)						
No Asbestos						
B00I - R0021 - P.E. Store (12.88 m2)						
No Asbestos						
B00I - R0022 - Canteen (43.58 m2)						
No Asbestos						
B00I - R0023 - Canteen Office/Store (7.08 m2)						
No Asbestos						
B00I - R0024 - Staff Toilet (3.58 m2)						
No Asbestos						
B00I - R0025 - Canteen Office/Store (2.71 m2)						
No Asbestos						
B00I - R0026 - Distribution Board (0.75 m2)				Note: No inspection of live electrical installation.		
No Asbestos						
B00I - R0027 - Kiln Room (6.09 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3796/B00I/R0013/Ceiling Structures/Linings/S10				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00I - R0028 - External Movement (22.15 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Ceiling Structures/Linings	Flat AC Sheeting	23m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3796/B001/R0013/Ceiling Structures/Linings/S10				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B001 - R0029 - Stairs (7.04 m2)						
No Asbestos						
B001 - R1001 - Practical Activities - 1hb (11.69 m2)						
Ceiling Structures/Linings	Vermiculite	12m2	All surfaces	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Unable to sample safely						
B001 - R1002 - Home Base (57.65 m2)						
Ceiling Structures/Linings	Vermiculite	58m2	All surfaces	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Unable to sample safely						
B001 - R1003 - Home Base (57.45 m2)						
Ceiling Structures/Linings	Vermiculite	58m2	All surfaces	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Unable to sample safely						
B001 - R1004 - Practical Activities - 1hb (11.69 m2)						
Ceiling Structures/Linings	Vermiculite	12m2	All surfaces	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Unable to sample safely						
B001 - R1005 - Distribution Board (0.41 m2)				Note: No inspection of live electrical installation.		
No Asbestos						
B001 - R1006 - Movement (40.83 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	41m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3796/B001/R0013/Ceiling Structures/Linings/S10				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B001 - R1007 - Stairs (14.42 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - General Learning/Pupil Facilities - 1966 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	20m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	3796/B00A/Eaves Linings/S1				Chrysotile (white asbestos)	
Gable Verge Lining	Flat AC Sheeting	18m	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	3796/B00J/R0019/Ceiling Structures/Linings/S4				Chrysotile (white asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00J - R0001 - Movement (4.63 m2)

Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3796/B00J/R0019/Ceiling Structures/Linings/S4				Chrysotile (white asbestos)	

B00J - R0005 - Home Base (56.75 m2)

No Asbestos

B00J - R0006 - Home Base (58.56 m2)

No Asbestos

B00J - R0008 - Personal Effects Storage (8.04 m2)

No Asbestos

B00J - R0016 - Home Base (57.22 m2)

No Asbestos

B00J - R0017 - Toilets - Girls (17.23 m2)

Ceiling Structures/Linings	Flat AC Sheeting	18m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3796/B00J/R0019/Ceiling Structures/Linings/S4				Chrysotile (white asbestos)	

Partition Walls (Cubicles)	Compressed AC Sheet	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3796/B00J/R0019/Partition Walls (Cubicles)/S5				Chrysotile (white asbestos)	

B00J - R0018 - Cleaning Distributed Store (1.31 m2)

Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3796/B00J/R0019/Ceiling Structures/Linings/S4				Chrysotile (white asbestos)	

B00J - R0019 - Toilets - Boys (19.45 m2)

Ceiling Structures/Linings	Flat AC Sheeting	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3796/B00J/R0019/Ceiling Structures/Linings/S4				Chrysotile (white asbestos)	

Partition Walls (Cubicles)	Compressed AC Sheet	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3796/B00J/R0019/Partition Walls (Cubicles)/S5				Chrysotile (white asbestos)	

B00J - R0021 - External Movement (2.88 m2)

Ceiling Structures/Linings	Compressed AC Sheet	2.88m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3796/B00J/R0019/Ceiling Structures/Linings/S4				Chrysotile (white asbestos)	

B00J - R0022 - Home Base Store (4.87 m2)

No Asbestos

B00J - R0023 - Practical Activities - 1hb (8.73 m2)

No Asbestos

B00J - R0026 - Home Base Store (9.75 m2)

No Asbestos

B00J - R0028 - Practical Activities - 2hb (9.75 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00J - R0029 - Home Base (56.36 m2)						
No Asbestos						
B00J - R0030 - External Movement (11.73 m2)						
Ceiling Structures/Linings	Compressed AC Sheet	11.7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3796/B00J/R0019/Ceiling Structures/Linings/S4					Chrysotile (white asbestos)	
B00J - R0031 - External Movement (2.88 m2)						
Ceiling Structures/Linings	Compressed AC Sheet	2.88m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3796/B00J/R0019/Ceiling Structures/Linings/S4					Chrysotile (white asbestos)	
B00J - R0032 - Practical Activities - 1hb (8.77 m2)						
No Asbestos						
B00J - R0033 - Home Base Store (4.69 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Administration - 1976 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids No Asbestos Found

Underfloor Voids No Asbestos Found

Interior

B00K - R0001 - General Assistant/Bulk Store (6.21 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Administration - 1975 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00L - R0001 - External Movement (12.9 m2)

No Asbestos

B00L - R0002 - Dental Clinic (14.48 m2)

No Asbestos

B00L - R0003 - Distribution Board (0.23 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00L - R0004 - Cleaning Distributed Store (3.64 m2)

No Asbestos

B00L - R0005 - Toilets - Boys/Girls (2.75 m2)

No Asbestos

B00L - R0006 - Staff Toilet (2.88 m2)

No Asbestos

B00L - R0007 - Dental Clinic (8.24 m2)

No Asbestos

B00L - R0008 - Dental Clinic (9.57 m2)

No Asbestos

B00L - R0009 - Dental Clinic (5.09 m2)

No Asbestos

B00L - R0010 - Dental Clinic (19.83 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

Available Asbestos Related Electronic Files

3796_ASB_261112_AMP.pdf

* Note : Refer to AMS for details of the attachment(s).

2017