

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Lismore Heights Public School (4085)
Region : North Coast
State Electorate : Lismore
Local Government Area : Lismore

Initial Survey : Noel Arnold & Associates : 11 - Jun - 2008
Reviewed By : Greencap-NAA : 14 - Apr - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/Staff Facilities - 1969 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	Non Accessible Area - Height Restriction 3m height
Underfloor Voids	No Asbestos Found

Interior

B00A - R0001 - Principal (17.17 m2)

No Asbestos

B00A - R0004 - Clerical Office (12.77 m2)

No Asbestos

B00A - R0006 - Sick Bay (8.26 m2)

Floor Coverings Res/Textile	Vinyl Tiles					
	4085/B00A/R0007/Floor Coverings Res/Textile/S8					No Asbestos Detected

B00A - R0007 - Duplicating Workroom (22.3 m2)

Floor Coverings Res/Textile	Vinyl Tiles					
	4085/B00A/R0007/Floor Coverings Res/Textile/S8					No Asbestos Detected

B00A - R0008 - Interview (11.26 m2)

No Asbestos

B00A - R0010 - Deputy Principal (11.36 m2)

No Asbestos

B00A - R0011 - Deputy Principal (11.3 m2)

No Asbestos

B00A - R0012 - Cleaning Distributed Store (1.29 m2)

No Asbestos

B00A - R0014 - Distribution Board (0.49 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0016 - General Storeroom (22.76 m2)

No Asbestos

B00A - R0017 - External Movement (57.4 m2)

Ceiling Structures/Linings	Flat AC Sheeting	57m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4085/B00A/R0017/Ceiling Structures/Linings/S26					Chrysotile (white asbestos)
Infill panels	Compressed AC Sheet	12m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	4085/B00B/R0011/Infill panels/S23					Chrysotile (white asbestos)

B00A - R0018 - External Movement (41.99 m2)

Ceiling Structures/Linings	Flat AC Sheeting	42m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4085/B00A/R0017/Ceiling Structures/Linings/S26					Chrysotile (white asbestos)

B00A - R0019 - External Movement (5.58 m2)

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4085/B00A/R0017/Ceiling Structures/Linings/S26					Chrysotile (white asbestos)

B00A - R0020 - Entry Vestibule (15.35 m2)

No Asbestos

B00A - R0021 - Movement (10.2 m2)

No Asbestos

B00A - R0022 - Movement (21.31 m2)

No Asbestos

B00A - R0023 - Toilet - Lobby (2.28 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00A - R0024 - Toilet - Lobby (3.17 m2)

No Asbestos

B00A - R0025 - Staff Toilet (1.38 m2)

No Asbestos

B00A - R0026 - Staff Toilet (1.92 m2)

No Asbestos

B00A - R0027 - Staff Kitchen (10.25 m2)

No Asbestos

B00A - R0028 - Staff Room (41.93 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 1956 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground Non Accessible Area
- Area inaccessible

Ceiling Voids No Asbestos Found

Interior

B00B - R0001 - Toilets - Boys/Girls (3.66 m2)

No Asbestos

B00B - R0002 - Practical Activities - 1hb (10.49 m2)

No Asbestos

B00B - R0003 - Home Base Store (4.1 m2)

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4085/B00B/R0003/Ceiling Structures/Linings/S22					Chrysotile (white asbestos)	

B00B - R0004 - Home Base (85.86 m2)

No Asbestos

B00B - R0005 - Home Base (56.56 m2)

No Asbestos

B00B - R0006 - Home Base Store (4.08 m2)

No Asbestos

B00B - R0007 - Practical Activities - 1hb (9.7 m2)

No Asbestos

B00B - R0008 - Home Base Store (4.05 m2)

No Asbestos

B00B - R0009 - Practical Activities - 1hb (9.97 m2)

No Asbestos

B00B - R0010 - Home Base (56.41 m2)

No Asbestos

B00B - R0011 - External Movement (53.2 m2)

Ceiling Structures/Linings	Flat AC Sheeting	4085/B00B/R0011/Ceiling Structures/Linings/S21			No Asbestos Detected	
Infill panels	Compressed AC Sheet	12Unit	South	Good Condition (1)	Low (1)	Low Priority (2-3)
4085/B00B/R0011/Infill panels/S23					Chrysotile (white asbestos)	

B00B - R0012 - External Movement (59.74 m2)

Ceiling Structures/Linings	Flat AC Sheeting	4085/B00B/R0011/Ceiling Structures/Linings/S21			No Asbestos Detected	
----------------------------	------------------	--	--	--	-----------------------------	--



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning/Pupil Facilities - 1969 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Ceiling Voids	No Asbestos Found					
Gable Verge Lining	Flat AC Sheeting	30m	North & South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4085/B00C/Gable Verge Lining/S24					Chrysotile (white asbestos)

Interior

B00C - R0001 - External Movement (95.98 m2)

No Asbestos

B00C - R0002 - General Storeroom (5.89 m2)

No Asbestos

B00C - R0003 - General Storeroom (9.4 m2)

No Asbestos

B00C - R0004 - Toilets - Girls (22.57 m2)

Ceiling Structures/Linings	Vermiculite 4085/B00C/R0005/Ceiling Structures/Linings/S9					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
----------------------------	--	--	--	--	--	---

Partition Walls (Cubicles)	Compressed AC Sheet	16m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	4085/B00C/R0005/Partition Walls (Cubicles)/S10					Chrysotile (white asbestos)

B00C - R0005 - Toilets - Boys (31.85 m2)

Ceiling Structures/Linings	Vermiculite 4085/B00C/R0005/Ceiling Structures/Linings/S9					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
----------------------------	--	--	--	--	--	---

Partition Walls (Cubicles)	Compressed AC Sheet	12m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	4085/B00C/R0005/Partition Walls (Cubicles)/S10					Chrysotile (white asbestos)

B00C - R0006 - Distribution Board (0.89 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0007 - Cleaning Distributed Store (5.71 m2)

No Asbestos

B00C - R0008 - External Movement (5.57 m2)

No Asbestos

B00C - R0009 - External Stairs (12.28 m2)

No Asbestos

B00C - R1001 - External Movement (40.63 m2)

Ceiling Structures/Linings	Flat AC Sheeting	41m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4085/B00C/R1001/Ceiling Structures/Linings/S25					Chrysotile (white asbestos)

Infill panels	Compressed AC Sheet	16m2	East & West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4085/B00B/R0011/Infill panels/S23					Chrysotile (white asbestos)

B00C - R1002 - Home Base (56.64 m2)

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	57m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4085/B00C/R0006/Floor Coverings Res/Textile/S7					Chrysotile (white asbestos)

B00C - R1003 - Home Base Store (3.89 m2)

Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4085/B00C/R0006/Floor Coverings Res/Textile/S7					Chrysotile (white asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00C - R1004 - Practical Activities - 1hb (10.12 m2)						
No Asbestos						
B00C - R1005 - Practical Activities - 1hb (10.12 m2)						
No Asbestos						
B00C - R1006 - Home Base Store (3.89 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4085/B00C/R0006/Floor Coverings Res/Textile/S7					Chrysotile (white asbestos)	
B00C - R1007 - Home Base (56.72 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	57m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4085/B00C/R0006/Floor Coverings Res/Textile/S7					Chrysotile (white asbestos)	
B00C - R1008 - External Stairs (12.28 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4085/B00C/R1001/Ceiling Structures/Linings/S25					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning/Library - 1969 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting 4085/B00D/Eaves Linings/S18	50m2	North, South, Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Ceiling Voids	Non Accessible Area - Height Restriction 3m height					
Underfloor Voids	No Asbestos Found					

Interior

B00D - R0001 - K.L.A. Store (13.25 m2)

No Asbestos

B00D - R0002 - Library Office/Workroom (22.12 m2)

No Asbestos

B00D - R0003 - Reading Area (155.03 m2)

No Asbestos

B00D - R0004 - Movement (8.82 m2)

No Asbestos

B00D - R0005 - Seminar/Study (12.39 m2)

No Asbestos

B00D - R0006 - Seminar/Study (12.67 m2)

No Asbestos

B00D - R0007 - Home Base (60.46 m2)

No Asbestos

B00D - R0008 - Distribution Board (0.38 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0009 - Practical Activities - 1hb (32.39 m2)

No Asbestos

B00D - R0010 - Home Base (59.3 m2)

No Asbestos

B00D - R0011 - External Movement (17.99 m2)

No Asbestos

B00D - R0012 - External Movement (15.39 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00E - General Learning - 1969 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	160m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4085/B00E/Eaves Linings/S12					Chrysotile (white asbestos)
Ceiling Voids	Non Accessible Area - Height Restriction 4m height					
Underfloor Voids	No Asbestos Found					

Interior

B00E - R0001 - Home Base (53.15 m2)

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4085/B00E/R0001/Floor Coverings Res/Textile/S13					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive					No Asbestos Detected
	4085/B00E/R0001/Floor Coverings Res/Textile/S14					

B00E - R0002 - Staff Toilet (2.09 m2)

Wall Linings Internal	Compressed AC Sheet	10m2	Throughout, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4085/B00E/R0002/Wall Linings Internal/S1					Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4085/B00E/R0002/Wall Linings Internal/S1					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00E - R0003 - Practical Activities - 1hb (31.11 m2)

No Asbestos

B00E - R0004 - Home Base (52.71 m2)

No Asbestos

B00E - R0005 - Movement (37.08 m2)

No Asbestos

B00E - R0006 - Withdrawal Space - 1hb (39.34 m2)

No Asbestos

B00E - R0008 - Staff Room Annexe (9.55 m2)

Wall Linings Internal	Flat AC Sheeting	22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4085/B00E/R0008/Wall Linings Internal/S16					Chrysotile (white asbestos)

B00E - R0009 - Staff Toilet (4.22 m2)

Wall Linings Internal	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4085/B00E/R0008/Wall Linings Internal/S16					Chrysotile (white asbestos)

B00E - R0010 - Practical Activities - 1hb (37.33 m2)

Ceiling Structures/Linings	Flat AC Sheeting	37m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4085/B00E/R0014/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)

B00E - R0011 - Home Base (52.31 m2)

No Asbestos

B00E - R0012 - Home Base (53.44 m2)

Floor Coverings Res/Textile	Adhesive					No Asbestos Detected
	4085/B00E/R0001/Floor Coverings Res/Textile/S14					
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4085/B00E/R0001/Floor Coverings Res/Textile/S13					Chrysotile (white asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00E - R0013 - Home Base (53.44 m2)						
Floor Coverings Res/Textile	Adhesive					
	4085/B00E/R0001/Floor Coverings Res/Textile/S14					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4085/B00E/R0001/Floor Coverings Res/Textile/S13					Chrysotile (white asbestos)
B00E - R0014 - Practical Activities - 1hb (33.67 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	34m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4085/B00E/R0014/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)
B00E - R0015 - Home Base (53.37 m2)						
Floor Coverings Res/Textile	Adhesive					
	4085/B00E/R0001/Floor Coverings Res/Textile/S14					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4085/B00E/R0001/Floor Coverings Res/Textile/S13					Chrysotile (white asbestos)
B00E - R0016 - General Storeroom (8.33 m2)						
Floor Coverings Res/Textile	Vinyl Tiles					
	4085/B00E/R0018/Floor Coverings Res/Textile/S2					No Asbestos Detected
B00E - R0017 - Cleaning Distributed Store (3.09 m2)						
Floor Coverings Res/Textile	Vinyl Tiles					
	4085/B00E/R0018/Floor Coverings Res/Textile/S2					No Asbestos Detected
B00E - R0018 - Withdrawal Space - 1hb (14.48 m2)						
Floor Coverings Res/Textile	Vinyl Tiles					
	4085/B00E/R0018/Floor Coverings Res/Textile/S2					No Asbestos Detected
B00E - R0019 - Distribution Board (0.74 m2)						
						Note: No inspection of live electrical installation.
Wall Linings Internal	Compressed AC Sheet	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4085/B00E/R0019/Wall Linings Internal/S15					Chrysotile (white asbestos)
B00E - R0022 - Disabled Toilet (7.42 m2)						
No Asbestos						
B00E - R0023 - Movement (1.14 m2)						
No Asbestos						
B00E - R0024 - External Movement (58.55 m2)						
No Asbestos						
B00E - R0025 - Movement (2.21 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4085/B00E/R0025/Ceiling Structures/Linings/S17					Chrysotile (white asbestos)
B00E - R0026 - Stairs (11.6 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4085/B00E/R0025/Ceiling Structures/Linings/S17					Chrysotile (white asbestos)
B00E - R9001 - General Storeroom (10.52 m2)						
No Asbestos						
B00E - R9002 - Plant (41.37 m2)						
No Asbestos						
B00E - R9003 - General Assistant/Bulk Store (12.41 m2)						
No Asbestos						
B00E - R9004 - External Movement (76.25 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
No Asbestos						
B00E - R9005 - Staff Toilet (2.53 m2)						
Floor Coverings Res/Textile	Vinyl Tiles					
	4085/B00E/R9007/Floor Coverings Res/Textile/S6					No Asbestos Detected
B00E - R9006 - General Storeroom (24.72 m2)						
Floor Coverings Res/Textile	Vinyl Tiles					
	4085/B00E/R9007/Floor Coverings Res/Textile/S6					No Asbestos Detected
B00E - R9007 - Out Of School Hours Care Centre (7.74 m2)						
Floor Coverings Res/Textile	Vinyl Tiles					
	4085/B00E/R9007/Floor Coverings Res/Textile/S6					No Asbestos Detected
B00E - R9008 - Movement (5.4 m2)						
No Asbestos						
B00E - R9009 - Movement (13.61 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4085/B00E/R9009/Wall Linings Internal/S11					Chrysotile (white asbestos) , Amosite (brown asbestos)
Wall Linings Internal	Flat AC Sheeting	50m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4085/B00E/R9009/Wall Linings Internal/S11					Chrysotile (white asbestos) , Amosite (brown asbestos)
B00E - R9011 - Toilets - Girls (12.04 m2)						
Wall Linings Internal	Flat AC Sheeting	34m2	North, South, East, Throughout, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4085/B00E/R9011/Wall Linings Internal/S4					Chrysotile (white asbestos)
B00E - R9012 - Toilets - Boys (13.82 m2)						
Wall Linings Internal	Flat AC Sheeting	34m2	North, South, West, Throughout, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4085/B00E/R9011/Wall Linings Internal/S4					Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4085/B00E/R9011/Wall Linings Internal/S4					Chrysotile (white asbestos)
B00E - R9013 - No Access (1.32 m2)						
No Asbestos						
B00E - R9014 - Kiln Room (7.05 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4085/B00E/R9009/Wall Linings Internal/S11					Chrysotile (white asbestos) , Amosite (brown asbestos)
Wall Linings Internal	Flat AC Sheeting	8m2	Throughout, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4085/B00E/R9009/Wall Linings Internal/S11					Chrysotile (white asbestos) , Amosite (brown asbestos)
B00E - R9015 - Movement (54.27 m2)						
Wall Linings Internal	Flat AC Sheeting	40m2	Throughout, Lower portion, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	4085/B00E/R9009/Wall Linings Internal/S11					Chrysotile (white asbestos) , Amosite (brown asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4085/B00E/R9009/Wall Linings Internal/S11				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00E - R9016 - Drinking Facilities (5.73 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4085/B00E/R0014/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)		
Wall Linings Internal	Flat AC Sheeting	8m2	Throughout, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
4085/B00E/R9009/Wall Linings Internal/S11				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00E - R9017 - External Stairs (14.04 m2)						
No Asbestos						
B00E - R9018 - Drinking Facilities (2.26 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Communal Facilities - 1982 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Ceiling Voids	Non Accessible Area - Height Restriction 4m height					

Interior

B00F - R0001 - External Movement (166.96 m2)

Ceiling Structures/Linings	Flat AC Sheeting	167m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4085/B00F/R0001/Ceiling Structures/Linings/S19					Chrysotile (white asbestos)	

B00F - R0002 - Cleaning Distributed Store (6.1 m2)

No Asbestos

B00F - R0003 - Staff Toilet (3.62 m2)

No Asbestos

B00F - R0004 - Canteen Office/Store (5.36 m2)

No Asbestos

B00F - R0005 - Canteen Office/Store (2.78 m2)

No Asbestos

B00F - R0006 - Canteen (27.39 m2)

No Asbestos

B00F - R0007 - General Assistant/Bulk Store (13.71 m2)

No Asbestos

B00F - R0008 - General Storeroom (5.4 m2)

No Asbestos

B00F - R0009 - Toilets - Boys (8.28 m2)

No Asbestos

B00F - R0010 - Music Store (4.19 m2)

No Asbestos

B00F - R0011 - Communal Space (164.17 m2)

No Asbestos

B00F - R0012 - Hall Chair Store (4.19 m2)

No Asbestos

B00F - R0013 - Raised Platform (35.73 m2)

No Asbestos

B00F - R0014 - Movement (28.39 m2)

No Asbestos

B00F - R0015 - Toilets - Girls (8.25 m2)

No Asbestos

B00F - R0016 - Sports Store (12.51 m2)

No Asbestos

B00F - R0017 - Distribution Board (0.39 m2)

Note: No inspection of live electrical installation.

Electrical Backing Board	Resinous Board	1Unit	East	Good Condition (1)	Low (1)	Low Priority (2-3)
--------------------------	----------------	-------	------	--------------------	---------	--------------------

Assumed Asbestos - Electrical Hazard

Door lining	Flat AC Sheeting	1Unit	West	Good Condition (1)	Low (1)	Low Priority (2-3)
4085/B00F/R0017/Door lining/S20					Chrysotile (white asbestos)	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00G - R0001 - External Movement (78.57 m2)

No Asbestos

B00G - R0002 - Access Shower/Toilet/Change (7.94 m2)

No Asbestos

B00G - R0003 - Toilets - Boys (17.44 m2)

No Asbestos

B00G - R0004 - Toilets - Girls (29.56 m2)

No Asbestos

B00G - R0005 - Cleaning Distributed Store (4.17 m2)

No Asbestos

B00G - R0006 - Home Base - P (5.4 m2)

No Asbestos

B00G - R0007 - Special Programs Room (38.49 m2)

No Asbestos

B00G - R0008 - Practical Activities - 1hb (19.09 m2)

No Asbestos

B00G - R0009 - Home Base Store (6.35 m2)

No Asbestos

B00G - R0010 - Home Base (60.8 m2)

No Asbestos

B00G - R0011 - Withdrawal Space - 1hb (11.7 m2)

No Asbestos

B00G - R0012 - Home Base (60.74 m2)

No Asbestos

B00G - R0013 - Home Base Store (6.32 m2)

No Asbestos

B00G - R0014 - Practical Activities - 1hb (19.06 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017