

# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Loftus Public School (4221)  
**Region :** Sydney  
**State Electorate :** Heathcote  
**Local Government Area :** Sutherland

**Initial Survey :** Noel Arnold & Associates : 21 - Mar - 2008  
**Reviewed By :** Parsons Brinckerhoff : 01 - Nov - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - Administration/Staff Facilities - 1950 - Brick/Block (Brick/Block)****Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting 4221/B00A/Eaves Linings/S19	10m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Infill panel below window	Flat AC Sheeting 4221/B00B/R1001/In-fill panel below window/S14	8m	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Gable verge lining	Flat AC Sheeting 4221/B00A/Gable verge lining/S22	15m	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Ceiling Void	No Asbestos Found					

**Interior****B00A - R0001 - Duplicating Workroom (16.64 m2)**

Ceiling Structures/Linings	Vermiculite 4221/B00A/R9004/Ceiling Structures/Linings/S16					Limited Samples Taken <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
----------------------------	---	--	--	--	--	--

**B00A - R0002 - Clerical Office (11.79 m2)**

Ceiling Structures/Linings	Vermiculite 4221/B00A/R9004/Ceiling Structures/Linings/S16					Limited Samples Taken <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
----------------------------	---	--	--	--	--	--

**B00A - R0003 - Entry Vestibule (10.27 m2)**

Ceiling Structures/Linings	Vermiculite 4221/B00A/R9004/Ceiling Structures/Linings/S16					Limited Samples Taken <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
----------------------------	---	--	--	--	--	--

**B00A - R0004 - General Storeroom (5.45 m2)**

Ceiling Structures/Linings	Vermiculite 4221/B00A/R9004/Ceiling Structures/Linings/S16					Limited Samples Taken <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
----------------------------	---	--	--	--	--	--

**B00A - R0005 - Deputy Principal (11.55 m2)**

Ceiling Structures/Linings	Vermiculite 4221/B00A/R9004/Ceiling Structures/Linings/S16					Limited Samples Taken <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
----------------------------	---	--	--	--	--	--

**B00A - R0006 - Sick Bay (13.1 m2)**

Ceiling Structures/Linings	Vermiculite 4221/B00A/R9004/Ceiling Structures/Linings/S16					Limited Samples Taken <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
----------------------------	---	--	--	--	--	--

**B00A - R0007 - Movement (3.15 m2)**

Ceiling Structures/Linings	Vermiculite 4221/B00A/R9004/Ceiling Structures/Linings/S16					Limited Samples Taken <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
----------------------------	---	--	--	--	--	--

**B00A - R0008 - Principal (16.03 m2)**

Ceiling Structures/Linings	Vermiculite 4221/B00A/R9004/Ceiling Structures/Linings/S16					Limited Samples Taken <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
----------------------------	---	--	--	--	--	--

**B00A - R0009 - Staff Toilet (3.56 m2)**

Ceiling Structures/Linings	Vermiculite 4221/B00A/R9004/Ceiling Structures/Linings/S16					Limited Samples Taken <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
----------------------------	---	--	--	--	--	--

**B00A - R0010 - Distribution Board (0.51 m2)**

Note: No inspection of live electrical installation.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite					
	4221/B00A/R9004/Ceiling Structures/Linings/S16					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00A - R001 - Movement (56.68 m2)</b>						
No Asbestos						
<b>B00A - R9001 - Movement (1.17 m2)</b>						
No Asbestos						
<b>B00A - R9002 - Security Store (28.76 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	4221/B00A/R9004/Ceiling Structures/Linings/S16					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00A - R9003 - Special Programs Room (44.34 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	4221/B00A/R9004/Ceiling Structures/Linings/S16					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00A - R9004 - Staff Kitchen (8.38 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	4221/B00A/R9004/Ceiling Structures/Linings/S16					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4221/B00A/R9007/Floor Coverings Res/Textile/S17					Chrysotile (white asbestos)
<b>B00A - R9005 - Staff Toilet (5.27 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	4221/B00A/R9004/Ceiling Structures/Linings/S16					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00A - R9006 - Cleaning Distributed Store (1.34 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	4221/B00A/R9004/Ceiling Structures/Linings/S16					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4221/B00A/R9007/Floor Coverings Res/Textile/S17					Chrysotile (white asbestos)
<b>B00A - R9007 - Movement (4.13 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4221/B00A/R9007/Floor Coverings Res/Textile/S17					Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite					
	4221/B00A/R9004/Ceiling Structures/Linings/S16					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00A - R9008 - Staff Toilet (3.41 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	4221/B00A/R9004/Ceiling Structures/Linings/S16					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00A - R9009 - Movement (3.72 m2)</b>						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - General Learning/Pupil Facilities - 1950 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	10m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	4221/B00J/Eaves Linings/S20				<b>Chrysotile (white asbestos)</b>	
Infill panel below window	Flat AC Sheeting	24m	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	4221/B00B/R1001/In-fill panel below window/S14				<b>Chrysotile (white asbestos)</b>	
Ceiling Void	No Asbestos Found					

**Interior**

**B00B - R0001 - Movement (79.58 m2)**

In-fill panel below window	Flat AC Sheeting	7m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	4221/B00B/R1001/In-fill panel below window/S14				<b>Chrysotile (white asbestos)</b>	

**B00B - R0004 - Communal Space (55.97 m2)**

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4221/B00B/R0002/Ceiling Structures/Linings/S12				<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>	
Floor Coverings Res/Textile	Vinyl Tiles	56m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4221/B00B/R0004/Floor Coverings Res/Textile/S13				<b>Chrysotile (white asbestos)</b>	

**B00B - R0005 - Toilets - Boys (22.16 m2)**

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4221/B00B/R0002/Ceiling Structures/Linings/S12				<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>	
Partition Walls (Cubicles)	Compressed AC Sheet	6m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	4221/B00B/R1005/Partition Walls (Cubicles)/S15				<b>Chrysotile (white asbestos)</b>	

**B00B - R0006 - Cleaning Distributed Store (3.18 m2)**

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4221/B00B/R0002/Ceiling Structures/Linings/S12				<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>	

**B00B - R0007 - Distribution Board (2.48 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00B - R0008 - Stairs (5.82 m2)**

No Asbestos

**B00B - R0009 - Home Base (58.57 m2)**

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4221/B00B/R0010/Ceiling Structures/Linings/S29				<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>	

**B00B - R0010 - Home Base (56.86 m2)**

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4221/B00B/R0010/Ceiling Structures/Linings/S29				<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>	

**B00B - R1001 - Movement (65.13 m2)**

In-fill panel below window	Flat AC Sheeting	9m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	4221/B00B/R1001/In-fill panel below window/S14				<b>Chrysotile (white asbestos)</b>	

**B00B - R1002 - Home Base (57.09 m2)**

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4221/B00B/R0002/Ceiling Structures/Linings/S12				<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00B - R1003 - Home Base (56.06 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	4221/B00B/R0002/Ceiling Structures/Linings/S12					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00B - R1004 - Home Base (55.83 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	4221/B00B/R0002/Ceiling Structures/Linings/S12					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00B - R1005 - Toilets - Girls (22.49 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	4221/B00B/R0002/Ceiling Structures/Linings/S12					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Partition Walls (Cubicles)	Compressed AC Sheet	6m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	4221/B00B/R1005/Partition Walls (Cubicles)/S15					Chrysotile (white asbestos)
<b>B00B - R1006 - Cleaning Distributed Store (2.49 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	4221/B00B/R0002/Ceiling Structures/Linings/S12					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00B - R1007 - Distribution Board (2.51 m2)</b>				Note: No inspection of live electrical installation.		
No Asbestos						
<b>B00B - R1008 - Stairs (14.86 m2)</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - Support Unit/Library - 1950 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting 4221/B00J/Eaves Linings/S20	60m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Gable verge lining	Flat AC Sheeting 4221/B00J/Gable verge lining/S23	20m	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Underfloor Voids	Flat AC Sheeting 4221/B00C/Underfloor Voids/S24	1m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5) <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
Ceiling Void	No Asbestos Found					

**Interior**

**B00C - R0001 - Home Base - E (44.84 m2)**

Ceiling Structures/Linings	Vermiculite 4221/B00C/R0004/Ceiling Structures/Linings/S9	<b>Limited Samples Taken</b> <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>				
----------------------------	--	---	--	--	--	--

**B00C - R0002 - Practical Activities - E (10.26 m2)**

Ceiling Structures/Linings	Vermiculite 4221/B00C/R0004/Ceiling Structures/Linings/S9	<b>Limited Samples Taken</b> <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>				
----------------------------	--	---	--	--	--	--

**B00C - R0003 - Home Base Store - E (4.06 m2)**

Ceiling Structures/Linings	Vermiculite 4221/B00C/R0004/Ceiling Structures/Linings/S9	<b>Limited Samples Taken</b> <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>				
----------------------------	--	---	--	--	--	--

**B00C - R0004 - Toilet - E (9.06 m2)**

Ceiling Structures/Linings	Vermiculite 4221/B00C/R0004/Ceiling Structures/Linings/S9	<b>Limited Samples Taken</b> <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>				
----------------------------	--	---	--	--	--	--

**B00C - R0005 - Home Base Store - E (4.06 m2)**

Ceiling Structures/Linings	Vermiculite 4221/B00C/R0004/Ceiling Structures/Linings/S9	<b>Limited Samples Taken</b> <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>				
----------------------------	--	---	--	--	--	--

Wall Linings Internal	Flat AC Sheeting 4221/B00C/R0005/Wall Linings Internal/S10	<b>No Asbestos Detected</b>				
-----------------------	---	-----------------------------	--	--	--	--

**B00C - R0006 - Home Base - E (55.8 m2)**

No Asbestos

**B00C - R0007 - Movement (5.97 m2)**

No Asbestos

**B00C - R0009 - Movement (18.3 m2)**

No Asbestos

**B00C - R1001 - Reading Area (111.48 m2)**

No Asbestos

**B00C - R1002 - Movement (6 m2)**

Floor Coverings Res/Textile	Vinyl Tiles 4221/B00C/R1002/Floor Coverings Res/Textile/S11	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
-----------------------------	--	-----	--------------	--------------------	---------	--

**B00C - R1003 - Library Office/Workroom (20.97 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - General Learning/Other-After School Care - 1950 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting	40m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4221/B00J/Eaves Linings/S20					<b>Chrysotile (white asbestos)</b>
Gable verge lining	Flat AC Sheeting	40m	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4221/B00J/Gable verge lining/S23					<b>Chrysotile (white asbestos)</b>
Ceiling Void	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior****B00D - R0001 - Movement (4.81 m2)**

No Asbestos

**B00D - R0002 - Personal Effects Storage (3.11 m2)**

No Asbestos

**B00D - R0003 - Toilets - Boys/Girls (3.1 m2)**

No Asbestos

**B00D - R0004 - General Storeroom (6.98 m2)**

No Asbestos

**B00D - R0005 - Home Base (56.81 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4221/B00D/R0005/Ceiling Structures/Linings/S7					<b>Chrysotile (white asbestos)</b>

**B00D - R0006 - Home Base (57.03 m2)**

No Asbestos

**B00D - R0007 - General Storeroom (7.4 m2)**

No Asbestos

**B00D - R0008 - Personal Effects Storage (2.99 m2)**

No Asbestos

**B00D - R0009 - Movement (5.77 m2)**

No Asbestos

**B00D - R0011 - Personal Effects Storage (2.99 m2)**

No Asbestos

**B00D - R0012 - Home Base Store (7.4 m2)**

No Asbestos

**B00D - R0013 - Home Base (57.45 m2)**

No Asbestos

**B00D - R0014 - Movement (11.28 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4221/B00D/R0005/Ceiling Structures/Linings/S7					<b>Chrysotile (white asbestos)</b>

**B00D - R9001 - Craft Store (3.2 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4221/B00D/R9005/Floor Coverings Res/Textile/S8					<b>Chrysotile (white asbestos)</b>

**B00D - R9002 - General Storeroom (23.5 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	3m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4221/B00D/R9005/Floor Coverings Res/Textile/S8					<b>Chrysotile (white asbestos)</b>

**B00D - R9003 - Special Programs Room (56.61 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00D - R9004 - Movement (3.68 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4221/B00D/R9005/Floor Coverings Res/Textile/S8					<b>Chrysotile (white asbestos)</b>	
<b>B00D - R9005 - General Storeroom (1.58 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4221/B00D/R9005/Floor Coverings Res/Textile/S8					<b>Chrysotile (white asbestos)</b>	
<b>B00D - R9006 - General Storeroom (0.73 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4221/B00D/R9005/Floor Coverings Res/Textile/S8					<b>Chrysotile (white asbestos)</b>	

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - General Learning - 1950 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting 4221/B00J/Eaves Linings/S20	90m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>
Gable verge lining	Flat AC Sheeting 4221/B00J/Gable verge lining/S23	20m	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>
Ceiling Void	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior****B00E - R0001 - Home Base (56.93 m2)**

No Asbestos

**B00E - R0002 - Home Base Store (6.32 m2)**

No Asbestos

**B00E - R0003 - Personal Effects Storage (7.67 m2)**

No Asbestos

**B00E - R0004 - Movement (6.39 m2)**

No Asbestos

**B00E - R0006 - Home Base Store (6.32 m2)**

No Asbestos

**B00E - R0007 - Home Base (57.16 m2)**

No Asbestos

**B00E - R0008 - Movement (7.1 m2)**

Ceiling Structures/Linings	Flat AC Sheeting 4221/B00F/R0008/Ceiling Structures/Linings/S5					<b>No Asbestos Detected</b>
----------------------------	---	--	--	--	--	-----------------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - General Learning - 1950 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Void	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00F - R0001 - Home Base (57.15 m2)**

No Asbestos

**B00F - R0002 - Personal Effects Storage (10.33 m2)**

No Asbestos

**B00F - R0003 - Movement (12.85 m2)**

No Asbestos

**B00F - R0005 - Uniform Shop (21.16 m2)**

Floor Coverings Res/Textile	Vinyl Sheet					
		4221/B00F/R0005/Floor Coverings Res/Textile/S28				<b>No Asbestos Detected</b>

**B00F - R0006 - Personal Effects Storage (10.37 m2)**

Wall Linings Internal	Flat AC Sheeting	1m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
		4221/B00F/R0006/Wall Linings Internal/S4				<b>Chrysotile (white asbestos)</b>

**B00F - R0007 - Home Base (57.05 m2)**

No Asbestos

**B00F - R0008 - Movement (9.54 m2)**

Ceiling Structures/Linings	Flat AC Sheeting					
		4221/B00F/R0008/Ceiling Structures/Linings/S5				<b>No Asbestos Detected</b>

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - General Learning - 1950 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting 4221/B00J/Eaves Linings/S20	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Gable verge lining	Flat AC Sheeting 4221/B00J/Gable verge lining/S23	20m	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Underfloor Voids	AC Fragments/Debris 4221/B00G/Underfloor Voids/S26	1m2	Variable positions	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5) <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
Ceiling Void	No Asbestos Found					

**Interior****B00G - R0001 - Withdrawal Space - 1hb (21.85 m2)**

No Asbestos

**B00G - R0002 - Disabled Shower/Toilet (4.11 m2)**

Wall Linings Internal	Flat AC Sheeting 4221/B00G/R0002/Wall Linings Internal/S2	<b>No Asbestos Detected</b>				
-----------------------	--	-----------------------------	--	--	--	--

**B00G - R0004 - Movement (7.69 m2)**

No Asbestos

**B00G - R0005 - Personal Effects Storage (11.06 m2)**

No Asbestos

**B00G - R0006 - Home Base (63.35 m2)**

No Asbestos

**B00G - R0007 - Practical Activities - 1hb (0.81 m2)**

No Asbestos

**B00G - R0008 - Home Base (85.57 m2)**

No Asbestos

**B00G - R0009 - Practical Activities - 1hb (2.11 m2)**

No Asbestos

**B00G - R0010 - Personal Effects Storage (11.38 m2)**

No Asbestos

**B00G - R0011 - Cleaning Distributed Store (2.87 m2)**

No Asbestos

**B00G - R0012 - Movement (20.29 m2)**

No Asbestos

**B00G - R0013 - Movement (3.02 m2)**

No Asbestos

**B00G - R0014 - General Storeroom (1.83 m2)**

No Asbestos

**B00G - R0015 - Deputy Principal (17.36 m2)**

No Asbestos

**B00G - R0016 - Movement (21.28 m2)**

Infill panel below window	Flat AC Sheeting 4221/B00G/R0016/Infill panel below window/S3	<b>No Asbestos Detected</b>				
---------------------------	--	-----------------------------	--	--	--	--

**B00G - R0017 - Movement (33.93 m2)**

No Asbestos

**B00G - R9001 - No Access (35.68 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - General Learning - 1950 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting 4221/B00J/Eaves Linings/S20	40m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>
Gable verge lining	Flat AC Sheeting 4221/B00J/Gable verge lining/S23	15m	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>
Ceiling Void	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior**

**B00H - R0001 - Home Base (57.01 m2)**

No Asbestos

**B00H - R0002 - Home Base Store (5.52 m2)**

No Asbestos

**B00H - R0003 - General Storeroom (5.47 m2)**

No Asbestos

**B00H - R0004 - Personal Effects Storage (10.33 m2)**

No Asbestos

**B00H - R0005 - Movement (6.48 m2)**

No Asbestos

**B00H - R0007 - Movement (10.55 m2)**

Ceiling Structures/Linings	Flat AC Sheeting 4221/B00J/R0022/Ceiling Structures/Linings/S1	4m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00J - General Learning/Pupil Facilities - 1950 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting	40m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4221/B00J/Eaves Linings/S20					<b>Chrysotile (white asbestos)</b>
Gable verge lining	Flat AC Sheeting	15m	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4221/B00J/Gable verge lining/S23					<b>Chrysotile (white asbestos)</b>
Ceiling Void	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior****B00J - R0001 - Movement (19.89 m2)**

No Asbestos

**B00J - R0002 - Canteen (22.38 m2)**

No Asbestos

**B00J - R0003 - Movement (2.31 m2)**

No Asbestos

**B00J - R0004 - Staff Toilet (3.35 m2)**

No Asbestos

**B00J - R0005 - Canteen Office/Store (4.41 m2)**

No Asbestos

**B00J - R0007 - General Storeroom (5.78 m2)**

No Asbestos

**B00J - R0008 - Movement (30.83 m2)**

No Asbestos

**B00J - R0010 - Movement (4.84 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4221/B00J/R0022/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>

**B00J - R0011 - No Access (3.84 m2)**

No Asbestos

**B00J - R0012 - Personal Effects Storage (3.37 m2)**

No Asbestos

**B00J - R0013 - Interview (14.94 m2)**

No Asbestos

**B00J - R0014 - Home Base Store (6.67 m2)**

No Asbestos

**B00J - R0015 - Staff Room (56.39 m2)**

No Asbestos

**B00J - R0016 - Staff Room (55.92 m2)**

No Asbestos

**B00J - R0017 - Home Base Store (6.94 m2)**

No Asbestos

**B00J - R0018 - Personal Effects Storage (3.81 m2)**

No Asbestos

**B00J - R0019 - Movement (3.24 m2)**

No Asbestos

**B00J - R0021 - Movement (53.77 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
4221/B00J/R0022/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	
<b>B00J - R0022 - Movement (31.1 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	32m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4221/B00J/R0022/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	
<b>B00J - R0023 - Staff Room (11.19 m2)</b>						
No Asbestos						
<b>B00J - R0024 - Staff Toilet (4.52 m2)</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00K - General Learning - 1950 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting 4221/B00J/Eaves Linings/S20	40m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Gable verge lining	Flat AC Sheeting 4221/B00J/Gable verge lining/S23	20m	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Underfloor Voids	Flat AC Sheeting 4221/B00K/Underfloor Voids/S25	1m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5) <b>Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)</b>
Underfloor Voids	AC Fragments/Debris 4221/B00K/Underfloor Voids/S27	1m2	Variable positions	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5) <b>Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)</b>
Ceiling Void	No Asbestos Found					

**Interior****B00K - R0001 - Home Base (57.35 m2)**

No Asbestos

**B00K - R0002 - Home Base Store (4.88 m2)**

No Asbestos

**B00K - R0003 - Personal Effects Storage (8.32 m2)**

No Asbestos

**B00K - R0004 - Movement (5.49 m2)**

No Asbestos

**B00K - R0006 - Home Base Store (4.88 m2)**

No Asbestos

**B00K - R0007 - Home Base (57.43 m2)**

No Asbestos

**B00K - R0008 - Home Base (57.03 m2)**

No Asbestos

**B00K - R0009 - Home Base Store (4.16 m2)**

No Asbestos

**B00K - R0010 - Personal Effects Storage (8.82 m2)**

No Asbestos

**B00K - R0011 - Movement (6.71 m2)**

No Asbestos

**B00K - R0013 - Home Base (57.27 m2)**

No Asbestos

**B00K - R0014 - Home Base Store (4.16 m2)**

No Asbestos

**B00K - R0015 - Movement (25.87 m2)**

Ceiling Structures/Linings	Flat AC Sheeting 4221/B00D/R0005/Ceiling Structures/Linings/S7	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
----------------------------	---	-----	--------------	--------------------	---------	--

**B00K - R0016 - Movement (24.25 m2)**

Ceiling Structures/Linings	Flat AC Sheeting 4221/B00D/R0005/Ceiling Structures/Linings/S7	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
----------------------------	---	-----	--------------	--------------------	---------	--

**B00K - R0017 - Movement (21.23 m2)**



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	<b>Sample No</b>					<b>Test Result</b>

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00L - Pupil Facilities - 1950 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	40m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4221/B00M/Eaves Linings/S21				<b>Chrysotile (white asbestos)</b>	
Ceiling Void	No Asbestos Found					

**Interior**

**B00L - R0001 - Toilets - Girls (56.38 m2)**

Partition Walls (Cubicles)	Compressed AC Sheet	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4221/B00L/R0001/Partition Walls (Cubicles)/S6				<b>Chrysotile (white asbestos)</b>	

**B00L - R0002 - General Storeroom (41.09 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00M - Pupil Facilities - 1950 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	40m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4221/B00M/Eaves Linings/S21				<b>Chrysotile (white asbestos)</b>	
Ceiling Void	No Asbestos Found					

**Interior**

**B00M - R0001 - Toilets - Boys (56.33 m2)**

Partition Walls (Cubicles)	Compressed AC Sheet	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4221/B00L/R0001/Partition Walls (Cubicles)/S6				<b>Chrysotile (white asbestos)</b>	

**B00M - R0002 - Sports Store (41 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00N - Communal Facilities - 2010 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior****B00N - R0001 - Communal Space (146.84 m2)**

No Asbestos

**B00N - R0002 - Raised Platform (57.59 m2)**

No Asbestos

**B00N - R0003 - Chair Storeroom (13 m2)**

No Asbestos

**B00N - R0004 - Communal/Performance Store (9.61 m2)**

No Asbestos

**B00N - R0005 - P.E. Store (13.05 m2)**

No Asbestos

**B00N - R0006 - Toilet - Lobby (2.4 m2)**

No Asbestos

**B00N - R0007 - Toilets - Girls (7.24 m2)**

No Asbestos

**B00N - R0008 - Sound Cupboard (1.97 m2)**

No Asbestos

**B00N - R0009 - Toilet - Lobby (3.51 m2)**

No Asbestos

**B00N - R0010 - Toilets - Boys (5.62 m2)**

No Asbestos

**B00N - R0011 - Cleaning Distributed Store (3 m2)**

No Asbestos

**B00N - R0012 - Other (1.57 m2)**

No Asbestos

**B00N - R0013 - Main Switch Board (3.69 m2)**

No Asbestos

**B00N - R0014 - Access Shower/Toilet/Change (6.9 m2)**

No Asbestos

**B00N - R0015 - Covered Outdoor Learning Area (223.9 m2)**

No Asbestos

**B00N - R0016 - Movement (6.86 m2)**

No Asbestos

**B00N - R0017 - Movement (10.8 m2)**

No Asbestos

**B00N - R0018 - Other (0.35 m2)**

No Asbestos

**B00N - R0019 - Movement (13.27 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00X - Other-Community Use - 1950 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Eaves Linings	Flat AC Sheeting	70m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4221/B00X/Eaves Linings/S18					<b>Chrysotile (white asbestos)</b>
Ceiling Void	Non Accessible Area - No Access - No manhole found in building (4 rooms not accessed - no keys at school)					
Underfloor Voids	Non Accessible Area - No Access - No keys to get into manholes at school - as is Scout Hut Building					
Wall Cladding	Flat AC Sheeting					<b>No Asbestos Detected</b>
	4221/B00X/Wall Cladding/S30					

**Interior**

**B00X - R0001 - Other-Community Use (237.64 m2)**

No Asbestos

**B00X - R0002 - Front Entrance Movement**

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4221/B00X/R0002/Ceiling Structures/Linings/S31					<b>Chrysotile (white asbestos)</b>

**B00X - R0003 - Kitchen**

No Asbestos

**B00X - R0004 - Toilet**

No Asbestos

**B00X - Room+4 - Added Room**

Non Accessible

**B00X - Room+5 - Added Room**

Non Accessible

**B00X - Room+6 - Added Room**

Non Accessible

**B00X - Room+7 - Added Room**

Non Accessible

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017