

# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Lynwood Park Public School (4258)  
**Region :** Western Sydney  
**State Electorate :** Blacktown  
**Local Government Area :** Blacktown

**Initial Survey :** Noel Arnold & Associates : 05 - Apr - 2008  
**Reviewed By :** Greencap-NAA : 10 - Jun - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - Library/General Learning - 1960 - Concrete Framed (Concrete Framed)**

**Exterior**

Eaves Linings	Flat AC Sheeting	70m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - Height Restriction</b>						
Ceiling Voids	Non Accessible Area - Height Restriction					
Underfloor Voids - Packing to Floor Joists	Flat AC Sheeting	4m2	Variable positions	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
4258/B00A/Underfloor Voids - Packing to Floor Joists/S17				<b>Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)</b>		

**Interior**

**B00A - R0001 - Home Base**

No Asbestos

**B00A - R0002 - Home Base Store**

No Asbestos

**B00A - R0004 - Movement**

No Asbestos

**B00A - R0005 - Craft Store**

No Asbestos

**B00A - R0006 - Library Office/Workroom**

No Asbestos

**B00A - R0007 - Cleaning Distributed Store**

No Asbestos

**B00A - R0008 - General Storeroom**

No Asbestos

**B00A - R0009 - Reading Area**

No Asbestos

**B00A - R0010 - General Storeroom**

No Asbestos

**B00A - R0011 - Sports Store**

No Asbestos

**B00A - R0012 - Movement**

No Asbestos

**B00A - R0013 - Interview**

No Asbestos

**B00A - R0014 - Sports Store**

No Asbestos

**B00A - R0015 - Personal Effects Storage**

No Asbestos

**B00A - R0017 - Home Base**

No Asbestos

**B00A - R0018 - Home Base Store**

No Asbestos

**B00A - R0019 - External Movement**

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - Pupil Facilities/Staff Facilities - 1960 - Concrete Framed (Concrete Framed)**

**Exterior**

Eaves Linings	Flat AC Sheeting	20m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
---------------	------------------	------	-------------------------------	--------------------	---------	--------------------

**Assumed Asbestos - Height Restriction**

**Interior**

**B00B - R0001 - Staff Room**

No Asbestos

**B00B - R0002 - General Storeroom**

Floor Coverings Res/Textile	Vinyl Tiles					
		4258/B00B/R0009/Floor Coverings Res/Textile/S1				<b>No Asbestos Detected</b>

**B00B - R0004 - Movement**

Floor Coverings Res/Textile	Vinyl Tiles					
		4258/B00B/R0009/Floor Coverings Res/Textile/S1				<b>No Asbestos Detected</b>

**B00B - R0005 - Movement**

Floor Coverings Res/Textile	Vinyl Tiles					
		4258/B00B/R0009/Floor Coverings Res/Textile/S1				<b>No Asbestos Detected</b>

**B00B - R0006 - Canteen**

Floor Coverings Res/Textile	Vinyl Tiles					
		4258/B00B/R0009/Floor Coverings Res/Textile/S1				<b>No Asbestos Detected</b>

**B00B - R0010 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting					
		4258/B00B/R0010/Ceiling Structures/Linings/S6				<b>No Asbestos Detected</b>
Wall Linings Internal	Flat AC Sheeting					
		4258/B00B/R0010/Wall Linings Internal/S5				<b>No Asbestos Detected</b>

**B00B - R0011 - External Movement**

No Asbestos

**B00B - R0012 - Staff Toilet**

Wall Linings Internal	Flat AC Sheeting					
		4258/B00B/R0010/Wall Linings Internal/S5				<b>No Asbestos Detected</b>

**B00B - R0013 - Staff Toilet**

Wall Linings Internal	Flat AC Sheeting					
		4258/B00B/R0010/Wall Linings Internal/S5				<b>No Asbestos Detected</b>

**B00B - R0014 - Movement**

Wall Linings Internal	Flat AC Sheeting					
		4258/B00B/R0010/Wall Linings Internal/S5				<b>No Asbestos Detected</b>

**B00B - R0015 - Handwashing Facilities**

Wall Linings Internal	Flat AC Sheeting					
		4258/B00B/R0010/Wall Linings Internal/S5				<b>No Asbestos Detected</b>

**B00B - R0016 - Canteen**

No Asbestos

**B00B - R0017 - Canteen Office/Store**

No Asbestos

**B00B - R0018 - Staff Kitchen**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - Administration/Communal Facilities - 1960 - Concrete Framed (Concrete Framed)**

**Exterior**

Eaves Linings	Flat AC Sheeting	60m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4258/B00C/R0011/Ceiling Structures/Linings/S11				<b>Chrysotile (white asbestos)</b>	
Gable verge linings	Flat AC Sheeting	30m	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4258/B00C/R0011/Ceiling Structures/Linings/S11				<b>Chrysotile (white asbestos)</b>	
Ceiling Voids	Non Accessible Area - Height Restriction					
Underfloor Voids	No Asbestos Found					

**Interior**

**B00C - R0001 - Home Base**

No Asbestos

**B00C - R0002 - Home Base Store**

No Asbestos

**B00C - R0003 - Personal Effects Storage**

No Asbestos

**B00C - R0004 - Movement**

No Asbestos

**B00C - R0007 - General Storeroom**

No Asbestos

**B00C - R0008 - General Storeroom**

No Asbestos

**B00C - R0009 - Personal Effects Storage**

No Asbestos

**B00C - R0010 - Movement**

No Asbestos

**B00C - R0012 - Home Base**

No Asbestos

**B00C - R0013 - Home Base Store**

No Asbestos

**B00C - R0014 - Duplicating Workroom**

No Asbestos

**B00C - R0015 - Cleaning Distributed Store**

No Asbestos

**B00C - R0017 - Interview**

No Asbestos

**B00C - R0018 - General Storeroom**

No Asbestos

**B00C - R0019 - Staff Toilet**

Wall Linings Internal	Flat AC Sheeting	30m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4258/B00C/R0019/Wall Linings Internal/S13				<b>Chrysotile (white asbestos)</b>	
Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4258/B00C/R0019/Wall Linings Internal/S13				<b>Chrysotile (white asbestos)</b>	

**B00C - R0020 - Clerical Office/Workroom**

Floor Coverings Res/Textile	Vinyl Sheet					
	4258/B00C/R0020/Floor Coverings Res/Textile/S16				<b>No Asbestos Detected</b>	

**B00C - R0022 - Movement**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	4258/B00C/R0022/Floor Coverings Res/Textile/S14				<b>No Asbestos Detected</b>	
Floor Coverings Res/Textile	Adhesive					
	4258/B00C/R0022/Floor Coverings Res/Textile/S15				<b>No Asbestos Detected</b>	
<b>B00C - R0025 - Home Base</b>						
No Asbestos						
<b>B00C - R0026 - Home Base</b>						
No Asbestos						
<b>B00C - R0027 - Entry Vestibule</b>						
No Asbestos						
<b>B00C - R0028 - Movement</b>						
No Asbestos						
<b>B00C - R0029 - Clerical Office</b>						
No Asbestos						
<b>B00C - R0030 - External Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting	20m2	Outside each entry door 6m2 each	Good Condition (1)	Low (1)	Low Priority (2-3)
	4258/B00C/R0011/Ceiling Structures/Linings/S11				<b>Chrysotile (white asbestos)</b>	
Panel above door	Flat AC Sheeting	1m2	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4258/B00C/R0011/Panel above door/S12				<b>Chrysotile (white asbestos)</b>	
<b>B00C - R9001 - Garden Store</b>						
Ceiling Structures/Linings	Flat AC Sheeting	54m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4258/B00C/R0011/Ceiling Structures/Linings/S11				<b>Chrysotile (white asbestos)</b>	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - General Learning - 1960 - Concrete Framed (Concrete Framed)**

**Exterior**

Eaves Linings	Flat AC Sheeting	20m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4258/B00D/R0003/Ceiling Structures/Linings/S10				<b>Chrysotile (white asbestos)</b>	
Gable verge linings	Flat AC Sheeting	20m	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4258/B00D/R0003/Ceiling Structures/Linings/S10				<b>Chrysotile (white asbestos)</b>	
Ceiling Voids	Non Accessible Area - Height Restriction					
Underfloor Voids	No Asbestos Found					

**Interior**

**B00D - R0001 - Home Base**

No Asbestos

**B00D - R0002 - Movement**

No Asbestos

**B00D - R0004 - Disabled Toilet**

No Asbestos

**B00D - R0005 - Home Base**

No Asbestos

**B00D - R0006 - Home Base Store**

No Asbestos

**B00D - R0007 - Home Base Store**

No Asbestos

**B00D - R0008 - External Movement**

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4258/B00D/R0003/Ceiling Structures/Linings/S10				<b>Chrysotile (white asbestos)</b>	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - Administration - 1960 - Concrete Framed (Concrete Framed)**

**Exterior**

Eaves Linings	Flat AC Sheeting	30m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
---------------	------------------	------	--------------	--------------------	---------	--------------------

**Assumed Asbestos - Height Restriction**

Ceiling Voids	Non Accessible Area - Height Restriction					
---------------	---	--	--	--	--	--

Underfloor Voids	No Asbestos Found					
------------------	-------------------	--	--	--	--	--

**Interior**

**B00E - R0001 - Home Base**

No Asbestos

**B00E - R0002 - Home Base Store**

No Asbestos

**B00E - R0003 - Personal Effects Storage**

No Asbestos

**B00E - R0004 - Movement**

No Asbestos

**B00E - R0005 - Community Clinic**

Floor Coverings Res/Textile	Vinyl Sheet					
4258/B00E/R0005/Floor Coverings Res/Textile/S18					<b>No Asbestos Detected</b>	

**B00E - R0007 - Home Base Store**

No Asbestos

**B00E - R0008 - Staff Room Annexe**

No Asbestos

**B00E - R0009 - General Storeroom**

No Asbestos

**B00E - R0010 - External Movement**

No Asbestos

**B00E - R9001 - General Storeroom**

Ceiling Structures/Linings	Flat AC Sheeting	34m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	------	------------	--------------------	---------	--------------------

4258/B00E/R9001/Ceiling Structures/Linings/S21 **Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - General Learning - 1960 - Concrete Framed (Concrete Framed)**

**Exterior**

Eaves Linings	Flat AC Sheeting	50m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4258/B00F/R9001/Ceiling Structures/Linings/S9			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Ceiling Voids	Non Accessible Area - Height Restriction					
Underfloor Voids	No Asbestos Found					

**Interior**

**B00F - R0002 - Movement**

No Asbestos

**B00F - R0003 - Staff Toilet**

No Asbestos

**B00F - R0004 - General Storeroom**

No Asbestos

**B00F - R0005 - Personal Effects Storage**

No Asbestos

**B00F - R0006 - Practical Activities - 1hb**

No Asbestos

**B00F - R0007 - Home Base**

No Asbestos

**B00F - R0008 - Home Base Store**

No Asbestos

**B00F - R0009 - Personal Effects Storage**

No Asbestos

**B00F - R0010 - Deputy Principal**

Floor Coverings Res/Textile	Vinyl Sheet					
	4258/B00F/R0010/Floor Coverings Res/Textile/S7			<b>No Asbestos Detected</b>		

**B00F - R0011 - Movement**

Floor Coverings Res/Textile	Vinyl Sheet					
	4258/B00F/R0011/Floor Coverings Res/Textile/S8			<b>No Asbestos Detected</b>		

**B00F - R0013 - Personal Effects Storage**

No Asbestos

**B00F - R0014 - Home Base**

No Asbestos

**B00F - R0015 - Home Base Store**

No Asbestos

**B00F - R0016 - Home Base**

No Asbestos

**B00F - R0017 - Home Base Store**

Panel in Window	Flat AC Sheeting					
	4258/B00F/R0017/Panel in Window/S20			<b>No Asbestos Detected</b>		

**B00F - R0018 - Personal Effects Storage**

No Asbestos

**B00F - R0019 - Movement**

No Asbestos

**B00F - R0020 - Staff Room Annexe**

Floor Coverings Res/Textile	Vinyl Sheet					
	4258/B00F/R0020/Floor Coverings Res/Textile/S19			<b>No Asbestos Detected</b>		



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No						Test Result
<b>B00F - R0021 - Staff Toilet</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	4258/B00F/R0010/Floor Coverings Res/Textile/S7					<b>No Asbestos Detected</b>
<b>B00F - R0023 - External Movement</b>						
No Asbestos						
<b>B00F - R9001 - Cleaning Supplies</b>						
Ceiling Structures/Linings	Flat AC Sheeting	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4258/B00F/R9001/Ceiling Structures/Linings/S9					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - General Learning - 1960 - Concrete Framed (Concrete Framed)**

**Exterior**

Eaves Linings	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
---------------	------------------	------	------------	--------------------	---------	--------------------

**Assumed Asbestos - Height Restriction**

Ceiling Voids	Non Accessible Area - Height Restriction					
Underfloor Voids	No Asbestos Found					

**Interior**

**B00G - R0001 - Home Base**

No Asbestos

**B00G - R0002 - Home Base Store**

No Asbestos

**B00G - R0003 - Personal Effects Storage**

No Asbestos

**B00G - R0004 - Personal Effects Storage**

No Asbestos

**B00G - R0005 - Movement**

No Asbestos

**B00G - R0006 - Movement**

No Asbestos

**B00G - R0007 - Home Base**

No Asbestos

**B00G - R0008 - Home Base Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - Pupil Facilities - 1960 - Concrete (Concrete)****Exterior**

Eaves Linings	Flat AC Sheeting 4258/B00H/R0001/Ceiling Structures/Linings/S22					<b>No Asbestos Detected</b>
Gable Ends	Flat AC Sheeting	8m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	<b>Assumed Asbestos - Height Restriction</b>					
Ceiling Voids	Non Accessible Area - Height Restriction					
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					

**Interior****B00H - R0001 - Drinking Facilities**

Ceiling Structures/Linings	Flat AC Sheeting 4258/B00H/R0001/Ceiling Structures/Linings/S22					<b>No Asbestos Detected</b>
----------------------------	--	--	--	--	--	-----------------------------

**B00H - R0002 - Toilets - Girls**

Ceiling Structures/Linings	Flat AC Sheeting 4258/B00H/R0001/Ceiling Structures/Linings/S22					<b>No Asbestos Detected</b>
Toilet cistern	Fibre Cement Casting (Monocrete) 4258/B00H/R0004/Toilet cistern/S3					<b>No Asbestos Detected</b>
Partition Walls (Cubicles)	Compressed AC Sheet 4258/B00H/R0002/Partition Walls (Cubicles)/S4					<b>No Asbestos Detected</b>

**B00H - R0003 - Cleaning Distributed Store**

Toilet cistern	Fibre Cement Casting (Monocrete) 4258/B00H/R0004/Toilet cistern/S3					<b>No Asbestos Detected</b>
----------------	---	--	--	--	--	-----------------------------

**B00H - R0004 - Toilets - Boys**

Toilet cistern	Fibre Cement Casting (Monocrete) 4258/B00H/R0004/Toilet cistern/S3					<b>No Asbestos Detected</b>
Ceiling Structures/Linings	Flat AC Sheeting 4258/B00H/R0001/Ceiling Structures/Linings/S22					<b>No Asbestos Detected</b>
Partition Walls (Cubicles)	Compressed AC Sheet 4258/B00H/R0002/Partition Walls (Cubicles)/S4					<b>No Asbestos Detected</b>

**B00H - R0005 - Drinking Facilities**

Ceiling Structures/Linings	Flat AC Sheeting 4258/B00H/R0001/Ceiling Structures/Linings/S22					<b>No Asbestos Detected</b>
----------------------------	--	--	--	--	--	-----------------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B001 - Pupil Facilities - 1960 - Concrete (Concrete)**

**Exterior**

Eaves Linings	Flat AC Sheeting	16m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - Height Restriction</b>						
Gable Ends	Flat AC Sheeting	8m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - Height Restriction</b>						

**Interior**

**B001 - R0001 - Drinking Facilities**

Ceiling Structures/Linings	Flat AC Sheeting	4258/B00H/R0001/Ceiling Structures/Linings/S22				<b>No Asbestos Detected</b>
----------------------------	------------------	--	--	--	--	-----------------------------

**B001 - R0002 - Toilets - Girls**

Partition Walls (Cubicles)	Compressed AC Sheet	4258/B00I/R0002/Partition Walls (Cubicles)/S2				<b>No Asbestos Detected</b>
----------------------------	---------------------	---	--	--	--	-----------------------------

**B001 - R0003 - Cleaning Distributed Store**

No Asbestos

**B001 - R0004 - Toilets - Boys**

Partition Walls (Cubicles)	Compressed AC Sheet	4258/B00I/R0002/Partition Walls (Cubicles)/S2				<b>No Asbestos Detected</b>
----------------------------	---------------------	---	--	--	--	-----------------------------

**B001 - R0005 - Drinking Facilities**

Ceiling Structures/Linings	Flat AC Sheeting	4258/B00H/R0001/Ceiling Structures/Linings/S22				<b>No Asbestos Detected</b>
----------------------------	------------------	--	--	--	--	-----------------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

### B00J - Pupil Facilities/Communal Facilities - 2010 - Brick/Veneer (Brick/Veneer)

#### Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

#### Interior

##### B00J - R0001 - Communal Space

No Asbestos

##### B00J - R0002 - Raised Platform

No Asbestos

##### B00J - R0003 - Movement

No Asbestos

##### B00J - R0004 - Ramp

No Asbestos

##### B00J - R0005 - Movement

No Asbestos

##### B00J - R0006 - Hall Chair Store

No Asbestos

##### B00J - R0007 - Communal/Performance Store

No Asbestos

##### B00J - R0008 - P.E. Store

No Asbestos

##### B00J - R0009 - Toilet - Lobby

No Asbestos

##### B00J - R0010 - Toilets - Girls

No Asbestos

##### B00J - R0011 - Sound Cupboard

No Asbestos

##### B00J - R0012 - Toilet - Lobby

No Asbestos

##### B00J - R0013 - Toilets - Boys

No Asbestos

##### B00J - R0014 - Cleaning Distributed Store

No Asbestos

##### B00J - R0015 - Main Switch Board

No Asbestos

##### B00J - R0016 - Disabled Shower/Toilet

No Asbestos

##### B00J - R0017 - Covered Outdoor Learning Area

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00K - Other-Community Use - 2008 - Steel (Steel)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

**Interior**

**B00K - R0001 - Other-Community Use**

No Asbestos

**B00K - R0002 - Other-Community Use**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017