


Asbestos Register

(Hazardous Materials and Risk Assessment)



School : Lurnea Public School (4289)
Region : South Western Sydney
State Electorate : Holsworthy
Local Government Area : Liverpool

Initial Survey : Noel Arnold & Associates : 16 - Dec - 2009
Reviewed By : Grencap-NAA : 26 - Aug - 2014



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration - 1963 - Brick/Veneer (Brick/Veneer)**Exterior**

Eaves Linings	Flat AC Sheeting 4289/B00A/Eaves Linings/S36					No Asbestos Detected
Gable Verge Lining	Flat AC Sheeting 4289/B00A/Gable Verge Lining/S37	10m2	North West & South East	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					
Window frame	Window frame putty 4289/B00A/Window frame/S38					No Asbestos Detected

Interior**B00A - R0001 - Movement**

In-fill-panel	Flat AC Sheeting 4289/B00S/R0001/In-fill-panel/S1	2m	South	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
---------------	--	----	-------	--------------------	---------	--

B00A - R0006 - General Storeroom

No Asbestos

B00A - R0007 - General Storeroom

No Asbestos

B00A - R0008 - Clerical Office/Workroom

No Asbestos

B00A - R0009 - Clerical Office

No Asbestos

B00A - R0010 - General Storeroom

No Asbestos

B00A - R0013 - Duplicating Workroom

No Asbestos

B00A - R0014 - Sick Bay

No Asbestos

B00A - R0015 - Uniform Shop

No Asbestos

B00A - R0016 - Toilet - Lobby

No Asbestos

B00A - R0017 - Staff Toilet

No Asbestos

B00A - R0018 - Staff Toilet

No Asbestos

B00A - R0019 - Toilet - Lobby

No Asbestos

B00A - R0020 - Toilet - Lobby

No Asbestos

B00A - R0021 - Staff Toilet

No Asbestos

B00A - R0022 - Movement

Recently Modified Space Requires Inspection

B00A - R0023 - Staff Kitchen

Recently Modified Space Requires Inspection

B00A - R0024 - Clerical Office

Recently Modified Space Requires Inspection

B00A - R0025 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Recently Modified Space Requires Inspection

B00A - R0026 - Principal

Recently Modified Space Requires Inspection

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 1961 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting 4289/B00A/Eaves Linings/S36					No Asbestos Detected
Gable Verge Lining	Flat AC Sheeting 4289/B00A/Gable Verge Lining/S37	10m2	North & South	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
Window Frames	Window Putty 4289/B00A/Window frame/S38					No Asbestos Detected
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Non Accessible Area - Height Restriction					

Interior

B00B - R0001 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 4289/B00B/R0001/Ceiling Structures/Linings/S45	5.05m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
----------------------------	--	--------	------------	--------------------	---------	---

B00B - R0002 - Home Base

No Asbestos

B00B - R0003 - Home Base Store

No Asbestos

B00B - R0004 - Personal Effects Storage

No Asbestos

B00B - R0005 - Movement

No Asbestos

B00B - R0006 - Home Base

No Asbestos

B00B - R0007 - Home Base Store

No Asbestos

B00B - R0008 - Home Base

No Asbestos

B00B - R0009 - Home Base Store

No Asbestos

B00B - R0012 - Movement

In-fill-panel	Flat AC Sheeting 4289/B00S/R0001/In-fill-panel/S1	1m	East	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
---------------	--	----	------	--------------------	---------	--

B00B - R0013 - Practical Activities - 1hb

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Staff Facilities - 1963 - Brick/Veneer (Brick/Veneer)

Exterior

Gable Verge Lining	Flat AC Sheeting	15m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4289/B00A/Gable Verge Lining/S37				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Eaves Linings	Flat AC Sheeting				No Asbestos Detected	
	4289/B00C/Eaves Linings/S39					
Window frame	Window putty				No Asbestos Detected	
	4289/B00A/Window frame/S38					
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					
Telcommunications pit	Moulded Fibre Cement	1Unit	Northwest	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4289/B00C/Telcommunications pit/S42				Chrysotile (white asbestos) , Amosite (brown asbestos)	

Interior

B00C - R0002 - No Access

No Asbestos

B00C - R0003 - General Storeroom

No Asbestos

B00C - R0006 - Movement

In-fill-panel	Flat AC Sheeting	1m	South, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4289/B00S/R0001/In-fill-panel/S1				Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	1.42m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4289/B00C/R0006/Ceiling Structures/Linings/S41				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	

B00C - R0007 - No Access

No Asbestos

B00C - R0008 - Special Programs Room

No Asbestos

B00C - R0009 - Home Base Store

No Asbestos

B00C - R0010 - Staff Room

No Asbestos

B00C - R0011 - Staff Kitchen

No Asbestos

B00C - R0012 - Movement

No Asbestos

B00C - R0013 - Toilet - Lobby

No Asbestos

B00C - R0014 - Staff Toilet

No Asbestos

B00C - R0015 - Personal Effects Storage

Electrical Backing Board	Resinous Board	0.450m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	4289/B00C/R0015/Electrical Backing Board/S40				Chrysotile (white asbestos)	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Library - 1961 - Concrete Framed (Concrete Framed)

Exterior

Gable Verge Lining	Flat AC Sheeting	15m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4289/B00B/Gable Verge Lining/S10				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Eaves Linings	Flat AC Sheeting				No Asbestos Detected	
	4289/B00A/Eaves Linings/S36					
Underfloor Voids	Fibrous Cement Debris	150m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4289/B00D/Underfloor Voids/S43				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Voids	No Asbestos Found					

Interior

B00D - R0001 - Movement	No Asbestos
B00D - R0004 - Interview	No Asbestos
B00D - R0005 - General Storeroom	No Asbestos
B00D - R0006 - General Storeroom	No Asbestos
B00D - R0007 - Movement	No Asbestos
B00D - R0010 - General Storeroom	No Asbestos
B00D - R0011 - K.L.A. Store	No Asbestos
B00D - R0012 - Movement	No Asbestos
B00D - R0016 - Library Office/Workroom	No Asbestos
B00D - R0017 - General Storeroom	No Asbestos
B00D - R0018 - Covered Outdoor Learning Area	No Asbestos
B00D - R0019 - Practical Activities - 2hb	No Asbestos
B00D - R0020 - Home Base	No Asbestos
B00D - R0021 - Practical Activities	No Asbestos
B00D - R0022 - Home Base	No Asbestos
B00D - R0023 - Home Base	No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning/Communal Facilities - 1961 - Concrete Framed (Concrete Framed)

Exterior

Gable Verge Lining	Flat AC Sheeting	15m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4289/B00A/Gable Verge Lining/S37				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Eaves Linings	Flat AC Sheeting				No Asbestos Detected	
	4289/B00A/Eaves Linings/S36					
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Non Accessible Area - Area inaccessible					

Interior

B00E - R0001 - Movement

No Asbestos

B00E - R0002 - Movement

No Asbestos

B00E - R0003 - Entry Vestibule

No Asbestos

B00E - R0004 - Community Clinic

No Asbestos

B00E - R0005 - Cleaning Distributed Store

No Asbestos

B00E - R0006 - Movement

No Asbestos

B00E - R0007 - Hall Chair Store

Wall Linings Internal	Flat AC Sheeting				No Asbestos Detected	
	4289/B00E/R0007/Wall Linings Internal/S5					

Wall Linings Internal	Flat AC Sheeting				No Asbestos Detected	
	4289/B00E/R0007/Wall Linings Internal/S55					

B00E - R0008 - Home Base Store

No Asbestos

B00E - R0010 - Hall Chair Store

No Asbestos

B00E - R0011 - Personal Effects Storage

No Asbestos

B00E - R0012 - Movement

No Asbestos

B00E - R0013 - Movement

No Asbestos

B00E - R0014 - Home Base Store

No Asbestos

B00E - R0015 - Home Base

No Asbestos

B00E - R0016 - Security Store

No Asbestos

B00E - R0019 - Practical Activities - S - 2hb

No Asbestos

B00E - R0020 - Home Base/Practical Activities - P

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning - 1961 - Brick/Veneer (Brick/Veneer)**Exterior**

Gable Verge Lining	Flat AC Sheeting	15m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4289/B00A/Gable Verge Lining/S37				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Voids	No Asbestos Found				No Asbestos Detected	
Eaves Linings	Flat AC Sheeting				No Asbestos Detected	
	4289/B00A/Eaves Linings/S36				No Asbestos Detected	
Underfloor Voids	Flat AC Sheeting	120m2	North West corner	Good Condition (1)	Low (1)	Low Priority (2-3)
	4289/B00F/Underfloor Voids/S56				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	

Interior**B00F - R0001 - Home Base**

No Asbestos

B00F - R0002 - Home Base Store

No Asbestos

B00F - R0005 - Movement

In-fill-panel	Flat AC Sheeting	2m	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	4289/B00B/R0001/Ceiling Structures/Linings/S45				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	

B00F - R0006 - Home Base Store

No Asbestos

B00F - R0007 - Home Base

No Asbestos

B00F - R0008 - Personal Effects Storage

No Asbestos

B00F - R0009 - Movement

No Asbestos

B00F - R0010 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4289/B00B/R0001/Ceiling Structures/Linings/S45				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
In-fill-panel	Flat AC Sheeting	1m	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4289/B00S/R0001/In-fill-panel/S1				Chrysotile (white asbestos)	

B00F - R0011 - Home Base

No Asbestos

B00F - R0012 - Home Base Store

No Asbestos

B00F - R0013 - Practical Activities/Movement - 2hb

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning - 1963 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting 4289/B00A/Eaves Linings/S36					No Asbestos Detected
Gable Verge Lining	Flat AC Sheeting 4289/B00A/Gable Verge Lining/S37	15m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00G - R0001 - Home Base

No Asbestos

B00G - R0002 - Staff Room Annexe

No Asbestos

B00G - R0003 - Movement

In-fill-panel	Flat AC Sheeting 4289/B00S/R0001/In-fill-panel/S1	1m	South, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting 4289/B00B/R0001/Ceiling Structures/Linings/S45	6.87m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)

B00G - R0004 - Covered Outdoor Learning Area

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Pupil Facilities - 1963 - Concrete (Concrete)**Exterior**

Ceiling Voids	Flat AC Sheeting	150m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4289/B00T/R0001/Ceiling Structures/Linings/S53			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Underfloor Voids - Slab on Ground	Non Accessible Area					
	- Area inaccessible					
Eaves Linings	Flat AC Sheeting					
	4289/B00A/Eaves Linings/S36					No Asbestos Detected

Interior**B00H - R0001 - Drinking Facilities**

Ceiling Structures/Linings	Flat AC Sheeting	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4289/B00T/R0001/Ceiling Structures/Linings/S53			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00H - R0002 - Handwashing Facilities

Ceiling Structures/Linings	Flat AC Sheeting	17.28m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4289/B00T/R0001/Ceiling Structures/Linings/S53			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00H - R0003 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting	35m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4289/B00T/R0001/Ceiling Structures/Linings/S53			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00H - R0004 - Cleaning Distributed Store

Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4289/B00T/R0001/Ceiling Structures/Linings/S53			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00H - R0005 - P.E. Store

Ceiling Structures/Linings	Flat AC Sheeting	5.9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4289/B00T/R0001/Ceiling Structures/Linings/S53			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00H - R0006 - Cleaning Supplies

Ceiling Structures/Linings	Flat AC Sheeting	5.92m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4289/B00T/R0001/Ceiling Structures/Linings/S53			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00H - R0007 - Drinking Facilities

Ceiling Structures/Linings	Flat AC Sheeting	15.23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4289/B00T/R0001/Ceiling Structures/Linings/S53			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00H - R0008 - Cleaning Supplies

Ceiling Structures/Linings	Flat AC Sheeting	34.02m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4289/B00T/R0001/Ceiling Structures/Linings/S53			Chrysotile (white asbestos) , Amosite (brown asbestos)		

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Pupil Facilities - 1961 - Concrete (Concrete)

Exterior

Ceiling Voids	No Asbestos Found					
Underfloor Voids	Non Accessible Area - Area inaccessible					
Eaves Linings	Flat AC Sheeting 4289/B00A/Eaves Linings/S36					No Asbestos Detected

Interior

B00K - R0001 - Drinking Facilities

Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4289/B00T/R0001/Ceiling Structures/Linings/S53				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00K - R0002 - Sports Store

Ceiling Structures/Linings	Flat AC Sheeting	45m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4289/B00T/R0001/Ceiling Structures/Linings/S53				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00K - R0003 - Hall Chair Store

Ceiling Structures/Linings	Flat AC Sheeting	27m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4289/B00T/R0001/Ceiling Structures/Linings/S53				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00K - R0004 - Handwashing Facilities

Ceiling Structures/Linings	Flat AC Sheeting	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4289/B00T/R0001/Ceiling Structures/Linings/S53				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00K - R0005 - Drinking Facilities

Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4289/B00T/R0001/Ceiling Structures/Linings/S53				Chrysotile (white asbestos) , Amosite (brown asbestos)		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Communal Facilities - 1963 - Concrete (Concrete)

Exterior

Eaves Linings	Flat AC Sheeting 4289/B00A/Eaves Linings/S36					No Asbestos Detected
Underfloor Voids	Non Accessible Area - Area inaccessible					
Ceiling Voids	Non Accessible Area - Area inaccessible					

Interior

B00L - R0001 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4289/B00T/R0001/Ceiling Structures/Linings/S53					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00L - R0003 - Hall Chair Store

Ceiling Structures/Linings	Flat AC Sheeting	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4289/B00T/R0001/Ceiling Structures/Linings/S53					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00L - R0004 - General Assistant/Bulk Store

Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4289/B00T/R0001/Ceiling Structures/Linings/S53					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00L - R0005 - Garden Store

Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4289/B00T/R0001/Ceiling Structures/Linings/S53					Chrysotile (white asbestos) , Amosite (brown asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - Special Purpose - 1963 - Timber (Timber)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00M - R0001 - Other-Community Use

No Asbestos

B00M - R0002 - Practical Activities - 1hb

No Asbestos

B00M - R0003 - Craft Store

No Asbestos

B00M - R0004 - No Access

No Asbestos

B00M - R0005 - Movement

Electrical Backing Board	Resinous Board	0.45m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
--------------------------	----------------	--------	-------	--------------------	---------	--------------------

Assumed Asbestos - Electrical Hazard

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00N - Support Unit - 1963 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting 4289/B00A/Eaves Linings/S36					No Asbestos Detected
Underfloor Voids	No Asbestos Found					
Ceiling Voids	No Asbestos Found					

Interior

B00N - R0001 - Movement

Electrical Backing Board	Resinous Board	0.45m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Electrical Hazard						

B00N - R0002 - Staff Room - Pre

No Asbestos

B00N - R0003 - Withdrawal - Pre

No Asbestos

B00N - R0004 - General Storeroom - Pre

No Asbestos

B00N - R0005 - Withdrawal - Pre

No Asbestos

B00N - R0008 - Toilets - Boys/Girls - Pre

Wall Linings Internal	Flat AC Sheeting 4289/B00N/R0008/Wall Linings Internal/S4					No Asbestos Detected
-----------------------	--	--	--	--	--	-----------------------------

B00N - R0009 - Kitchen - Pre

No Asbestos

B00N - R0011 - No Access

No Asbestos

B00N - R0013 - Movement

No Asbestos

B00N - R0014 - Home Base - Pre

No Asbestos

B00N - R0015 - Practical Activities - Pre

No Asbestos

B00N - R0016 - Toilet - Lobby

No Asbestos

B00N - R0017 - Staff Toilet

Partition Walls (Cubicles)	Compressed AC Sheet 4289/B00N/R0017/Partition Walls (Cubicles)/S54					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00P - General Learning/Staff Facilities - 1961 - Concrete Framed (Concrete Framed)

Exterior

Eaves Linings	Flat AC Sheeting 4289/B00A/Eaves Linings/S36					No Asbestos Detected
Gable Verge Lining	Flat AC Sheeting 4289/B00T/Gable Verge Lining/S44	15m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

- B00P - R0001 - Movement**
No Asbestos
- B00P - R0002 - Movement**
No Asbestos
- B00P - R0003 - Craft Store**
No Asbestos
- B00P - R0004 - Special Programs Room**
No Asbestos
- B00P - R0005 - Staff Room Annexe**
No Asbestos
- B00P - R0006 - Home Base**
No Asbestos
- B00P - R0007 - Personal Effects Storage**
No Asbestos
- B00P - R0008 - No Access**
No Asbestos
- B00P - R0009 - Personal Effects Storage**
No Asbestos
- B00P - R0010 - Movement**
No Asbestos
- B00P - R0011 - Movement**
No Asbestos
- B00P - R0012 - Home Base**
No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00Q - General Learning - 1961 - Concrete (Concrete)

Exterior

Eaves Linings	Flat AC Sheeting 4289/B00A/Eaves Linings/S36					No Asbestos Detected
Gable Verge Lining	Flat AC Sheeting 4289/B00T/Gable Verge Lining/S44	40m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos) , Amosite (brown asbestos)
Underfloor Voids	Packing 4289/B00Q/Underfloor Voids/S50	150m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found					

Interior

B00Q - R0001 - External Movement	No Asbestos
B00Q - R0002 - Movement	No Asbestos
B00Q - R0003 - Home Base	No Asbestos
B00Q - R0004 - General Storeroom	No Asbestos
B00Q - R0010 - General Storeroom	No Asbestos
B00Q - R0011 - Home Base	No Asbestos
B00Q - R0012 - Home Base	No Asbestos
B00Q - R0013 - Craft Store	No Asbestos
B00Q - R0014 - Movement	No Asbestos
B00Q - R0015 - Movement	No Asbestos
B00Q - R0016 - Practical Activities - 2hb	No Asbestos
B00Q - R0017 - Home Base Store	No Asbestos
B00Q - R0018 - Home Base Store	No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00R - General Learning - 1961 - Concrete Framed (Concrete Framed)

Exterior

Eaves Linings	Flat AC Sheeting 4289/B00A/Eaves Linings/S36					No Asbestos Detected
Gable Verge Lining	Flat AC Sheeting 4289/B00A/Gable Verge Lining/S37	15m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
Underfloor Voids	Flat AC Sheeting 4289/B00R/Underfloor Voids/S48	2m2	North West corner	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)

Interior

B00R - R0001 - Movement

No Asbestos

B00R - R0002 - Deputy Principal

No Asbestos

B00R - R0003 - General Storeroom

No Asbestos

B00R - R0004 - General Storeroom

No Asbestos

B00R - R0006 - Movement

Upper infill panel	Flat AC Sheeting 4289/B00R/R0006/Upper infill panel/S49					No Asbestos Detected
--------------------	--	--	--	--	--	-----------------------------

B00R - R0007 - Movement

No Asbestos

B00R - R0008 - Distribution Board

Note: No inspection of live electrical installation.

Wall Linings Internal	Flat AC Sheeting 4289/B00R/R0008/Wall Linings Internal/S3					No Asbestos Detected
-----------------------	--	--	--	--	--	-----------------------------

B00R - R0009 - Personal Effects Storage

No Asbestos

B00R - R0010 - Home Base

No Asbestos

B00R - R0011 - Home Base

No Asbestos

B00R - R0012 - Movement

No Asbestos

B00R - R0015 - Home Base Store

Wall Linings Internal	Flat AC Sheeting 4289/B00R/R0015/Wall Linings Internal/S2	5m2	South	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
-----------------------	--	-----	-------	--------------------	---------	--

B00R - R0017 - Home Base

No Asbestos

B00R - R0018 - Toilet - Lobby

No Asbestos

B00R - R0019 - Staff Toilet

No Asbestos

B00R - R0020 - Practical Activities - 2hb

No Asbestos

B00R - R0021 - Home Base Store

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00S - General Learning/Pupil Facilities - 1961 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting 4289/B00A/Eaves Linings/S36					No Asbestos Detected
Gable Verge Lining	Flat AC Sheeting 4289/B00A/Gable Verge Lining/S37	15m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
Window frames	Window putty 4289/B00A/Window frame/S38					No Asbestos Detected
Underfloor Voids	Non Accessible Area - Area inaccessible					
Ceiling Voids	No Asbestos Found					

Interior

B00S - R0001 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 4289/B00B/R0001/Ceiling Structures/Linings/S45	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
In-fill-panel	Flat AC Sheeting 4289/B00S/R0001/In-fill-panel/S1	1m	North	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

B00S - R0002 - Home Base

No Asbestos

B00S - R0003 - Home Base Store

No Asbestos

B00S - R0004 - Movement

No Asbestos

B00S - R0005 - Personal Effects Storage

Electrical Backing Board	Resinous Board 4289/B00S/R0005/Electrical Backing Board/S46	0.6m2	North	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
--------------------------	--	-------	-------	--------------------	---------	--

B00S - R0006 - Home Base

No Asbestos

B00S - R0007 - Home Base Store

No Asbestos

B00S - R0008 - Canteen Office/Store

Ceiling Structures/Linings	Flat AC Sheeting 4289/B00S/R0008/Ceiling Structures/Linings/S47	2.92m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	--	--------	------------	--------------------	---------	--

B00S - R0009 - Canteen Office/Store

Ceiling Structures/Linings	Flat AC Sheeting 4289/B00S/R0008/Ceiling Structures/Linings/S47	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	--	-----	------------	--------------------	---------	--

B00S - R0010 - Canteen

Ceiling Structures/Linings	Flat AC Sheeting 4289/B00S/R0008/Ceiling Structures/Linings/S47	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	--	------	------------	--------------------	---------	--

B00S - R0011 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 4289/B00S/R0008/Ceiling Structures/Linings/S47	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Electrical Mounting Board	Resinous Board	0.6m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)

Assumed Asbestos - Area inaccessible

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00T - Pupil Facilities - 1963 - Concrete (Concrete)

Exterior

Eaves Linings	Flat AC Sheeting 4289/B00A/Eaves Linings/S36					No Asbestos Detected
Gable Verge Lining	Moulded fibrous cement 4289/B00T/Gable Verge Lining/S44	8m2	East & West	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
Underfloor Voids	Non Accessible Area - Area inaccessible					
Ceiling Voids	No Asbestos Found					
Ceiling Voids	No Asbestos Found					

Interior

B00T - R0001 - Drinking Facilities

Ceiling Structures/Linings	Flat AC Sheeting 4289/B00T/R0001/Ceiling Structures/Linings/S53	11.47m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
----------------------------	--	---------	------------	--------------------	---------	---

B00T - R0002 - Handwashing Facilities

Ceiling Structures/Linings	Flat AC Sheeting 4289/B00T/R0001/Ceiling Structures/Linings/S53	17.28m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
----------------------------	--	---------	------------	--------------------	---------	---

B00T - R0003 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting 4289/B00T/R0001/Ceiling Structures/Linings/S53	55m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
----------------------------	--	------	------------	--------------------	---------	---

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00U - General Learning - 2000 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					
Eaves Linings	Flat AC Sheeting 4289/B00U/Eaves Linings/S51					No Asbestos Detected

Interior

B00U - R0001 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00U - R0002 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00U - R0003 - Practical Activities - 1hb

No Asbestos

B00U - R0004 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00U - R0005 - Practical Activities - 1hb

No Asbestos

B00U - R0006 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00U - R0007 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00U - R0008 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 4289/B00U/R0008/Ceiling Structures/Linings/S52					No Asbestos Detected
----------------------------	--	--	--	--	--	-----------------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00V - Communal Facilities - 2009 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	Non Accessible Area - Area inaccessible
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

Interior

B00V - R0001 - Communal Space

No Asbestos

B00V - R0002 - Raised Platform

No Asbestos

B00V - R0003 - Movement

No Asbestos

B00V - R0004 - Movement

No Asbestos

B00V - R0005 - Movement

No Asbestos

B00V - R0006 - Hall Chair Store

No Asbestos

B00V - R0007 - Communal/Performance Store

No Asbestos

B00V - R0008 - P.E. Store

No Asbestos

B00V - R0009 - Toilets - Girls

No Asbestos

B00V - R0010 - Toilet - Lobby

No Asbestos

B00V - R0011 - Sound Cupboard

No Asbestos

B00V - R0012 - Toilets - Boys

No Asbestos

B00V - R0013 - Toilet - Lobby

No Asbestos

B00V - R0014 - Cleaning Distributed Store

No Asbestos

B00V - R0015 - Plant

No Asbestos

B00V - R0016 - Access Shower/Toilet

No Asbestos

B00V - R0017 - Main Switch Board

No Asbestos

B00V - R0018 - External Movement

No Asbestos

B00V - R0019 - Covered Outdoor Learning Area

No Asbestos

B00V - R0020 - External Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00W - Library - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible
Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible

Interior

B00W - R0001 - External Movement

No Asbestos

B00W - R0002 - Toilet - Lobby

No Asbestos

B00W - R0003 - Staff Toilet

No Asbestos

B00W - R0004 - Cleaning Distributed Store

No Asbestos

B00W - R0005 - Main Switch Board

No Asbestos

B00W - R0006 - Reading Area

No Asbestos

B00W - R0007 - K.L.A. Store

No Asbestos

B00W - R0008 - Communications Room

No Asbestos

B00W - R0009 - Library Office/Workroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017