

# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Lapstone Public School (4424)  
**Region :** Western Sydney  
**State Electorate :** Penrith  
**Local Government Area :** Blue Mountains

**Initial Survey :** Noel Arnold & Associates : 26 - Mar - 2008  
**Reviewed By :** Parsons Brinckerhoff : 07 - Feb - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - Administration/General Learning - 1971 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor void	No Asbestos Found
Ceiling Voids	No Asbestos Found

**Interior**

**B00A - R0002 - Staff Toilet**

No Asbestos

**B00A - R0005 - General Storeroom**

No Asbestos

**B00A - R0006 - Personal Effects Storage**

No Asbestos

**B00A - R0007 - Home Base Store**

No Asbestos

**B00A - R0008 - Toilets - Boys/Girls**

No Asbestos

**B00A - R0009 - Home Base**

No Asbestos

**B00A - R0010 - Home Base**

No Asbestos

**B00A - R0011 - Toilets - Boys/Girls**

No Asbestos

**B00A - R0012 - Home Base Store**

No Asbestos

**B00A - R0013 - Personal Effects Storage**

No Asbestos

**B00A - R0014 - Staff Toilet**

No Asbestos

**B00A - R0015 - Canteen Office/Store**

Floor Coverings Res/Textile	Vinyl Tiles	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4424/B00A/R0025/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	

**B00A - R0016 - Canteen Office/Store**

Floor Coverings Res/Textile	Vinyl Tiles	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4424/B00A/R0025/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	

**B00A - R0017 - Canteen**

Floor Coverings Res/Textile	Vinyl Tiles	24m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4424/B00A/R0025/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	

**B00A - R0018 - Movement**

No Asbestos

**B00A - R0019 - Main Switch Board**

Electrical Mounting Board	Resinous Board					<b>No Asbestos Detected</b>
4424/B00A/R0019/Electrical Mounting Board/S3						

**B00A - R0020 - Cleaning Distributed Store**

No Asbestos

**B00A - R0021 - Staff Toilet**

No Asbestos

**B00A - R0022 - Principal**

No Asbestos

**B00A - R0025 - Security Store**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4424/B00A/R0025/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0027 - General Storeroom</b>						
Floor Coverings Res/Textile	Vinyl Tiles	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4424/B00A/R0025/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0028 - Entry Vestibule</b>						
No Asbestos						
<b>B00A - R0029 - Clerical Office</b>						
No Asbestos						
<b>B00A - R0030 - Interview</b>						
No Asbestos						
<b>B00A - R0031 - Sick Bay</b>						
No Asbestos						
<b>B00A - R0033 - External Movement</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - Pupil Facilities - 1971 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor void	No Asbestos Found
Ceiling Voids	No Asbestos Found

**Interior**

**B00B - R0001 - Shelter**

No Asbestos

**B00B - R0002 - External Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - General Learning/Pupil Facilities - 1971 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor void	No Asbestos Found
Ceiling voids	No Asbestos Found

**Interior**

**B00C - R0002 - Home Base Store**

No Asbestos

**B00C - R0003 - Home Base**

No Asbestos

**B00C - R0004 - Personal Effects Storage**

No Asbestos

**B00C - R0005 - Toilets - Boys**

Partition Walls (Cubicles)	Compressed AC Sheet	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4424/B00C/R0005/Partition Walls (Cubicles)/S2					<b>Chrysotile (white asbestos)</b>	

**B00C - R0006 - Cleaning Supplies**

No Asbestos

**B00C - R0007 - Personal Effects Storage**

No Asbestos

**B00C - R0008 - Home Base Store**

No Asbestos

**B00C - R0009 - Home Base**

No Asbestos

**B00C - R0010 - Home Base**

No Asbestos

**B00C - R0011 - Home Base Store**

No Asbestos

**B00C - R0012 - Music Store**

No Asbestos

**B00C - R0013 - Movement**

No Asbestos

**B00C - R0014 - General Storeroom**

Floor Coverings Res/Textile	Vinyl Tiles	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4424/B00A/R0025/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	

**B00C - R0015 - Toilets - Girls**

Partition Walls (Cubicles)	Compressed AC Sheet	16m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4424/B00C/R0005/Partition Walls (Cubicles)/S2					<b>Chrysotile (white asbestos)</b>	

**B00C - R0016 - Personal Effects Storage**

No Asbestos

**B00C - R0017 - Distribution Board**

No Asbestos

Note: No inspection of live electrical installation.

**B00C - R0018 - Home Base Store**

No Asbestos

**B00C - R0019 - Home Base**

No Asbestos

**B00C - R0020 - Hall Chair Store**

No Asbestos

**B00C - R0021 - Communal/Performance Store**

No Asbestos

**B00C - R0022 - Covered Outdoor Learning Area**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

**B00C - R0023 - External Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Building Services/Communal Facilities - 1972 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling voids	No Asbestos Found
Underfloor void	No Asbestos Found

**Interior**

**B00D - R0001 - Garden Store**

No Asbestos

**B00D - R0002 - Garden Store**

No Asbestos

**B00D - R0003 - Sports Store**

No Asbestos

**B00D - R0004 - External Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00E - General Learning/Pupil Facilities - 1972 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor void

Ceiling voids                      No Asbestos Found

**Interior**

**B00E - R0002 - Practical Activities - 1hb**

No Asbestos

**B00E - R0003 - Home Base**

No Asbestos

**B00E - R0004 - Toilets - Girls**

No Asbestos

**B00E - R0005 - Cleaning Distributed Store**

No Asbestos

**B00E - R0006 - Practical Activities - 1hb**

No Asbestos

**B00E - R0007 - Home Base**

No Asbestos

**B00E - R0008 - General Storeroom**

No Asbestos

**B00E - R0009 - Home Base**

No Asbestos

**B00E - R0010 - Practical Activities - 1hb**

No Asbestos

**B00E - R0011 - Toilets - Boys**

No Asbestos

**B00E - R0012 - Disabled Toilet**

No Asbestos

**B00E - R0013 - Practical Activities - 1hb**

No Asbestos

**B00E - R0014 - Home Base**

No Asbestos

**B00E - R0015 - External Movement**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00F - Administration - 1972 - Steel (Steel)**

**Exterior**

Ceiling Voids No Asbestos Found

Underfloor void

**Interior**

**B00F - R0001 - General Storeroom**

No Asbestos

**B00F - R0002 - External Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - Other-After School Care - 1972 - Steel (Steel)**

**Exterior**

Underfloor void	No Asbestos Found
Ceiling Voids	No Asbestos Found

**Interior**

**B00G - R0001 - Out Of School Hours Care Centre**

No Asbestos

**B00G - R0002 - Out Of School Hours Care Centre**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - Other-After School Care - 1972 - Fibre Cement Clad (Fibre Cement Clad)**

**Exterior**

Eaves Linings	Flat AC Sheeting 4424/B00H/Eaves Linings/S4					No Asbestos Detected
Underfloor void	No Asbestos Found					
Ceiling Voids	No Asbestos Found					

**Interior**

**B00H - R0002 - Out Of School Hours Care Centre**

No Asbestos

**B00H - R0003 - Out Of School Hours Care Centre**

No Asbestos

**B00H - R0005 - Out Of School Hours Care Centre**

No Asbestos

**B00H - R0006 - Out Of School Hours Care Centre**

No Asbestos

**B00H - R0007 - Out Of School Hours Care Centre**

No Asbestos

**B00H - R0008 - Out Of School Hours Care Centre**

No Asbestos

**B00H - R0009 - Out Of School Hours Care Centre**

No Asbestos

**B00H - R0010 - Out Of School Hours Care Centre**

No Asbestos

**B00H - R0011 - Out Of School Hours Care Centre**

No Asbestos

**B00H - R0012 - Out Of School Hours Care Centre**

No Asbestos

**B00H - R0013 - Out Of School Hours Care Centre**

No Asbestos

**B00H - R0014 - Out Of School Hours Care Centre**

No Asbestos

**B00H - R0015 - Out Of School Hours Care Centre**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00J - Pupil Facilities/Communal Facilities - 2010 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor void	

**Interior**

**B00J - R0001 - Communal Space**

No Asbestos

**B00J - R0002 - Raised Platform**

No Asbestos

**B00J - R0003 - Movement**

No Asbestos

**B00J - R0004 - Movement**

No Asbestos

**B00J - R0005 - Ramp**

No Asbestos

**B00J - R0006 - Hall Chair Store**

No Asbestos

**B00J - R0007 - Communal/Performance Store**

No Asbestos

**B00J - R0008 - P.E. Store**

No Asbestos

**B00J - R0009 - Toilet - Lobby**

No Asbestos

**B00J - R0010 - Toilets - Girls**

No Asbestos

**B00J - R0011 - Sound Cupboard**

No Asbestos

**B00J - R0012 - Toilet - Lobby**

No Asbestos

**B00J - R0013 - Toilets - Boys**

No Asbestos

**B00J - R0014 - Cleaning Distributed Store**

No Asbestos

**B00J - R0015 - Plant**

No Asbestos

**B00J - R0016 - Disabled Shower/Toilet**

No Asbestos

**B00J - R0017 - Main Switch Board**

No Asbestos

**B00J - R0018 - Covered Outdoor Learning Area**

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00K - Special Purpose/General Learning - 2013 - Steel (Steel)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor void	

**Interior**

**B00K - R0001 - Withdrawal Space - 1hb**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

## Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

**OS 521 - D13333 - Staff Study : Placement Date - 12/01/2004**

### Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

### Interior

#### R1 - Staff Room

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

#### R2 - Staff Toilet

Toilet partitions	Compressed AC Sheet	Assumed Asbestos	6 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	4 m2

#### R3 - Staff Toilet

Toilet partitions	Compressed AC Sheet	Assumed Asbestos	6 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	4 m2

#### R4 - Lobby

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2

**OS 534 - D14349 - Library/Group Study/Office/A V Store : Placement Date - 30/06/1995**

### Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	23.04 m2

### Interior

#### R1 - Clerical Office

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

#### R2 - Staff Room

Ceiling	Flat AC Sheet	Assumed Asbestos	36 m2
---------	---------------	------------------	-------

#### R3 - Security Store

Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2
---------	---------------	------------------	------

#### R4 - Principal

Ceiling	Flat AC Sheet	Assumed Asbestos	16 m2
---------	---------------	------------------	-------

#### R5 - Staff Toilet

Toilet partitions	Compressed AC Sheet	Assumed Asbestos	4 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	5 m2

#### R6 - Staff Toilet

Toilet partitions	Compressed AC Sheet	Assumed Asbestos	4 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	5 m2

#### R7 - Reading Area

Ceiling	Flat AC Sheet	Assumed Asbestos	54 m2
---------	---------------	------------------	-------

#### R8 - Entry

Ceiling	Flat AC Sheet	Assumed Asbestos	14 m2
---------	---------------	------------------	-------

**OS 602 - D14545 - Learning Unit - Standard With P.A.A. : Placement Date - 19/11/2015**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
No Asbestos Found.						
<b>R2 - Home Base Store</b>						
No Asbestos Found.						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017