


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Lake Cathie Public School (4654)
Region : North Coast
State Electorate : Port Macquarie
Local Government Area : Port Macquarie-Hastings

Initial Survey : :
Register Issue Date : 23 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration - 2014 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00A - R0001 - Clerical/Printing

No Asbestos

B00A - R0002 - Entry Vestibule

No Asbestos

B00A - R0003 - Principal

No Asbestos

B00A - R0004 - Sick Bay

No Asbestos

B00A - R0005 - Deputy Principal - Type 1

No Asbestos

B00A - R0006 - Interview

No Asbestos

B00A - R0007 - Interview

No Asbestos

B00A - R0008 - Toilets-Unisex

No Asbestos

B00A - R0009 - Toilets-Unisex

No Asbestos

B00A - R0010 - Toilets-Unisex

No Asbestos

B00A - R0011 - Disabled Toilet

No Asbestos

B00A - R0012 - Security Store

No Asbestos

B00A - R0013 - Staff Room

No Asbestos

B00A - R0014 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0015 - Plant

No Asbestos

B00A - R0016 - Staff Kitchen

No Asbestos

B00A - R0017 - External Movement

No Asbestos

B00A - R0018 - Movement

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Library/Pupil Facilities - 2014 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00B - R0001 - Reading Area

No Asbestos

B00B - R0002 - Library Office/Workroom

No Asbestos

B00B - R0003 - K.L.A. Store

No Asbestos

B00B - R0004 - Communications Room

No Asbestos

B00B - R0005 - Special Programs Room

No Asbestos

B00B - R0006 - Special Programs Store

No Asbestos

B00B - R0007 - Cleaning Supplies

No Asbestos

B00B - R0008 - General Assistant/Bulk Store

No Asbestos

B00B - R0009 - Access Shower/Toilet/Change

No Asbestos

B00B - R0010 - Toilets - Boys

No Asbestos

B00B - R0011 - Toilets - Girls

No Asbestos

B00B - R0012 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00B - R0013 - Plant

No Asbestos

B00B - R0014 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00C - Communal Facilities - 2014 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00C - R0001 - Garden Store

No Asbestos

B00C - R0002 - Access Shower/Toilet/Change

No Asbestos

B00C - R0003 - Cleaning Distributed Store

No Asbestos

B00C - R0004 - Movement

No Asbestos

B00C - R0005 - Movement

No Asbestos

B00C - R0006 - Sound Cupboard

No Asbestos

B00C - R0007 - Hall Chair Store

No Asbestos

B00C - R0008 - P.E. Store

No Asbestos

B00C - R0009 - Communal/Performance Store

No Asbestos

B00C - R0010 - Sports Store

No Asbestos

B00C - R0011 - Movement

No Asbestos

B00C - R0012 - Plant

No Asbestos

B00C - R0013 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0014 - Toilets - Girls

No Asbestos

B00C - R0015 - Toilets - Boys

No Asbestos

B00C - R0016 - Raised Platform

No Asbestos

B00C - R0017 - Communal Space

No Asbestos

B00C - R0018 - External Movement

No Asbestos

B00C - R0019 - Ramp

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Communal Facilities - 2014 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00D - R0001 - Canteen

No Asbestos

B00D - R0002 - Canteen Office/Store

No Asbestos

B00D - R0003 - External Movement

No Asbestos

B00D - R0004 - Servery Covered Area

No Asbestos

B00D - R0005 - External Movement

No Asbestos

B00D - R0006 - Distribution Board

No Asbestos

Note: No inspection of live electrical installation.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

NS 100 - D12377 - Learning Unit - Single Primary/PAA : Placement Date - 8/08/2014

Exterior

No Asbestos Found.

Interior

R1 - Home Base

No Asbestos Found.

R2 - Practical Activity Area

No Asbestos Found.

R3 - Home Base Store

No Asbestos Found.

R4 - Entry

No Asbestos Found.

NS 100 - D12432 - Learning Unit - Single Primary/PAA : Placement Date - 4/08/2014

Exterior

No Asbestos Found.

Interior

R1 - Home Base

No Asbestos Found.

R2 - Practical Activity Area

No Asbestos Found.

R3 - Home Base Store

No Asbestos Found.

R4 - Entry

No Asbestos Found.

NS 100 - D15887 - Learning Unit - Single Primary/PAA : Placement Date - 5/08/2014

Exterior

No Asbestos Found.

Interior

R1 - Home Base

No Asbestos Found.

R2 - Practical Activity Area

No Asbestos Found.

R3 - Home Base Store

No Asbestos Found.

R4 - Entry

No Asbestos Found.

NS 100 - D16170 - Learning Unit - Single Primary/PAA : Placement Date - 7/08/2014

Exterior

No Asbestos Found.



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Interior

R1 - Home Base

No Asbestos Found.

R2 - Practical Activity Area

No Asbestos Found.

R3 - Home Base Store

No Asbestos Found.

R4 - Entry

No Asbestos Found.

NS 100 - D16821 - Learning Unit - Single Primary/PAA : Placement Date - 4/08/2014

Exterior

No Asbestos Found.

Interior

R1 - Home Base

No Asbestos Found.

R2 - Practical Activity Area

No Asbestos Found.

R3 - Home Base Store

No Asbestos Found.

R4 - Entry

No Asbestos Found.

NS 100 - D16904 - Learning Unit - Single Primary/PAA : Placement Date - 6/08/2014

Exterior

No Asbestos Found.

Interior

R1 - Home Base

No Asbestos Found.

R2 - Practical Activity Area

No Asbestos Found.

R3 - Home Base Store

No Asbestos Found.

R4 - Entry

No Asbestos Found.

NS 100 - D16905 - Learning Unit - Single Primary/PAA : Placement Date - 7/08/2014

Exterior

No Asbestos Found.

Interior

R1 - Home Base

No Asbestos Found.

R2 - Practical Activity Area


No Asbestos Found.

R3 - Home Base Store

No Asbestos Found.

R4 - Entry

No Asbestos Found.



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

NS 100 - D16906 - Learning Unit - Single Primary/PAA : Placement Date - 7/08/2014

Exterior

No Asbestos Found.

Interior

R1 - Home Base

No Asbestos Found.

R2 - Practical Activity Area

No Asbestos Found.

R3 - Home Base Store

No Asbestos Found.

R4 - Entry

No Asbestos Found.

NS 100 - D16907 - Learning Unit - Single Primary/PAA : Placement Date - 5/08/2014

Exterior

No Asbestos Found.

Interior

R1 - Home Base

No Asbestos Found.

R2 - Practical Activity Area

No Asbestos Found.

R3 - Home Base Store

No Asbestos Found.

R4 - Entry

No Asbestos Found.

NS 100 - D16908 - Learning Unit - Single Primary/PAA : Placement Date - 6/08/2014

Exterior

No Asbestos Found.

Interior

R1 - Home Base

No Asbestos Found.

R2 - Practical Activity Area

No Asbestos Found.

R3 - Home Base Store

No Asbestos Found.

R4 - Entry

No Asbestos Found.



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017