

# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Lakeside School (5686)  
**Region :** Hunter/Central Coast  
**State Electorate :** Charlestown  
**Local Government Area :** Lake Macquarie

**Initial Survey :** Noel Arnold & Associates : 22 - Apr - 2008  
**Reviewed By :** AECOM : 29 - Jun - 2016



# 2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - Library - 1971 - Timber (Timber)****Exterior**

Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible no void entrance located.					
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Infill panels	Compressed AC Sheet	80m2	Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	5686/B00G/R0008/In-fill-panel/S3					<b>Chrysotile (white asbestos)</b>

**Interior****B00E - R0001 - External Movement**

No Asbestos

**B00E - R0003 - Clerical Office/Workroom**

Wall Linings Internal	Compressed AC Sheet	8m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	5686/B00G/R0008/In-fill-panel/S3					<b>Chrysotile (white asbestos)</b>

**B00E - R0004 - Clerical Office/Workroom**

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	12.79m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	5686/B00G/R0011/Floor Coverings Res/Textile/S9					<b>Chrysotile (white asbestos)</b>
Wall Linings Internal	Compressed AC Sheet	8m2	North, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	5686/B00G/R0008/In-fill-panel/S3					<b>Chrysotile (white asbestos)</b>

**B00E - R0005 - Home Base**

Wall Linings Internal	Compressed AC Sheet	28m2	Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	5686/B00G/R0008/In-fill-panel/S3					<b>Chrysotile (white asbestos)</b>

**B00E - R0006 - Practical Activities/Movement - 1hb**

Wall Linings Internal	Compressed AC Sheet	3m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	5686/B00G/R0008/In-fill-panel/S3					<b>Chrysotile (white asbestos)</b>

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - Staff Facilities/General Learning - 1971 - Timber (Timber)****Exterior**

Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible no void entrance located					
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Infill panels	Compressed AC Sheet	70m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	5686/B00G/R0008/In-fill-panel/S3					<b>Chrysotile (white asbestos)</b>

**Interior****B00F - R0002 - Sports Store**

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 5686/B00F/R0002/Floor Coverings Res/Textile/S10					<b>No Asbestos Detected</b>
Wall Linings Internal	Compressed AC Sheet	7m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	5686/B00G/R0008/In-fill-panel/S3					<b>Chrysotile (white asbestos)</b>
Wall Linings Internal	Flat AC Sheeting	13.5m2	North and West	Good Condition (1)	Low (1)	Low Priority (2-3)
	5686/B00G/R0011/Wall Linings Internal/S8					<b>Chrysotile (white asbestos)</b>

**B00F - R0003 - Home Base**

Wall Linings Internal	Flat AC Sheeting	32m2	East and West	Good Condition (1)	Low (1)	Low Priority (2-3)
	5686/B00G/R0011/Wall Linings Internal/S8					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 5686/B00G/R0011/Floor Coverings Res/Textile/S9	52.03m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
Wall Linings Internal	Compressed AC Sheet	14m2	North and South	Good Condition (1)	Low (1)	Low Priority (2-3)
	5686/B00G/R0008/In-fill-panel/S3					<b>Chrysotile (white asbestos)</b>

**B00F - R0004 - Staff Room**

Wall Linings Internal	Flat AC Sheeting	32m2	East and West	Good Condition (1)	Low (1)	Low Priority (2-3)
	5686/B00G/R0011/Wall Linings Internal/S8					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 5686/B00G/R0011/Floor Coverings Res/Textile/S9	52.1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
Wall Linings Internal	Compressed AC Sheet	14m2	North and South	Good Condition (1)	Low (1)	Low Priority (2-3)
	5686/B00G/R0008/In-fill-panel/S3					<b>Chrysotile (white asbestos)</b>

**B00F - R0005 - General Storeroom**

Ceiling Structures/Linings	Flat AC Sheeting	4.05m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	5686/B00I/R0004/Wall Linings Internal/S4					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 5686/B00G/R0011/Floor Coverings Res/Textile/S9	4.05m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
Wall Linings Internal	Compressed AC Sheet	12m2	North and West	Good Condition (1)	Low (1)	Low Priority (2-3)
	5686/B00I/R0004/Wall Linings Internal/S4					<b>Chrysotile (white asbestos)</b>

**B00F - R0006 - Sick Bay**

Floor Coverings Res/Textile	Vinyl Tiles 5686/B00G/R0011/Floor Coverings Res/Textile/S9	5.12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
Wall Linings Internal	Flat AC Sheeting	12m2	East and North	Good Condition (1)	Low (1)	Low Priority (2-3)
	5686/B00G/R0011/Wall Linings Internal/S8					<b>Chrysotile (white asbestos)</b>

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Wall Linings Internal	Compressed AC Sheet	4.5m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
5686/B00G/R0008/In-fill-panel/S3					Chrysotile (white asbestos)	
<b>B00F - R0007 - Movement</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
5686/B00G/R0011/Floor Coverings Res/Textile/S9					Chrysotile (white asbestos)	
Wall Linings Internal	Compressed AC Sheet	5m2	East and West	Good Condition (1)	Low (1)	Low Priority (2-3)
5686/B00G/R0008/In-fill-panel/S3					Chrysotile (white asbestos)	
<b>B00F - R0008 - General Storeroom</b>						
Floor Coverings Res/Textile	Vinyl Tiles	4.09m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
5686/B00G/R0011/Floor Coverings Res/Textile/S9					Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	4.09m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
5686/B00I/R0004/Wall Linings Internal/S4					Chrysotile (white asbestos)	
Wall Linings Internal	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
5686/B00I/R0004/Wall Linings Internal/S4					Chrysotile (white asbestos)	
<b>B00F - R0009 - External Movement</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - General Learning - 1971 - Timber (Timber)****Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible no void entrance located.					
Eaves Linings	Flat AC Sheeting 5686/B00G/Eaves Linings/S1	80m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Infill panels	Compressed AC Sheet 5686/B00G/R0008/In-fill-panel/S3	70m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos)</b>	
Infill panels	Compressed AC Sheet 5686/B00G/R0008/In-fill-panel/S3	70m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos)</b>	

**Interior****B00G - R0004 - External Movement**

No Asbestos

**B00G - R0007 - External Movement**

In-fill-panel	Compressed AC Sheet 5686/B00G/R0008/In-fill-panel/S3	2m	South, West, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos)</b>	

**B00G - R0008 - General Assistant/Bulk Store**

In-fill-panel	Compressed AC Sheet 5686/B00G/R0008/In-fill-panel/S3	2m	South, West, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos)</b>	

**B00G - R0009 - Toilet - S**

Ceiling Structures/Linings	Flat AC Sheeting 5686/B00G/R0010/Ceiling Structures/Linings/S2	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	

**B00G - R0010 - Other**

Wall Linings Internal	Compressed AC Sheet 5686/B00G/R0008/In-fill-panel/S3	6m2	North, East	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos)</b>	

**B00G - R0011 - Communal Space**

Wall Linings Internal	Flat AC Sheeting 5686/B00G/R0011/Wall Linings Internal/S8	21m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos)</b>	
Wall Linings Internal	Compressed AC Sheet 5686/B00G/R0008/In-fill-panel/S3	45m2	Lower Portion North, South, East	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos)</b>	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 5686/B00G/R0011/Floor Coverings Res/Textile/S9	46.05m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos)</b>	

**B00G - R0012 - Communal Space**

Wall Linings Internal	Flat AC Sheeting 5686/B00G/R0011/Wall Linings Internal/S8	25m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos)</b>	
Wall Linings Internal	Compressed AC Sheet 5686/B00G/R0008/In-fill-panel/S3	45m2	Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos)</b>	

**B00G - R0013 - Other**

Wall Linings Internal	Compressed AC Sheet 5686/B00G/R0008/In-fill-panel/S3	6m2	Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos)</b>	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

### B00H - Pupil Facilities/Building Services - 1971 - Brick/Block (Brick/Block)

#### Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible
Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible no void entrance located.

#### Interior

##### B00H - R0003 - Sports Store

No Asbestos

##### B00H - R0006 - Sports Store

No Asbestos

##### B00H - R0009 - Canteen

No Asbestos

##### B00H - R0010 - Canteen Office/Store

No Asbestos

##### B00H - R0011 - Canteen Office/Store

No Asbestos

##### B00H - R0012 - Canteen

No Asbestos

##### B00H - R0014 - External Movement

No Asbestos

##### B00H - R0020 - General Assistant/Bulk Store

No Asbestos

##### B00H - R0021 - Communal Space

No Asbestos

##### B00H - R0022 - Toilet - S

No Asbestos

##### B00H - R0023 - External Movement

No Asbestos

##### B00H - R0024 - External Movement

No Asbestos

##### B00H - R0025 - Ramp

No Asbestos

##### B00H - R0026 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B001 - Administration/Staff Facilities - 1971 - Timber (Timber)****Exterior**

Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible no void entrance located.					
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Infill panels	Compressed AC Sheet	100m2	Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	5686/B001/R0006/Wall Linings Internal/S6					<b>Chrysotile (white asbestos)</b>

**Interior****B001 - R0001 - External Movement**

No Asbestos

**B001 - R0002 - External Movement**

No Asbestos

**B001 - R0003 - Clerical Office**

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 5686/B001/R0004/Floor Coverings Res/Textile/S5	19.08m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>
Wall Linings Internal	Flat AC Sheeting 5686/B001/R0006/Wall Linings Internal/S7	12m2	West, South	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>
Wall Linings Internal	Compressed AC Sheet 5686/B001/R0006/Wall Linings Internal/S6	8m2	North, East	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>

**B001 - R0004 - Security Store**

Wall Linings Internal	Flat AC Sheeting 5686/B001/R0004/Wall Linings Internal/S4	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 5686/B001/R0004/Floor Coverings Res/Textile/S5	12.83m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>

**B001 - R0005 - Entry Vestibule**

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 5686/B001/R0004/Floor Coverings Res/Textile/S5	26.64m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>
Wall Linings Internal	Flat AC Sheeting 5686/B001/R0006/Wall Linings Internal/S7	25m2	East, North, West	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>
Wall Linings Internal	Compressed AC Sheet 5686/B001/R0006/Wall Linings Internal/S6	5m2	Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>

**B001 - R0006 - Duplicating Workroom**

Wall Linings Internal	Compressed AC Sheet 5686/B001/R0006/Wall Linings Internal/S6	5.5m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>
Wall Linings Internal	Flat AC Sheeting 5686/B001/R0006/Wall Linings Internal/S7	17.31m2	North, East	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 5686/B001/R0004/Floor Coverings Res/Textile/S5	18.16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>

**B001 - R0007 - Cleaning Supplies**

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 5686/B001/R0004/Floor Coverings Res/Textile/S5	6.06m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Wall Linings Internal	Compressed AC Sheet	6m2	South, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	5686/B001/R0006/Wall Linings Internal/S6					<b>Chrysotile (white asbestos)</b>
Wall Linings Internal	Flat AC Sheeting	2.5m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	5686/B001/R0006/Wall Linings Internal/S7					<b>Chrysotile (white asbestos)</b>
<b>B001 - R0008 - Principal</b>						
Wall Linings Internal	Compressed AC Sheet	8m2	North, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	5686/B001/R0006/Wall Linings Internal/S6					<b>Chrysotile (white asbestos)</b>
Wall Linings Internal	Flat AC Sheeting	12m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	5686/B001/R0006/Wall Linings Internal/S7					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	25.83m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	5686/B001/R0004/Floor Coverings Res/Textile/S5					<b>Chrysotile (white asbestos)</b>
<b>B001 - R0009 - Staff Toilet</b>						
Ceiling Structures/Linings	Flat AC Sheeting	4.17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	5686/B001/R0004/Wall Linings Internal/S4					<b>Chrysotile (white asbestos)</b>
Wall Linings Internal	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	5686/B001/R0004/Wall Linings Internal/S4					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	4.17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	5686/B001/R0004/Floor Coverings Res/Textile/S5					<b>Chrysotile (white asbestos)</b>
<b>B001 - R0010 - Staff Toilet</b>						
Wall Linings Internal	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	5686/B001/R0004/Wall Linings Internal/S4					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting	4.15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	5686/B001/R0004/Wall Linings Internal/S4					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	4.15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	5686/B001/R0004/Wall Linings Internal/S4					<b>Chrysotile (white asbestos)</b>
<b>B001 - R0011 - Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting	9.08m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	5686/B001/R0006/Wall Linings Internal/S7					<b>Chrysotile (white asbestos)</b>
Wall Linings Internal	Flat AC Sheeting	35m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	5686/B001/R0006/Wall Linings Internal/S7					<b>Chrysotile (white asbestos)</b>
<b>B001 - R0012 - Distribution Board</b>						
Wall Linings Internal	Flat AC Sheeting	8.5m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	5686/B001/R0006/Wall Linings Internal/S7					<b>Chrysotile (white asbestos)</b>
FC insulation around base of electrical box	Flat AC Sheeting	3m2	Throughout	Some Damage - Unsealed (3)	Medium (2)	Medium Priority (4-5)
	5686/B001/R0006/Wall Linings Internal/S7					<b>Chrysotile (white asbestos)</b>
Electrical Backing Board	Non Accessible Area - Electrical Hazard					

Note: No inspection of live electrical installation.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00J - General Learning - 1971 - Timber (Timber)****Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible no void entrance located.					
In-fill-panels	Compressed AC Sheet	70m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	5686/B00G/R0008/In-fill-panel/S3					<b>Chrysotile (white asbestos)</b>
In-fill-panels	Compressed AC Sheet	70m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	5686/B00G/R0008/In-fill-panel/S3					<b>Chrysotile (white asbestos)</b>

**Interior****B00J - R0007 - General Assistant/Bulk Store**

Wall Linings Internal	Flat AC Sheeting	8m2	North and East	Good Condition (1)	Low (1)	Low Priority (2-3)
	5686/B00G/R0011/Wall Linings Internal/S8					<b>Chrysotile (white asbestos)</b>

**B00J - R0008 - Toilet - S**

No Asbestos

**B00J - R0009 - Communal Space**

Wall Linings Internal	Compressed AC Sheet	28m2	North, West, and South	Good Condition (1)	Low (1)	Low Priority (2-3)
	5686/B00G/R0008/In-fill-panel/S3					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	45.91m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	5686/B00G/R0011/Floor Coverings Res/Textile/S9					<b>Chrysotile (white asbestos)</b>

**B00J - R0010 - Other**

Wall Linings Internal	Compressed AC Sheet	5m2	West and South	Good Condition (1)	Low (1)	Low Priority (2-3)
	5686/B00G/R0008/In-fill-panel/S3					<b>Chrysotile (white asbestos)</b>

**B00J - R0011 - Communal Space**

Wall Linings Internal	Compressed AC Sheet	28m2	North, East, and South	Good Condition (1)	Low (1)	Low Priority (2-3)
	5686/B00G/R0008/In-fill-panel/S3					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	46.16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	5686/B00G/R0011/Floor Coverings Res/Textile/S9					<b>Chrysotile (white asbestos)</b>

**B00J - R0012 - Other**

Wall Linings Internal	Compressed AC Sheet	5m2	South and East	Good Condition (1)	Low (1)	Low Priority (2-3)
	5686/B00G/R0008/In-fill-panel/S3					<b>Chrysotile (white asbestos)</b>

**B00J - R0013 - External Movement**

No Asbestos

**B00J - R0014 - External Movement**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00K - General Learning - 1971 - Timber (Timber)****Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Ceiling Voids - Flat Roof	No Asbestos Found					
In-fill-panels	Compressed AC Sheet	70m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	5686/B00G/R0008/In-fill-panel/S3					<b>Chrysotile (white asbestos)</b>
In-fill-panels	Compressed AC Sheet	70m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	5686/B00G/R0008/In-fill-panel/S3					<b>Chrysotile (white asbestos)</b>

**Interior****B00K - R0007 - External Movement**

No Asbestos

**B00K - R0008 - Communal Space**

Wall Linings Internal	Compressed AC Sheet	22m2	North, East, and South	Good Condition (1)	Low (1)	Low Priority (2-3)
	5686/B00G/R0008/In-fill-panel/S3					<b>Chrysotile (white asbestos)</b>

**B00K - R0009 - Other**

Wall Linings Internal	Compressed AC Sheet	5m2	South and West	Good Condition (1)	Low (1)	Low Priority (2-3)
	5686/B00G/R0008/In-fill-panel/S3					<b>Chrysotile (white asbestos)</b>

**B00K - R0010 - General Assistant/Bulk Store**

Wall Linings Internal	Compressed AC Sheet	3m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	5686/B00G/R0008/In-fill-panel/S3					<b>Chrysotile (white asbestos)</b>
Wall Linings Internal	Flat AC Sheeting	1m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	5686/B00G/R0011/Wall Linings Internal/S8					<b>Chrysotile (white asbestos)</b>

**B00K - R0011 - Toilet - S**

No Asbestos

**B00K - R0012 - Communal Space**

Wall Linings Internal	Compressed AC Sheet	22m2	North, West, and South	Good Condition (1)	Low (1)	Low Priority (2-3)
	5686/B00G/R0008/In-fill-panel/S3					<b>Chrysotile (white asbestos)</b>

**B00K - R0013 - Other**

Wall Linings Internal	Compressed AC Sheet	5m2	South and East	Good Condition (1)	Low (1)	Low Priority (2-3)
	5686/B00G/R0008/In-fill-panel/S3					<b>Chrysotile (white asbestos)</b>

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00L - Mechanical Services - 2013 - Steel (Steel)**

**Exterior**

Underfloor Voids - Slab on Ground      Non Accessible Area  
 - Area inaccessible

Ceiling Voids      No Asbestos Found

**Interior**

**B00L - R0001 - Garage/Carport**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017