


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Lomandra School (5753)
Region : South Western Sydney
State Electorate : Campbelltown
Local Government Area : Campbelltown

Initial Survey : Noel Arnold & Associates : 01 - Apr - 2008
Reviewed By : Parsons Brinckerhoff : 25 - Nov - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Other-Tutorial Centre/Administration - 1978 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids - Raked Ceiling	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior**B00A - R0001 - Special Programs Room**

No Asbestos

B00A - R0002 - Home Base

No Asbestos

B00A - R0003 - Home Base

No Asbestos

B00A - R0004 - Home Base

No Asbestos

B00A - R0005 - Sports Store

No Asbestos

B00A - R0006 - Movement

No Asbestos

B00A - R0007 - Plant

Floor Coverings Res/Textile	Vinyl Tiles	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	5753/B00A/R0007/Floor Coverings Res/Textile/S1				Chrysotile (white asbestos)	
Electrical Mounting Board	Resinous Board	2Unit	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	5753/B00A/R0007/Electrical Mounting Board/S2				Chrysotile (white asbestos)	

B00A - R0008 - No Access

No Asbestos

B00A - R0009 - Movement

No Asbestos

B00A - R0010 - Movement

No Asbestos

B00A - R0011 - Stairs

No Asbestos

B00A - R0012 - Toilets - Girls/Disabled Cubicle

No Asbestos

B00A - R0013 - Toilets - Boys

No Asbestos

B00A - R0015 - Movement

No Asbestos

B00A - R0016 - Staff Study

No Asbestos

B00A - R0017 - General Storeroom

No Asbestos

B00A - R0018 - Interview

No Asbestos

B00A - R0019 - General Storeroom

No Asbestos

B00A - R0020 - General Storeroom

No Asbestos

B00A - R0021 - Staff Toilet

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R0022 - Staff Toilet						
No Asbestos						
B00A - R0023 - Movement						
No Asbestos						
B00A - R0024 - Security Store						
No Asbestos						
B00A - R0027 - No Access						
Electrical Mounting Board	Resinous Board	2Unit	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
5753/B00A/R0027/Electrical Mounting Board/S3					Chrysotile (white asbestos)	
A/C Sheeting	Flat AC Sheeting					
5753/B00A/R0027/A/C Sheeting/S4					No Asbestos Detected	
B00A - R0028 - Main Switch Board						
Electrical Backing Board	Resinous Board					
5753/B00A/R0028/Electrical Backing Board/S5					No Asbestos Detected	
B00A - R0029 - Stairs						
No Asbestos						
B00A - R0030 - Communications Cupboard						
No Asbestos						
B00A - R0032 - Movement						
No Asbestos						
B00A - R0033 - Entry Vestibule						
No Asbestos						
B00A - R0034 - Interview						
No Asbestos						
B00A - R0035 - Clerical Office						
No Asbestos						
B00A - R0036 - Principal						
No Asbestos						
B00A - R0037 - Deputy Principal						
No Asbestos						
B00A - R0038 - Sick Bay						
No Asbestos						
B00A - R0039 - Toilet - Lobby						
No Asbestos						
B00A - R0040 - Staff Toilet						
No Asbestos						
B00A - R0041 - Staff Room						
No Asbestos						
B00A - R0042 - Staff Kitchen						
No Asbestos						
B00A - R0043 - Movement						
No Asbestos						
B00A - R0044 - Movement						
No Asbestos						
B00A - R0045 - External Movement						
No Asbestos						
B00A - R0046 - Practical Activities						
No Asbestos						
B00A - R0047 - Practical Activities						
No Asbestos						
B00A - R1001 - No Access						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
	No Asbestos					
	B00A - R1003 - Stairs					
	No Asbestos					
	B00A - R1004 - Toilets - Boys					
	No Asbestos					
	B00A - R1005 - Toilets - Girls					
	No Asbestos					
	B00A - R1006 - Visual Arts Workshop					
	No Asbestos					
	B00A - R1007 - Visual Arts Store					
	No Asbestos					
	B00A - R1008 - Other - Regional Use					
	No Asbestos					
	B00A - R1009 - Movement					
	No Asbestos					
	B00A - R1010 - Stairs					
	No Asbestos					
	B00A - R1012 - Cleaning Distributed Store					
	No Asbestos					
	B00A - R1013 - Staff Study					
	No Asbestos					
	B00A - R1014 - Main Area					
	No Asbestos					
	B00A - R1015 - Home Base					
	No Asbestos					
	B00A - R1016 - General Storeroom					
	No Asbestos					
	B00A - R1018 - Distribution Board Cupboard					Note: No inspection of live electrical installation.
	No Asbestos					
	B00A - R1019 - Toilet - Lobby					
	No Asbestos					
	B00A - R1020 - Staff Toilet					
	No Asbestos					
	B00A - R1021 - Movement					
	No Asbestos					
	B00A - R1022 - No Access					
	No Asbestos					
	B00A - R1023 - Movement					
	No Asbestos					
	B00A - R1024 - General Storeroom					
	No Asbestos					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Building Services - 2010 - Steel (Steel)**Exterior**

Underfloor Voids - Slab on Ground Non Accessible Area
- No Voids

Ceiling Voids No Asbestos Found

Interior**B00B - R0001 - General Storeroom**

No Asbestos

B00B - R0002 - General Assistant/Bulk Store

No Asbestos

B00B - R0003 - General Storeroom

No Asbestos

B00B - R0004 - Garden Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 601 - D14377 - Learning Unit - Standard/Withdrawal : Placement Date - 27/07/2011

Exterior

No Asbestos Found.

Interior

R1 - Entry

No Asbestos Found.

R2 - General Learning Space

No Asbestos Found.

R3 - Store

No Asbestos Found.

NS 111 - D16254 - Learning Unit - Double Secondary/Secure : Placement Date - 27/10/2010

Exterior

No Asbestos Found.

Interior

R1 - General Learning Space

No Asbestos Found.

R2 - General Learning Space

No Asbestos Found.

R3 - Entry

No Asbestos Found.

R4 - Secure Storeroom

No Asbestos Found.

R5 - Secure Storeroom

No Asbestos Found.

R6 - Entry

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

Available Asbestos Related Electronic Files

5753_ASB_010313_AMP.pdf

* Note : Refer to AMS for details of the attachment(s).

2017