

# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Liverpool Public School (7424)  
**Region :** South Western Sydney  
**State Electorate :** Liverpool  
**Local Government Area :** Liverpool

**Initial Survey :** Noel Arnold & Associates : 31 - Mar - 2008  
**Reviewed By :** Parsons Brinckerhoff : 03 - Jan - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - General Learning/Administration - 1989 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

**Interior**

**B00A - R0001 - Personal Effects Storage**

No Asbestos

**B00A - R0002 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0003 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0004 - Security Store**

No Asbestos

**B00A - R0005 - Practical Activities - 1hb**

No Asbestos

**B00A - R0006 - Cleaning Distributed Store**

No Asbestos

**B00A - R0007 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0008 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0009 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0010 - Personal Effects Storage**

No Asbestos

**B00A - R0011 - Staff Room**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0012 - Staff Room Annexe**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0013 - Clerical Office**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0014 - Deputy Principal**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0015 - Movement**

No Asbestos

**B00A - R0016 - Principal**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0017 - Cleaning Distributed Store**

No Asbestos

**B00A - R0018 - Sick Bay - Shower/Toilet**

No Asbestos

**B00A - R0019 - Sick Bay**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00A - R0020 - Interview</b>						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
<b>B00A - R0021 - Movement</b>						
No Asbestos						
<b>B00A - R0022 - Entry Vestibule</b>						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
<b>B00A - R0023 - Movement</b>						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
<b>B00A - R0024 - Clerical Office</b>						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
<b>B00A - R0025 - Security Store</b>						
No Asbestos						
<b>B00A - R0026 - Distribution Board</b>					Note: No inspection of live electrical installation.	
No Asbestos						
<b>B00A - R0027 - Security Store</b>						
No Asbestos						
<b>B00A - R0028 - Staff Toilet</b>						
No Asbestos						
<b>B00A - R0029 - Staff Toilet</b>						
No Asbestos						
<b>B00A - R0030 - Duplicating Workroom</b>						
No Asbestos						
<b>B00A - R0031 - Movement</b>						
No Asbestos						
<b>B00A - R0032 - Movement</b>						
No Asbestos						
<b>B00A - R0033 - Entry Vestibule</b>						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
<b>B00A - R0034 - Staff Toilet</b>						
No Asbestos						
<b>B00A - R0035 - Community Clinic</b>						
No Asbestos						
<b>B00A - R0036 - Entry Vestibule</b>						
No Asbestos						
<b>B00A - R0037 - Cleaning Distributed Store</b>						
No Asbestos						
<b>B00A - R0038 - Cleaning Supplies</b>						
No Asbestos						
<b>B00A - R0039 - Plant</b>						
No Asbestos						
<b>B00A - R0040 - Distribution Board</b>					Note: No inspection of live electrical installation.	
No Asbestos						
<b>B00A - R0041 - Hall Chair Store</b>						
No Asbestos						
<b>B00A - R0042 - Communal Space</b>						
No Asbestos						
<b>B00A - R0043 - Sports Store</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
<b>B00A - R0044 - Raised Platform</b>						
No Asbestos						
<b>B00A - R0045 - Movement</b>						
No Asbestos						
<b>B00A - R0046 - Movement</b>						
No Asbestos						
<b>B00A - R0047 - Plant</b>						
No Asbestos						
<b>B00A - R0048 - General Assistant/Bulk Store</b>						
No Asbestos						
<b>B00A - R0049 - Cleaning Supplies</b>						
No Asbestos						
<b>B00A - R0050 - Disabled Toilet</b>						
No Asbestos						
<b>B00A - R0051 - Toilets - Girls</b>						
No Asbestos						
<b>B00A - R0054 - Toilets - Boys</b>						
No Asbestos						
<b>B00A - R0055 - Canteen</b>						
No Asbestos						
<b>B00A - R0056 - Canteen Office/Store</b>						
No Asbestos						
<b>B00A - R0057 - Canteen Office/Store</b>						
No Asbestos						
<b>B00A - R0058 - Garden Store</b>						
No Asbestos						
<b>B00A - R0059 - Main Switch Board</b>						
No Asbestos						
<b>B00A - R1001 - Personal Effects Storage</b>						
No Asbestos						
<b>B00A - R1002 - Home Base</b>						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
<b>B00A - R1003 - Home Base Store</b>						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
<b>B00A - R1004 - Distribution Board</b>					Note: No inspection of live electrical installation.	
No Asbestos						
<b>B00A - R1005 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00A - R1006 - Security Store</b>						
No Asbestos						
<b>B00A - R1007 - Home Base Store</b>						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
<b>B00A - R1008 - Home Base</b>						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
<b>B00A - R1009 - Withdrawal Space - 1hb</b>						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00A - R1010 - Personal Effects Storage</b>						
No Asbestos						
<b>B00A - R1011 - Personal Effects Storage</b>						
No Asbestos						
<b>B00A - R1012 - Home Base</b>						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
<b>B00A - R1013 - Home Base Store</b>						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
<b>B00A - R1014 - Cleaning Distributed Store</b>						
No Asbestos						
<b>B00A - R1015 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00A - R1016 - Security Store</b>						
No Asbestos						
<b>B00A - R1017 - Home Base Store</b>						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
<b>B00A - R1018 - Home Base</b>						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
<b>B00A - R1019 - Withdrawal Space - 1hb</b>						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
<b>B00A - R1020 - Personal Effects Storage</b>						
No Asbestos						
<b>B00A - R1021 - Drinking Facilities</b>						
No Asbestos						
<b>B00A - R1022 - Toilets - Girls</b>						
No Asbestos						
<b>B00A - R1023 - Distribution Board</b>					Note: No inspection of live electrical installation.	
No Asbestos						
<b>B00A - R1024 - Toilets - Boys</b>						
No Asbestos						
<b>B00A - R1025 - General Storeroom</b>						
No Asbestos						
<b>B00A - R1026 - Personal Effects Storage</b>						
No Asbestos						
<b>B00A - R1027 - Home Base</b>						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
<b>B00A - R1028 - Home Base Store</b>						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
<b>B00A - R1029 - Cleaning Distributed Store</b>						
No Asbestos						
<b>B00A - R1030 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00A - R1031 - Security Store</b>						
No Asbestos						
<b>B00A - R1032 - Home Base Store</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00A - R1033 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00A - R1034 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00A - R1035 - Personal Effects Storage**

No Asbestos

**B00A - R1036 - Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - General Learning - 1928 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting	120m2	North facing, South facing, East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	7424/B00B/Eaves Linings/S6					<b>Chrysotile (white asbestos)</b>
Ceiling Void	AC Fragments/Debris	10m2	East	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5)
	7424/B00B/Ceiling Void/S9					<b>Chrysotile (white asbestos)</b>
Underfloor Voids	No Asbestos Found					

**Interior**

**B00B - R0001 - Staff Room Annexe**

No Asbestos

**B00B - R0002 - Home Base**

No Asbestos

**B00B - R0003 - Home Base**

No Asbestos

**B00B - R0004 - Home Base**

No Asbestos

**B00B - R0005 - Home Base**

No Asbestos

**B00B - R0006 - Withdrawal Space - 1hb**

No Asbestos

**B00B - R0007 - Practical Activities - 1hb**

No Asbestos

**B00B - R0008 - Security Store**

No Asbestos

**B00B - R0009 - Movement**

No Asbestos

**B00B - R0010 - Movement**

No Asbestos

**B00B - R0011 - General Storeroom**

No Asbestos

**B00B - R0012 - Movement**

No Asbestos

**B00B - R0013 - Movement**

No Asbestos

**B00B - R0014 - Movement**

No Asbestos

**B00B - R1001 - Cleaning Distributed Store**

No Asbestos

**B00B - R1002 - General Storeroom**

No Asbestos

**B00B - R1003 - Home Base**

No Asbestos

**B00B - R1004 - Home Base**

No Asbestos

**B00B - R1005 - Home Base**

No Asbestos

**B00B - R1006 - Home Base**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00B - R1007 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00B - R1008 - Movement</b>						
No Asbestos						
<b>B00B - R1009 - Movement</b>						
No Asbestos						
<b>B00B - R1010 - Craft Store</b>						
No Asbestos						

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - General Learning - 1882 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids	Flat AC Sheeting 7424/B00C/Underfloor Voids/S8	<b>No Asbestos Detected</b>				
Ceiling Void	Non Accessible Area - No Access - Manhole >6m high					

**Interior**

**B00C - R0001 - Home Base**

No Asbestos

**B00C - R0002 - Withdrawal Space - 1hb**

No Asbestos

**B00C - R0003 - Home Base Store**

No Asbestos

**B00C - R0004 - Home Base Store**

No Asbestos

**B00C - R0005 - Home Base**

No Asbestos

**B00C - R0006 - Practical Activities - 1hb**

No Asbestos

**B00C - R0007 - Distribution Board**

Note: No inspection of live electrical installation.

Floor Coverings Res/Textile	Flat AC Sheeting  7424/B00C/R0007/Floor Coverings Res/Textile/S2	<b>No Asbestos Detected</b>				
--------------------------------	--	-----------------------------	--	--	--	--

**B00C - R0008 - Movement**

No Asbestos

**B00C - R0009 - Toilets - Boys**

No Asbestos

**B00C - R0010 - Toilets - Girls**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00D - Library/Tiered Learning - 1889 - Brick/Block (Brick/Block)****Exterior**

Ceiling Void	Non Accessible Area - No Access - Manhole >5.4m high
Underfloor Voids	No Asbestos Found

**Interior****B00D - R0001 - Library Office/Workroom**

No Asbestos

**B00D - R0002 - General Storeroom**

No Asbestos

**B00D - R0003 - Reading Area**

No Asbestos

**B00D - R0004 - Reading Area**

No Asbestos

**B00D - R0005 - P.E. Store**

No Asbestos

**B00D - R0006 - Movement**

No Asbestos

**B00D - R0007 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00D - R0008 - Disabled Toilet**

No Asbestos

**B00D - R0009 - Cleaning Distributed Store**

No Asbestos

**B00D - R0010 - Plant**

No Asbestos

**B00D - R0011 - Special Programs Room**

No Asbestos

**B00D - R0012 - Special Programs Store**

No Asbestos

**B00D - R0013 - Movement**

No Asbestos

**B00D - R0014 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - General Learning/Support Unit - 1871 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Void	Non Accessible Area - No Access - Manhole >6m high
Underfloor Voids	No Asbestos Found

**Interior**

**B00E - R0001 - Practical Activities - 1hb**

Floor Coverings Res/Textile	Vinyl Sheet 7424/B00E/R0013/Floor Coverings Res/Textile/S4	No Asbestos Detected
Panels under vinyl sheeting	Flat AC Sheeting 7424/B00E/R0012/Floor Coverings Res/Textile/S5	No Asbestos Detected

**B00E - R0002 - Home Base**

Floor Coverings Res/Textile	Vinyl Sheet 7424/B00E/R0013/Floor Coverings Res/Textile/S4	No Asbestos Detected
Panels under vinyl sheeting	Flat AC Sheeting 7424/B00E/R0012/Floor Coverings Res/Textile/S5	No Asbestos Detected

**B00E - R0003 - Withdrawal Space - 1hb**

No Asbestos

**B00E - R0004 - Staff Room Annexe**

Ceiling Structures/Linings	Flat AC Sheeting	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	7424/B00E/R0004/Ceiling Structures/Linings/S10					<b>Chrysotile (white asbestos)</b>

**B00E - R0005 - Movement**

Floor Coverings Res/Textile	Vinyl Sheet 7424/B00E/R0013/Floor Coverings Res/Textile/S4	No Asbestos Detected
Panels under vinyl sheeting	Flat AC Sheeting 7424/B00E/R0012/Floor Coverings Res/Textile/S5	No Asbestos Detected

**B00E - R0006 - Practical Activities - 1hb**

Floor Coverings Res/Textile	Vinyl Sheet 7424/B00E/R0013/Floor Coverings Res/Textile/S4	No Asbestos Detected
Panels under vinyl sheeting	Flat AC Sheeting 7424/B00E/R0012/Floor Coverings Res/Textile/S5	No Asbestos Detected

**B00E - R0007 - Outdoor Learning Area**

No Asbestos

**B00E - R0008 - Withdrawal Space - 1hb**

No Asbestos

**B00E - R0009 - Home Base**

No Asbestos

**B00E - R0010 - Special Programs Room**

No Asbestos

**B00E - R0011 - Personal Effects Storage**

Floor Coverings Res/Textile	Vinyl Sheet 7424/B00E/R0013/Floor Coverings Res/Textile/S4	No Asbestos Detected
Panels under vinyl sheeting	Flat AC Sheeting 7424/B00E/R0012/Floor Coverings Res/Textile/S5	No Asbestos Detected

**B00E - R0012 - Cleaning Distributed Store**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Sheet					
	7424/B00E/R0013/Floor Coverings Res/Textile/S4					<b>No Asbestos Detected</b>
Panels under vinyl sheeting	Flat AC Sheeting					
	7424/B00E/R0012/Floor Coverings Res/Textile/S5					<b>No Asbestos Detected</b>
<b>B00E - R0013 - Home Base Store</b>						
Floor Coverings Res/Textile	Vinyl Sheet					
	7424/B00E/R0013/Floor Coverings Res/Textile/S4					<b>No Asbestos Detected</b>
Panels under vinyl sheeting	Flat AC Sheeting					
	7424/B00E/R0012/Floor Coverings Res/Textile/S5					<b>No Asbestos Detected</b>
<b>B00E - R0014 - General Storeroom</b>						
Floor Coverings Res/Textile	Vinyl Sheet					
	7424/B00E/R0013/Floor Coverings Res/Textile/S4					<b>No Asbestos Detected</b>
Panels under vinyl sheeting	Flat AC Sheeting					
	7424/B00E/R0012/Floor Coverings Res/Textile/S5					<b>No Asbestos Detected</b>
<b>B00E - R0015 - Distribution Board</b>						
Floor Coverings Res/Textile	Flat AC Sheeting					
	7424/B00E/R0015/Floor Coverings Res/Textile/S3					<b>No Asbestos Detected</b>
					Note: No inspection of live electrical installation.	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - General Learning - 1992 - Brick/Veneer (Brick/Veneer)****Exterior**

Underfloor Voids - Slab on Ground      No Asbestos Found

Ceiling Voids      No Asbestos Found

**Interior****B00F - R0001 - Movement**

No Asbestos

**B00F - R0002 - Cleaning Distributed Store**

No Asbestos

**B00F - R0003 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00F - R0004 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00F - R0005 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00F - R0006 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00F - R0007 - Practical Activities - 1hb**

No Asbestos

**B00F - R0008 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - Pupil Facilities - 1989 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	6m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	7424/B00G/Eaves Linings/S7				<b>Chrysotile (white asbestos)</b>	
Ceiling Voids	No Asbestos Found					

**Interior**

**B00G - R0001 - Toilets - Girls**

Partition Walls (Cubicles)	Compressed AC Sheet	12m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	7424/B00G/R0001/Partition Walls (Cubicles)/S1				<b>Chrysotile (white asbestos)</b>	

**B00G - R0002 - Toilets - Boys**

Partition Walls (Cubicles)	Compressed AC Sheet	6m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	7424/B00G/R0001/Partition Walls (Cubicles)/S1				<b>Chrysotile (white asbestos)</b>	

**B00G - R0003 - Staff Toilet**

No Asbestos

**B00G - R0004 - Movement**

No Asbestos

**B00G - R0005 - Staff Toilet**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00H - General Learning - 2010 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

**Interior**

**B00H - R0001 - Practical Activities - 1hb**

No Asbestos

**B00H - R0002 - Home Base**

No Asbestos

**B00H - R0003 - Home Base Store**

No Asbestos

**B00H - R0004 - Withdrawal Space - 1hb**

No Asbestos

**B00H - R0005 - Practical Activities - 1hb**

No Asbestos

**B00H - R0006 - Home Base**

No Asbestos

**B00H - R0007 - Home Base Store**

No Asbestos

**B00H - R0008 - Withdrawal Space - 2hb**

No Asbestos

**B00H - R0009 - Practical Activities - 1hb**

No Asbestos

**B00H - R0010 - Home Base**

No Asbestos

**B00H - R0011 - Home Base Store**

No Asbestos

**B00H - R0012 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00H - R0013 - External Movement**

No Asbestos

**B00H - R0014 - External Stairs**

No Asbestos

**B00H - R1001 - Practical Activities - 1hb**

No Asbestos

**B00H - R1002 - Home Base**

No Asbestos

**B00H - R1003 - Home Base Store**

No Asbestos

**B00H - R1004 - Withdrawal Space - 1hb**

No Asbestos

**B00H - R1005 - Practical Activities - 1hb**

No Asbestos

**B00H - R1006 - Home Base**

No Asbestos

**B00H - R1007 - Home Base Store**

No Asbestos

**B00H - R1008 - Withdrawal Space - 2hb**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00H - R1009 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00H - R1010 - Home Base</b>						
No Asbestos						
<b>B00H - R1011 - Home Base Store</b>						
No Asbestos						
<b>B00H - R1012 - External Movement</b>						
No Asbestos						
<b>B00H - R1013 - External Stairs</b>						
No Asbestos						

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

## Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

**OS 601 - D11247 - Learning Unit - Standard/Withdrawal : Placement Date - 12/01/2001**

### Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

### Interior

#### R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

#### R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

#### R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2
---------	---------------	------------------	-------

**OS 604 - D11320 - Learning Unit - Single Kindergarten : Placement Date - 30/06/1995**

### Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	14.4 m2

### Interior

#### R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

#### R2 - Home Base/Kindergarten

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	73 m2

#### R3 - Practical Activity Area

Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2
---------	---------------	------------------	------

#### R4 - Trainer toilet

Toilet partitions	Compressed AC Sheet	Assumed Asbestos	4 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	1 m2

#### R5 - Cupboard

Ceiling	Flat AC Sheet	Assumed Asbestos	1 m2
---------	---------------	------------------	------

**OS 601 - D11643 - Learning Unit - Standard/Withdrawal : Placement Date - 23/07/1998**

### Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>Interior</b>						
<b>R1 - Entry</b>						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
<b>R2 - General Learning Space</b>						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
<b>R3 - Store</b>						
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2
<b>OS 602 - D13651 - Learning Unit - Standard With P.A.A. : Placement Date - 1/02/2006</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
No Asbestos Found.						
<b>R2 - Home Base Store</b>						
No Asbestos Found.						
<b>OS 602 - D15364 - Learning Unit - Standard With P.A.A. : Placement Date - 18/08/2016</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
No Asbestos Found.						
<b>R2 - Home Base Store</b>						
No Asbestos Found.						
<b>OS 603 - D18182 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 2/01/2006</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
No Asbestos Found.						
<b>R2 - Home Base Store</b>						
No Asbestos Found.						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Listing of Electronic Attachments as of 22/03/2017***

**There are no asbestos related file attachment(s) for this school.**

2017