


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Lake Munmorah High School (8279)
Region : Hunter/Central Coast
State Electorate : Swansea
Local Government Area : Wyong

Initial Survey : Noel Arnold & Associates : 14 - Mar - 2008
Register Issue Date : 24 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00A - Administration/Staff Facilities - 2001 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00A - R0001 - Interview/Office - Type 1**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0002 - Interview/Office - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0003 - Clinic - Boys

No Asbestos

B00A - R0004 - Staff - Toilet

No Asbestos

B00A - R0005 - Staff - Toilet

No Asbestos

B00A - R0006 - Clinic - Girls

No Asbestos

B00A - R0007 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0008 - Principal Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0009 - Staff - Toilet

No Asbestos

B00A - R0010 - Staff - Toilet

No Asbestos

B00A - R0013 - Interview/Office - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0014 - Public Entry

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0016 - Staff Kitchen

No Asbestos

B00A - R0017 - Administration - Clerical

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0019 - Pupil Entry

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0020 - External Movement

No Asbestos

B00A - R0021 - Interview/Office - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0022 - Deputy Principal Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0023 - Cleaning Supplies Store

No Asbestos

B00A - R0024 - Security Store

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
	No Asbestos					
	B00A - R0025 - Security Store					
	No Asbestos					
	B00A - R0026 - Security Store					
	No Asbestos					
	B00A - R0027 - Cleaning Store - Distributed					
	No Asbestos					
	B00A - R0028 - Distribution Board Cupboard			Note: No inspection of live electrical installation.		
	No Asbestos					
	B00A - R0029 - Plant					
	No Asbestos					
	B00A - R0030 - Distribution Board Cupboard			Note: No inspection of live electrical installation.		
	No Asbestos					
	B00A - R0031 - Plant					
	No Asbestos					
	B00A - R0032 - External Stairs					
	No Asbestos					
	B00A - R0033 - Stairs					
	No Asbestos					
	B00A - R0034 - External Movement					
	No Asbestos					
	B00A - R0035 - Interview/Meeting					
	No Asbestos					
	B00A - R0036 - Movement					
	No Asbestos					
	B00A - R0037 - Administration - Clerical					
	No Asbestos					
	B00A - R1001 - Staff Study					
	Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found				
	B00A - R1002 - Commonroom					
	Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found				
	B00A - R1003 - Staff Study					
	Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found				
	B00A - R1004 - Staff - Toilet					
	No Asbestos					
	B00A - R1005 - Staff - Toilet					
	No Asbestos					
	B00A - R1006 - Staff - Toilet					
	No Asbestos					
	B00A - R1007 - Disabled Toilet					
	No Asbestos					
	B00A - R1008 - Staff - Toilet					
	No Asbestos					
	B00A - R1009 - Staff - Toilet					
	No Asbestos					
	B00A - R1010 - Interview/Office - Type 1					
	Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found				
	B00A - R1011 - Interview/Office - Type 1					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R1012 - Duplicating Workroom						
No Asbestos						
B00A - R1013 - Interview/Office - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R1014 - Interview/Office - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R1015 - Plant						
No Asbestos						
B00A - R1016 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B00A - R1017 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B00A - R1018 - Plant						
No Asbestos						
B00A - R1019 - Movement						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R1020 - External Movement						
No Asbestos						
B00A - R1021 - External Movement						
No Asbestos						
B00A - R1022 - External Stairs						
No Asbestos						
B00A - R1023 - Stairs						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Technological & Applied Studies/Pupil Facilities - 2001 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00B - R0001 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0002 - General Learning Space

No Asbestos

B00B - R0003 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0004 - General Learning Space

No Asbestos

B00B - R0005 - General Learning Space

No Asbestos

B00B - R0006 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0007 - Garden Store Room

No Asbestos

B00B - R0008 - Toilets - Boys

No Asbestos

B00B - R0010 - Toilets - Girls

No Asbestos

B00B - R0012 - Darkroom Space

No Asbestos

B00B - R0013 - Cleaning Store - Distributed

No Asbestos

B00B - R0015 - Materials Workshop - Type 2

No Asbestos

B00B - R0016 - Resource/Project Store

No Asbestos

B00B - R0017 - Secure Storeroom

No Asbestos

B00B - R0025 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00B - R0028 - Materials Workshop - Type 2

No Asbestos

B00B - R0029 - Resource/Project Store

No Asbestos

B00B - R0030 - Dust Extraction Space

No Asbestos

B00B - R0031 - Toilets-Disabled

No Asbestos

B00B - R0032 - Dust Extraction Space

No Asbestos

B00B - R0033 - Staff - Toilet

No Asbestos

B00B - R0034 - Staff Shower

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
B00B - R0035 - Materials Workshop - Type 2						
No Asbestos						
B00B - R0036 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B00B - R0037 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B00B - R0038 - Other-Vacant						
No Asbestos						
B00B - R0039 - Main Switchroom						
No Asbestos						
B00B - R0040 - External Movement						
No Asbestos						
B00B - R0041 - Movement						
No Asbestos						
B00B - R0042 - Stairs						
No Asbestos						
B00B - R0043 - Craft Store						
No Asbestos						
B00B - R0044 - Kiln Space						
No Asbestos						
B00B - R0045 - Plant						
No Asbestos						
B00B - R0046 - Plant						
No Asbestos						
B00B - R0047 - Materials Store						
No Asbestos						
B00B - R0048 - Workshop Area						
No Asbestos						
B00B - R0049 - Materials Store						
No Asbestos						
B00B - R0050 - Workshop Area						
No Asbestos						
B00B - R0051 - Agriculture Covered Area						
No Asbestos						
B00B - R1001 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R1002 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R1003 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R1004 - General Learning Space						
No Asbestos						
B00B - R1005 - General Learning Space						
No Asbestos						
B00B - R1006 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B00B - R1008 - Materials Store						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00B - R1009 - Kitchen - Type 1						
No Asbestos						
B00B - R1011 - Seminar/Technology Space						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00B - R1014 - Distribution Board Cupboard				Note: No inspection of live electrical installation.		
No Asbestos						
B00B - R1015 - Preparation - Materials						
No Asbestos						
B00B - R1016 - Pantry						
No Asbestos						
B00B - R1018 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00B - R1021 - Movement						
No Asbestos						
B00B - R1022 - Music Store						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00B - R1023 - Practice/Seminar						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00B - R1024 - Performance Workshop						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00B - R1025 - Movement						
No Asbestos						
B00B - R1026 - Stairs						
No Asbestos						
B00B - R1027 - Distribution Board Cupboard				Note: No inspection of live electrical installation.		
No Asbestos						
B00B - R1028 - Pantry						
No Asbestos						
B00B - R1029 - Food/Research Space						
No Asbestos						
B00B - R1030 - Food Technology L.S.						
No Asbestos						
B00B - R1031 - Hospitality Space						
No Asbestos						
B00B - R1032 - Laundry						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Multi Purpose Facilities - 2001 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00C - R0001 - Sport Equipment Store

No Asbestos

B00C - R0002 - Student Canteen

No Asbestos

B00C - R0003 - Office/Store

No Asbestos

B00C - R0004 - Staff - Toilet

No Asbestos

B00C - R0005 - Sport Equipment Store

No Asbestos

B00C - R0006 - Performing Arts Store

No Asbestos

B00C - R0007 - Performance Workshop

No Asbestos

B00C - R0008 - Sport Equipment Store

No Asbestos

B00C - R0009 - Control Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0010 - Chair Store

No Asbestos

B00C - R0011 - Clinic-Waiting

No Asbestos

B00C - R0012 - Multi-Purpose Space

No Asbestos

B00C - R0013 - Stage

No Asbestos

B00C - R0014 - General Storeroom

No Asbestos

B00C - R0015 - Plant

No Asbestos

B00C - R0016 - General Storeroom

No Asbestos

B00C - R0017 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0018 - Plant

No Asbestos

B00C - R0019 - General Storeroom

No Asbestos

B00C - R0020 - Plant

No Asbestos

B00C - R0021 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0022 - Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00C - R0023 - Movement						
No Asbestos						
B00C - R0024 - Movement						
No Asbestos						
B00C - R0025 - Movement						
No Asbestos						
B00C - R0026 - Movement						
No Asbestos						
B00C - R0027 - Machine Storage						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning - 2001 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00D - R0001 - General Learning Space**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0002 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0003 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0004 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0005 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0006 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0007 - Study Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0009 - Seminar

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0012 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0013 - Plant

No Asbestos

B00D - R0014 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0015 - Secure Storeroom

No Asbestos

B00D - R0016 - Movement

No Asbestos

B00D - R0017 - Stairs

No Asbestos

B00D - R0018 - Movement

No Asbestos

B00D - R0019 - Stairs

No Asbestos

B00D - R0020 - Student Kitchen

No Asbestos

B00D - R0021 - Practical Activities

No Asbestos

B00D - R1001 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R1002 - General Learning Space

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R1003 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R1004 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R1005 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R1006 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R1007 - Study Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R1008 - Study Space						
No Asbestos						
B00D - R1009 - Seminar						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R1010 - Study Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R1011 - Secure Storeroom						
No Asbestos						
B00D - R1012 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B00D - R1013 - Plant						
No Asbestos						
B00D - R1014 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B00D - R1015 - Movement						
No Asbestos						
B00D - R1016 - Movement						
No Asbestos						
B00D - R1017 - Stairs						
No Asbestos						
B00D - R1018 - Stairs						
No Asbestos						
B00D - R2001 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R2002 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R2003 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R2004 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R2005 - General Learning Space						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R2006 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R2007 - Study Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R2008 - Study Space						
No Asbestos						
B00D - R2009 - Seminar						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R2010 - Study Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R2011 - Secure Storeroom						
No Asbestos						
B00D - R2012 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B00D - R2013 - Plant						
No Asbestos						
B00D - R2014 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B00D - R2015 - Movement						
No Asbestos						
B00D - R2016 - Movement						
No Asbestos						
B00D - R2017 - Stairs						
No Asbestos						
B00D - R2018 - Stairs						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00E - General Learning/Science Learning - 2001 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00E - R0001 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0002 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0003 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0004 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0005 - Movement

No Asbestos

B00E - R0006 - Growing/Breeding

No Asbestos

B00E - R0007 - Cleaning Store - Distributed

No Asbestos

B00E - R0008 - Plant

No Asbestos

B00E - R0009 - Science Laboratory

No Asbestos

B00E - R0010 - General Storeroom

No Asbestos

B00E - R0011 - Preparation

No Asbestos

B00E - R0012 - Chemical Store

No Asbestos

B00E - R0013 - Preparation

No Asbestos

B00E - R0014 - Science Laboratory

No Asbestos

B00E - R0015 - Distribution Board Cupboard

No Asbestos

Note: No inspection of live electrical installation.

B00E - R0016 - Plant

No Asbestos

B00E - R0017 - Distribution Board Cupboard

No Asbestos

Note: No inspection of live electrical installation.

B00E - R0018 - Seminar

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0019 - Lift

No Asbestos

B00E - R0020 - Movement

No Asbestos

B00E - R0021 - Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00E - R0022 - Stairs						
No Asbestos						
B00E - R0023 - Stairs						
No Asbestos						
B00E - R0024 - Movement						
No Asbestos						
B00E - R1001 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00E - R1002 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00E - R1003 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00E - R1004 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00E - R1005 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00E - R1006 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00E - R1007 - Study Space						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00E - R1008 - Study Space						
No Asbestos						
B00E - R1009 - Seminar						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00E - R1010 - Study Space						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00E - R1011 - Secure Storeroom						
No Asbestos						
B00E - R1012 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B00E - R1013 - Plant						
No Asbestos						
B00E - R1014 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B00E - R1015 - Stairs						
No Asbestos						
B00E - R1016 - Movement						
No Asbestos						
B00E - R1017 - Movement						
No Asbestos						
B00E - R1018 - Lift						
No Asbestos						
B00E - R1019 - Stairs						
No Asbestos						
B00E - R2001 - General Learning Space						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00E - R2002 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00E - R2003 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00E - R2004 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00E - R2005 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00E - R2006 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00E - R2007 - Study Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00E - R2008 - Study Space						
No Asbestos						
B00E - R2009 - Seminar						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00E - R2010 - Study Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00E - R2011 - Secure Storeroom						
No Asbestos						
B00E - R2012 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B00E - R2013 - Plant						
No Asbestos						
B00E - R2014 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B00E - R2015 - Stairs						
No Asbestos						
B00E - R2016 - Movement						
No Asbestos						
B00E - R2017 - Movement						
No Asbestos						
B00E - R2018 - Lift						
No Asbestos						
B00E - R2019 - Stairs						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Library/Computer Learning - 2001 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00F - R0001 - Study Space**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00F - R0002 - Careers Advisers Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00F - R0003 - Entry

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00F - R0004 - Administration - Clerical

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00F - R0005 - Communications Cupboard

No Asbestos

B00F - R0006 - Computer Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00F - R0007 - Computer Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00F - R0008 - Duplicating Workroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00F - R0009 - Main Area

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00F - R0010 - Workroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00F - R0011 - Seminar

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00F - R0012 - Seminar

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00F - R0013 - Seminar

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00F - R0014 - Staff - Toilet

No Asbestos

B00F - R0015 - Toilets-Unisex

No Asbestos

B00F - R0016 - General Storeroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00F - R0017 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0018 - Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00G - Pupil Facilities/General Learning - 2001 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00G - R0001 - General Learning Space**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R0002 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R0003 - Shower/Change

No Asbestos

B00G - R0004 - Shower/Change

No Asbestos

B00G - R0005 - Shower/Change

No Asbestos

B00G - R0006 - Toilets - Boys

No Asbestos

B00G - R0007 - Shower/Change

No Asbestos

B00G - R0008 - Shower/Change

No Asbestos

B00G - R0009 - Seminar

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R0010 - Sport Equipment Store

No Asbestos

B00G - R0011 - Fitness Laboratory

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R0012 - Toilets - Girls

No Asbestos

B00G - R0013 - Shower/Change

No Asbestos

B00G - R0014 - Toilets - Boys

No Asbestos

B00G - R0015 - Toilets - Girls

No Asbestos

B00G - R0016 - Cleaning Store - Distributed

No Asbestos

B00G - R0017 - Staff - Toilet

No Asbestos

B00G - R0018 - Distribution Board Cupboard

No Asbestos

Note: No inspection of live electrical installation.

B00G - R0019 - Distribution Board Cupboard

No Asbestos

Note: No inspection of live electrical installation.

B00G - R0020 - Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 837 - D17113 - Hcap Shower/Change/Toilet : Placement Date - 23/01/2012

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	2.88 m2

Interior

R1 - Disabled Shower/Toilet

Toilet partitions	Compressed AC Sheet	Assumed Asbestos	12 m2
End wall panel	Flat AC Sheet	Assumed Asbestos	36 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	18 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017