


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Pacific Palms Public School (1551)
Region : North Coast
State Electorate : Myall Lakes
Local Government Area : Great Lakes

Initial Survey : Noel Arnold & Associates : 16 - Apr - 2008
Reviewed By : Parsons Brinckerhoff : 31 - Oct - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/Staff Facilities - 1920 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting 1551/B00A/Eaves Linings/S1					No Asbestos Detected
Underfloor Void	AC Fragments/Debris 1551/B00A/Underfloor Void/S15					No Asbestos Detected
Ceiling Void	No Asbestos Found					

Interior

B00A - R0001 - Clerical Office

No Asbestos

B00A - R0002 - Entry Vestibule

No Asbestos

B00A - R0004 - Sick Bay

No Asbestos

B00A - R0005 - Sick Bay - Shower/Toilet

No Asbestos

B00A - R0006 - Movement

No Asbestos

B00A - R0007 - Principal

No Asbestos

B00A - R0009 - Staff Toilet

No Asbestos

B00A - R0010 - Security Store

No Asbestos

B00A - R0011 - Movement

No Asbestos

B00A - R0013 - Movement

No Asbestos

B00A - R0014 - External Movement

No Asbestos

B00A - R0015 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 1551/B00A/R0015/Ceiling Structures/Linings/S16					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

B00A - R0016 - Clerical Office/Workroom

No Asbestos

B00A - R0017 - Clerical Office

No Asbestos

B00A - R0018 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Staff Facilities/Administration - 1920 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting 1551/B00B/Eaves Linings/S13					No Asbestos Detected
Ceiling Void	No Asbestos Found					
Underfloor Void	No Asbestos Found					

Interior

B00B - R0001 - Staff Room Annexe

No Asbestos

B00B - R0002 - Staff Room

No Asbestos

B00B - R0003 - Movement

No Asbestos

B00B - R0004 - Interview

No Asbestos

B00B - R0005 - Staff Toilet

No Asbestos

B00B - R0006 - Staff Kitchen

No Asbestos

B00B - R0008 - Clerical/Printing

Floor Coverings Res/Textile	Vinyl Tiles 1551/B00B/R0008/Floor Coverings Res/Textile/S19					No Asbestos Detected
--------------------------------	--	--	--	--	--	-----------------------------

B00B - R0009 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning - 1925 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting 1551/B00B/Eaves Linings/S13					No Asbestos Detected
Ceiling Void	No Asbestos Found					
Underfloor Void	No Asbestos Found					

Interior

B00C - R0001 - Home Base Store

Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1551/B00C/R0001/Floor Coverings Res/Textile/S12					Chrysotile (white asbestos)

B00C - R0002 - Home Base

No Asbestos

B00C - R0003 - Practical Activities - 1hb

No Asbestos

B00C - R0004 - Movement

Wall Linings Internal	Flat AC Sheeting 1551/B00C/R0004/Wall Linings Internal/S18					No Asbestos Detected
-----------------------	---	--	--	--	--	-----------------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning - 1979 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids - Raked Ceiling	No Asbestos Found					
Eaves Linings	Flat AC Sheeting 1551/B00D/Eaves Linings/S14					No Asbestos Detected
Underfloor Void	No Asbestos Found					

Interior**B00D - R0001 - Movement**

No Asbestos

B00D - R0002 - Practical Activities - 1hb

No Asbestos

B00D - R0003 - Home Base

No Asbestos

B00D - R0004 - Home Base Store

No Asbestos

B00D - R0006 - Withdrawal Space - 1hb

No Asbestos

B00D - R0007 - Movement

No Asbestos

B00D - R0008 - Home Base

No Asbestos

B00D - R0009 - Home Base Store

No Asbestos

B00D - R0010 - Practical Activities - 1hb

No Asbestos

B00D - R0011 - Toilets - Boys

Wall Linings Internal	Flat AC Sheeting 1551/B00D/R0011/Wall Linings Internal/S11					No Asbestos Detected
-----------------------	---	--	--	--	--	-----------------------------

Ceiling Structures/Linings	Flat AC Sheeting 1551/B00D/R0015/Ceiling Structures/Linings/S10					No Asbestos Detected
----------------------------	--	--	--	--	--	-----------------------------

B00D - R0012 - Toilets - Boys/Disabled Cubicle

Ceiling Structures/Linings	Flat AC Sheeting 1551/B00D/R0015/Ceiling Structures/Linings/S10					No Asbestos Detected
----------------------------	--	--	--	--	--	-----------------------------

B00D - R0013 - Toilets - Girls/Disabled Cubicle

Ceiling Structures/Linings	Flat AC Sheeting 1551/B00D/R0015/Ceiling Structures/Linings/S10					No Asbestos Detected
----------------------------	--	--	--	--	--	-----------------------------

B00D - R0014 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting 1551/B00D/R0015/Ceiling Structures/Linings/S10					No Asbestos Detected
----------------------------	--	--	--	--	--	-----------------------------

B00D - R0015 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 1551/B00D/R0015/Ceiling Structures/Linings/S10					No Asbestos Detected
----------------------------	--	--	--	--	--	-----------------------------

B00D - R0016 - Sports Store

No Asbestos

B00D - R0017 - Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Library - 1983 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Wall Cladding	Flat AC Sheeting 1551/B00E/Wall Cladding/S9					No Asbestos Detected
Ceiling Void	No Asbestos Found					

Interior

B00E - R0001 - Movement	No Asbestos					
B00E - R0002 - Library Office/Workroom	No Asbestos					
B00E - R0004 - Movement	No Asbestos					
B00E - R0007 - Cleaning Distributed Store	No Asbestos					
B00E - R0008 - Distribution Board	No Asbestos					Note: No inspection of live electrical installation.
B00E - R0009 - Reading Area	No Asbestos					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning/Pupil Facilities - 1912 - Timber (Timber)**Exterior**

Eaves Linings	Flat AC Sheeting 1551/B00A/Eaves Linings/S1					No Asbestos Detected
Ceiling Void	No Asbestos Found					
Underfloor Void	No Asbestos Found					

Interior**B00F - R0004 - Home Base**

No Asbestos

B00F - R0005 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting	4m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1551/B00F/R0011/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)

B00F - R0006 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting	4m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1551/B00F/R0011/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)

B00F - R0007 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1551/B00F/R0007/Partition Walls (Cubicles)/S6					Chrysotile (white asbestos)

Wall Linings Internal	Flat AC Sheeting	15m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1551/B00F/R0007/Wall Linings Internal/S7					Chrysotile (white asbestos)

Ceiling Structures/Linings	Flat AC Sheeting	15m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1551/B00F/R0011/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)

B00F - R0008 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1551/B00F/R0007/Partition Walls (Cubicles)/S6					Chrysotile (white asbestos)

Wall Linings Internal	Flat AC Sheeting	30m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1551/B00F/R0007/Wall Linings Internal/S7					Chrysotile (white asbestos)

Ceiling Structures/Linings	Flat AC Sheeting	15m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1551/B00F/R0011/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)

B00F - R0009 - Cleaning Distributed Store

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1551/B00F/R0009/Ceiling Structures/Linings/S17					Chrysotile (white asbestos)

Wall Linings Internal	Flat AC Sheeting	16m2	South, East & West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1551/B00F/R0009/Ceiling Structures/Linings/S17					Chrysotile (white asbestos)

B00F - R0010 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1551/B00F/R0011/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)

B00F - R0011 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1551/B00F/R0011/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)

B00F - R0012 - Practical Activities

No Asbestos

B00F - R0013 - Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Pupil Facilities - 1912 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting 1551/B00A/Eaves Linings/S1					No Asbestos Detected
Underfloor Void	No Asbestos Found					
Ceiling Void	Non Accessible Area - No Manhole - Not accessible					

Interior

B00G - R0001 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 1551/B00G/R0001/Ceiling Structures/Linings/S3					No Asbestos Detected
----------------------------	---	--	--	--	--	----------------------

B00G - R0002 - Movement

Wall Linings Internal	Flat AC Sheeting 1551/B00G/R0004/Wall Linings Internal/S4					No Asbestos Detected
-----------------------	--	--	--	--	--	----------------------

B00G - R0003 - Canteen Office/Store

Wall Linings Internal	Flat AC Sheeting 1551/B00G/R0004/Wall Linings Internal/S4					No Asbestos Detected
-----------------------	--	--	--	--	--	----------------------

B00G - R0004 - Canteen Office/Store

Wall Linings Internal	Flat AC Sheeting 1551/B00G/R0004/Wall Linings Internal/S4					No Asbestos Detected
-----------------------	--	--	--	--	--	----------------------

B00G - R0005 - Canteen

Wall Linings Internal	Flat AC Sheeting 1551/B00G/R0004/Wall Linings Internal/S4					No Asbestos Detected
-----------------------	--	--	--	--	--	----------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - General Learning - 2001 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior

B00I - R0001 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00I - R0002 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00I - R0003 - Practical Activities - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00I - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00I - R0005 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00I - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00I - R0007 - Practical Activities - 1hb

No Asbestos

B00I - R0008 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00I - R0009 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - General Learning - 2001 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00J - R0001 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00J - R0002 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00J - R0003 - Practical Activities - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00J - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00J - R0005 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00J - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00J - R0007 - Practical Activities - 1hb

No Asbestos

B00J - R0008 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00J - R0009 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Communal Facilities - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00K - R0001 - Communal Space

No Asbestos

B00K - R0002 - Raised Platform

No Asbestos

B00K - R0003 - Hall Chair Store

No Asbestos

B00K - R0004 - Communal/Performance Store

No Asbestos

B00K - R0005 - P.E. Store

No Asbestos

B00K - R0006 - Toilet - Lobby

No Asbestos

B00K - R0007 - Toilets - Girls

No Asbestos

B00K - R0008 - Sound Cupboard

No Asbestos

B00K - R0009 - Toilet - Lobby

No Asbestos

B00K - R0010 - Toilets - Boys

No Asbestos

B00K - R0011 - Cleaning Distributed Store

No Asbestos

B00K - R0012 - Plant

No Asbestos

B00K - R0013 - Main Switch Board

No Asbestos

B00K - R0014 - Access Shower/Toilet

No Asbestos

B00K - R0015 - Covered Outdoor Learning Area

No Asbestos

B00K - R0016 - Movement

No Asbestos

B00K - R0017 - Stairs

No Asbestos

B00K - R0018 - Movement

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Building Services - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00L - R0001 - General Assistant/Bulk Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - Communal Facilities - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00M - R0001 - Sports Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D11280 - Learning Unit - Standard With P.A.A. : Placement Date - 26/11/2008

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D11583 - Learning Unit - Standard With P.A.A. : Placement Date - 8/01/2014

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D12121 - Learning Unit - Standard With P.A.A. : Placement Date - 27/02/2009

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D12597 - Learning Unit - Standard With P.A.A. : Placement Date - 4/03/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D15596 - Learning Unit - Standard With P.A.A. : Placement Date - 13/01/2012

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017