

# Asbestos Register

(Hazardous Materials and Risk Assessment)



**School :** Pelican Flat Public School (2476)  
**Region :** Hunter/Central Coast  
**State Electorate :** Swansea  
**Local Government Area :** Lake Macquarie

**Initial Survey :** Noel Arnold & Associates : 29 - Mar - 2008  
**Reviewed By :** AECOM : 17 - Jun - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - Administration/Staff Facilities - 1957 - Timber (Timber)**

**Exterior**

Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible, no man hole access hatch.					
Underfloor Voids	Compressed AC Sheet	4m2	North east corner under wet areas R0004, R0005	Good Condition (1)	Low (1)	Low Priority (2-3)
	2476/B00A/Underfloor Voids/S6					<b>Chrysotile (white asbestos)</b>

**Interior**

**B00A - R0001 - Entry Vestibule**

No Asbestos

**B00A - R0002 - Clerical Office**

No Asbestos

**B00A - R0003 - Staff Room**

No Asbestos

**B00A - R0004 - Staff Toilet**

No Asbestos

**B00A - R0005 - Staff Toilet**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

**B00C - General Learning/Library - 1956 - Timber (Timber)**

**Exterior**

Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible, height restriction, 3.5m					
Eaves Linings	Flat AC Sheeting 2476/B00C/Eaves Linings/S7	150m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos) , Crocidolite (blue asbestos)</b>
Underfloor Voids - Packing to Floor Joists	Compressed AC Sheet 2476/B00A/Underfloor Voids/S6	5m2	Compressed underfloor to wet area below CR0019, CR0020	Some Damage - Unsealed (3)	Medium (2)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>

**Interior**

**B00C - R0001 - Home Base**

Wall Linings Internal	Flat AC Sheeting 2476/B00C/R0001/Wall Linings Internal/S4	2m2	Behind Heater	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
-----------------------	--	-----	---------------	--------------------	---------	--

**B00C - R0002 - Practical Activities - 1hb**

Floor Coverings Res/Textile	Vinyl Tiles 2476/B00C/R0002/Floor Coverings Res/Textile/S3	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
-----------------------------	---	------	------------	--------------------	---------	--

**B00C - R0003 - Home Base**

Wall Linings Internal	Flat AC Sheeting 2476/B00C/R0001/Wall Linings Internal/S4	2m2	Behind Heater	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
-----------------------	--	-----	---------------	--------------------	---------	--

**B00C - R0004 - External Movement**

Ceiling Structures/Linings	Flat AC Sheeting 2476/B00C/Eaves Linings/S7	96m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos) , Crocidolite (blue asbestos)</b>
----------------------------	--	------	------------	--------------------	---------	--

**B00C - R0005 - External Movement**

Ceiling Structures/Linings	Flat AC Sheeting 2476/B00C/Eaves Linings/S7	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos) , Crocidolite (blue asbestos)</b>
----------------------------	--	-----	------------	--------------------	---------	--

**B00C - R0006 - Duplicating Workroom**

No Asbestos

**B00C - R0007 - Principal**

No Asbestos

**B00C - R0008 - Movement**

No Asbestos

**B00C - R0011 - General Storeroom**

No Asbestos

**B00C - R0012 - General Storeroom**

No Asbestos

**B00C - R0013 - Home Base**

Wall Linings Internal	Flat AC Sheeting 2476/B00C/R0001/Wall Linings Internal/S4	2m2	Behind Heater	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
-----------------------	--	-----	---------------	--------------------	---------	--

**B00C - R0014 - Reading Area**

Wall Linings Internal	Flat AC Sheeting 2476/B00C/R0001/Wall Linings Internal/S4	2m2	Behind Heater	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
-----------------------	--	-----	---------------	--------------------	---------	--

**B00C - R0015 - Canteen**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

**B00C - R0016 - Cleaning Supplies**

No Asbestos

**B00C - R0017 - Cleaning Distributed Store**

Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
-----------------------------	-------------	-----	------------	--------------------	---------	--------------------

2476/B00C/R0002/Floor Coverings Res/Textile/S3

**Chrysotile (white asbestos)**

**B00C - R0018 - Withdrawal Space - 1hb**

No Asbestos

**B00C - R0019 - Staff Toilet**

No Asbestos

**B00C - R0020 - Staff Toilet**

No Asbestos

**B00C - R0021 - Movement**

Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
-----------------------------	-------------	-----	------------	--------------------	---------	--------------------

2476/B00C/R0002/Floor Coverings Res/Textile/S3

**Chrysotile (white asbestos)**

**B00C - R0022 - Home Base**

Recently Modified Space Requires Inspection

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Pupil Facilities - 1957 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible, small man hole access hatch, ceiling space 150mm high.					
Eaves Linings	Flat AC Sheeting 2476/B00D/R0002/Ceiling Structures/Linings/S8					<b>No Asbestos Detected</b>

**Interior**

**B00D - R0001 - Toilets - Girls**

Ceiling Structures/Linings	Flat AC Sheeting 2476/B00D/R0001/Ceiling Structures/Linings/S9	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Partition Walls (Cubicles)	Compressed AC Sheet 2476/B00D/R0004/Partition Walls (Cubicles)/S5	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00D - R0002 - External Movement**

Ceiling Structures/Linings	Flat AC Sheeting 2476/B00D/R0002/Ceiling Structures/Linings/S8					<b>No Asbestos Detected</b>
----------------------------	---	--	--	--	--	-----------------------------

**B00D - R0003 - External Movement**

Ceiling Structures/Linings	Flat AC Sheeting 2476/B00D/R0002/Ceiling Structures/Linings/S8					<b>No Asbestos Detected</b>
----------------------------	---	--	--	--	--	-----------------------------

**B00D - R0004 - Toilets - Boys**

Ceiling Structures/Linings	Flat AC Sheeting 2476/B00D/R0001/Ceiling Structures/Linings/S9	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Partition Walls (Cubicles)	Compressed AC Sheet 2476/B00D/R0004/Partition Walls (Cubicles)/S5	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - Communal Facilities/Administration - 1957 - Timber (Timber)**

**Exterior**

Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Wall Cladding	Flat AC Sheeting 2476/B00E/Wall Cladding/S1					<b>No Asbestos Detected</b>

**Interior**

**B00E - R0001 - General Storeroom**

No Asbestos

**B00E - R0002 - Sports Store**

Wall Linings Internal	Flat AC Sheeting 2476/B00E/Wall Cladding/S1					<b>No Asbestos Detected</b>
-----------------------	--	--	--	--	--	-----------------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - Library - 2010 - Fibre Cement Clad (Fibre Cement Clad)**

**Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible
Ceiling Voids	No Asbestos Found

**Interior**

**B00F - R0001 - External Movement**

No Asbestos

**B00F - R0002 - Reading Area**

No Asbestos

**B00F - R0003 - Library Office/Workroom**

No Asbestos

**B00F - R0004 - Communications Room**

No Asbestos

**B00F - R0005 - K.L.A. Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - Storage - 2015 - Metal Shed (Metal Shed)**

**Exterior**

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

**Interior**

**B00G - R0001 - General Assistant/Bulk Store**

No Asbestos

**B00G - R0002 - Sports Store**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017