

# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Pambula Public School (2831)  
**Region :** Illawarra and South East  
**State Electorate :** Bega  
**Local Government Area :** Bega Valley

**Initial Survey :** Noel Arnold & Associates : 07 - May - 2008  
**Reviewed By :** AECOM : 18 - Jun - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - Administration/Staff Facilities - 1978 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids - Raked Ceiling  
Non Accessible Area  
- Area inaccessible

Underfloor Voids - Slab on Ground  
No Asbestos Found

**Interior****B00A - R0001 - Main Switch Board**

Electrical Mounting Board Resinous Board 1Unit East Good Condition (1) Low (1) Low Priority (2-3)

**Assumed Asbestos - Electrical Hazard****B00A - R0002 - Staff Toilet**

Partition Walls (Cubicles) Compressed AC Sheet 3m2 Variable positions Good Condition (1) Low (1) Low Priority (2-3)  
2831/B00A/R0002/Partition Walls (Cubicles)/S4 **Chrysotile (white asbestos)**

**B00A - R0003 - Cleaning Distributed Store**

No Asbestos

**B00A - R0004 - Staff Toilet**

Partition Walls (Cubicles) Compressed AC Sheet 3m2 Variable positions Good Condition (1) Low (1) Low Priority (2-3)  
2831/B00A/R0002/Partition Walls (Cubicles)/S4 **Chrysotile (white asbestos)**

**B00A - R0005 - Interview**

No Asbestos

**B00A - R0006 - Staff Room Annexe**

No Asbestos

**B00A - R0007 - Entry Vestibule**

No Asbestos

**B00A - R0008 - General Storeroom**

Floor Coverings Res/Textile Vinyl Tiles  
2831/B00A/R0008/Floor Coverings Res/Textile/S1 **No Asbestos Detected**

**B00A - R0009 - Sick Bay**

Floor Coverings Res/Textile Vinyl Tiles  
2831/B00A/R0008/Floor Coverings Res/Textile/S1 **No Asbestos Detected**

**B00A - R0010 - Principal**

No Asbestos

**B00A - R0011 - Clerical Office**

No Asbestos

**B00A - R0012 - Duplicating Workroom**

Floor Coverings Res/Textile Vinyl Tiles  
2831/B00A/R0008/Floor Coverings Res/Textile/S1 **No Asbestos Detected**

**B00A - R0013 - General Storeroom**

Floor Coverings Res/Textile Vinyl Tiles  
2831/B00A/R0008/Floor Coverings Res/Textile/S1 **No Asbestos Detected**

**B00A - R0014 - Staff Room**

No Asbestos

**B00A - R0015 - Movement**

No Asbestos

**B00A - R0016 - External Movement**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - General Learning/Pupil Facilities - 1978 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids - Raked Ceiling  
 Non Accessible Area  
 - Area inaccessible

Underfloor Voids - Slab on Ground  
 No Asbestos Found

**Interior**

**B00B - R0001 - Distribution Board** Note: No inspection of live electrical installation.

No Asbestos

**B00B - R0002 - Toilets - Girls**

Partition Walls (Cubicles)	Compressed AC Sheet	6m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
2831/B00A/R0002/Partition Walls (Cubicles)/S4						<b>Chrysotile (white asbestos)</b>

**B00B - R0003 - Cleaning Distributed Store**

No Asbestos

**B00B - R0004 - Toilets - Boys/Girls**

No Asbestos

**B00B - R0005 - Practical Activities - 1hb**

Floor Coverings Res/Textile	Vinyl Tiles				
2831/B00A/R0008/Floor Coverings Res/Textile/S1					<b>No Asbestos Detected</b>

**B00B - R0006 - Home Base**

No Asbestos

**B00B - R0007 - Home Base**

No Asbestos

**B00B - R0008 - Practical Activities - 1hb**

Floor Coverings Res/Textile	Vinyl Tiles				
2831/B00A/R0008/Floor Coverings Res/Textile/S1					<b>No Asbestos Detected</b>

**B00B - R0009 - Toilets - Boys/Girls**

No Asbestos

**B00B - R0010 - Toilets - Boys**

Partition Walls (Cubicles)	Compressed AC Sheet	6m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
2831/B00A/R0002/Partition Walls (Cubicles)/S4						<b>Chrysotile (white asbestos)</b>

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - General Learning/Pupil Facilities - 1978 - Brick/Block (Brick/Block)**

**Exterior**

In-fill-panel	Compressed AC Sheet	15m2	North, East, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	2831/B00E/R0008/In-fill-panel/S7					<b>Chrysotile (white asbestos)</b>
Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible					
Underfloor Voids - Slab on Ground	No Asbestos Found					

**Interior**

<b>B00C - R0001 - Distribution Board</b>	Note: No inspection of live electrical installation.					
No Asbestos						

<b>B00C - R0002 - Toilets - Girls</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	8m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	2831/B00A/R0002/Partition Walls (Cubicles)/S4					<b>Chrysotile (white asbestos)</b>

<b>B00C - R0003 - Cleaning Distributed Store</b>						
No Asbestos						

<b>B00C - R0004 - Home Base</b>						
No Asbestos						

<b>B00C - R0005 - Practical Activities - 1hb</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	2831/B00A/R0008/Floor Coverings Res/Textile/S1					<b>No Asbestos Detected</b>

<b>B00C - R0006 - External Movement</b>						
In-fill-panel	Compressed AC Sheet	3m	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	2831/B00E/R0008/In-fill-panel/S7					<b>Chrysotile (white asbestos)</b>

<b>B00C - R0007 - Withdrawal Space - 1hb</b>						
No Asbestos						

<b>B00C - R0008 - Home Base</b>						
No Asbestos						

<b>B00C - R0009 - Practical Activities - 1hb</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	2831/B00A/R0008/Floor Coverings Res/Textile/S1					<b>No Asbestos Detected</b>

<b>B00C - R0010 - External Movement</b>						
In-fill-panel	Compressed AC Sheet	6m	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	2831/B00E/R0008/In-fill-panel/S7					<b>Chrysotile (white asbestos)</b>

<b>B00C - R0011 - External Movement</b>						
No Asbestos						

<b>B00C - R0012 - Garden Store</b>						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Communal Facilities/Pupil Facilities - 1978 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids - Raked Ceiling  
 Non Accessible Area  
 - Area inaccessible

Underfloor Voids - Slab on Ground  
 No Asbestos Found

**Interior**

**B00D - R0001 - Kiln Room**

No Asbestos

**B00D - R0002 - Toilets - Girls**

Partition Walls (Cubicles)	Compressed AC Sheet	14m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
2831/B00A/R0002/Partition Walls (Cubicles)/S4					<b>Chrysotile (white asbestos)</b>	

**B00D - R0003 - Cleaning Distributed Store**

No Asbestos

**B00D - R0004 - P.E. Store**

No Asbestos

**B00D - R0005 - Hall Chair Store**

No Asbestos

**B00D - R0007 - Raised Platform**

Floor Coverings Res/Textile	Vinyl Tiles					
2831/B00A/R0008/Floor Coverings Res/Textile/S1					<b>No Asbestos Detected</b>	

**B00D - R0008 - Movement**

Floor Coverings Res/Textile	Vinyl Tiles					
2831/B00A/R0008/Floor Coverings Res/Textile/S1					<b>No Asbestos Detected</b>	

**B00D - R0009 - Music Store**

No Asbestos

**B00D - R0010 - Canteen**

Floor Coverings Res/Textile	Vinyl Tiles					
2831/B00A/R0008/Floor Coverings Res/Textile/S1					<b>No Asbestos Detected</b>	

**B00D - R0011 - Canteen Office/Store**

Floor Coverings Res/Textile	Vinyl Tiles					
2831/B00A/R0008/Floor Coverings Res/Textile/S1					<b>No Asbestos Detected</b>	

**B00D - R0012 - Canteen Office/Store**

Floor Coverings Res/Textile	Vinyl Tiles					
2831/B00A/R0008/Floor Coverings Res/Textile/S1					<b>No Asbestos Detected</b>	

**B00D - R0013 - Staff Toilet**

Partition Walls (Cubicles)	Compressed AC Sheet	3m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
2831/B00A/R0002/Partition Walls (Cubicles)/S4					<b>Chrysotile (white asbestos)</b>	

**B00D - R0014 - Toilets - Boys**

Partition Walls (Cubicles)	Compressed AC Sheet	6m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
2831/B00A/R0002/Partition Walls (Cubicles)/S4					<b>Chrysotile (white asbestos)</b>	

**B00D - R0015 - Canteen Covered Area**

No Asbestos

**B00D - R0016 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00D - R0017 - Cleaning Supplies**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Floor Coverings Res/Textile	Vinyl Tiles		2831/B00A/R0008/Floor Coverings Res/Textile/S1			No Asbestos Detected
-----------------------------	-------------	--	--	--	--	----------------------

**B00D - R0018 - Communal Space**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - General Learning - 1978 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids - Raked Ceiling  
 Non Accessible Area  
 - Area inaccessible

Underfloor Voids - Slab on Ground  
 No Asbestos Found

**Interior**

**B00E - R0001 - Withdrawal Space - 1hb**

No Asbestos

**B00E - R0002 - Home Base**

No Asbestos

**B00E - R0003 - Practical Activities - 1hb**

Floor Coverings Res/Textile  
 Vinyl Tiles  
 2831/B00A/R0008/Floor Coverings Res/Textile/S1  
**No Asbestos Detected**

**B00E - R0004 - External Movement**

No Asbestos

**B00E - R0005 - Withdrawal Space - 1hb**

No Asbestos

**B00E - R0006 - Home Base**

No Asbestos

**B00E - R0007 - Practical Activities - 1hb**

Floor Coverings Res/Textile  
 Vinyl Tiles  
 2831/B00A/R0008/Floor Coverings Res/Textile/S1  
**No Asbestos Detected**

**B00E - R0008 - External Movement**

In-fill-panel  
 Compressed AC Sheet  
 6m East  
 Good Condition (1)  
 Low (1) Low Priority (2-3)  
 2831/B00E/R0008/In-fill-panel/S7  
**Chrysotile (white asbestos)**

Ceiling Structures/Linings  
 Flat AC Sheeting  
 27m2 Throughout  
 Good Condition (1)  
 Low (1) Low Priority (2-3)  
 2831/B00E/R0008/Ceiling Structures/Linings/S5  
**Chrysotile (white asbestos)**

**B00E - R0009 - Craft Store**

Floor Coverings Res/Textile  
 Vinyl Tiles  
 2831/B00A/R0008/Floor Coverings Res/Textile/S1  
**No Asbestos Detected**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - General Learning/Pupil Facilities - 1978 - Brick/Block (Brick/Block)**

**Exterior**

In-fill-panel	Compressed AC Sheet	6m2	South, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2831/B00E/R0008/In-fill-panel/S7					<b>Chrysotile (white asbestos)</b>
Ceiling Voids - Raked Ceiling	Non Accessible Area					
	- Area inaccessible					
Underfloor Voids - Slab on Ground	No Asbestos Found					

**Interior**

**B00F - R0002 - Library Office/Workroom**

Ceiling Structures/Linings	Flat AC Sheeting	12m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	2831/B00F/R0003/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>
Wall Linings Internal	Flat AC Sheeting					
	2831/B00F/R0003/Wall Linings Internal/S2					<b>No Asbestos Detected</b>

**B00F - R0003 - K.L.A. Store**

Wall Linings Internal	Flat AC Sheeting					
	2831/B00F/R0003/Wall Linings Internal/S2					<b>No Asbestos Detected</b>
Ceiling Structures/Linings	Flat AC Sheeting	13m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	2831/B00F/R0003/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>

**B00F - R0005 - Toilets - Boys**

Partition Walls (Cubicles)	Compressed AC Sheet	4m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2831/B00A/R0002/Partition Walls (Cubicles)/S4					<b>Chrysotile (white asbestos)</b>

**B00F - R0006 - General Storeroom**

Floor Coverings Res/Textile	Vinyl Tiles					
	2831/B00A/R0008/Floor Coverings Res/Textile/S1					<b>No Asbestos Detected</b>

**B00F - R0007 - Garden Store**

No Asbestos

**B00F - R0009 - Library Office/Workroom**

Wall Linings Internal	Flat AC Sheeting					
	2831/B00F/R0003/Wall Linings Internal/S2					<b>No Asbestos Detected</b>

**B00F - R0010 - Movement**

No Asbestos

**B00F - R0011 - Home Base**

No Asbestos

**B00F - R0012 - Practical Activities/Movement - 1hb**

No Asbestos





Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - Music/Pupil Facilities - 1978 - Timber (Timber)**

**Exterior**

Ceiling Voids	No Asbestos Found				
Underfloor Voids	No Asbestos Found				
Wall Cladding	Flat AC Sheeting 2831/B00G/Wall Cladding/S6				
<b>No Asbestos Detected</b>					

**Interior**

**B00G - R0001 - Movement**

No Asbestos

**B00G - R0002 - Withdrawal Space - 1hb**

No Asbestos

**B00G - R0003 - External Movement**

No Asbestos

**B00G - R0004 - Sports Store**

Electrical Mounting Board	Resinous Board	1Unit	West	Good Condition (1)	Low (1)	Low Priority (2-3)
---------------------------	----------------	-------	------	--------------------	---------	--------------------

**Assumed Asbestos - Electrical Hazard**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B001 - Support Unit - 2003 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B001 - R0001 - Other-Community Use**

No Asbestos

**B001 - R0002 - Other-Community Use**

No Asbestos

**B001 - R0003 - Other-Community Use**

No Asbestos

**B001 - R0004 - Other-Community Use**

No Asbestos

**B001 - R0005 - Other-Community Use**

No Asbestos

**B001 - R0006 - Other-Community Use**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00J - Support Unit/Staff Facilities - 2003 - Timber (Timber)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00J - R0001 - Other-Community Use**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00J - R0002 - Other-Community Use**

No Asbestos

**B00J - R0003 - Other-Community Use**

No Asbestos

**B00J - R0004 - Other-Community Use**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00J - R0005 - Other-Community Use**

No Asbestos

**B00J - R0006 - Other-Community Use**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00K - General Learning - 2006 - Fibre Cement Clad (Fibre Cement Clad)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00K - R0001 - External Movement**

No Asbestos

**B00K - R0002 - Practical Activities - 1hb**

No Asbestos

**B00K - R0003 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00K - R0004 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00K - R0005 - Withdrawal Space - 2hb**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00K - R0006 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00K - R0007 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00K - R0008 - Practical Activities - 1hb**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00L - Building Services - 2007 - Metal Shed (Metal Shed)**

**Exterior**

No Asbestos

**Interior**

**B00L - R0001 - Garden Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00M - General Learning - 2011 - Brick/Veneer (Brick/Veneer)**

**Exterior**

No Asbestos

**Interior**

**B00M - R0001 - External Movement**

No Asbestos

**B00M - R0002 - Practical Activities/Movement - 1hb**

No Asbestos

**B00M - R0003 - Home Base Store**

No Asbestos

**B00M - R0004 - Home Base**

No Asbestos

**B00M - R0005 - Withdrawal Space - 2hb**

No Asbestos

**B00M - R0006 - Home Base**

No Asbestos

**B00M - R0007 - Home Base Store**

No Asbestos

**B00M - R0008 - Practical Activities/Movement - 1hb**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00N - Library - 2011 - Brick/Veneer (Brick/Veneer)**

**Exterior**

No Asbestos

**Interior**

**B00N - R0001 - External Movement**

No Asbestos

**B00N - R0002 - Reading Area**

No Asbestos

**B00N - R0003 - Library Office/Workroom**

No Asbestos

**B00N - R0004 - Communications Room**

No Asbestos

**B00N - R0005 - K.L.A. Store**

No Asbestos

**B00N - R0006 - Cleaning Distributed Store**

No Asbestos

**B00N - R0007 - Staff Toilet**

No Asbestos

**B00N - R0008 - Toilet - Lobby**

No Asbestos

**B00N - R0009 - No Access**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B000 - Building Services - 2011 - Brick/Veneer (Brick/Veneer)**

**Exterior**

No Asbestos

**Interior**

**B000 - R0001 - No Access**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Demountables**

**Demountable details as per the AMS records as of 15 Feb 2017.**

**OS 601 - D13661 - Learning Unit - Standard/Withdrawal : Placement Date - 5/02/2003**

**Exterior**

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

**Interior**

**R1 - Entry**

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

**R2 - General Learning Space**

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

**R3 - Store**

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2
---------	---------------	------------------	-------

**NS 100 - D14268 - Learning Unit - Single Primary/PAA : Placement Date - 10/02/2015**

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Home Base**

No Asbestos Found.

**R2 - Practical Activity Area**

No Asbestos Found.

**R3 - Home Base Store**

No Asbestos Found.

**R4 - Entry**

No Asbestos Found.

**OS 602 - D14469 - Learning Unit - Standard With P.A.A. : Placement Date - 8/12/2015**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 620 - D15337 - Single Learning Unit - H/Cap : Placement Date - 9/02/2003**

**Exterior**

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>Interior</b>						
<b>R1 - Entry</b>						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
<b>R2 - Home Base-I.O.</b>						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
<b>R3 - Disabled Shower/laundry</b>						
Toilet partitions	Compressed AC Sheet	Assumed Asbestos				2 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2
<b>OS 621 - D15797 - Single Learning Unit - H/Cap : Placement Date - 31/03/2000</b>						
<b>Exterior</b>						
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				14.4 m2
<b>Interior</b>						
<b>R1 - Home Base-I.O.</b>						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				77 m2
<b>R2 - Toilets-Disabled</b>						
Toilet partitions	Compressed AC Sheet	Assumed Asbestos				2 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2
<b>R3 - Laundry</b>						
Ceiling	Flat AC Sheet	Assumed Asbestos				4 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017