


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Parklea Public School (2838)  
**Region :** Western Sydney  
**State Electorate :** Riverstone  
**Local Government Area :** Blacktown

**Initial Survey :** Noel Arnold & Associates : 23 - May - 2008  
**Register Issue Date :** 22 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - Administration - 1994 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior****B00A - R0001 - Entry Vestibule**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00A - R0002 - Duplicating Workroom**

No Asbestos

**B00A - R0003 - Principal**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00A - R0004 - Security Store**

No Asbestos

**B00A - R0005 - Deputy Principal**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00A - R0006 - Staff Room Annexe**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00A - R0007 - Staff Room**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00A - R0008 - General Storeroom**

No Asbestos

**B00A - R0009 - Staff Toilet**

No Asbestos

**B00A - R0010 - Staff Toilet**

No Asbestos

**B00A - R0011 - Staff Toilet**

No Asbestos

**B00A - R0012 - Deputy Principal**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00A - R0013 - Interview**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00A - R0014 - Shower/Change**

No Asbestos

**B00A - R0015 - Sick Bay**

No Asbestos

**B00A - R0016 - Clerical Office/Workroom**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00A - R0017 - Movement**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00A - R0018 - Community Clinic**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00A - R0019 - Staff Toilet**

No Asbestos

**B00A - R0020 - Community Clinic**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00A - R0021 - Movement**

No Asbestos

**B00A - R0022 - Distribution Board** Note: No inspection of live electrical installation.

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - General Learning - 1994 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00B - R0001 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00B - R0002 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00B - R0003 - Practical Activities - 1hb**

No Asbestos

**B00B - R0004 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00B - R0005 - Practical Activities - 1hb**

No Asbestos

**B00B - R0006 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00B - R0007 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00B - R0008 - General Assistant/Bulk Store**

No Asbestos

**B00B - R0009 - Sports Store**

No Asbestos

**B00B - R0010 - Toilets - Girls**

No Asbestos

**B00B - R0011 - Kiln Room**

No Asbestos

**B00B - R0012 - Toilets - Boys**

No Asbestos

**B00B - R0013 - Garden Store**

No Asbestos

**B00B - R0014 - Garden Store**

No Asbestos

**B00B - R0018 - Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00C - General Learning - 1994 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior****B00C - R0001 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00C - R0002 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00C - R0003 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00C - R0004 - Practical Activities - 1hb**

No Asbestos

**B00C - R0005 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00C - R0006 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00C - R0007 - Practical Activities - 1hb**

No Asbestos

**B00C - R0008 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00C - R0009 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00C - R0010 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00C - R0011 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00C - R0012 - Practical Activities - 1hb**

No Asbestos

**B00C - R0013 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00C - R0014 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00C - R0015 - Practical Activities - 1hb**

No Asbestos

**B00C - R0016 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00C - R0017 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00C - R0018 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00C - R0022 - Movement**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	<b>Sample No</b>					<b>Test Result</b>

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Library - 1994 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00D - R0001 - Distribution Board** Note: No inspection of live electrical installation.

No Asbestos

**B00D - R0002 - Plant**

No Asbestos

**B00D - R0003 - Cleaning Distributed Store**

No Asbestos

**B00D - R0004 - Disabled Shower/Toilet**

No Asbestos

**B00D - R0005 - Special Programs Store**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00D - R0006 - Special Programs Room**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00D - R0007 - K.L.A. Store**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00D - R0008 - Library Office/Workroom**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00D - R0009 - Reading Area**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00D - R0010 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00D - R0011 - Practical Activities - 1hb**

No Asbestos

**B00D - R0012 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00D - R0013 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00D - R0014 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00D - R0015 - Practical Activities - 1hb**

No Asbestos

**B00D - R0016 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00D - R0021 - Movement**

No Asbestos

**B00D - R0022 - Plant**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - Pupil Facilities - 1994 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior****B00E - R0001 - Movement**

No Asbestos

**B00E - R0002 - Canteen**

No Asbestos

**B00E - R0003 - Canteen Office/Store**

No Asbestos

**B00E - R0004 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00E - R0005 - Cleaning Supplies**

No Asbestos

**B00E - R0006 - Cleaning Supplies**

No Asbestos

**B00E - R0007 - Movement**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - Communal Facilities - 1996 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00F - R0001 - Toilets - Boys**

No Asbestos

**B00F - R0002 - Toilets - Girls**

No Asbestos

**B00F - R0003 - Movement**

No Asbestos

**B00F - R0004 - Movement**

No Asbestos

**B00F - R0005 - Disabled Toilet**

No Asbestos

**B00F - R0006 - Cleaning Distributed Store**

No Asbestos

**B00F - R0007 - Movement**

No Asbestos

**B00F - R0008 - Plant**

No Asbestos

**B00F - R0009 - Hall Chair Store**

No Asbestos

**B00F - R0010 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00F - R0011 - P.E. Store**

No Asbestos

**B00F - R0012 - Staff Shower/Change**

No Asbestos

**B00F - R0013 - Toilets - Girls**

No Asbestos

**B00F - R0014 - Toilets - Boys**

No Asbestos

**B00F - R0016 - Movement**

No Asbestos

**B00F - R0017 - Movement**

No Asbestos

**B00F - R0018 - Communal Space**

No Asbestos

**B00F - R0019 - Movement**

No Asbestos

**B00F - R0020 - Movement**

No Asbestos

**B00F - R0021 - Lift**

No Asbestos

**B00F - R0022 - Raised Platform**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - General Learning - 1996 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior****B00G - R0001 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00G - R0002 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00G - R0003 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00G - R0004 - Practical Activities - 1hb**

No Asbestos

**B00G - R0005 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00G - R0006 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00G - R0007 - Practical Activities - 1hb**

No Asbestos

**B00G - R0008 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00G - R0009 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00G - R0010 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00G - R0011 - Practical Activities - 1hb**

No Asbestos

**B00G - R0012 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00G - R0013 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00G - R0014 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00G - R0015 - Practical Activities - 1hb**

No Asbestos

**B00G - R0016 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00G - R0017 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00G - R0018 - Practical Activities - 1hb**

No Asbestos

**B00G - R0019 - Home Base**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00G - R0020 - Withdrawal Space - 1hb</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00G - R0021 - Home Base</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00G - R0022 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00G - R0023 - Home Base Store</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00G - R0030 - Distribution Board</b>				Note: No inspection of live electrical installation.		
No Asbestos						
<b>B00G - R0032 - Movement</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - General Learning - 2005 - Fibre Cement Clad (Fibre Cement Clad)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00H - R0001 - Movement**

No Asbestos

**B00H - R0002 - Practical Activities - 1hb**

No Asbestos

**B00H - R0003 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00H - R0004 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00H - R0005 - Withdrawal Space - 2hb**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00H - R0006 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00H - R0007 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00H - R0008 - Practical Activities - 1hb**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00J - General Learning/Pupil Facilities - 2009 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00J - R0001 - Practical Activities - 1hb**

No Asbestos

**B00J - R0002 - Practical Activities - 1hb**

No Asbestos

**B00J - R0003 - Home Base Store**

No Asbestos

**B00J - R0004 - Home Base**

No Asbestos

**B00J - R0005 - External Movement**

No Asbestos

**B00J - R0006 - Withdrawal Space - 2hb**

No Asbestos

**B00J - R0007 - Home Base**

No Asbestos

**B00J - R0008 - Home Base Store**

No Asbestos

**B00J - R0009 - Toilets - Girls**

No Asbestos

**B00J - R0010 - Disabled Shower/Toilet**

No Asbestos

**B00J - R0011 - Toilets - Boys**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00K - General Learning - 2010 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00K - R0001 - Practical Activities - 1hb**

No Asbestos

**B00K - R0002 - Practical Activities - 1hb**

No Asbestos

**B00K - R0003 - External Movement**

No Asbestos

**B00K - R0004 - Special Programs Room**

No Asbestos

**B00K - R0005 - Special Programs Room**

No Asbestos

**B00K - R0006 - Special Programs Room**

No Asbestos

**B00K - R0007 - Special Programs Store**

No Asbestos

**B00K - R0008 - Home Base Store**

No Asbestos

**B00K - R0009 - Home Base**

No Asbestos

**B00K - R0010 - Home Base**

No Asbestos

**B00K - R0011 - Home Base Store**

No Asbestos

**B00K - R0012 - Withdrawal Space - 2hb**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

## Demountables

**Demountable details as per the AMS records as of 15 Feb 2017.**

### OS 603 - D10055 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 19/12/2000

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

#### Exterior

No Asbestos Found.

#### Interior

##### R1 - Learning space/withdrawal/entry

No Asbestos Found.

##### R2 - Home Base Store

No Asbestos Found.

### OS 602 - D11872 - Learning Unit - Standard With P.A.A. : Placement Date - 2/01/2009

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

#### Exterior

No Asbestos Found.

#### Interior

##### R1 - Learning space/withdrawal/entry

No Asbestos Found.

##### R2 - Home Base Store

No Asbestos Found.

### OS 750 - D11892 - Learning Unit - ESL : Placement Date - 15/02/2001

#### Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	5.76 m2

#### Interior

##### R1 - Esl

End wall panel	Flat AC Sheet	Assumed Asbestos	50 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	36 m2

### OS 603 - D12526 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 5/12/2007

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

#### Exterior

No Asbestos Found.

#### Interior

##### R1 - Learning space/withdrawal/entry

No Asbestos Found.

##### R2 - Home Base Store

No Asbestos Found.

### OS 603 - D12555 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 27/12/2000

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

#### Exterior

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
No Asbestos Found.						
<b>R2 - Home Base Store</b>						
No Asbestos Found.						
<b>OS 602 - D13397 - Learning Unit - Standard With P.A.A. : Placement Date - 14/01/2013</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
No Asbestos Found.						
<b>R2 - Home Base Store</b>						
No Asbestos Found.						
<b>OS 602 - D13607 - Learning Unit - Standard With P.A.A. : Placement Date - 10/12/2009</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
No Asbestos Found.						
<b>R2 - Home Base Store</b>						
No Asbestos Found.						
<b>OS 602 - D16154 - Learning Unit - Standard With P.A.A. : Placement Date - 26/01/2007</b>						
<b>Exterior</b>						
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
Ceiling	Flat AC Sheet	Assumed Asbestos				70 m2
<b>R2 - Home Base Store</b>						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				3 m2
<b>OS 603 - D16314 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 13/03/2007</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
No Asbestos Found.						
<b>R2 - Home Base Store</b>						
No Asbestos Found.						



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017