


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Parramatta North Public School (2842)  
**Region :** Western Sydney  
**State Electorate :** Parramatta  
**Local Government Area :** Parramatta

**Initial Survey :** Noel Arnold & Associates : 21 - May - 2008  
**Reviewed By :** Parsons Brinckerhoff : 07 - Feb - 2017



# 2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00A - General Learning/Library - 1945 - Brick/Block (Brick/Block)****Exterior**

|                  |                   |
|------------------|-------------------|
| Underfloor Voids | No Asbestos Found |
| Ceiling Voids    | No Asbestos Found |

**Interior****B00A - R0001 - Home Base**

No Asbestos

**B00A - R0002 - Movement**

No Asbestos

**B00A - R0003 - Cleaning Distributed Store**

|   |                  |     |            |                    |                                    |                    |
|---|------------------|-----|------------|--------------------|------------------------------------|--------------------|
| Ceiling Structures/Linings                    | Flat AC Sheeting | 3m2 | Throughout | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 2842/B00A/R0003/Ceiling Structures/Linings/S7 |                  |     |            |                    | <b>Chrysotile (white asbestos)</b> |                    |

**B00A - R0004 - General Storeroom**

|   |                  |     |            |                    |                                    |                    |
|---|------------------|-----|------------|--------------------|------------------------------------|--------------------|
| Ceiling Structures/Linings                    | Flat AC Sheeting | 6m2 | Throughout | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 2842/B00A/R0004/Ceiling Structures/Linings/S8 |                  |     |            |                    | <b>Chrysotile (white asbestos)</b> |                    |

**B00A - R0005 - Movement**

|   |                  |  |  |  |                             |  |
|---|------------------|--|--|--|-----------------------------|--|
| Ceiling Structures/Linings                    | Flat AC Sheeting |  |  |  |                             |  |
| 2842/B00A/R0005/Ceiling Structures/Linings/S6 |                  |  |  |  | <b>No Asbestos Detected</b> |  |

**B00A - R0006 - Home Base**

No Asbestos

**B00A - R0007 - Home Base**

No Asbestos

**B00A - R0008 - Movement**

No Asbestos

**B00A - R0009 - Staff Room Annexe**

No Asbestos

**B00A - R0010 - Toilets - Boys**

|   |                     |      |            |                    |                                    |                    |
|---|---------------------|------|------------|--------------------|------------------------------------|--------------------|
| Disabled Toilet Cubicle Wall                    | Compressed AC Sheet | 4m2  | West       | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 2842/B00A/R0023/Disabled Toilet Cubicle Wall/S4 |                     |      |            |                    | <b>Chrysotile (white asbestos)</b> |                    |
| Ceiling Structures/Linings                      | Flat AC Sheeting    | 38m2 | Throughout | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 2842/B00A/R0003/Ceiling Structures/Linings/S7   |                     |      |            |                    | <b>Chrysotile (white asbestos)</b> |                    |

**B00A - R0011 - Staff Toilet**

No Asbestos

**B00A - R0012 - Staff Toilet**

No Asbestos

**B00A - R0013 - General Storeroom**

No Asbestos

**B00A - R0014 - Special Programs Room**

No Asbestos

**B00A - R0015 - General Storeroom**

No Asbestos

**B00A - R0016 - Reading Area**

No Asbestos

**B00A - R0017 - General Storeroom**

No Asbestos

**B00A - R0018 - General Storeroom**

No Asbestos

**B00A - R0019 - Movement**

| Product  | Material Description                            | Extent | Location Reference | Material Condition | Risk Status | Control Priority                   |
|--|---|--------|--------------------|--------------------|-------------|------------------------------------|
| Sample No  |   |        |                    |                    | Test Result |                                    |
| Ceiling Structures/Linings                       | Flat AC Sheeting                                |        |                    |                    |             |                                    |
|  | 2842/B00A/R0005/Ceiling Structures/Linings/S6   |        |                    |                    |             | <b>No Asbestos Detected</b>        |
| Electrical Backing Board                         | No Asbestos Found                               |        |                    |                    |             |                                    |
| <b>B00A - R0020 - Home Base</b>                  |   |        |                    |                    |             |                                    |
| No Asbestos                                      |   |        |                    |                    |             |                                    |
| <b>B00A - R0021 - Home Base</b>                  |   |        |                    |                    |             |                                    |
| No Asbestos                                      |   |        |                    |                    |             |                                    |
| <b>B00A - R0022 - Cleaning Distributed Store</b> |   |        |                    |                    |             |                                    |
| No Asbestos                                      |   |        |                    |                    |             |                                    |
| <b>B00A - R0023 - Toilets - Girls</b>            |   |        |                    |                    |             |                                    |
| Disabled Toilet Cubicle Wall                     | Corrugated AC Sheeting                          | 4m2    | East               | Good Condition (1) | Low (1)     | Low Priority (2-3)                 |
|  | 2842/B00A/R0023/Disabled Toilet Cubicle Wall/S4 |        |                    |                    |             | <b>Chrysotile (white asbestos)</b> |
| Ceiling Structures/Linings                       | Flat AC Sheeting                                | 50m2   | Throughout         | Good Condition (1) | Low (1)     | Low Priority (2-3)                 |
|  | 2842/B00A/R0003/Ceiling Structures/Linings/S7   |        |                    |                    |             | <b>Chrysotile (white asbestos)</b> |

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00B - Communal Facilities - 1910 - Timber (Timber)****Exterior**

|                  |                   |
|------------------|-------------------|
| Underfloor Voids | No Asbestos Found |
| Ceiling Voids    | No Asbestos Found |

**Interior****B00B - R0001 - Toilets - Boys/Girls**

|                            |   |                             |
|----------------------------|---|-----------------------------|
| Ceiling Structures/Linings | Flat AC Sheeting<br>2842/B00B/R0003/Ceiling Structures/Linings/S1 | <b>No Asbestos Detected</b> |
| Wall Linings Internal      | Flat AC Sheeting<br>2842/B00B/R0003/Wall Linings Internal/S2      | <b>No Asbestos Detected</b> |

**B00B - R0002 - Communal Space**

No Asbestos

**B00B - R0003 - Movement**

|                            |   |                             |
|----------------------------|---|-----------------------------|
| Ceiling Structures/Linings | Flat AC Sheeting<br>2842/B00B/R0003/Ceiling Structures/Linings/S1 | <b>No Asbestos Detected</b> |
| Wall Linings Internal      | Flat AC Sheeting<br>2842/B00B/R0003/Wall Linings Internal/S2      | <b>No Asbestos Detected</b> |

**B00B - R0004 - Sports Store**

|                             |   |                             |
|-----------------------------|---|-----------------------------|
| Floor Coverings Res/Textile | Vinyl Tiles<br>2842/B00B/R0004/Floor Coverings Res/Textile/S3     | <b>No Asbestos Detected</b> |
| Ceiling Structures/Linings  | Flat AC Sheeting<br>2842/B00B/R0003/Ceiling Structures/Linings/S1 | <b>No Asbestos Detected</b> |
| Wall Linings Internal       | Flat AC Sheeting<br>2842/B00B/R0003/Wall Linings Internal/S2      | <b>No Asbestos Detected</b> |

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00C - Other-Community Use - 1975 - Steel (Steel)**

**Exterior**

|                  |                   |
|------------------|-------------------|
| Underfloor Voids | No Asbestos Found |
| Ceiling Voids    | No Asbestos Found |

**Interior**

**B00C - R0001 - Community Clinic**

No Asbestos

**B00C - R0002 - Movement**

No Asbestos

**B00C - R0003 - Staff Toilet**

No Asbestos

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00D - Building Services - 1945 - Brick/Block (Brick/Block)****Exterior**

|                  |                            |     |            |                    |         |                                    |
|------------------|----------------------------|-----|------------|--------------------|---------|------------------------------------|
| Eaves Linings    | Flat AC Sheeting           | 8m2 | East, West | Good Condition (1) | Low (1) | Low Priority (2-3)                 |
|                  | 2842/B00D/Eaves Linings/S5 |     |            |                    |         | <b>Chrysotile (white asbestos)</b> |
| Underfloor Voids | No Asbestos Found          |     |            |                    |         |                                    |
| Ceiling Voids    | No Asbestos Found          |     |            |                    |         |                                    |

**Interior****B00D - R0002 - Garden Store**

|                            |   |     |            |                    |         |                                    |
|----------------------------|---|-----|------------|--------------------|---------|------------------------------------|
| Ceiling Structures/Linings | Flat AC Sheeting                              | 5m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3)                 |
|                            | 2842/B00D/R0003/Ceiling Structures/Linings/S9 |     |            |                    |         | <b>Chrysotile (white asbestos)</b> |

**B00D - R0003 - General Assistant/Bulk Store**

|                            |   |     |            |                    |         |                                    |
|----------------------------|---|-----|------------|--------------------|---------|------------------------------------|
| Ceiling Structures/Linings | Flat AC Sheeting                              | 4m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3)                 |
|                            | 2842/B00D/R0003/Ceiling Structures/Linings/S9 |     |            |                    |         | <b>Chrysotile (white asbestos)</b> |

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|---------|----------------------|--------|--------------------|--------------------|-------------|------------------|
|         | Sample No            |        |                    |                    |             | Test Result      |

**B00E - General Learning - 2010 - Brick/Veneer (Brick/Veneer)****Exterior**

|                  |                   |
|------------------|-------------------|
| Ceiling Voids    | No Asbestos Found |
| Underfloor Voids | No Asbestos Found |

**Interior****B00E - R0001 - Home Base**

No Asbestos

**B00E - R0002 - Home Base Store**

No Asbestos

**B00E - R0003 - Practical Activities - 1hb**

No Asbestos

**B00E - R0004 - Withdrawal Space - 2hb**

No Asbestos

**B00E - R0005 - Home Base**

No Asbestos

**B00E - R0006 - Practical Activities - 1hb**

No Asbestos

**B00E - R0007 - Home Base Store**

No Asbestos

**B00E - R0008 - Home Base**

No Asbestos

**B00E - R0009 - Home Base Store**

No Asbestos

**B00E - R0010 - Practical Activities - 1hb**

No Asbestos

**B00E - R0011 - Withdrawal Space - 2hb**

No Asbestos

**B00E - R0012 - Home Base**

No Asbestos

**B00E - R0013 - Home Base Store**

No Asbestos

**B00E - R0014 - Practical Activities - 1hb**

No Asbestos

**B00E - R0015 - External Movement**

No Asbestos

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

## Demountables

### Demountable details as per the AMS records as of 15 Feb 2017.

#### OS 602 - D10326 - Learning Unit - Standard With P.A.A. : Placement Date - 27/01/2012

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

#### Exterior

No Asbestos Found.

#### Interior

##### R1 - Learning space/withdrawal/entry

No Asbestos Found.

##### R2 - Home Base Store

No Asbestos Found.

#### OS 601 - D11457 - Learning Unit - Standard/Withdrawal : Placement Date - 14/07/2000

#### Exterior

|             |                     |                  |          |
|-------------|---------------------|------------------|----------|
| Step Treads | Compressed AC Sheet | Assumed Asbestos | 1.08 m2  |
| Landing     | Compressed AC Sheet | Assumed Asbestos | 1.2 m2   |
| Eave Lining | Flat AC Sheet       | Assumed Asbestos | 11.52 m2 |

#### Interior

##### R1 - Entry

|                |               |                  |       |
|----------------|---------------|------------------|-------|
| End wall panel | Flat AC Sheet | Assumed Asbestos | 18 m2 |
| Ceiling        | Flat AC Sheet | Assumed Asbestos | 8 m2  |

##### R2 - General Learning Space

|                |               |                  |       |
|----------------|---------------|------------------|-------|
| End wall panel | Flat AC Sheet | Assumed Asbestos | 18 m2 |
| Ceiling        | Flat AC Sheet | Assumed Asbestos | 55 m2 |

##### R3 - Store

|         |               |                  |       |
|---------|---------------|------------------|-------|
| Ceiling | Flat AC Sheet | Assumed Asbestos | 10 m2 |
|---------|---------------|------------------|-------|

#### OS 602 - D11732 - Learning Unit - Standard With P.A.A. : Placement Date - 24/12/2015

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

#### Exterior

No Asbestos Found.

#### Interior

##### R1 - Learning space/withdrawal/entry

No Asbestos Found.

##### R2 - Home Base Store

No Asbestos Found.

#### OS 601 - D13780 - Learning Unit - Standard/Withdrawal : Placement Date - 6/01/2009

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

#### Exterior

No Asbestos Found.

#### Interior

##### R1 - Entry

No Asbestos Found.

##### R2 - General Learning Space

No Asbestos Found.

##### R3 - Store

No Asbestos Found.

#### OS 801 - D14426 - FSU : Placement Date - 30/06/1995



| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**Exterior**

|             |                     |                  |  |  |  |         |
|-------------|---------------------|------------------|--|--|--|---------|
| Step Treads | Compressed AC Sheet | Assumed Asbestos |  |  |  | 1.08 m2 |
| Landing     | Compressed AC Sheet | Assumed Asbestos |  |  |  | 1.2 m2  |
| Eave Lining | Flat AC Sheet       | Assumed Asbestos |  |  |  | 8.64 m2 |

**Interior****R1 - Canteen**

|                |               |                  |  |  |  |       |
|----------------|---------------|------------------|--|--|--|-------|
| End wall panel | Flat AC Sheet | Assumed Asbestos |  |  |  | 18 m2 |
| Ceiling        | Flat AC Sheet | Assumed Asbestos |  |  |  | 45 m2 |

**R2 - Covered Area**

|                |               |                  |  |  |  |       |
|----------------|---------------|------------------|--|--|--|-------|
| End wall panel | Flat AC Sheet | Assumed Asbestos |  |  |  | 18 m2 |
| Ceiling        | Flat AC Sheet | Assumed Asbestos |  |  |  | 10 m2 |

**OS 602 - D14801 - Learning Unit - Standard With P.A.A. : Placement Date - 18/09/2013**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior****R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 504 - D15128 - Admin Principal/Deputy/Clerk/Store : Placement Date - 30/06/1995****Exterior**

|             |                     |                  |  |  |  |          |
|-------------|---------------------|------------------|--|--|--|----------|
| Step Treads | Compressed AC Sheet | Assumed Asbestos |  |  |  | 1.08 m2  |
| Landing     | Compressed AC Sheet | Assumed Asbestos |  |  |  | 1.2 m2   |
| Eave Lining | Flat AC Sheet       | Assumed Asbestos |  |  |  | 23.04 m2 |

2017

| Product                          | Material Description | Extent           | Location Reference | Material Condition | Risk Status | Control Priority |
|----------------------------------|----------------------|------------------|--------------------|--------------------|-------------|------------------|
| Sample No                        |                      |                  |                    |                    | Test Result |                  |
| <b>Interior</b>                  |                      |                  |                    |                    |             |                  |
| <b>R1 - Clerical Office</b>      |                      |                  |                    |                    |             |                  |
| End wall panel                   | Flat AC Sheet        | Assumed Asbestos |                    |                    |             | 18 m2            |
| Ceiling                          | Flat AC Sheet        | Assumed Asbestos |                    |                    |             | 16 m2            |
| <b>R10 - Entry</b>               |                      |                  |                    |                    |             |                  |
| End wall panel                   | Flat AC Sheet        | Assumed Asbestos |                    |                    |             | 18 m2            |
| Ceiling                          | Flat AC Sheet        | Assumed Asbestos |                    |                    |             | 27 m2            |
| <b>R11 - Store</b>               |                      |                  |                    |                    |             |                  |
| Ceiling                          | Flat AC Sheet        | Assumed Asbestos |                    |                    |             | 1 m2             |
| <b>R2 - Security Store</b>       |                      |                  |                    |                    |             |                  |
| Ceiling                          | Flat AC Sheet        | Assumed Asbestos |                    |                    |             | 12 m2            |
| <b>R3 - Duplicating Wookroom</b> |                      |                  |                    |                    |             |                  |
| Ceiling                          | Flat AC Sheet        | Assumed Asbestos |                    |                    |             | 12 m2            |
| <b>R4 - Clinic-Waiting</b>       |                      |                  |                    |                    |             |                  |
| Ceiling                          | Flat AC Sheet        | Assumed Asbestos |                    |                    |             | 16 m2            |
| <b>R5 - Deputy Principal</b>     |                      |                  |                    |                    |             |                  |
| Ceiling                          | Flat AC Sheet        | Assumed Asbestos |                    |                    |             | 18 m2            |
| <b>R6 - Principal</b>            |                      |                  |                    |                    |             |                  |
| Ceiling                          | Flat AC Sheet        | Assumed Asbestos |                    |                    |             | 18 m2            |
| <b>R7 - Staff Toilet</b>         |                      |                  |                    |                    |             |                  |
| Toilet partitions                | Compressed AC Sheet  | Assumed Asbestos |                    |                    |             | 4 m2             |
| Ceiling                          | Flat AC Sheet        | Assumed Asbestos |                    |                    |             | 5 m2             |
| <b>R8 - Staff Toilet</b>         |                      |                  |                    |                    |             |                  |
| Toilet partitions                | Compressed AC Sheet  | Assumed Asbestos |                    |                    |             | 4 m2             |
| Ceiling                          | Flat AC Sheet        | Assumed Asbestos |                    |                    |             | 5 m2             |
| <b>R9 - Clerk</b>                |                      |                  |                    |                    |             |                  |
| Ceiling                          | Flat AC Sheet        | Assumed Asbestos |                    |                    |             | 16 m2            |

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017