

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Parramatta West Public School (2843)
Region : Western Sydney
State Electorate : Granville
Local Government Area : Holroyd

Initial Survey : Noel Arnold & Associates : 21 - Apr - 2008
Reviewed By : Parsons Brinckerhoff : 14 - May - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning - 1976 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting 2843/B00A/Eaves Linings/S14	40m2	South	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting 2843/B00A/Gable Verge Lining/S15	10m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00A - R0001 - Movement (82.56 m2)**

In-fill-panel	Flat AC Sheeting 2843/B00A/R1001/In-fill-panel/S3	12m	South	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
---------------	--	-----	-------	--------------------	---------	--

B00A - R0002 - General Storeroom (7.53 m2)

No Asbestos

B00A - R0003 - Distribution Board (0.71 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0004 - Home Base (79.03 m2)

Ceiling Structures/Linings	Vermiculite 2843/B00A/R0006/Ceiling Structures/Linings/S5					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
----------------------------	--	--	--	--	--	--

B00A - R0005 - Toilets - Boys/Girls (3.13 m2)

Ceiling Structures/Linings	Vermiculite 2843/B00A/R0006/Ceiling Structures/Linings/S5					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
----------------------------	--	--	--	--	--	--

In-fill-panel	Flat AC Sheeting 2843/B00A/R1001/In-fill-panel/S3	12m	North, South	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
---------------	--	-----	--------------	--------------------	---------	--

B00A - R0006 - Practical Activities - 1hb (18.76 m2)

Floor Coverings Res/Textile	Vinyl Tiles 2843/B00A/R1002/Floor Coverings Res/Textile/S4	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
-----------------------------	---	------	------------	--------------------	---------	--

Ceiling Structures/Linings	Vermiculite 2843/B00A/R0006/Ceiling Structures/Linings/S5					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
----------------------------	--	--	--	--	--	--

B00A - R0007 - Home Base (79.06 m2)

Ceiling Structures/Linings	Vermiculite 2843/B00A/R0006/Ceiling Structures/Linings/S5					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
----------------------------	--	--	--	--	--	--

In-fill-panel	Flat AC Sheeting 2843/B00A/R1001/In-fill-panel/S3	12m	North, South	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
---------------	--	-----	--------------	--------------------	---------	--

B00A - R0008 - Staff Toilet (3.11 m2)

Ceiling Structures/Linings	Vermiculite 2843/B00A/R0006/Ceiling Structures/Linings/S5					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
----------------------------	--	--	--	--	--	--

B00A - R0009 - Toilets - Girls (22.62 m2)

Partition Walls (Cubicles)	Compressed AC Sheet 2843/B00A/R0009/Partition Walls (Cubicles)/S6	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	--	------	------------	--------------------	---------	--

B00A - R0010 - Toilets - Boys (22.83 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority	
Sample No					Test Result		
Partition Walls (Cubicles)	Compressed AC Sheet	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	
2843/B00A/R0009/Partition Walls (Cubicles)/S6					Chrysotile (white asbestos)		
B00A - R0011 - Garden Store (7.64 m2)							
No Asbestos							
B00A - R0012 - Stairs (8.11 m2)							
Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)	
2843/B00A/R1008/Ceiling Structures/Linings/S20					Chrysotile (white asbestos)		
B00A - R0013 - Stairs (5.01 m2)							
No Asbestos							
B00A - R0014 - Movement (6.67 m2)							
No Asbestos							
B00A - R0015 - Stairs (0.54 m2)							
No Asbestos							
B00A - R1001 - Movement (84.81 m2)							
Ceiling Structures/Linings	Flat AC Sheeting	85m2	Throughout	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)	
2843/B00A/R1001/Ceiling Structures/Linings/S1					Chrysotile (white asbestos) , Amosite (brown asbestos)		
Wall Linings Internal	Flat AC Sheeting	2843/B00A/R1001/Wall Linings Internal/S2				No Asbestos Detected	
In-fill-panel	Flat AC Sheeting	10m	South	Good Condition (1)	Low (1)	Low Priority (2-3)	
2843/B00A/R1001/In-fill-panel/S3					Chrysotile (white asbestos)		
B00A - R1002 - K.L.A. Store (22.7 m2)							
In-fill-panel	Flat AC Sheeting	1m	North	Good Condition (1)	Low (1)	Low Priority (2-3)	
2843/B00A/R1001/In-fill-panel/S3					Chrysotile (white asbestos)		
Floor Coverings Res/Textile	Vinyl Tiles	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	
2843/B00A/R1002/Floor Coverings Res/Textile/S4					Chrysotile (white asbestos)		
B00A - R1003 - Distribution Board (0.67 m2)							
Note: No inspection of live electrical installation.							
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)	
2843/B00A/R1003/Ceiling Structures/Linings/S19					Chrysotile (white asbestos)		
B00A - R1004 - Home Base (59.23 m2)							
In-fill-panel	Flat AC Sheeting	12m	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	
2843/B00A/R1001/In-fill-panel/S3					Chrysotile (white asbestos)		
B00A - R1005 - Practical Activities - 1hb (18.76 m2)							
Floor Coverings Res/Textile	Vinyl Tiles	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	
2843/B00A/R1002/Floor Coverings Res/Textile/S4					Chrysotile (white asbestos)		
B00A - R1006 - Home Base (59.19 m2)							
In-fill-panel	Flat AC Sheeting	8m	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	
2843/B00A/R1001/In-fill-panel/S3					Chrysotile (white asbestos)		
B00A - R1007 - Home Base (70.2 m2)							
In-fill-panel	Flat AC Sheeting	8m	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	
2843/B00A/R1001/In-fill-panel/S3					Chrysotile (white asbestos)		
B00A - R1008 - Stairs (7.98 m2)							
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)	
2843/B00A/R1008/Ceiling Structures/Linings/S20					Chrysotile (white asbestos)		

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R1009 - Stairs (17.13 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	18m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
2843/B00A/R1008/Ceiling Structures/Linings/S20					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Administration/Library - 1976 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	80m2	North, South	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
	2843/B00A/R1001/Ceiling Structures/Linings/S1			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Gable Verge Lining	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2843/B00A/Gable Verge Lining/S15			Chrysotile (white asbestos)		
In-fill-panel	Flat AC Sheeting	20m2	South, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2843/B00A/R1001/In-fill-panel/S3			Chrysotile (white asbestos)		
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00B - R0001 - Movement (63.21 m2)**

In-fill-panel	Flat AC Sheeting	24m	South, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2843/B00A/R1001/In-fill-panel/S3			Chrysotile (white asbestos)		

B00B - R0002 - Deputy Principal (13.61 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2843/B00A/R0006/Ceiling Structures/Linings/S5					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
In-fill-panel	Flat AC Sheeting	2m	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	2843/B00A/R1001/In-fill-panel/S3			Chrysotile (white asbestos)		

B00B - R0003 - Staff Toilet (4.16 m2)

No Asbestos

B00B - R0004 - Staff Toilet (4.19 m2)

No Asbestos

B00B - R0005 - Duplicating Workroom (13.43 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2843/B00A/R0006/Ceiling Structures/Linings/S5					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
In-fill-panel	Flat AC Sheeting	2m	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	2843/B00A/R1001/In-fill-panel/S3			Chrysotile (white asbestos)		

B00B - R0006 - Movement (19.49 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2843/B00A/R0006/Ceiling Structures/Linings/S5					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00B - R0007 - Entry Vestibule (16.2 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2843/B00A/R0006/Ceiling Structures/Linings/S5					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00B - R0008 - Clerical Office/Workroom (16.2 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2843/B00A/R0006/Ceiling Structures/Linings/S5					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
In-fill-panel	Flat AC Sheeting	3m	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2843/B00A/R1001/In-fill-panel/S3			Chrysotile (white asbestos)		

B00B - R0009 - Movement (22.32 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite 2843/B00A/R0006/Ceiling Structures/Linings/S5				Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>	
B00B - R0010 - Sick Bay (14.31 m2)						
Ceiling Structures/Linings	Vermiculite 2843/B00A/R0006/Ceiling Structures/Linings/S5				Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>	
In-fill-panel	Flat AC Sheeting 2843/B00A/R1001/In-fill-panel/S3	2m	South	Good Condition (1)	Low (1)	Low Priority (2-3) <i>Chrysotile (white asbestos)</i>
Floor Coverings Res/Textile	Vinyl Tiles 2843/B00A/R1002/Floor Coverings Res/Textile/S4	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <i>Chrysotile (white asbestos)</i>
B00B - R0011 - Principal (18.64 m2)						
Ceiling Structures/Linings	Vermiculite 2843/B00A/R0006/Ceiling Structures/Linings/S5				Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>	
In-fill-panel	Flat AC Sheeting 2843/B00A/R1001/In-fill-panel/S3	3m	South	Good Condition (1)	Low (1)	Low Priority (2-3) <i>Chrysotile (white asbestos)</i>
B00B - R0012 - Interview (12.09 m2)						
Ceiling Structures/Linings	Vermiculite 2843/B00A/R0006/Ceiling Structures/Linings/S5				Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>	
In-fill-panel	Flat AC Sheeting 2843/B00A/R1001/In-fill-panel/S3	1m	South	Good Condition (1)	Low (1)	Low Priority (2-3) <i>Chrysotile (white asbestos)</i>
B00B - R0013 - Deputy Principal (18.6 m2)						
Ceiling Structures/Linings	Vermiculite 2843/B00A/R0006/Ceiling Structures/Linings/S5				Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>	
In-fill-panel	Flat AC Sheeting 2843/B00A/R1001/In-fill-panel/S3	2m	South	Good Condition (1)	Low (1)	Low Priority (2-3) <i>Chrysotile (white asbestos)</i>
B00B - R0014 - Cleaning Supplies (5.22 m2)						
No Asbestos						
B00B - R0015 - Main Switch Board (7.74 m2)						
No Asbestos						
B00B - R0016 - Staff Room (111.18 m2)						
Ceiling Structures/Linings	Vermiculite 2843/B00A/R0006/Ceiling Structures/Linings/S5				Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>	
In-fill-panel	Flat AC Sheeting 2843/B00A/R1001/In-fill-panel/S3	5m	North	Good Condition (1)	Low (1)	Low Priority (2-3) <i>Chrysotile (white asbestos)</i>
B00B - R0017 - General Storeroom (21.18 m2)						
Ceiling Structures/Linings	Vermiculite 2843/B00A/R0006/Ceiling Structures/Linings/S5				Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>	
B00B - R0018 - Community Clinic (17.56 m2)						
Ceiling Structures/Linings	Vermiculite 2843/B00A/R0006/Ceiling Structures/Linings/S5				Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
In-fill-panel	Flat AC Sheeting	2m	North	Good Condition (1)	Low (1)	Low Priority (2-3)
2843/B00A/R1001/In-fill-panel/S3					Chrysotile (white asbestos)	
B00B - R0019 - Movement (9.99 m2)						
No Asbestos						
B00B - R0020 - Stairs (4.95 m2)						
No Asbestos						
B00B - R1001 - Movement (56.51 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	57m2	Throughout	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
2843/B00A/R1001/Ceiling Structures/Linings/S1					Chrysotile (white asbestos) , Amosite (brown asbestos)	
In-fill-panel	Flat AC Sheeting	12m	South	Good Condition (1)	Low (1)	Low Priority (2-3)
2843/B00A/R1001/In-fill-panel/S3					Chrysotile (white asbestos)	
B00B - R1002 - K.L.A. Store (15.41 m2)						
In-fill-panel	Flat AC Sheeting	2m	North	Good Condition (1)	Low (1)	Low Priority (2-3)
2843/B00A/R1001/In-fill-panel/S3					Chrysotile (white asbestos)	
B00B - R1003 - Staff Toilet (3.24 m2)						
Partition Walls (Cubicles)	Compressed AC Sheet	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2843/B00B/R1003/Partition Walls (Cubicles)/S13					Chrysotile (white asbestos)	
B00B - R1004 - Distribution Board (1.93 m2)						
					Note: No inspection of live electrical installation.	
No Asbestos						
B00B - R1005 - Movement (11.66 m2)						
No Asbestos						
B00B - R1006 - Staff Toilet (3.18 m2)						
Partition Walls (Cubicles)	Compressed AC Sheet	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2843/B00B/R1003/Partition Walls (Cubicles)/S13					Chrysotile (white asbestos)	
B00B - R1007 - Cleaning Distributed Store (1.85 m2)						
No Asbestos						
B00B - R1008 - Communications Room (15.93 m2)						
In-fill-panel	Flat AC Sheeting	2m	South	Good Condition (1)	Low (1)	Low Priority (2-3)
2843/B00A/R1001/In-fill-panel/S3					Chrysotile (white asbestos)	
B00B - R1009 - Library Office/Workroom (25.81 m2)						
In-fill-panel	Flat AC Sheeting	2m	South	Good Condition (1)	Low (1)	Low Priority (2-3)
2843/B00A/R1001/In-fill-panel/S3					Chrysotile (white asbestos)	
B00B - R1010 - Library Office/Workroom (12.47 m2)						
No Asbestos						
B00B - R1011 - Reading Area (237.77 m2)						
In-fill-panel	Flat AC Sheeting	12m	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
2843/B00A/R1001/In-fill-panel/S3					Chrysotile (white asbestos)	
B00B - R1012 - K.L.A. Store (15.84 m2)						
In-fill-panel	Flat AC Sheeting	2m	North	Good Condition (1)	Low (1)	Low Priority (2-3)
2843/B00A/R1001/In-fill-panel/S3					Chrysotile (white asbestos)	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00C - General Learning - 1976 - Brick/Block (Brick/Block)						
Exterior						
Eaves Linings	Flat AC Sheeting	40m2	North, South	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
	2843/B00A/R1001/Ceiling Structures/Linings/S1				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Gable Verge Lining	Flat AC Sheeting	10m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2843/B00A/Gable Verge Lining/S15				Chrysotile (white asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					
Interior						
B00C - R0001 - Movement (53 m2)						
In-fill-panel	Flat AC Sheeting	18m	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2843/B00A/R1001/In-fill-panel/S3				Chrysotile (white asbestos)	
B00C - R0002 - Cleaning Distributed Store (4.68 m2)						
No Asbestos						
B00C - R0003 - Home Base (59.56 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2843/B00A/R0006/Ceiling Structures/Linings/S5				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
In-fill-panel	Flat AC Sheeting	9m	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2843/B00A/R1001/In-fill-panel/S3				Chrysotile (white asbestos)	
B00C - R0004 - Practical Activities - 1hb (18.89 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2843/B00A/R1002/Floor Coverings Res/Textile/S4				Chrysotile (white asbestos)	
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2843/B00A/R0006/Ceiling Structures/Linings/S5				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
B00C - R0005 - Home Base (59.71 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2843/B00A/R0006/Ceiling Structures/Linings/S5				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
In-fill-panel	Flat AC Sheeting	9m	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2843/B00A/R1001/In-fill-panel/S3				Chrysotile (white asbestos)	
B00C - R0006 - Distribution Board (3.19 m2)						
No Asbestos						
B00C - R0007 - Stairs (10.99 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Some Damage - Unsealed (3)	Medium (2)	Medium Priority (4-5)
	2843/B00A/R1008/Ceiling Structures/Linings/S20				Chrysotile (white asbestos)	
B00C - R0008 - Stairs (12.25 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	13m2	Throughout	Some Damage - Unsealed (3)	Medium (2)	Medium Priority (4-5)
	2843/B00A/R1008/Ceiling Structures/Linings/S20				Chrysotile (white asbestos)	
B00C - R1001 - Movement (58.24 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	59m2	Throughout	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
	2843/B00A/R1001/Ceiling Structures/Linings/S1				Chrysotile (white asbestos) , Amosite (brown asbestos)	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
In-fill-panel	Flat AC Sheeting	18m	South	Good Condition (1)	Low (1)	Low Priority (2-3)
2843/B00A/R1001/In-fill-panel/S3					Chrysotile (white asbestos)	
B00C - R1002 - Home Base (59.49 m2)						
In-fill-panel	Flat AC Sheeting	9m	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
2843/B00A/R1001/In-fill-panel/S3					Chrysotile (white asbestos)	
B00C - R1003 - Practical Activities - 1hb (18.94 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2843/B00A/R1002/Floor Coverings Res/Textile/S4					Chrysotile (white asbestos)	
B00C - R1004 - Home Base (59.23 m2)						
In-fill-panel	Flat AC Sheeting	9m	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
2843/B00A/R1001/In-fill-panel/S3					Chrysotile (white asbestos)	
B00C - R1005 - Distribution Board (3.19 m2)						
				Note: No inspection of live electrical installation.		
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Some Damage - Unsealed (3)	Medium (2)	Medium Priority (4-5)
2843/B00C/R1005/Ceiling Structures/Linings/S21					Chrysotile (white asbestos)	
B00C - R1006 - Stairs (10.22 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Some Damage - Unsealed (3)	Medium (2)	Medium Priority (4-5)
2843/B00A/R1008/Ceiling Structures/Linings/S20					Chrysotile (white asbestos)	
B00C - R1007 - Stairs (8.94 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Some Damage - Unsealed (3)	Medium (2)	Medium Priority (4-5)
2843/B00A/R1008/Ceiling Structures/Linings/S20					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Pupil Facilities/Communal Facilities - 1976 - Brick/Block (Brick/Block)

Exterior

Gable Verge Lining	Flat AC Sheeting	3m2	North & South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2843/B00D/Gable Verge Lining/S16				Chrysotile (white asbestos)	
Gable Ends	Flat AC Sheeting					No Asbestos Detected
	2843/B00D/Gable Ends/S17					
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00D - R0001 - Movement (216.34 m2)

Ceiling Structures/Linings	Flat AC Sheeting	217m2	Variable positions	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
	2843/B00D/R0001/Ceiling Structures/Linings/S10				Chrysotile (white asbestos)	

B00D - R0002 - Toilets - Boys (23.45 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2843/B00D/R0002/Partition Walls (Cubicles)/S11				Chrysotile (white asbestos)	

B00D - R0003 - Toilets - Girls (24.4 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2843/B00D/R0002/Partition Walls (Cubicles)/S11				Chrysotile (white asbestos)	

B00D - R0004 - Distribution Board (0.66 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0005 - Hall Chair Store (9.39 m2)

No Asbestos

B00D - R0006 - Communal Space (223.38 m2)

No Asbestos

B00D - R0007 - Raised Platform (78.56 m2)

No Asbestos

B00D - R0008 - P.E. Store (13.44 m2)

No Asbestos

B00D - R0009 - Cleaning Supplies (13.5 m2)

No Asbestos

B00D - R0010 - Distribution Board (0.41 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0011 - Cleaning Distributed Store (5.1 m2)

No Asbestos

B00D - R0012 - General Assistant/Bulk Store (12.18 m2)

No Asbestos

B00D - R0013 - Garden Store (13.16 m2)

No Asbestos

B00D - R0014 - Staff Toilet (3.83 m2)

Incinerate	Encapsulated Insulation material within unit	1Unit(s)	East	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Unable to Access sealed unit -					

B00D - R0015 - Canteen Office/Store (7.05 m2)

Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2843/B00D/R0016/Floor Coverings Res/Textile/S9				Chrysotile (white asbestos)	

B00D - R0016 - Canteen (43.96 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles	44m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2843/B00D/R0016/Floor Coverings Res/Textile/S9					Chrysotile (white asbestos)	
B00D - R0017 - Canteen Office/Store (4.41 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2843/B00D/R0016/Floor Coverings Res/Textile/S9					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning - 1887 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00E - R0001 - Movement (2.63 m2)

No Asbestos

B00E - R0002 - General Storeroom (7.92 m2)

No Asbestos

B00E - R0003 - General Storeroom (3.39 m2)

No Asbestos

B00E - R0004 - Home Base (49.43 m2)

No Asbestos

B00E - R0008 - Movement (2.25 m2)

No Asbestos

B00E - R0009 - Movement (80.24 m2)

No Asbestos

B00E - R0010 - Disabled Toilet (9.41 m2)

No Asbestos

B00E - R0011 - Withdrawal Space - 1hb (13.15 m2)

No Asbestos

B00E - R0012 - Home Base (62.36 m2)

No Asbestos

B00E - R0013 - Special Programs Room (10.99 m2)

No Asbestos

B00E - R0014 - Home Base (46.8 m2)

No Asbestos

B00E - R0015 - Practical Activities - 1hb (15.7 m2)

No Asbestos

B00E - R0016 - Practical Activities (8.78 m2)

No Asbestos

B00E - R0017 - General Storeroom (4.77 m2)

No Asbestos

B00E - R0018 - Practical Activities - 1hb (15.14 m2)

No Asbestos

B00E - R0019 - Home Base (47.04 m2)

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning/Pupil Facilities - 1887 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior**B00F - R0001 - Uniform Shop (7.6 m2)**

No Asbestos

B00F - R0003 - Movement (3.15 m2)

No Asbestos

B00F - R0004 - Other-Community Use (26.54 m2)

No Asbestos

B00F - R0006 - Personal Effects Storage (11.04 m2)

No Asbestos

B00F - R0008 - Home Base (55.92 m2)

No Asbestos

B00F - R0012 - Special Programs Room (59.93 m2)

In-fill-panel	Flat AC Sheeting	12m	East	Good Condition (1)	Low (1)	Low Priority (2-3)
2843/B00F/R0012/In-fill-panel/S12				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00F - R0013 - Toilets - Girls (22.55 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2843/B00D/R0002/Partition Walls (Cubicles)/S11				Chrysotile (white asbestos)		

B00F - R0014 - Toilets - Boys (22.62 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2843/B00D/R0002/Partition Walls (Cubicles)/S11				Chrysotile (white asbestos)		

B00F - R0015 - Movement (117.46 m2)

No Asbestos

B00F - R0016 - General Storeroom (11.96 m2)

No Asbestos

B00F - R0017 - General Storeroom (15.71 m2)

No Asbestos

B00F - R0018 - Craft Store (15.75 m2)

No Asbestos

B00F - R0019 - Home Base/Practical Activities (55.47 m2)

No Asbestos

B00F - R0020 - Home Base Store (13.18 m2)

No Asbestos

B00F - R0021 - Home Base Store (11.31 m2)

No Asbestos

B00F - R0022 - Withdrawal Space - 2hb (17.71 m2)

No Asbestos

B00F - R0023 - Home Base Store (13.17 m2)

No Asbestos

B00F - R0024 - Home Base/Practical Activities (55.41 m2)

No Asbestos

B00F - R0025 - Home Base/Practical Activities (70.49 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - R0026 - Withdrawal Space - 2hb (11.15 m2)

No Asbestos

B00F - R0027 - Home Base/Practical Activities (65.88 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Other-After School Care - 1937 - Timber (Timber)**Exterior**

Underfloor Voids - Packing to Floor Joists	Flat AC Sheeting					
	2843/B00G/Underfloor Voids - Packing to Floor Joists/S18					No Asbestos Detected
Ceiling Voids	No Asbestos Found					

Interior**B00G - R0001 - General Storeroom (7.41 m2)**

No Asbestos

B00G - R0002 - Out Of School Hours Care Centre (52.99 m2)

Floor Coverings Res/Textile	Vinyl Tiles					
	2843/B00G/R0002/Floor Coverings Res/Textile/S7					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting	50m2	Throughout, Upper portion, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	2843/B00G/R0002/Wall Linings Internal/S8					Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	53m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2843/B00G/R0003/Ceiling Structures/Linings/S22					Chrysotile (white asbestos)

B00G - R0003 - Out Of School Hours Care Centre (52.99 m2)

Wall Linings Internal	Flat AC Sheeting	50m2	Throughout, Upper portion, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	2843/B00G/R0002/Wall Linings Internal/S8					Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	53m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2843/B00G/R0003/Ceiling Structures/Linings/S22					Chrysotile (white asbestos)

B00G - R0004 - Movement (27.96 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Shed - 1937 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids No Asbestos Found

Underfloor Voids No Asbestos Found

Interior

B00H - R0001 - General Storeroom (38.02 m2)

No Asbestos

B00H - R0002 - General Storeroom (38.02 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Building Services - 2007 - Concrete (Concrete)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00L - R0001 - Movement (2.56 m2)

No Asbestos

B00L - R0002 - Lift (1.85 m2)

No Asbestos

B00L - R1001 - Movement (2.15 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00M - R0001 - Home Base (60.19 m2)	No Asbestos
B00M - R0002 - Home Base Store (6.16 m2)	No Asbestos
B00M - R0003 - Practical Activities/Movement - 1hb (19.58 m2)	No Asbestos
B00M - R0004 - Withdrawal Space - 2hb (11.51 m2)	No Asbestos
B00M - R0005 - Home Base (60.35 m2)	No Asbestos
B00M - R0006 - Practical Activities - 1hb (19.62 m2)	No Asbestos
B00M - R0007 - Home Base Store (6.29 m2)	No Asbestos
B00M - R0008 - Home Base (60.16 m2)	No Asbestos
B00M - R0009 - Home Base Store (6.31 m2)	No Asbestos
B00M - R0010 - Practical Activities - 1hb (19.67 m2)	No Asbestos
B00M - R0011 - Withdrawal Space - 2hb (11.52 m2)	No Asbestos
B00M - R0012 - Home Base (60.13 m2)	No Asbestos
B00M - R0013 - Practical Activities - 1hb (19.58 m2)	No Asbestos
B00M - R0014 - Home Base Store (6.29 m2)	No Asbestos
B00M - R0015 - External Movement (100.11 m2)	No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D10679 - Learning Unit - Standard With P.A.A. : Placement Date - 15/04/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 751 - D11117 - Learning Unit - ESL : Placement Date - 13/02/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Es1

No Asbestos Found.

R2 - Es1

No Asbestos Found.

OS 602 - D11353 - Learning Unit - Standard With P.A.A. : Placement Date - 7/10/2014

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D12005 - Learning Unit - Standard With P.A.A. : Placement Date - 7/10/2014

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D12606 - Learning Unit - Standard With P.A.A. : Placement Date - 5/09/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 603 - D12884 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 20/01/2012						
Exterior						
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 601 - D12996 - Learning Unit - Standard/Withdrawal : Placement Date - 31/07/2009						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Entry						
No Asbestos Found.						
R2 - General Learning Space						
No Asbestos Found.						
R3 - Store						
No Asbestos Found.						
OS 750 - D13100 - Learning Unit - ESL : Placement Date - 27/10/2014						
Exterior						
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				5.76 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Interior						
R1 - Esl						
End wall panel	Flat AC Sheet	Assumed Asbestos				50 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				36 m2
OS 602 - D13357 - Learning Unit - Standard With P.A.A. : Placement Date - 28/03/2013						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 750 - D15134 - Learning Unit - ESL : Placement Date - 27/10/2014						
Exterior						
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Eave Lining	Flat AC Sheet	Assumed Asbestos				5.76 m2
Interior						
R1 - Es1						
End wall panel	Flat AC Sheet	Assumed Asbestos				50 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				36 m2
OS 602 - D15373 - Learning Unit - Standard With P.A.A. : Placement Date - 16/01/2016						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 602 - D15820 - Learning Unit - Standard With P.A.A. : Placement Date - 9/01/2017						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 602 - D16227 - Learning Unit - Standard With P.A.A. : Placement Date - 16/01/2016						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 602 - D16273 - Learning Unit - Standard With P.A.A. : Placement Date - 20/01/2012						
Exterior						
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Interior						
R1 - Learning space/withdrawal/entry						
Ceiling	Flat AC Sheet	Assumed Asbestos				70 m2
R2 - Home Base Store						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				3 m2
OS 602 - D16348 - Learning Unit - Standard With P.A.A. : Placement Date - 17/01/2014						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 602 - D18142 - Learning Unit - Standard With P.A.A. : Placement Date - 9/01/2017						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

Available Asbestos Related Electronic Files

2843_ASB_231112_AMP.pdf

* Note : Refer to AMS for details of the attachment(s).

2017