


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Paterson Public School (2844)  
**Region :** Hunter/Central Coast  
**State Electorate :** Upper Hunter  
**Local Government Area :** Dungog

**Initial Survey :** Noel Arnold & Associates : 19 - May - 2008  
**Register Issue Date :** 22 - Mar - 2017



# 2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - General Learning/Administration - 1978 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting	100m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	<b>Assumed Asbestos</b>					
Gable Verge Lining	Flat AC Sheeting	50m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	<b>Assumed Asbestos</b>					
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

**Interior**

**B00A - R0001 - Staff Toilet**

No Asbestos

**B00A - R0002 - Canteen Office/Store**

No Asbestos

**B00A - R0003 - Movement**

No Asbestos

**B00A - R0004 - Canteen**

No Asbestos

**B00A - R0005 - Movement**

No Asbestos

**B00A - R0006 - Toilets - Boys**

Partition Walls (Cubicles)	Compressed AC Sheet	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2844/B00A/R0007/Partition Walls (Cubicles)/S2					<b>Chrysotile (white asbestos)</b>

**B00A - R0007 - Toilets - Girls**

Partition Walls (Cubicles)	Compressed AC Sheet	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2844/B00A/R0007/Partition Walls (Cubicles)/S2					<b>Chrysotile (white asbestos)</b>

**B00A - R0008 - Sports Store**

No Asbestos

**B00A - R0009 - Personal Effects Storage**

Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2844/B00A/R0031/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>

**B00A - R0010 - Home Base Store**

Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2844/B00A/R0031/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>

**B00A - R0011 - Toilets - Boys/Girls**

No Asbestos

**B00A - R0012 - Practical Activities - 1hb**

Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2844/B00A/R0031/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>

**B00A - R0013 - Home Base**

No Asbestos

**B00A - R0014 - Home Base**

No Asbestos

**B00A - R0015 - Home Base Store**

Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2844/B00A/R0031/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>

**B00A - R0016 - Personal Effects Storage**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2844/B00A/R0031/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	
<b>B00A - R0017 - General Storeroom</b>						
No Asbestos						
<b>B00A - R0018 - General Assistant/Bulk Store</b>						
No Asbestos						
<b>B00A - R0019 - General Storeroom</b>						
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2844/B00A/R0031/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	
<b>B00A - R0020 - Staff Toilet</b>						
No Asbestos						
<b>B00A - R0021 - Staff Toilet</b>						
No Asbestos						
<b>B00A - R0022 - Movement</b>						
Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2844/B00A/R0031/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	
<b>B00A - R0023 - Security Store</b>						
Floor Coverings Res/Textile	Vinyl Tiles	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2844/B00A/R0031/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	
<b>B00A - R0024 - Entry Vestibule</b>						
Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2844/B00A/R0031/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	
<b>B00A - R0025 - Distribution Board</b>						
					Note: No inspection of live electrical installation.	
No Asbestos						
<b>B00A - R0026 - Movement</b>						
Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2844/B00A/R0031/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	
<b>B00A - R0027 - Sick Bay</b>						
No Asbestos						
<b>B00A - R0028 - Principal</b>						
No Asbestos						
<b>B00A - R0029 - Clerical Office</b>						
No Asbestos						
<b>B00A - R0030 - Cleaning Supplies</b>						
No Asbestos						
<b>B00A - R0031 - Home Base Store</b>						
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2844/B00A/R0031/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	
<b>B00A - R0032 - Movement</b>						
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2844/B00A/R0031/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	
<b>B00A - R0033 - Home Base</b>						
No Asbestos						
<b>B00A - R0034 - General Storeroom</b>						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - Library - 2000 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior****B00B - R0001 - Reading Area**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00B - R0002 - Library Office/Workroom**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00B - R0003 - Audio Visual Workroom**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00B - R0004 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

**B00B - R0005 - Staff Room**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00B - R0006 - Movement**

No Asbestos

**B00B - R0007 - Movement**

No Asbestos

**B00B - R0008 - Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

### B00C - Communal Facilities/Pupil Facilities - 2010 - Brick/Veneer (Brick/Veneer)

#### Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

#### Interior

##### B00C - R0001 - External Movement

No Asbestos

##### B00C - R0002 - Communal Space

No Asbestos

##### B00C - R0003 - P.E. Store

No Asbestos

##### B00C - R0004 - External Movement

No Asbestos

##### B00C - R0005 - Disabled Toilet

No Asbestos

##### B00C - R0006 - Main Switch Board

No Asbestos

# 2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

### Demountables

**Demountable details as per the AMS records as of 15 Feb 2017.**

**OS 602 - D13137 - Learning Unit - Standard With P.A.A. : Placement Date - 30/06/1995**

#### Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

#### Interior

##### R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos	70 m2
---------	---------------	------------------	-------

##### R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	3 m2

**OS 603 - D13395 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 4/04/2006**

#### Exterior

No Asbestos Found.

#### Interior

##### R1 - Learning space/withdrawal/entry

No Asbestos Found.

##### R2 - Home Base Store

No Asbestos Found.

# 2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017