


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Paxton Public School (2846)
Region : Hunter/Central Coast
State Electorate : Cessnock
Local Government Area : Cessnock

Initial Survey : Noel Arnold & Associates : 15 - May - 2008
Register Issue Date : 22 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning - 1923 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	80m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos					
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

Interior

B00A - R0001 - Withdrawal Space - 1hb

No Asbestos

B00A - R0002 - Canteen

No Asbestos

B00A - R0003 - Home Base

No Asbestos

B00A - R0004 - Home Base

No Asbestos

B00A - R0005 - Home Base

No Asbestos

B00A - R0006 - Home Base

No Asbestos

B00A - R0007 - General Storeroom

No Asbestos

B00A - R0008 - External Movement

Floor Coverings Res/Textile Compressed AC Sheet

2846/B00A/R0008/Floor Coverings Res/Textile/S1

No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Pupil Facilities - 1965 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

Interior

B00B - R0001 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting	24m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2846/B00B/R0001/Ceiling Structures/Linings/S3				Chrysotile (White asbestos) , Amosite (Brown asbestos)		

B00B - R0002 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2846/B00B/R0001/Ceiling Structures/Linings/S3				Chrysotile (White asbestos) , Amosite (Brown asbestos)		

B00B - R0003 - Drinking Facilities

Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2846/B00B/R0001/Ceiling Structures/Linings/S3				Chrysotile (White asbestos) , Amosite (Brown asbestos)		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Communal Facilities - 1950 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting 2846/B00C/Eaves Linings/S2					No Asbestos Detected
Wall Cladding	Flat AC Sheeting 2846/B00C/Wall Cladding/S4					No Asbestos Detected
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

Interior

B00C - R0001 - Cleaning Supplies

No Asbestos

B00C - R0002 - Sports Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Pupil Facilities - 1995 - Steel (Steel)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00D - R0001 - Canteen Covered Area

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Library - 2010 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00E - R0001 - External Movement

No Asbestos

B00E - R0002 - Reading Area

No Asbestos

B00E - R0003 - Library Office/Workroom

No Asbestos

B00E - R0004 - Communications Room

No Asbestos

B00E - R0005 - K.L.A. Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 505 - D15436 - Admin Staff/Principal/Secure Store : Placement Date - 30/06/1995

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2

R2 - Principal

Ceiling	Flat AC Sheet	Assumed Asbestos				16 m2
---------	---------------	------------------	--	--	--	-------

R3 - Staff Room

Ceiling	Flat AC Sheet	Assumed Asbestos				20 m2
---------	---------------	------------------	--	--	--	-------

R4 - Security Store

Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
---------	---------------	------------------	--	--	--	------

R5 - Clerical Office

End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				18 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017