


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Pitt Town Public School (2884)
Region : Western Sydney
State Electorate : Hawkesbury
Local Government Area : Hawkesbury

Initial Survey : Noel Arnold & Associates : 30 - Mar - 2008
Reviewed By : Parsons Brinckerhoff : 01 - Nov - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration - 1878 - Sandstone (Sandstone)

Exterior

Ceiling Void	No Asbestos Found
Underfloor Voids	Non Accessible Area - No Manhole located in building

Interior

B00A - R0001 - Staff Toilet

No Asbestos

B00A - R0002 - Duplicating Workroom

No Asbestos

B00A - R0003 - General Storeroom

No Asbestos

B00A - R0004 - Staff Kitchen

No Asbestos

B00A - R0005 - Staff Room

No Asbestos

B00A - R0006 - Movement

In-fill-panel	Flat AC Sheeting 2884/B00A/R0006/In-fill-panel/S1	No Asbestos Detected
---------------	--	-----------------------------

B00A - R0007 - Principal

No Asbestos

B00A - R0008 - Clerical Office/Workroom

No Asbestos

B00A - R0009 - Movement

No Asbestos

B00A - R0010 - Clerical Office/Workroom

No Asbestos

B00A - R0011 - Community Clinic

No Asbestos

B00A - R0012 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning/Pupil Facilities - 1971 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2884/B00B/Eaves Linings/S6			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Gable Verge Lining	Flat AC Sheeting					No Asbestos Detected
	2884/B00B/Gable Verge Lining/S8					
In-fill-panel	Flat AC Sheeting					No Asbestos Detected
	2884/B00C/In-fill-panel/S3					
Ceiling Void	No Asbestos Found					

Interior

B00B - R0001 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2884/B00B/R0001/Partition Walls (Cubicles)/S4			Chrysotile (white asbestos)		

B00B - R0002 - Staff Toilet

No Asbestos

B00B - R0003 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2884/B00B/R0003/Ceiling Structures/Linings/S5			Chrysotile (white asbestos)		

B00B - R0004 - Staff Toilet

No Asbestos

B00B - R0005 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet	22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2884/B00B/R0001/Partition Walls (Cubicles)/S4			Chrysotile (white asbestos)		

B00B - R0006 - Craft Store

No Asbestos

B00B - R0010 - External Movement

No Asbestos

B00B - R0012 - Main Switch Board

Electrical Mounting Board	Resinous Board					No Asbestos Detected
	2884/B00B/R0012/Electrical Mounting Board/S12					
Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	2884/B00B/R0012/Wall Linings Internal/S11					
Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	2884/B00B/R0012/Ceiling Structures/Linings/S10					

B00B - R0015 - Home Base

No Asbestos

B00B - R0016 - Home Base Store

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning - 1971 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting 2884/B00C/Eaves Linings/S7	8m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
Gable Verge Lining	Flat AC Sheeting 2884/B00C/Gable Verge Lining/S9					No Asbestos Detected
In-fill-panel	Flat AC Sheeting 2884/B00C/In-fill-panel/S3					No Asbestos Detected
Ceiling Void	No Asbestos Found					
Underfloor Voids	Non Accessible Area - No Access - Manhole does not open. Unable to open.					

Interior

B00C - R0001 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 2884/B00B/R0003/Ceiling Structures/Linings/S5	58m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	---	------	------------	--------------------	---------	--

B00C - R0002 - Home Base

No Asbestos

B00C - R0003 - Home Base Store

No Asbestos

B00C - R0004 - Personal Effects Storage

No Asbestos

B00C - R0005 - Home Base Store

No Asbestos

B00C - R0006 - Home Base

No Asbestos

B00C - R0007 - Home Base

No Asbestos

B00C - R0008 - Toilets - Boys/Girls

No Asbestos

B00C - R0009 - Home Base Store

No Asbestos

B00C - R0010 - Personal Effects Storage

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Pupil Facilities/Multi Purpose Facilities - 1878 - Brick/Block (Brick/Block)

Exterior

Ceiling Void	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00D - R0001 - Communications Room

No Asbestos

B00D - R0002 - Special Programs Room

No Asbestos

B00D - R0003 - Special Programs Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning - 1991 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00E - R0001 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0002 - Movement

No Asbestos

B00E - R0003 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0005 - Practical Activities - 1hb

No Asbestos

B00E - R0006 - Movement

No Asbestos

B00E - R0007 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0008 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0009 - Practical Activities - 1hb

No Asbestos

B00E - R0010 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Staff Facilities - 2003 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Wall Cladding	Flat AC Sheeting	50m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2884/B00F/R0001/Wall Linings Internal/S2			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Voids	No Asbestos Found					

Interior

B00F - R0001 - Garage/Carport

Wall Linings Internal	Flat AC Sheeting	50m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2884/B00F/R0001/Wall Linings Internal/S2			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Structures/Linings	Flat AC Sheeting	2884/B00F/R0001/Ceiling Structures/Linings/S13				No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Library - 2010 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior

B00G - R0001 - Reading Area

No Asbestos

B00G - R0002 - Library Office/Workroom

No Asbestos

B00G - R0003 - Communications Room

No Asbestos

B00G - R0004 - K.L.A. Store

No Asbestos

B00G - R0005 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Storage - 2011 - Steel (Steel)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior

B00H - R0001 - Covered Outdoor Learning Area

No Asbestos

B00H - R0002 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - Other - 2011 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior

B00I - R0001 - Cleaning Distributed Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 840 - D11108 - Girls Toilet : Placement Date - 6/06/2013

Exterior

No Asbestos Found.

Interior

R1 - Toilets-Girls

No Asbestos Found.

OS 602 - D12717 - Learning Unit - Standard With P.A.A. : Placement Date - 9/10/2014

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D13335 - Learning Unit - Standard With P.A.A. : Placement Date - 15/01/2011

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 535 - D13930 - Library/Group Study/Office/A V Store : Placement Date - 5/04/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Interior

R1 - Clerical Office

No Asbestos Found.

R2 - Staff Room

No Asbestos Found.

R3 - Security Store

No Asbestos Found.

R4 - Principal

No Asbestos Found.

R5 - Staff Toilet

No Asbestos Found.

R6 - Staff Toilet

No Asbestos Found.

R7 - Reading Area

No Asbestos Found.

R8 - Entry

No Asbestos Found.

OS 602 - D14064 - Learning Unit - Standard With P.A.A. : Placement Date - 23/09/2015

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D14334 - Learning Unit - Standard With P.A.A. : Placement Date - 12/01/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

NS 300 - D14432 - FSU /Bulk Store/Toilet : Placement Date - 30/06/1995

Exterior

No Asbestos Found.



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Interior

R1 - Canteen

No Asbestos Found.

R2 - Bulk Store

No Asbestos Found.

R3 - Cleaning Supplies

No Asbestos Found.

R4 - Toilets-Boys/Girls

No Asbestos Found.

OS 602 - D15741 - Learning Unit - Standard With P.A.A. : Placement Date - 28/10/2013

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos	70 m2
---------	---------------	------------------	-------

R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	3 m2

OS 837 - D17101 - Hcap Shower/Change/Toilet : Placement Date - 9/10/2014

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	2.88 m2

Interior

R1 - Disabled Shower/Toilet

Toilet partitions	Compressed AC Sheet	Assumed Asbestos	12 m2
End wall panel	Flat AC Sheet	Assumed Asbestos	36 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	18 m2

OS 603 - D18171 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 11/12/2012

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017