


Asbestos Register

(Hazardous Materials and Risk Assessment)



School : Plumpton Public School (2887)
Region : Western Sydney
State Electorate : Mount DrUITt
Local Government Area : Blacktown

Initial Survey : Noel Arnold & Associates : 23 - May - 2008
Register Issue Date : 22 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/General Learning - 1989 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00A - R0001 - Practical Activities - 1hb**

No Asbestos

B00A - R0002 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0003 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0004 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0005 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0007 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0008 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0009 - Practical Activities - 1hb

No Asbestos

B00A - R0010 - Practical Activities - 1hb

No Asbestos

B00A - R0011 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0012 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0013 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0014 - Cleaning Distributed Store

No Asbestos

B00A - R0016 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0017 - Practical Activities - 1hb

No Asbestos

B00A - R0018 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0019 - Practical Activities - 1hb

No Asbestos

B00A - R0020 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0021 - Withdrawal Space - 1hb

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0022 - Home Base Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0023 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						
B00A - R0025 - Home Base Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0026 - Practical Activities - 1hb						
No Asbestos						
B00A - R0027 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0028 - Practical Activities - 1hb						
No Asbestos						
B00A - R0029 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0030 - Withdrawal Space - 1hb						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0031 - Home Base Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0032 - Cleaning Distributed Store						
No Asbestos						
B00A - R0034 - Home Base Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0035 - Practical Activities - 1hb						
No Asbestos						
B00A - R0036 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0037 - Staff Room						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0038 - Staff Room Annexe						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0039 - Main Switch Board						
No Asbestos						
B00A - R0040 - Movement						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0041 - Staff Toilet						
No Asbestos						
B00A - R0042 - Staff Toilet						
No Asbestos						
B00A - R0043 - Disabled Shower/Toilet						
No Asbestos						
B00A - R0044 - Movement						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R0045 - Movement						
No Asbestos						
B00A - R0046 - Entry Vestibule						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00A - R0047 - Interview						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00A - R0048 - Deputy Principal						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00A - R0049 - Deputy Principal						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00A - R0050 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						
B00A - R0051 - Clerical Office						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00A - R0052 - Duplicating Workroom						
No Asbestos						
B00A - R0053 - Principal						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00A - R0054 - Cleaning Distributed Store						
No Asbestos						
B00A - R0055 - Security Store						
No Asbestos						
B00A - R0056 - General Assistant/Bulk Store						
No Asbestos						
B00A - R0057 - Sick Bay						
No Asbestos						
B00A - R0058 - Staff Shower/Change						
No Asbestos						
B00A - R0059 - Movement						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00A - R0060 - Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00B - Communal Facilities/Pupil Facilities - 1989 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00B - R0001 - Toilets - Boys**

No Asbestos

B00B - R0002 - Shower/Change

No Asbestos

B00B - R0003 - Drinking Facilities

No Asbestos

B00B - R0004 - Shower/Change

No Asbestos

B00B - R0005 - Toilets - Girls

No Asbestos

B00B - R0006 - Movement

No Asbestos

B00B - R0007 - Canteen

No Asbestos

B00B - R0008 - Canteen Office/Store

No Asbestos

B00B - R0009 - Disabled Toilet

No Asbestos

B00B - R0010 - Cleaning Supplies

No Asbestos

B00B - R0011 - Community Clinic

No Asbestos

B00B - R0012 - Staff Toilet

No Asbestos

B00B - R0013 - Community ClinicVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00B - R0014 - Hall Chair Store**

No Asbestos

B00B - R0015 - Cleaning Supplies

No Asbestos

B00B - R0016 - Movement

No Asbestos

B00B - R0017 - Craft Store

No Asbestos

B00B - R0018 - P.E. Store

No Asbestos

B00B - R0019 - General Assistant/Bulk Store

No Asbestos

B00B - R0020 - Movement

No Asbestos

B00B - R0021 - Plant

No Asbestos

B00B - R0022 - Communal Space

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00B - R0023 - Cleaning Distributed Store						
No Asbestos						
B00B - R0024 - Movement						
No Asbestos						
B00B - R0025 - Raised Platform						
No Asbestos						
B00B - R0026 - Movement						
No Asbestos						
B00B - R0027 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						
B00B - R0028 - Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Library - 1989 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00C - R0001 - Movement

No Asbestos

B00C - R0003 - K.L.A. Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0004 - Cleaning Distributed Store

No Asbestos

B00C - R0005 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0006 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0007 - Reading Area

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0008 - K.L.A. Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Tiered Learning/Pupil Facilities - 1989 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00D - R0001 - Movement

No Asbestos

B00D - R0002 - Special Programs Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0003 - Special Programs Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0004 - Movement

No Asbestos

B00D - R0005 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting	1Unit	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	-------	------------	--------------------	---------	--------------------

B00D - R0006 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting		Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	--	------------	--------------------	---------	--------------------

B00D - R0007 - Plant

No Asbestos

B00D - R0008 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning/Pupil Facilities - 1989 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00E - R0001 - Practical Activities - 1hb**

No Asbestos

B00E - R0002 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0003 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0004 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0005 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0006 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0007 - Practical Activities - 1hb

No Asbestos

B00E - R0008 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0009 - Toilets - Boys

No Asbestos

B00E - R0010 - Kiln Room

No Asbestos

B00E - R0011 - Toilets - Girls

No Asbestos

B00E - R0012 - Practical Activities - 1hb

No Asbestos

B00E - R0013 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0014 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0015 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0016 - Cleaning Distributed Store

No Asbestos

B00E - R0017 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0018 - Practical Activities - 1hb

No Asbestos

B00E - R0019 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0020 - Home Base

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00E - R0021 - Practical Activities - 1hb						
No Asbestos						
B00E - R0022 - Withdrawal Space - 1hb						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00E - R0023 - Home Base Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00E - R0024 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						
B00E - R0025 - Home Base Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00E - R0026 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00E - R0027 - Practical Activities - 1hb						
No Asbestos						
B00E - R0031 - Movement						
No Asbestos						
B00E - R0032 - Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning - 2005 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00F - R0001 - Movement

No Asbestos

B00F - R0002 - Practical Activities - 1hb

No Asbestos

B00F - R0003 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0005 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0007 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0008 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00G - R0001 - External Movement

No Asbestos

B00G - R0002 - Home Base Store

No Asbestos

B00G - R0003 - Home Base

No Asbestos

B00G - R0004 - Withdrawal Space - 2hb

No Asbestos

B00G - R0005 - Home Base Store

No Asbestos

B00G - R0006 - Home Base

No Asbestos

B00G - R0007 - Home Base Store

No Asbestos

B00G - R0008 - Home Base

No Asbestos

B00G - R0009 - Withdrawal Space - 2hb

No Asbestos

B00G - R0010 - Home Base Store

No Asbestos

B00G - R0011 - Home Base

No Asbestos

B00G - R0012 - Home Base - P

No Asbestos

B00G - R0013 - Home Base - P

No Asbestos

B00G - R0014 - Home Base Store

No Asbestos

B00G - R0015 - Toilet - P

No Asbestos

B00G - R0016 - Practical Activities

No Asbestos

B00G - R0017 - Practical Activities

No Asbestos

B00G - R0018 - Practical Activities

No Asbestos

B00G - R0019 - Practical Activities

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017