

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Port Kembla Public School (2896)
Region : Illawarra and South East
State Electorate : Wollongong
Local Government Area : Wollongong

Initial Survey : Noel Arnold & Associates : 05 - Apr - 2008
Register Issue Date : 22 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning - 1999 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00A - R0001 - Practical Activities - 1hb

No Asbestos

B00A - R0002 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0003 - Home Base Store

No Asbestos

B00A - R0004 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0005 - Practical Activities - 1hb

No Asbestos

B00A - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0007 - Home Base Store

No Asbestos

B00A - R0008 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0009 - Toilets - Boys

No Asbestos

B00A - R0010 - Kiln Room

No Asbestos

B00A - R0011 - Toilets - Girls

No Asbestos

B00A - R0012 - Craft Store

No Asbestos

B00A - R0013 - General Assistant/Bulk Store

No Asbestos

B00A - R0014 - External Movement

No Asbestos

B00A - R1001 - Practical Activities - 1hb

No Asbestos

B00A - R1002 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R1003 - Home Base Store

No Asbestos

B00A - R1004 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R1005 - Practical Activities - 1hb

No Asbestos

B00A - R1006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R1007 - Home Base Store

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
B00A - R1008 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						
B00A - R1009 - Practical Activities - 1hb						
No Asbestos						
B00A - R1010 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00A - R1011 - Home Base Store						
No Asbestos						
B00A - R1012 - Withdrawal Space - 1hb						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00A - R1013 - Practical Activities - 1hb						
No Asbestos						
B00A - R1014 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00A - R1015 - Home Base Store						
No Asbestos						
B00A - R1016 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						
B00A - R1017 - Practical Activities - 1hb						
No Asbestos						
B00A - R1018 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00A - R1019 - Home Base Store						
No Asbestos						
B00A - R1020 - Withdrawal Space - 1hb						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00A - R1021 - Practical Activities - 1hb						
No Asbestos						
B00A - R1022 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00A - R1023 - Home Base Store						
No Asbestos						
B00A - R1024 - External Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Administration/Library - 1999 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00B - R0001 - Entry Vestibule**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0002 - Clerical Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0003 - Duplicating Workroom

No Asbestos

B00B - R0004 - Sick Bay

No Asbestos

B00B - R0005 - Disabled Toilet

No Asbestos

B00B - R0006 - Interview

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0007 - Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0008 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00B - R0009 - Security Store

No Asbestos

B00B - R0010 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0011 - Staff Toilet

No Asbestos

B00B - R0012 - Staff Toilet

No Asbestos

B00B - R0013 - Staff Toilet

No Asbestos

B00B - R0014 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0015 - Cleaning Distributed Store

No Asbestos

B00B - R0016 - Staff Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0017 - Staff Room Annexe

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0018 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0019 - Main Switch Board

No Asbestos

B00B - R0020 - Canteen

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
B00B - R0021 - Canteen Office/Store						
No Asbestos						
B00B - R0022 - External Movement						
No Asbestos						
B00B - R0023 - External Stairs						
No Asbestos						
B00B - R0024 - External Stairs						
No Asbestos						
B00B - R0025 - Plant						
No Asbestos						
B00B - R0026 - No Access						
No Asbestos						
B00B - R0027 - External Movement						
No Asbestos						
B00B - R0028 - External Movement						
No Asbestos						
B00B - R1001 - Reading Area						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00B - R1002 - Library Office/Workroom						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00B - R1003 - Communications Room						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00B - R1004 - Seminar/Study						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00B - R1005 - K.L.A. Store						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00B - R1006 - Staff Toilet						
No Asbestos						
B00B - R1007 - Cleaning Distributed Store						
No Asbestos						
B00B - R1008 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						
B00B - R1009 - External Stairs						
No Asbestos						
B00B - R1010 - External Stairs						
No Asbestos						
B00B - R1011 - No Access						
No Asbestos						
B00B - R1012 - External Movement						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00C - Communal Facilities - 1999 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00C - R0001 - Communal Space**

No Asbestos

B00C - R0002 - Raised Platform

No Asbestos

B00C - R0003 - Toilets - Boys

No Asbestos

B00C - R0004 - Hall Chair Store

No Asbestos

B00C - R0005 - P.E. Store

No Asbestos

B00C - R0006 - Toilets - Girls

No Asbestos

B00C - R0007 - Plant

No Asbestos

B00C - R0008 - Disabled Toilet

No Asbestos

B00C - R0009 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0010 - Sports Store

No Asbestos

B00C - R0011 - Cleaning Supplies

No Asbestos

B00C - R0012 - Garden Store

No Asbestos

B00C - R0013 - Toilets - Girls

No Asbestos

B00C - R0014 - Toilets - Boys

No Asbestos

B00C - R0015 - Cleaning Distributed Store

No Asbestos

B00C - R0016 - Ramp

No Asbestos

B00C - R0017 - External Movement

No Asbestos

B00C - R0018 - Lift

No Asbestos

B00C - R0019 - Movement

No Asbestos

B00C - R0020 - Movement

No Asbestos

B00C - R0021 - External Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00D - R0001 - Home Base

No Asbestos

B00D - R0002 - Home Base Store

No Asbestos

B00D - R0003 - Practical Activities - 1hb

No Asbestos

B00D - R0004 - Withdrawal Space - 2hb

No Asbestos

B00D - R0005 - Home Base

No Asbestos

B00D - R0006 - Home Base Store

No Asbestos

B00D - R0007 - Practical Activities - 1hb

No Asbestos

B00D - R0008 - Sports Store

No Asbestos

B00D - R0009 - General Assistant/Bulk Store

No Asbestos

B00D - R0010 - Garden Store

No Asbestos

B00D - R0011 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D14495 - Learning Unit - Standard With P.A.A. : Placement Date - 1/03/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017