


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Pottsville Beach Public School (3578)
Region : North Coast
State Electorate : Tweed
Local Government Area : Tweed

Initial Survey : Noel Arnold & Associates : 27 - May - 2008
Register Issue Date : 23 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/Staff Facilities - 1996 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00A - R0001 - Clerical Office**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0002 - Entry Vestibule

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0003 - External Movement

No Asbestos

B00A - R0004 - Duplicating Workroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0005 - Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0006 - Security Store

No Asbestos

B00A - R0010 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0011 - Staff Room Annexe

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0013 - Main Switch Board

No Asbestos

B00A - R0014 - Cleaning Distributed Store

No Asbestos

B00A - R0015 - Communications Cupboard

No Asbestos

B00A - R0016 - Staff Room Annexe

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0017 - Staff Room Annexe

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0018 - Interview

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0020 - Sick Bay

No Asbestos

B00A - R0021 - Toilet - Lobby

No Asbestos

B00A - R0022 - Staff Shower/Change

No Asbestos

B00A - R0023 - Staff Toilet

No Asbestos

B00A - R0024 - Toilet - Lobby

No Asbestos

B00A - R0025 - Toilet - Lobby

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00A - R0026 - Toilet - Lobby

No Asbestos

B00A - R0027 - Staff Toilet

No Asbestos

B00A - R0028 - Staff Toilet

No Asbestos

B00A - R0029 - Staff Toilet

No Asbestos

B00A - R0030 - Staff Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0031 - Staff Kitchen

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning/Pupil Facilities - 1996 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00B - R0001 - External Movement

No Asbestos

B00B - R0002 - Toilets - Boys

No Asbestos

B00B - R0003 - Cleaning Distributed Store

No Asbestos

B00B - R0004 - Toilets - Girls

No Asbestos

B00B - R0005 - External Movement

No Asbestos

B00B - R0006 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00B - R0007 - Practical Activities - 1hb

No Asbestos

B00B - R0008 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0009 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0010 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0011 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0012 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0013 - External Movement

No Asbestos

B00B - R0014 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0015 - Practical Activities - 1hb

No Asbestos

B00B - R0016 - Practical Activities - 1hb

No Asbestos

B00B - R0017 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0018 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0019 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0020 - Home Base

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R0021 - External Movement						
No Asbestos						
B00B - R0022 - Withdrawal Space - 1hb						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R0023 - Home Base Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R0024 - Practical Activities - 1hb						
No Asbestos						
B00B - R0025 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning/Library - 1996 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00C - R0001 - External Movement

No Asbestos

B00C - R0002 - Special Programs Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0003 - Cleaning Distributed Store

No Asbestos

B00C - R0005 - Plant

No Asbestos

B00C - R0006 - Special Programs Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0007 - Reading Area

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0008 - Communications Cupboard

No Asbestos

B00C - R0009 - Communications Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0010 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0011 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0012 - Practical Activities - 1hb

No Asbestos

B00C - R0013 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0014 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0015 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0016 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0017 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0018 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0019 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0020 - Practical Activities - 1hb

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - R0021 - Toilet - Lobby

No Asbestos

B00C - R0022 - Staff Toilet

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning/Pupil Facilities - 1996 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00D - R0001 - External Movement

No Asbestos

B00D - R0002 - Toilets - Boys

No Asbestos

B00D - R0003 - Kiln Room

No Asbestos

B00D - R0004 - External Movement

No Asbestos

B00D - R0005 - Toilets - Girls

No Asbestos

B00D - R0006 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0007 - Practical Activities - 1hb

No Asbestos

B00D - R0008 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0009 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0010 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0011 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0012 - Practical Activities - 1hb

No Asbestos

B00D - R0013 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0014 - External Movement

No Asbestos

B00D - R0015 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0016 - Practical Activities - 1hb

No Asbestos

B00D - R0017 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0018 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0019 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0020 - External Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00D - R0021 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0022 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0023 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Communal Facilities/Pupil Facilities - 1996 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00E - R0001 - Disabled Toilet

No Asbestos

B00E - R0002 - Cleaning Distributed Store

No Asbestos

B00E - R0003 - Plant

No Asbestos

B00E - R0004 - P.E. Store

No Asbestos

B00E - R0005 - Sports Store

No Asbestos

B00E - R0006 - Hall Chair Store

No Asbestos

B00E - R0008 - Movement

No Asbestos

B00E - R0009 - Raised Platform

No Asbestos

B00E - R0010 - Movement

No Asbestos

B00E - R0011 - Communal Space

No Asbestos

B00E - R0012 - Shower/Change

No Asbestos

B00E - R0013 - Toilets - Girls

No Asbestos

B00E - R0014 - Movement

No Asbestos

B00E - R0015 - Cleaning Supplies

No Asbestos

B00E - R0016 - Garden Store

No Asbestos

B00E - R0017 - Cleaning Supplies

No Asbestos

B00E - R0018 - General Assistant/Bulk Store

No Asbestos

B00E - R0019 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0020 - Plant

No Asbestos

B00E - R0022 - External Movement

No Asbestos

B00E - R0023 - Toilet - Lobby

No Asbestos

B00E - R0024 - Toilets - Boys

No Asbestos

B00E - R0025 - Toilets - Boys

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Pupil Facilities - 1996 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00F - R0001 - Canteen Office/Store

No Asbestos

B00F - R0002 - Plant

No Asbestos

B00F - R0003 - Plant

No Asbestos

B00F - R0004 - Canteen

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning - 2004 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00G - R0001 - External Movement

No Asbestos

B00G - R0002 - Practical Activities - 1hb

No Asbestos

B00G - R0003 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0005 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0007 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0008 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Communal Facilities - 2007 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00H - R0001 - Other

No Asbestos

B00H - R0002 - Other

No Asbestos

B00H - R0003 - Disabled Toilet

No Asbestos

B00H - R0004 - External Movement

No Asbestos

B00H - R0005 - Other

No Asbestos

B00H - R0006 - Uniform Shop

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - Building Services - 2007 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00I - R0001 - Other

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Building Services - 2009 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00J - R0001 - General Assistant/Bulk Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - General Learning - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00K - R0001 - Practical Activities - 1hb

No Asbestos

B00K - R0002 - Home Base Store

No Asbestos

B00K - R0003 - Home Base

No Asbestos

B00K - R0004 - Withdrawal Space - 2hb

No Asbestos

B00K - R0005 - Home Base

No Asbestos

B00K - R0006 - Home Base Store

No Asbestos

B00K - R0007 - Practical Activities - 1hb

No Asbestos

B00K - R0008 - Practical Activities - 1hb

No Asbestos

B00K - R0009 - Withdrawal Space - 1hb

No Asbestos

B00K - R0010 - Home Base Store

No Asbestos

B00K - R0011 - Home Base

No Asbestos

B00K - R0012 - External Movement

No Asbestos

B00K - R0013 - Stairs

No Asbestos

B00K - R0014 - Stairs

No Asbestos

B00K - R0015 - General Storeroom

No Asbestos

B00K - R0016 - General Storeroom

No Asbestos

B00K - R0017 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00K - R1001 - Practical Activities - 1hb

No Asbestos

B00K - R1002 - Home Base Store

No Asbestos

B00K - R1003 - Home Base

No Asbestos

B00K - R1004 - Withdrawal Space - 2hb

No Asbestos

B00K - R1005 - Home Base

No Asbestos

B00K - R1006 - Practical Activities - 1hb

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00K - R1007 - Home Base Store

No Asbestos

B00K - R1008 - Practical Activities - 1hb

No Asbestos

B00K - R1009 - Withdrawal Space - 1hb

No Asbestos

B00K - R1010 - Home Base Store

No Asbestos

B00K - R1011 - Special Programs Room

No Asbestos

B00K - R1012 - External Movement

No Asbestos

B00K - R1013 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00K - R1014 - Stairs

No Asbestos

B00K - R1015 - Stairs

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Pupil Facilities - 2015 - Steel Framed (Steel Framed)

Exterior

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior

B00L - R0001 - Movement

No Asbestos

B00L - R0002 - General Storeroom

No Asbestos

B00L - R0003 - Covered Outdoor Learning Area

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 603 - D10053 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 23/12/2005

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 603 - D10072 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 9/10/2007

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D10097 - Learning Unit - Standard With P.A.A. : Placement Date - 2/02/2006

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 603 - D10120 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 19/01/2010

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D10370 - Learning Unit - Standard With P.A.A. : Placement Date - 14/01/2008

Exterior

Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Interior						
R1 - Learning space/withdrawal/entry						
Ceiling	Flat AC Sheet	Assumed Asbestos				70 m2
R2 - Home Base Store						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				3 m2
OS 602 - D10484 - Learning Unit - Standard With P.A.A. : Placement Date - 14/12/2009						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 602 - D11898 - Learning Unit - Standard With P.A.A. : Placement Date - 25/01/2007						
Exterior						
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Interior						
R1 - Learning space/withdrawal/entry						
Ceiling	Flat AC Sheet	Assumed Asbestos				70 m2
R2 - Home Base Store						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				3 m2
OS 840 - D12057 - Girls Toilet : Placement Date - 21/11/2008						
Exterior						
No Asbestos Found.						
Interior						
R1 - Toilets-Girls						
No Asbestos Found.						
OS 602 - D12330 - Learning Unit - Standard With P.A.A. : Placement Date - 21/03/2013						
Exterior						
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 602 - D12776 - Learning Unit - Standard With P.A.A. : Placement Date - 3/04/1998						
Exterior						
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Interior

R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos				70 m2
---------	---------------	------------------	--	--	--	-------

R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				3 m2

OS 602 - D12787 - Learning Unit - Standard With P.A.A. : Placement Date - 8/01/1997

Exterior

Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2

Interior

R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos				70 m2
---------	---------------	------------------	--	--	--	-------

R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				3 m2

OS 603 - D13645 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 15/01/1999

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 841 - D15107 - Boys Toilet : Placement Date - 21/11/2008

Exterior

No Asbestos Found.

Interior

R1 - Toilets-Boys

No Asbestos Found.

OS 602 - D15630 - Learning Unit - Standard With P.A.A. : Placement Date - 15/10/2013

Exterior

Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2

Interior

R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos				70 m2
---------	---------------	------------------	--	--	--	-------

R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				3 m2

OS 602 - D17674 - Learning Unit - Standard With P.A.A. : Placement Date - 5/02/2009

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017