

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Pymble Public School (3777)
Region : Northern Sydney
State Electorate : Ku-ring-gai
Local Government Area : Ku-Ring-Gai

Initial Survey : Noel Arnold & Associates : 26 - Mar - 2008
Reviewed By : Greencap-NAA : 13 - Aug - 2014



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration - 1963 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00A - R0001 - External Movement (22.88 m2)

No Asbestos

B00A - R0002 - Clerical Office (20.32 m2)

No Asbestos

B00A - R0003 - Security Store (15.28 m2)

No Asbestos

B00A - R0004 - Distribution Board (0.36 m2)

Note: No inspection of live electrical installation.

Wall Linings Internal	Flat AC Sheeting	3777/B00A/R0004/Wall Linings Internal/S9
-----------------------	------------------	--

No Asbestos Detected

B00A - R0005 - Principal (15.82 m2)

No Asbestos

B00A - R0008 - Staff Shower/Change (3.64 m2)

No Asbestos

B00A - R0009 - Staff Toilet (2.89 m2)

No Asbestos

B00A - R0010 - Staff Toilet (4.1 m2)

No Asbestos

B00A - R0011 - Cleaning Distributed Store (1.17 m2)

No Asbestos

B00A - R0012 - Deputy Principal (12.93 m2)

No Asbestos

B00A - R0013 - External Movement (4.54 m2)

No Asbestos

B00A - R0014 - Sick Bay (9.3 m2)

No Asbestos

B00A - R0015 - Clerical Office (14.4 m2)

No Asbestos

B00A - R0016 - Movement (17.82 m2)

No Asbestos

B00A - R0017 - Entry Vestibule (10 m2)

No Asbestos

B00A - R0019 - Special Programs Room (10.06 m2)

No Asbestos

B00A - R0020 - Staff Room (9.41 m2)

No Asbestos

B00A - R0023 - Staff Room (9.8 m2)

No Asbestos

B00A - R0024 - External Movement (2.01 m2)

No Asbestos

B00A - R0025 - Staff Room (45.22 m2)

No Asbestos

B00A - R0026 - Staff Kitchen (12.71 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning - 1963 - Brick/Veneer (Brick/Veneer)**Exterior**

Eaves Linings	Flat AC Sheeting	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00H/Eaves Linings/S4					Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					
Gable Verge Lining	Flat AC Sheeting	30m	North & South	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00H/Eaves Linings/S4					Chrysotile (white asbestos) , Amosite (brown asbestos)

Interior**B00D - R0001 - Home Base (57.76 m2)**

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	58m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00F/R9006/Floor Coverings Res/Textile/S8					Chrysotile (white asbestos)

B00D - R0002 - Home Base Store (6.98 m2)

Floor Coverings Res/Textile	Vinyl Tiles	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00F/R9006/Floor Coverings Res/Textile/S8					Chrysotile (white asbestos)

B00D - R0003 - Personal Effects Storage (3.65 m2)

No Asbestos

B00D - R0004 - Movement (6.01 m2)

No Asbestos

B00D - R0005 - External Movement (7.51 m2)

Ceiling Structures/Linings	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00H/R0003/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)

B00D - R0006 - Personal Effects Storage (3.55 m2)

No Asbestos

B00D - R0008 - Home Base Store (6.84 m2)

Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00F/R9006/Floor Coverings Res/Textile/S8					Chrysotile (white asbestos)

B00D - R0009 - Home Base (57.29 m2)

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	58m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00F/R9006/Floor Coverings Res/Textile/S8					Chrysotile (white asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning - 1963 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00H/Eaves Linings/S4				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00E - R0001 - External Movement (4.37 m2)

Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00H/R0003/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)	

Infil panels over doors	Flat AC Sheeting	1m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00H/R0003/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)	

B00E - R0002 - Movement (4.07 m2)

No Asbestos

B00E - R0004 - Personal Effects Storage (3.83 m2)

No Asbestos

B00E - R0005 - Home Base Store (7.92 m2)

No Asbestos

B00E - R0006 - Home Base (65.07 m2)

No Asbestos

B00E - R0007 - Home Base (65.07 m2)

No Asbestos

B00E - R0008 - Home Base Store (8.26 m2)

No Asbestos

B00E - R0009 - Personal Effects Storage (3.77 m2)

No Asbestos

B00E - R0010 - Movement (4.02 m2)

No Asbestos

B00E - R0011 - External Movement (4.51 m2)

Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00H/R0003/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)	

Infil panels over doors	Flat AC Sheeting	1m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00H/R0003/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)	

B00E - R0012 - External Movement (4.76 m2)

Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00H/R0003/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)	

Infil panels over doors	Flat AC Sheeting	1m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00H/R0003/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)	

B00E - R0013 - Movement (13.26 m2)

No Asbestos

B00E - R0014 - Special Programs Room (17.51 m2)

Floor Coverings Res/Textile	Vinyl Sheet					
	3777/B00E/R0014/Floor Coverings Res/Textile/S12					No Asbestos Detected

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Floor Coverings
Res/Textile

Vinyl sheet underlay

3777/B00E/R0014/Floor Coverings Res/Textile/S12

No Asbestos Detected

B00E - R0015 - Cleaning Distributed Store (1.06 m2)

No Asbestos

B00E - R0016 - General Storeroom (1.1 m2)

No Asbestos

B00E - R0017 - General Storeroom (2.89 m2)

No Asbestos

B00E - R0018 - Personal Effects Storage (4.16 m2)

No Asbestos

B00E - R0019 - Home Base Store (8.12 m2)

No Asbestos

B00E - R0020 - Home Base (65.34 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning - 1963 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00H/Eaves Linings/S4				Chrysotile (white asbestos) , Amosite (brown asbestos)	

Interior

B00F - R0001 - Home Base (83.7 m2)

No Asbestos

B00F - R0002 - Withdrawal Space - 1hb (20.52 m2)

No Asbestos

B00F - R0003 - Movement (5.96 m2)

No Asbestos

B00F - R0005 - Home Base (56.76 m2)

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	3777/B00F/R0008/Floor Coverings Res/Textile/S7				No Asbestos Detected	

B00F - R0006 - External Movement (4.67 m2)

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00H/R0003/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)	

B00F - R0007 - Movement (6.53 m2)

Floor Coverings Res/Textile	Vinyl Tiles					
	3777/B00F/R0008/Floor Coverings Res/Textile/S7				No Asbestos Detected	

B00F - R0008 - Personal Effects Storage (10.71 m2)

Floor Coverings Res/Textile	Vinyl Tiles					
	3777/B00F/R0008/Floor Coverings Res/Textile/S7				No Asbestos Detected	

B00F - R0010 - Home Base Store (4.84 m2)

No Asbestos

B00F - R0011 - Home Base Store (4.84 m2)

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00H/R0003/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)	

B00F - R0012 - Home Base (57.07 m2)

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	58m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00H/R0003/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)	

B00F - R0013 - External Movement (14.81 m2)

Ceiling Structures/Linings	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00H/R0003/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)	

B00F - R0014 - External Stairs (4.11 m2)

No Asbestos

B00F - R0015 - External Movement (67.39 m2)

No Asbestos

B00F - R9001 - Distribution Board (0.12 m2)

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Vermiculite					
	3777/B00F/R9016/Ceiling Structures/Linings/S11				Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

B00F - R9002 - Cleaning Distributed Store (0.82 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite					
	3777/B00F/R9016/Ceiling Structures/Linings/S11					Limited Samples Taken
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
B00F - R9003 - General Storeroom (0.92 m2)						
Ceiling Structures/Linings	Vermiculite					
	3777/B00F/R9016/Ceiling Structures/Linings/S11					Limited Samples Taken
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
B00F - R9004 - Interview (17.75 m2)						
Ceiling Structures/Linings	Vermiculite					
	3777/B00F/R9016/Ceiling Structures/Linings/S11					Limited Samples Taken
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	3777/B00F/R0008/Floor Coverings Res/Textile/S7					No Asbestos Detected
B00F - R9005 - General Storeroom (4.5 m2)						
Ceiling Structures/Linings	Vermiculite					
	3777/B00F/R9016/Ceiling Structures/Linings/S11					Limited Samples Taken
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
Floor Coverings Res/Textile	Vinyl Tiles	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00F/R9006/Floor Coverings Res/Textile/S8					Chrysotile (white asbestos)
B00F - R9007 - Home Base Store (4.5 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00F/R9006/Floor Coverings Res/Textile/S8					Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite					
	3777/B00F/R9016/Ceiling Structures/Linings/S11					Limited Samples Taken
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
B00F - R9008 - Home Base (55.18 m2)						
Ceiling Structures/Linings	Vermiculite					
	3777/B00F/R9016/Ceiling Structures/Linings/S11					Limited Samples Taken
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
B00F - R9009 - Movement (12.8 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00F/R9006/Floor Coverings Res/Textile/S8					Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite					
	3777/B00F/R9016/Ceiling Structures/Linings/S11					Limited Samples Taken
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
B00F - R9011 - Staff Toilet (2.93 m2)						
No Asbestos						
B00F - R9012 - General Storeroom (19.39 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00H/R0003/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)
B00F - R9013 - Sports Store (20.23 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	21m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00H/R0003/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)
B00F - R9014 - Sports Store (4.95 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	21m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00H/R0003/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)
B00F - R9015 - Special Programs Room (5.42 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles					
	3777/B00F/R0008/Floor Coverings Res/Textile/S7					No Asbestos Detected
Ceiling Structures/Linings	Vermiculite					
	3777/B00F/R9016/Ceiling Structures/Linings/S11					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00F - R9016 - General Storeroom (5.45 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	3777/B00F/R0008/Floor Coverings Res/Textile/S7					No Asbestos Detected
Ceiling Structures/Linings	Vermiculite					
	3777/B00F/R9016/Ceiling Structures/Linings/S11					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00F - R9017 - Movement (19.1 m2)						
Ceiling Structures/Linings	Vermiculite					
	3777/B00F/R9016/Ceiling Structures/Linings/S11					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00F - R9018 - External Stairs (4.85 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00H/R0003/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning - 1963 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00H/Eaves Linings/S4				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Gable Verge Lining	Flat AC Sheeting	30m	North & South	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00H/Eaves Linings/S4				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00G - R0001 - External Movement (4.99 m2)

Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00H/R0003/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)	

B00G - R0002 - Movement (3.17 m2)

No Asbestos

B00G - R0003 - Personal Effects Storage (4.15 m2)

No Asbestos

B00G - R0004 - Home Base Store (6.28 m2)

No Asbestos

B00G - R0005 - Home Base (56.83 m2)

No Asbestos

B00G - R0006 - Home Base (56.75 m2)

No Asbestos

B00G - R0007 - Home Base Store (6.24 m2)

No Asbestos

B00G - R0008 - Personal Effects Storage (4 m2)

No Asbestos

B00G - R0009 - Movement (15.04 m2)

No Asbestos

B00G - R0011 - Cleaning Distributed Store (3.19 m2)

No Asbestos

B00G - R0012 - Cleaning Supplies (15.24 m2)

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	3777/B00H/R0005/Floor Coverings Res/Textile/S6				No Asbestos Detected	

B00G - R0013 - Home Base Store (6.23 m2)

No Asbestos

B00G - R0014 - Personal Effects Storage (4.01 m2)

No Asbestos

B00G - R0015 - Home Base (57.28 m2)

No Asbestos

B00G - R0016 - External Movement (8.31 m2)

Ceiling Structures/Linings	Flat AC Sheeting	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00H/R0003/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)	

B00G - R0017 - Drinking Facilities (18.57 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - R0018 - External Movement (25.52 m2)

No Asbestos

B00G - R0019 - External Movement (42.24 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - General Learning - 1963 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	30m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00H/Eaves Linings/S4				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00H - R0001 - Toilets - Girls (25.61 m2)

Ceiling Structures/Linings	Flat AC Sheeting	26m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00H/R0003/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)	

B00H - R0002 - Kiln Room (2.92 m2)

Ceiling Structures/Linings	Flat AC Sheeting	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00H/R0003/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)	

B00H - R0003 - External Movement (8.91 m2)

Ceiling Structures/Linings	Flat AC Sheeting	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00H/R0003/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)	

B00H - R0004 - General Storeroom (3.2 m2)

Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00H/R0003/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)	

Floor Coverings Res/Textile	Vinyl Tiles					
	3777/B00H/R0005/Floor Coverings Res/Textile/S6				No Asbestos Detected	

B00H - R0006 - Toilets - Boys (30.62 m2)

Ceiling Structures/Linings	Flat AC Sheeting	31m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00H/R0003/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)	

B00H - R0007 - Cleaning Distributed Store (1.56 m2)

Ceiling Structures/Linings	Flat AC Sheeting	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00H/R0003/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)	

B00H - R0008 - External Movement (10.35 m2)

Ceiling Structures/Linings	Flat AC Sheeting	11m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00H/R0003/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)	

B00H - R0009 - Other-After School Care (58.91 m2)

Ceiling Structures/Linings	Flat AC Sheeting	59m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00H/R0003/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)	

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	3777/B00H/R0005/Floor Coverings Res/Textile/S6				No Asbestos Detected	

B00H - R0010 - Staff Kitchen (9.9 m2)

Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00H/R0003/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)	

B00H - R0011 - Home Base Store (5.38 m2)

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00H/R0003/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result
B00H - R0012 - External Movement (64.56 m2)						

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - Communal Facilities - 1963 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	80m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00H/Eaves Linings/S4				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Gable Verge Lining	Flat AC Sheeting	30m	East & West	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00H/Eaves Linings/S4				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior**B00I - R0001 - Canteen (16.74 m2)**

No Asbestos

B00I - R0002 - External Movement (1.9 m2)

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00H/R0003/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)	

B00I - R0003 - Movement (15.8 m2)

No Asbestos

B00I - R0004 - External Movement (2.59 m2)

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00H/R0003/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)	

B00I - R0005 - Communal Space (201.83 m2)

No Asbestos

B00I - R0006 - External Movement (2.09 m2)

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00H/R0003/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)	

B00I - R0007 - External Movement (2.21 m2)

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00H/R0003/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)	

B00I - R0008 - Raised Platform (52 m2)

No Asbestos

B00I - R0009 - Stairs (3.15 m2)

No Asbestos

B00I - R0010 - Stairs (6 m2)

No Asbestos

B00I - R9003 - Cleaning Distributed Store (1.47 m2)

No Asbestos

B00I - R9004 - External Movement (1.8 m2)

Ceiling Structures/Linings	Flat AC Sheeting	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3777/B00H/R0003/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)	

B00I - R9005 - Movement (35.12 m2)

No Asbestos

B00I - R9006 - Uniform Shop (14.82 m2)

No Asbestos

B00I - R9007 - Stairs (3.8 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Wall Linings Internal	Flat AC Sheeting		3777/B001/R9002/Wall Linings Internal/S5			No Asbestos Detected
B001 - R9008 - General Storeroom (21.63 m2)						
Wall Linings Internal	Flat AC Sheeting		3777/B001/R9002/Wall Linings Internal/S5			No Asbestos Detected
B001 - R9009 - Stairs (1.73 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00K - General Learning - 1963 - Steel (Steel)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00K - R0001 - Home Base Store (5.9 m2)

No Asbestos

B00K - R0002 - Home Base (53.8 m2)

No Asbestos

B00K - R0003 - Home Base (53.8 m2)

No Asbestos

B00K - R0004 - Home Base Store (5.9 m2)

No Asbestos

B00K - R0005 - External Movement (23.15 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Library - 1963 - Steel (Steel)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00L - R0001 - Clerical Office/Workroom (23.84 m2)

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	24m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3777/B00L/R0001/Floor Coverings Res/Textile/S10					Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive					
3777/B00L/R0001/Floor Coverings Res/Textile/S13					No Asbestos Detected	

B00L - R0003 - Special Programs Room (34.33 m2)

No Asbestos

B00L - R0004 - K.L.A. Store (12.05 m2)

No Asbestos

B00L - R0005 - K.L.A. Store (4.73 m2)

No Asbestos

B00L - R0006 - Reading Area (131.28 m2)

No Asbestos

B00L - R0007 - Special Programs Room (27.77 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00N - Building Services - 1959 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00N - R0001 - Plant (11.05 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B000 - General Learning/Pupil Facilities - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B000 - R0001 - Home Base (58.35 m2)

No Asbestos

B000 - R0002 - Home Base (61.19 m2)

No Asbestos

B000 - R0003 - Home Base (61.34 m2)

No Asbestos

B000 - R0004 - Home Base (61.3 m2)

No Asbestos

B000 - R0005 - Home Base (61.32 m2)

No Asbestos

B000 - R0006 - Practical Activities - 1hb (21.18 m2)

No Asbestos

B000 - R0007 - Withdrawal Space - 1hb (9.33 m2)

No Asbestos

B000 - R0008 - Home Base Store (6.17 m2)

No Asbestos

B000 - R0009 - Home Base Store (6.35 m2)

No Asbestos

B000 - R0010 - Practical Activities - 1hb (19.26 m2)

No Asbestos

B000 - R0011 - Withdrawal Space - 2hb (11.78 m2)

No Asbestos

B000 - R0012 - Practical Activities - 1hb (19.17 m2)

No Asbestos

B000 - R0013 - Home Base Store (6.35 m2)

No Asbestos

B000 - R0014 - Home Base Store (6.34 m2)

No Asbestos

B000 - R0015 - Practical Activities - 1hb (19.24 m2)

No Asbestos

B000 - R0016 - Withdrawal Space - 2hb (11.81 m2)

No Asbestos

B000 - R0017 - Practical Activities - 1hb (19.14 m2)

No Asbestos

B000 - R0018 - Home Base Store (6.34 m2)

No Asbestos

B000 - R0019 - Toilets - Girls (41.9 m2)

No Asbestos

B000 - R0020 - Toilets - Boys (41.67 m2)

No Asbestos

B000 - R0021 - Access Shower/Toilet/Change (7.54 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B000 - R0022 - Main Switch Board (1.43 m2)						
No Asbestos						
B000 - R0023 - External Movement (67.59 m2)						
No Asbestos						
B000 - R0024 - External Movement (62.94 m2)						
No Asbestos						
B000 - R9001 - General Storeroom (98.88 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00P - General Learning - 2012 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00P - R0001 - Practical Activities (22.47 m2)

No Asbestos

B00P - R0002 - Home Base (59.55 m2)

No Asbestos

B00P - R0003 - Home Base Store (7.25 m2)

No Asbestos

B00P - R0004 - Practical Activities (22.44 m2)

No Asbestos

B00P - R0005 - Home Base (60.54 m2)

No Asbestos

B00P - R0006 - Home Base Store (6.39 m2)

No Asbestos

B00P - R0007 - External Movement (57.73 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D10825 - Learning Unit - Standard With P.A.A. : Placement Date - 24/07/2014

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D10846 - Learning Unit - Standard With P.A.A. : Placement Date - 21/11/2009

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D12596 - Learning Unit - Standard With P.A.A. : Placement Date - 20/05/2008

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D13971 - Learning Unit - Standard With P.A.A. : Placement Date - 5/01/2006

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos	70 m2
---------	---------------	------------------	-------

R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	3 m2

OS 603 - D14896 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 17/01/2005

Exterior

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017