

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Parramatta East Public School (3840)
Region : Western Sydney
State Electorate : Parramatta
Local Government Area : Parramatta

Initial Survey : Noel Arnold & Associates : 21 - Apr - 2008
Register Issue Date : 23 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Library - 1995 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	3840/B00B/Eaves Linings/S9					Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Requires Inspection					

Interior

B00A - R0003 - Library Office/Workroom

No Asbestos

B00A - R0004 - Library Office/Workroom

No Asbestos

B00A - R0006 - Reading Area

No Asbestos

B00A - R0007 - Communications Room

No Asbestos

B00A - R0008 - Movement

No Asbestos

B00A - R0009 - Library Office/Workroom

Ceiling Structures/Linings	Flat AC Sheeting	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3840/B00A/R0009/Ceiling Structures/Linings/S10					Chrysotile (white asbestos) , Amosite (brown asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 1950 - Brick/Veneer (Brick/Veneer)**Exterior**

Eaves Linings	Flat AC Sheeting	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	3840/B00B/Eaves Linings/S9					Chrysotile (white asbestos)
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

Interior**B00B - R0001 - Home Base Store**

Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3840/B00B/R0004/Ceiling Structures/Linings/S8					Chrysotile (white asbestos)

B00B - R0002 - Home Base

Ceiling Structures/Linings	Flat AC Sheeting	53m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3840/B00B/R0004/Ceiling Structures/Linings/S8					Chrysotile (white asbestos)

B00B - R0003 - Home Base

Ceiling Structures/Linings	Flat AC Sheeting	53m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3840/B00B/R0004/Ceiling Structures/Linings/S8					Chrysotile (white asbestos)

B00B - R0004 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	27m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3840/B00B/R0004/Ceiling Structures/Linings/S8					Chrysotile (white asbestos)

B00B - R0005 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Administration - 1950 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	20m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos						
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos						
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

Interior**B00C - R0001 - Staff Room**

No Asbestos

B00C - R0002 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	71m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3840/B00C/R0002/Ceiling Structures/Linings/S2					Chrysotile (white asbestos)	

B00C - R0003 - Sick Bay

Floor Coverings Res/Textile	Vinyl Tiles	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3840/B00C/R0003/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	

B00C - R0004 - Deputy Principal

No Asbestos

B00C - R0005 - Staff Toilet

No Asbestos

B00C - R0006 - Main Switch Board

No Asbestos

B00C - R0007 - Staff Toilet

No Asbestos

B00C - R0008 - Plant

Floor Coverings Res/Textile	Vinyl Tiles	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3840/B00C/R0003/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	

B00C - R0009 - Principal

No Asbestos

B00C - R0010 - General Storeroom

Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3840/B00C/R0003/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	

B00C - R0011 - Interview

Floor Coverings Res/Textile	Vinyl Tiles	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3840/B00C/R0003/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	

B00C - R0012 - Clerical Office/Workroom

No Asbestos

B00C - R0013 - Movement

No Asbestos

B00C - R0014 - Entry Vestibule

No Asbestos

B00C - R0015 - Movement

No Asbestos

B00C - R0016 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3840/B00C/R0002/Ceiling Structures/Linings/S2					Chrysotile (white asbestos)	
Wall Linings Internal	Flat AC Sheeting	4m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
3840/B00C/R0002/Ceiling Structures/Linings/S2					Chrysotile (white asbestos)	
B00C - R0017 - Movement						
No Asbestos						
B00C - R0018 - Duplicating Workroom						
No Asbestos						
B00C - R0019 - General Storeroom						
Floor Coverings Res/Textile	Vinyl Tiles	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3840/B00C/R0003/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Communal Facilities - 1950 - Steel (Steel)**Exterior**

Wall Cladding	Flat AC Sheeting	8m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	3840/B00D/Wall Cladding/S6					Chrysotile (white asbestos)
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

Interior**B00D - R0001 - Special Programs Room**

No Asbestos

B00D - R0002 - Communal Space

No Asbestos

B00D - R0003 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	26m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3840/B00D/R0003/Ceiling Structures/Linings/S7					Chrysotile (white asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning - 1950 - Steel (Steel)**Exterior**

Eaves Linings	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
---------------	------------------	------	------------	--------------------	---------	--------------------

Assumed Asbestos

Ceiling Voids	Requires Inspection
---------------	---------------------

Underfloor Voids	Requires Inspection
------------------	---------------------

Interior**B00E - R0001 - Uniform Shop**

No Asbestos

B00E - R0002 - Home Base

No Asbestos

B00E - R0003 - Home Base

No Asbestos

B00E - R0004 - Movement

No Asbestos

B00E - R0005 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning - 1950 - Brick/Veneer (Brick/Veneer)**Exterior**

Eaves Linings	Flat AC Sheeting	10m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	3840/B00F/R0004/Ceiling Structures/Linings/S5				Chrysotile (white asbestos)	
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

Interior**B00F - R0001 - Home Base Store**

Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3840/B00F/R0004/Ceiling Structures/Linings/S5				Chrysotile (white asbestos)	

B00F - R0002 - Withdrawal Space - 1hb

Wall Linings Internal	Flat AC Sheeting	53m2	Throughout, Upper portion, Middle portion	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	3840/B00F/R0002/Wall Linings Internal/S4				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	53m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3840/B00F/R0004/Ceiling Structures/Linings/S5				Chrysotile (white asbestos)	

B00F - R0003 - Home Base

Wall Linings Internal	Flat AC Sheeting	50m2	Throughout, Upper portion, Middle portion	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	3840/B00F/R0002/Wall Linings Internal/S4				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	53m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3840/B00F/R0004/Ceiling Structures/Linings/S5				Chrysotile (white asbestos)	

B00F - R0004 - Movement

Wall Linings Internal	Flat AC Sheeting	4m2	West	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	3840/B00F/R0002/Wall Linings Internal/S4				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	28m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3840/B00F/R0004/Ceiling Structures/Linings/S5				Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning/Other-Community Use - 1950 - Timber (Timber)**Exterior**

Eaves Linings	Flat AC Sheeting	10m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos					
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

Interior**B00G - R0001 - Home Base Store**

Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3840/B00G/R0007/Wall Linings Internal/S3					Chrysotile (white asbestos)

B00G - R0002 - Home Base

Ceiling Structures/Linings	Flat AC Sheeting	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3840/B00G/R0007/Wall Linings Internal/S3					Chrysotile (white asbestos)

B00G - R0003 - Home Base

Ceiling Structures/Linings	Flat AC Sheeting	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3840/B00G/R0007/Wall Linings Internal/S3					Chrysotile (white asbestos)

B00G - R0004 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3840/B00G/R0007/Wall Linings Internal/S3					Chrysotile (white asbestos)

B00G - R0005 - Community Clinic

Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3840/B00G/R0007/Wall Linings Internal/S3					Chrysotile (white asbestos)

B00G - R0006 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3840/B00G/R0007/Wall Linings Internal/S3					Chrysotile (white asbestos)

B00G - R0007 - Movement

Wall Linings Internal	Flat AC Sheeting	8m2	West	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	3840/B00G/R0007/Wall Linings Internal/S3					Chrysotile (white asbestos)

Ceiling Structures/Linings	Flat AC Sheeting	27m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3840/B00G/R0007/Wall Linings Internal/S3					Chrysotile (white asbestos)

B00G - R0008 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	50m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3840/B00G/R0007/Wall Linings Internal/S3					Chrysotile (white asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Pupil Facilities/General Learning - 1950 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

Interior**B00H - R0001 - Staff Toilet**

Wall Linings Internal	Flat AC Sheeting					
	3840/B00H/R0001/Wall Linings Internal/S11					No Asbestos Detected

B00H - R0002 - Canteen

No Asbestos

B00H - R0003 - Cleaning Distributed Store

No Asbestos

B00H - R0004 - Canteen Office/Store

No Asbestos

B00H - R0005 - Sports Store

No Asbestos

B00H - R0006 - Home Base

No Asbestos

B00H - R0007 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3840/B00G/R0007/Wall Linings Internal/S3					Chrysotile (white asbestos)

B00H - R0008 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Pupil Facilities - 1992 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00J - R0001 - Garden Store

No Asbestos

B00J - R0002 - Toilets - Boys

No Asbestos

B00J - R0003 - Drinking Facilities

No Asbestos

B00J - R0004 - Toilets - Girls

No Asbestos

B00J - R0005 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00Q - Pupil Facilities/Multi Purpose Facilities - 2010 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00Q - R0001 - Communal Space**

No Asbestos

B00Q - R0002 - Raised Platform

No Asbestos

B00Q - R0003 - Chair Storeroom

No Asbestos

B00Q - R0004 - Communal/Performance Store

No Asbestos

B00Q - R0005 - Toilet - Lobby

No Asbestos

B00Q - R0006 - Toilets - Girls

No Asbestos

B00Q - R0007 - Sound Cupboard

No Asbestos

B00Q - R0008 - Toilet - Lobby

No Asbestos

B00Q - R0009 - Toilets - Boys

No Asbestos

B00Q - R0010 - Cleaning Distributed Store

No Asbestos

B00Q - R0011 - Plant

No Asbestos

B00Q - R0012 - Main Switch Board

No Asbestos

B00Q - R0013 - Access Shower/Toilet/Change

No Asbestos

B00Q - R0014 - Covered Outdoor Learning Area

No Asbestos

B00Q - R0015 - Movement

No Asbestos

B00Q - R0016 - Movement

No Asbestos

B00Q - R0017 - Ramp

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D10084 - Learning Unit - Standard With P.A.A. : Placement Date - 21/03/2014

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 603 - D11333 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 15/11/2006

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D11831 - Learning Unit - Standard With P.A.A. : Placement Date - 6/01/2009

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D11936 - Learning Unit - Standard With P.A.A. : Placement Date - 29/03/2012

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 603 - D12264 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 17/11/2014

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
OS 602 - D12644 - Learning Unit - Standard With P.A.A. : Placement Date - 5/01/2008						
Exterior						
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Interior						
R1 - Learning space/withdrawal/entry						
Ceiling	Flat AC Sheet	Assumed Asbestos				70 m2
R2 - Home Base Store						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				3 m2
OS 750 - D12960 - Learning Unit - ESL : Placement Date - 22/12/1998						
Exterior						
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				5.76 m2
Interior						
R1 - Esl						
End wall panel	Flat AC Sheet	Assumed Asbestos				50 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				36 m2
OS 603 - D13695 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 28/06/2010						
Exterior						
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 602 - D13729 - Learning Unit - Standard With P.A.A. : Placement Date - 18/01/2017						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 601 - D14394 - Learning Unit - Standard/Withdrawal : Placement Date - 22/04/1999						
Exterior						
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Interior						
R1 - Entry						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
R2 - General Learning Space						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
R3 - Store						
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2
OS 602 - D14937 - Learning Unit - Standard With P.A.A. : Placement Date - 31/08/2016						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 602 - D16826 - Learning Unit - Standard With P.A.A. : Placement Date - 24/11/2016						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017