

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/General Learning - 1974 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting 4050/B00A/Eaves Linings/S9	60m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting 4050/B00A/Gable Verge Lining/S25					No Asbestos Detected
Panels under windows	Flat AC Sheeting 4050/B00A/R1012/Panel Under Window/S13	16m2	South, East	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00A - R0001 - Toilets - Boys (18.66 m2)

Partition Walls (Cubicles)	Compressed AC Sheet 4050/B00A/R0001/Partition Walls (Cubicles)/S16	6m2	West	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	---	-----	------	--------------------	---------	--

B00A - R0002 - Toilets - Girls (19.8 m2)

Partition Walls (Cubicles)	Compressed AC Sheet 4050/B00A/R0001/Partition Walls (Cubicles)/S16	6m2	West	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	---	-----	------	--------------------	---------	--

B00A - R0004 - Canteen Office/Store (2.09 m2)

No Asbestos

B00A - R0005 - Canteen Office/Store (4.55 m2)

No Asbestos

B00A - R0006 - Staff Toilet (1.88 m2)

No Asbestos

B00A - R0008 - Home Base (58.66 m2)

Ceiling Structures/Linings	Vermiculite 4050/B00A/R1008/Ceiling Structures/Linings/S35					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
----------------------------	---	--	--	--	--	---

B00A - R0009 - Practical Activities - 1hb (17.94 m2)

Ceiling Structures/Linings	Vermiculite 4050/B00A/R1008/Ceiling Structures/Linings/S35					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
----------------------------	---	--	--	--	--	---

B00A - R0010 - Principal (25.27 m2)

Ceiling Structures/Linings	Vermiculite 4050/B00A/R1008/Ceiling Structures/Linings/S35					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
----------------------------	---	--	--	--	--	---

B00A - R0011 - Clerical Office (16.31 m2)

Ceiling Structures/Linings	Vermiculite 4050/B00A/R1008/Ceiling Structures/Linings/S35					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
----------------------------	---	--	--	--	--	---

B00A - R0012 - Movement (7.31 m2)

Ceiling Structures/Linings	Flat AC Sheeting 4050/B00A/R1008/Ceiling Structures/Linings/S35					No Asbestos Detected
----------------------------	--	--	--	--	--	-----------------------------

B00A - R0013 - Entry Vestibule (14.49 m2)

Ceiling Structures/Linings	Vermiculite 4050/B00A/R1008/Ceiling Structures/Linings/S35					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
----------------------------	---	--	--	--	--	---

Floor Coverings Res/Textile	Vinyl Tiles 4050/B00A/R0013/Floor Coverings Res/Textile/S14					No Asbestos Detected
-----------------------------	--	--	--	--	--	-----------------------------

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R0014 - Movement (10.47 m2)						
Ceiling Structures/Linings	Vermiculite					
	4050/B00A/R1008/Ceiling Structures/Linings/S35					Limited Samples Taken
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
Floor Coverings Res/Textile	Vinyl Tiles					
	4050/B00A/R0013/Floor Coverings Res/Textile/S14					No Asbestos Detected
B00A - R0015 - Interview (13.14 m2)						
Ceiling Structures/Linings	Vermiculite					
	4050/B00A/R1008/Ceiling Structures/Linings/S35					Limited Samples Taken
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
B00A - R0016 - Duplicating Workroom (13.07 m2)						
Ceiling Structures/Linings	Vermiculite					
	4050/B00A/R1008/Ceiling Structures/Linings/S35					Limited Samples Taken
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
B00A - R0017 - Sick Bay (8.79 m2)						
Ceiling Structures/Linings	Vermiculite					
	4050/B00A/R1008/Ceiling Structures/Linings/S35					Limited Samples Taken
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
Floor Coverings Res/Textile	Vinyl Tiles					
	4050/B00A/R0013/Floor Coverings Res/Textile/S14					No Asbestos Detected
B00A - R0018 - Movement (35.94 m2)						
Panel Under Window	Flat AC Sheeting	3m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	4050/B00A/R1012/Panel Under Window/S13					Chrysotile (white asbestos)
B00A - R0019 - Main Switch Board (8.31 m2)						
No Asbestos						
B00A - R0020 - Canteen (36.1 m2)						
No Asbestos						
B00A - R0021 - Movement (85.18 m2)						
No Asbestos						
B00A - R0022 - Stairs (20.75 m2)						
No Asbestos						
B00A - R0023 - Stairs (9.74 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4050/B00A/R1014/Ceiling Structures/Linings/S29					Chrysotile (white asbestos)
B00A - R1001 - General Storeroom (6.52 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4050/B00A/R1014/Ceiling Structures/Linings/S29					Chrysotile (white asbestos)
B00A - R1002 - Movement (11.48 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4050/B00D/R0009/Ceiling Structures/Linings/S8					Chrysotile (white asbestos) , Amosite (brown asbestos)
B00A - R1003 - Craft Store (4.24 m2)						
No Asbestos						
B00A - R1004 - Home Base (56.75 m2)						
Ceiling Structures/Linings	Vermiculite					
	4050/B00A/R1008/Ceiling Structures/Linings/S35					Limited Samples Taken
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
B00A - R1005 - Practical Activities - 1hb (18.48 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Ceiling Structures/Linings	Vermiculite 4050/B00A/R1008/Ceiling Structures/Linings/S35					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00A - R1006 - Home Base (57.26 m2)						
Ceiling Structures/Linings	Vermiculite 4050/B00A/R1008/Ceiling Structures/Linings/S35					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00A - R1007 - Practical Activities - 1hb (18.65 m2)						
Ceiling Structures/Linings	Vermiculite 4050/B00A/R1008/Ceiling Structures/Linings/S35					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00A - R1008 - Home Base (74.79 m2)						
Floor Coverings Res/Textile	Vinyl Sheet 4050/B00A/R1008/Floor Coverings Res/Textile/S10					No Asbestos Detected
Ceiling Structures/Linings	Vermiculite 4050/B00A/R1008/Ceiling Structures/Linings/S35					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00A - R1009 - Withdrawal Space - 1hb (10.91 m2)						
Ceiling Structures/Linings	Vermiculite 4050/B00A/R1008/Ceiling Structures/Linings/S35					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00A - R1010 - Staff Room Annexe (10.09 m2)						
Ceiling Structures/Linings	Vermiculite 4050/B00A/R1008/Ceiling Structures/Linings/S35					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00A - R1011 - Security Store (8.64 m2)						
Wall Linings Internal	Flat AC Sheeting 4050/B00A/R1011/Wall Linings Internal/S11	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <i>Chrysotile (white asbestos)</i>
B00A - R1012 - Movement (50.17 m2)						
Ceiling Structures/Linings	Flat AC Sheeting 4050/B00A/R1012/Ceiling Structures/Linings/S12	51m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <i>Chrysotile (white asbestos)</i>
Panel Under Window	Flat AC Sheeting 4050/B00A/R1012/Panel Under Window/S13	4m2	North	Good Condition (1)	Low (1)	Low Priority (2-3) <i>Chrysotile (white asbestos)</i>
Panels Above Windows	Flat AC Sheeting 4050/B00A/R1012/Panels Above Windows/S33	3m2	North	Good Condition (1)	Low (1)	Low Priority (2-3) <i>Chrysotile (white asbestos)</i>
B00A - R1013 - Stairs (18.29 m2)						
Ceiling Structures/Linings	Flat AC Sheeting 4050/B00A/R1014/Ceiling Structures/Linings/S29	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <i>Chrysotile (white asbestos)</i>
Panel Under Window	Flat AC Sheeting 4050/B00A/R1012/Panel Under Window/S13	2m2	North	Good Condition (1)	Low (1)	Low Priority (2-3) <i>Chrysotile (white asbestos)</i>
B00A - R1014 - Stairs (18.9 m2)						
Ceiling Structures/Linings	Flat AC Sheeting 4050/B00A/R1014/Ceiling Structures/Linings/S29	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <i>Chrysotile (white asbestos)</i>

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 1970 - Brick/Veneer (Brick/Veneer)

Exterior

Panels Above Windows	Flat AC Sheeting 4050/B00B/Panels Above Windows/S34	4m2	East & West	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Eaves Linings	Flat AC Sheeting 4050/B00B/Eaves Linings/S20	60m2	East & West	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting 4050/B00A/Gable Verge Lining/S25					No Asbestos Detected
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00B - R0001 - Practical Activities - 1hb (18.08 m2)

No Asbestos

B00B - R0002 - Home Base (52.66 m2)

No Asbestos

B00B - R0003 - Home Base (53.05 m2)

Floor Coverings Res/Textile	Vinyl Tiles 4050/B00B/R0007/Floor Coverings Res/Textile/S15	2m2	West	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
-----------------------------	--	-----	------	--------------------	---------	--

B00B - R0004 - Practical Activities - 1hb (18.08 m2)

No Asbestos

B00B - R0006 - Toilets - Boys/Girls (3.08 m2)

Wall Linings Internal	Flat AC Sheeting 4050/B00B/R0006/Wall Linings Internal/S17	6m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting 4050/B00B/R0006/Ceiling Structures/Linings/S30	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

B00B - R0007 - Home Base Store (3.37 m2)

Floor Coverings Res/Textile	Vinyl Tiles 4050/B00B/R0007/Floor Coverings Res/Textile/S15	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting 4050/B00B/R0006/Wall Linings Internal/S17	8m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting 4050/B00B/R0006/Ceiling Structures/Linings/S30	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

B00B - R0008 - Distribution Board (0.13 m2)

Note: No inspection of live electrical installation.

Floor Coverings Res/Textile	Vinyl Tiles 4050/B00B/R0007/Floor Coverings Res/Textile/S15	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
-----------------------------	--	-----	------------	--------------------	---------	--

B00B - R0009 - Personal Effects Storage (6.58 m2)

Floor Coverings Res/Textile	Vinyl Tiles 4050/B00B/R0007/Floor Coverings Res/Textile/S15	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
-----------------------------	--	-----	------------	--------------------	---------	--

B00B - R0010 - Movement (5.72 m2)

Floor Coverings Res/Textile	Vinyl Tiles 4050/B00B/R0007/Floor Coverings Res/Textile/S15	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
-----------------------------	--	-----	------------	--------------------	---------	--

B00B - R0011 - Staff Toilet (3.38 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4050/B00B/R0006/Ceiling Structures/Linings/S30					Chrysotile (white asbestos)	
Wall Linings Internal	Flat AC Sheeting	8m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
4050/B00B/R0006/Wall Linings Internal/S17					Chrysotile (white asbestos)	
B00B - R0012 - Cleaning Distributed Store (0.92 m2)						
No Asbestos						
B00B - R0013 - Staff Toilet (3.78 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4050/B00B/R0006/Ceiling Structures/Linings/S30					Chrysotile (white asbestos)	
Wall Linings Internal	Flat AC Sheeting	8m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
4050/B00B/R0006/Wall Linings Internal/S17					Chrysotile (white asbestos)	
B00B - R0014 - Staff Kitchen (14.67 m2)						
No Asbestos						
B00B - R0015 - Staff Room (20.81 m2)						
No Asbestos						
B00B - R0016 - Garden Store (6.39 m2)						
Panel Above Door	Flat AC Sheeting	1m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
4050/B00B/R0016/Panel Above Door/S21					Clerical Error - No Sample Taken	
B00B - R0018 - External Movement (75.71 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	76m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4050/B00A/R1014/Ceiling Structures/Linings/S29					Chrysotile (white asbestos)	
B00B - R0019 - Home Base (57.49 m2)						
No Asbestos						
B00B - R0020 - Practical Activities - 1hb (5.05 m2)						
No Asbestos						
B00B - R0021 - Home Base Store (3.89 m2)						
No Asbestos						
B00B - R0022 - External Movement (134.68 m2)						
No Asbestos						
B00B - R0023 - Staff Room Annexe (11.77 m2)						
No Asbestos						
B00B - R0024 - Staff Room (72.31 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	73m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4050/B00B/R0024/Floor Coverings Res/Textile/S36					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00C - General Learning - 1954 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting 4050/B00C/Eaves Linings/S22					No Asbestos Detected
Ceiling Voids	AC Fragments/Debris 4050/B00C/Ceiling Voids/S27	1m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5) Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Underfloor Voids	Compressed AC Sheet 4050/B00C/Underfloor Voids/S28					No Asbestos Detected

Interior

B00C - R0001 - Special Programs Room (51.98 m2)

Ceiling Structures/Linings	Flat AC Sheeting 4050/B00C/R0002/Ceiling Structures/Linings/S31	52m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
Wall Linings Internal	Flat AC Sheeting 4050/B00C/R0002/Wall Linings Internal/S6	100m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)

B00C - R0002 - Home Base (51.98 m2)

Wall Linings Internal	Flat AC Sheeting 4050/B00C/R0002/Wall Linings Internal/S6	100m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Structures/Linings	Flat AC Sheeting 4050/B00C/R0002/Ceiling Structures/Linings/S31	52m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)

B00C - R0005 - Personal Effects Storage (3.62 m2)

Ceiling Structures/Linings	Flat AC Sheeting 4050/B00C/R0002/Ceiling Structures/Linings/S31	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
----------------------------	--	-----	------------	--------------------	---------	---

B00C - R0006 - Practical Activities - 1hb (8.71 m2)

Ceiling Structures/Linings	Flat AC Sheeting 4050/B00C/R0002/Ceiling Structures/Linings/S31	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
----------------------------	--	-----	------------	--------------------	---------	---

B00C - R0007 - Home Base Store (4.77 m2)

Ceiling Structures/Linings	Flat AC Sheeting 4050/B00C/R0002/Ceiling Structures/Linings/S31	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
----------------------------	--	-----	------------	--------------------	---------	---

B00C - R0008 - Personal Effects Storage (3.86 m2)

Ceiling Structures/Linings	Flat AC Sheeting 4050/B00C/R0002/Ceiling Structures/Linings/S31	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
----------------------------	--	-----	------------	--------------------	---------	---

B00C - R0009 - Practical Activities - 1hb (8.68 m2)

Ceiling Structures/Linings	Flat AC Sheeting 4050/B00C/R0002/Ceiling Structures/Linings/S31	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
----------------------------	--	-----	------------	--------------------	---------	---

B00C - R0010 - Home Base Store (4.75 m2)

Ceiling Structures/Linings	Flat AC Sheeting 4050/B00C/R0002/Ceiling Structures/Linings/S31	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
----------------------------	--	-----	------------	--------------------	---------	---

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning - 1963 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting	30m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4050/B00D/Eaves Linings/S23				Chrysotile (white asbestos)	
Gable Verge Lining	Flat AC Sheeting					No Asbestos Detected
	4050/B00D/Gable Verge Lining/S26					
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00D - R0001 - Home Base (57.38 m2)

No Asbestos

B00D - R0002 - Home Base Store (6.7 m2)

Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4050/B00D/R0002/Ceiling Structures/Linings/S32				Chrysotile (white asbestos)	

B00D - R0003 - Personal Effects Storage (7.68 m2)

No Asbestos

B00D - R0004 - Personal Effects Storage (7.03 m2)

No Asbestos

B00D - R0005 - Movement (4.66 m2)

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4050/B00D/R0002/Ceiling Structures/Linings/S32				Chrysotile (white asbestos)	

B00D - R0006 - Home Base Store (4.25 m2)

100 mm Flue Pipe	Fibre Cement Pipe	3m	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4050/B00D/R0006/100 mm Flue Pipe/S2				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00D - R0007 - Home Base (57.38 m2)

In-fill-panel	Flat AC Sheeting	2m	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4050/B00D/R0007/In-fill-panel/S3				Chrysotile (white asbestos)	

B00D - R0008 - Staff Room Annexe (15.24 m2)

No Asbestos

B00D - R0009 - Distribution Board (0.33 m2)

Note: No inspection of live electrical installation.

Wall Linings Internal	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4050/B00D/R0009/Wall Linings Internal/S7				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4050/B00D/R0009/Ceiling Structures/Linings/S8				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00D - R0010 - Movement (3.14 m2)

No Asbestos

B00D - R0011 - Movement (3.8 m2)

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4050/B00C/R0002/Ceiling Structures/Linings/S31				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00D - R0012 - General Storeroom (6.62 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Pupil Facilities - 1963 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	15m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4050/B00E/Eaves Linings/S24				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00E - R0001 - Toilets - Boys (27.55 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	6m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	4050/B00E/R0003/Partition Walls (Cubicles)/S1				Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	28m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4050/B00E/Eaves Linings/S24				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00E - R0002 - Cleaning Distributed Store (5.64 m2)

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4050/B00E/Eaves Linings/S24				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00E - R0003 - Toilets - Girls (27.55 m2)

Ceiling Structures/Linings	Flat AC Sheeting	28m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4050/B00E/Eaves Linings/S24				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Partition Walls (Cubicles)	Compressed AC Sheet	6m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	4050/B00E/R0003/Partition Walls (Cubicles)/S1				Chrysotile (white asbestos)	

B00E - R0004 - General Assistant/Bulk Store (5.64 m2)

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4050/B00E/Eaves Linings/S24				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00E - R0005 - Movement (27.24 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Building Services - 1963 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00F - R0001 - General Storeroom (24.63 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Library - 2004 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00H - R0001 - Staff Toilet (4.66 m2)

No Asbestos

B00H - R0002 - K.L.A. Store (14.81 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R0003 - Movement (2.42 m2)

No Asbestos

B00H - R0004 - Cleaning Distributed Store (3.66 m2)

No Asbestos

B00H - R0005 - Distribution Board (0.85 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00H - R0006 - Communications Room (8.06 m2)

No Asbestos

B00H - R0007 - Library Office/Workroom (23.26 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R0008 - Reading Area (168.1 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R0009 - Movement (71.74 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - Other-Community Use/Other - 2008 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00I - R0001 - Other-Community Use (47.61 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00J - Communal Facilities - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00J - R0001 - Cleaning Distributed Store (3.59 m2)	No Asbestos
B00J - R0002 - Cleaning Distributed Store (1.59 m2)	No Asbestos
B00J - R0003 - Movement (3.49 m2)	No Asbestos
B00J - R0004 - Toilets - Boys (5.58 m2)	No Asbestos
B00J - R0005 - Sound Cupboard (2.22 m2)	No Asbestos
B00J - R0006 - Movement (2.5 m2)	No Asbestos
B00J - R0007 - Toilets - Girls (7.36 m2)	No Asbestos
B00J - R0008 - Sports Store (16.42 m2)	No Asbestos
B00J - R0009 - Chair Storeroom (10.92 m2)	No Asbestos
B00J - R0010 - Chair Storeroom (11.11 m2)	No Asbestos
B00J - R0011 - Movement (18.61 m2)	No Asbestos
B00J - R0012 - Ramp (12.77 m2)	No Asbestos
B00J - R0013 - Movement (8.2 m2)	No Asbestos
B00J - R0014 - Raised Platform (63.27 m2)	No Asbestos
B00J - R0015 - Communal Space (189.98 m2)	No Asbestos
B00J - R0016 - Covered Outdoor Learning Area (197.12 m2)	No Asbestos
B00J - R0017 - Distribution Board (3.26 m2)	No Asbestos Note: No inspection of live electrical installation.
B00J - R0018 - Disabled Shower/Toilet (6.91 m2)	No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - General Learning - 2013 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00K - R0001 - Home Base (61.1 m2)

No Asbestos

B00K - R0002 - Communications Room (3.95 m2)

No Asbestos

B00K - R0003 - Practical Activities (18.16 m2)

No Asbestos

B00K - R0004 - Withdrawal Space - 2hb (16.55 m2)

No Asbestos

B00K - R0005 - Home Base (61.27 m2)

No Asbestos

B00K - R0006 - Practical Activities (17.96 m2)

No Asbestos

B00K - R0007 - Home Base Store (4 m2)

No Asbestos

B00K - R0008 - External Movement (48.47 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D10931 - Learning Unit - Standard With P.A.A. : Placement Date - 17/01/2013

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 970 - D70114 - Store - Single Module : Placement Date - 1/11/2004

Exterior

No Asbestos Found.

Interior

R1 - Bulk Store

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017