

# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Penshurst West Public School (4051)  
**Region :** Sydney  
**State Electorate :** Oatley  
**Local Government Area :** Hurstville

**Initial Survey :** Noel Arnold & Associates : 03 - Feb - 2010  
**Reviewed By :** AECOM : 30 - Oct - 2014



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

**B00A - General Learning/Administration - 1957 - Timber (Timber)**

**Exterior**

Pier In-fill	Flat AC Sheeting 4051/B00A/Pier In-fill/S11					<b>No Asbestos Detected</b>
Eaves Linings	Flat AC Sheeting  4051/B00A/Eaves Linings/S22	60m2	North facing, South facing, East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)  <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior**

**B00A - R0001 - Home Base**

Wall Linings Internal	Flat AC Sheeting  4051/B00A/R0004/Wall Linings Internal/S15	4m2	South facing, East facing, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)  <b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting  4051/B00A/R0004/Wall Linings Internal/S15	54m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)  <b>Chrysotile (white asbestos)</b>

**B00A - R0002 - Cleaning Distributed Store**

Window Insert	Flat AC Sheeting  4051/B00A/R0002/Window Insert/S7	2m2	East facing, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)  <b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting  4051/B00A/R0004/Wall Linings Internal/S15	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)  <b>Chrysotile (white asbestos)</b>

**B00A - R0003 - Cleaning Distributed Store**

Window Insert	Flat AC Sheeting  4051/B00A/R0003/Window Insert/S6	1m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)  <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting  4051/B00A/Eaves Linings/S22	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)  <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00A - R0004 - Home Base**

Wall Linings Internal	Flat AC Sheeting  4051/B00A/R0004/Wall Linings Internal/S15	3m2	South facing, East facing, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)  <b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting  4051/B00A/Eaves Linings/S22	54m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)  <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00A - R0005 - Staff Toilet**

Wall Linings Internal	Flat AC Sheeting 4051/B00A/R0005/Wall Linings Internal/S14					<b>No Asbestos Detected</b>
Ceiling Structures/Linings	Flat AC Sheeting  4051/B00A/Eaves Linings/S22	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)  <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00A - R0006 - General Storeroom**

Floor Coverings Res/Textile	Vinyl Tiles 4051/B00A/R0006/Floor Coverings Res/Textile/S13					<b>No Asbestos Detected</b>
-----------------------------	--	--	--	--	--	-----------------------------

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Ceiling Structures/Linings	Flat AC Sheeting	19m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4051/B00A/Eaves Linings/S22			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00A - R0008 - External Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4051/B00A/Eaves Linings/S22			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00A - R0010 - Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting	25m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4051/B00A/Eaves Linings/S22			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00A - R0011 - General Storeroom</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	4051/B00A/R0011/Floor Coverings Res/Textile/S8			<b>No Asbestos Detected</b>		
<b>B00A - R0012 - Home Base</b>						
Wall Linings Internal	Flat AC Sheeting	4m2	South facing, West facing, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4051/B00A/R0004/Wall Linings Internal/S15			<b>Chrysotile (white asbestos)</b>		
Ceiling Structures/Linings	Flat AC Sheeting	54m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4051/B00A/Eaves Linings/S22			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00A - R0013 - Home Base</b>						
Wall Linings Internal	Flat AC Sheeting	4m2	South facing, West facing, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4051/B00A/R0004/Wall Linings Internal/S15			<b>Chrysotile (white asbestos)</b>		
Ceiling Structures/Linings	Flat AC Sheeting	54m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4051/B00A/Eaves Linings/S22			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00A - R0014 - Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4051/B00A/Eaves Linings/S22			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00A - R0015 - Entry Vestibule</b>						
Ceiling Structures/Linings	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4051/B00A/Eaves Linings/S22			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00A - R0016 - Deputy Principal - Type 1</b>						
Ceiling Structures/Linings	Flat AC Sheeting	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4051/B00A/Eaves Linings/S22			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00A - R0017 - Deputy Principal - Type 1</b>						
Ceiling Structures/Linings	Flat AC Sheeting	13m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4051/B00A/Eaves Linings/S22			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00A - R0019 - Home Base</b>						
Ceiling Structures/Linings	Flat AC Sheeting	54m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4051/B00A/Eaves Linings/S22			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Wall Linings Internal	Flat AC Sheeting	4m2	South facing, West facing, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
4051/B00A/R0004/Wall Linings Internal/S15				Chrysotile (white asbestos)		
<b>B00A - R0020 - Home Base</b>						
Ceiling Structures/Linings	Flat AC Sheeting	54m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4051/B00A/Eaves Linings/S22				Chrysotile (white asbestos) , Amosite (brown asbestos)		
Wall Linings Internal	Flat AC Sheeting	4m2	South facing, West facing, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
4051/B00A/R0004/Wall Linings Internal/S15				Chrysotile (white asbestos)		
<b>B00A - R0021 - E.S.L.</b>						
Ceiling Structures/Linings	Flat AC Sheeting	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4051/B00A/Eaves Linings/S22				Chrysotile (white asbestos) , Amosite (brown asbestos)		
<b>B00A - R0022 - General Storeroom</b>						
Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4051/B00A/Eaves Linings/S22				Chrysotile (white asbestos) , Amosite (brown asbestos)		
<b>B00A - R0023 - Staff Toilet</b>						
Ceiling Structures/Linings	Flat AC Sheeting	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4051/B00A/Eaves Linings/S22				Chrysotile (white asbestos) , Amosite (brown asbestos)		
Wall Linings Internal	Flat AC Sheeting					
4051/B00A/R0023/Wall Linings Internal/S20				No Asbestos Detected		
<b>B00A - R0024 - Cleaning Distributed Store</b>						
Ceiling Structures/Linings	Flat AC Sheeting	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4051/B00A/Eaves Linings/S22				Chrysotile (white asbestos) , Amosite (brown asbestos)		
<b>B00A - R0027 - Movement</b>						
No Asbestos						
<b>B00A - R0028 - External Movement</b>						
No Asbestos						
<b>B00A - R0029 - Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting	11m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4051/B00A/Eaves Linings/S22				Chrysotile (white asbestos) , Amosite (brown asbestos)		
<b>B00A - R0030 - Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting	30m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4051/B00A/Eaves Linings/S22				Chrysotile (white asbestos) , Amosite (brown asbestos)		
<b>B00A - R0031 - External Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4051/B00A/Eaves Linings/S22				Chrysotile (white asbestos) , Amosite (brown asbestos)		
<b>B00A - R0032 - Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting	25m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4051/B00A/Eaves Linings/S22				Chrysotile (white asbestos) , Amosite (brown asbestos)		
<b>B00A - R9001 - General Storeroom</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

**B00A - R9002 - General Storeroom**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - Staff Facilities/Special Purpose - 1957 - Timber (Timber)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00C - R0003 - Movement**

No Asbestos

**B00C - R0004 - General Storeroom**

No Asbestos

**B00C - R0005 - Home Base**

No Asbestos

**B00C - R0006 - Home Base**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Library - 1972 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting	12m2	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4051/B00D/Verge Lining/S25					<b>Chrysotile (white asbestos)</b>
Verge Lining	Flat AC Sheeting	35m	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4051/B00D/Verge Lining/S25					<b>Chrysotile (white asbestos)</b>
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior**

**B00D - R0001 - General Storeroom**

Floor Coverings Res/Textile	Vinyl Sheet					
	4051/B00D/R0001/Floor Coverings Res/Textile/S9					<b>No Asbestos Detected</b>

**B00D - R0002 - Reading Area**

Thermacon Heater	Encapsulated Insulation material within unit	3Unit	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	<b>Assumed Asbestos - Sealed unit, no access</b>					

**B00D - R0003 - Library Office/Workroom**

No Asbestos

**B00D - R0005 - Stairs**

No Asbestos

**B00D - R0006 - Special Programs Room**

No Asbestos

**B00D - R0007 - Ramp**

Ceiling Structures/Linings	Flat AC Sheeting	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4051/B00D/R0004/Ceiling Structures/Linings/S10					<b>Chrysotile (white asbestos)</b>

**B00D - R0008 - General Storeroom**

Ceiling Structures/Linings	Flat AC Sheeting	18m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4051/B00D/R0004/Ceiling Structures/Linings/S10					<b>Chrysotile (white asbestos)</b>

**B00D - R0009 - External Movement**

Ceiling Structures/Linings	Flat AC Sheeting	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4051/B00D/R0004/Ceiling Structures/Linings/S10					<b>Chrysotile (white asbestos)</b>

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - Pupil Facilities - 1957 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

**Interior**

**B00E - R0001 - External Movement**

Ceiling Structures/Linings	Flat AC Sheeting 4051/B00E/R0001/Ceiling Structures/Linings/S5	<b>No Asbestos Detected</b>
----------------------------	---	-----------------------------

**B00E - R0002 - Toilets - Girls**

Partition Walls (Cubicles)	Compressed AC Sheet 4051/B00E/R0003/Partition Walls (Cubicles)/S4	<b>No Asbestos Detected</b>
----------------------------	--	-----------------------------

**B00E - R0003 - Toilets - Boys**

Partition Walls (Cubicles)	Compressed AC Sheet 4051/B00E/R0003/Partition Walls (Cubicles)/S4	<b>No Asbestos Detected</b>
----------------------------	--	-----------------------------

**B00E - R0004 - Cleaning Distributed Store**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

**B00F - General Learning - 1957 - Timber (Timber)****Exterior**

Gable Ends	Flat AC Sheeting 4051/B00A/Eaves Linings/S22	15m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
Wall Cladding	Flat AC Sheeting 4051/B00F/Wall Cladding/S16					<b>No Asbestos Detected</b>
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					
Eaves Linings	Compressed AC Sheet 4051/B00A/Eaves Linings/S22	80m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**Interior****B00F - R0006 - Staff Toilet**

Wall Linings Internal	Flat AC Sheeting 4051/B00F/R0006/Wall Linings Internal/S17	6m2	North facing, South facing, East facing, West facing, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting 4051/B00F/R0030/Ceiling Structures/Linings/S18	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00F - R0007 - General Storeroom**

Ceiling Structures/Linings	Flat AC Sheeting 4051/B00F/R0030/Ceiling Structures/Linings/S18	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00F - R0008 - Home Base**

Wall Linings Internal	Flat AC Sheeting 4051/B00F/R0008/Wall Linings Internal/S19	5m2	South facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting 4051/B00F/R0030/Ceiling Structures/Linings/S18	54m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00F - R0009 - Home Base**

Wall Linings Internal	Flat AC Sheeting 4051/B00F/R0008/Wall Linings Internal/S19	5m2	South facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting 4051/B00F/R0030/Ceiling Structures/Linings/S18	54m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00F - R0010 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting 4051/B00F/R0030/Ceiling Structures/Linings/S18	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00F - R0011 - Withdrawal Space - 1hb**

No Asbestos

**B00F - R0012 - Deputy Principal**

Ceiling Structures/Linings	Flat AC Sheeting 4051/B00F/R0011/Ceiling Structures/Linings/S27					<b>No Asbestos Detected</b>
----------------------------	--	--	--	--	--	-----------------------------

**B00F - R0013 - Home Base**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Wall Linings Internal	Flat AC Sheeting	5m2	South facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
4051/B00F/R0008/Wall Linings Internal/S19				Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
4051/B00F/R0011/Ceiling Structures/Linings/S27						
<b>B00F - R0015 - Staff Room</b>						
Wall Linings Internal	Flat AC Sheeting	3m2	South facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
4051/B00F/R0008/Wall Linings Internal/S19				Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
4051/B00F/R0011/Ceiling Structures/Linings/S27						
<b>B00F - R0016 - Movement</b>						
No Asbestos						
<b>B00F - R0017 - Special Programs Room</b>						
Ceiling Structures/Linings	Flat AC Sheeting	23m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4051/B00F/R0030/Ceiling Structures/Linings/S18				Chrysotile (white asbestos) , Amosite (brown asbestos)		
<b>B00F - R0030 - Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4051/B00F/R0030/Ceiling Structures/Linings/S18				Chrysotile (white asbestos) , Amosite (brown asbestos)		
<b>B00F - R0031 - Staff Toilet</b>						
No Asbestos						
<b>B00F - R0032 - Entry Vestibule</b>						
No Asbestos						
<b>B00F - R0033 - Sick Bay</b>						
No Asbestos						
<b>B00F - R0034 - Uniform Shop</b>						
No Asbestos						
<b>B00F - R0035 - Interview/Office - Type 3</b>						
No Asbestos						
<b>B00F - R0036 - Deputy Principal</b>						
No Asbestos						
<b>B00F - R0037 - Principal</b>						
No Asbestos						
<b>B00F - R0038 - Clerical Office</b>						
No Asbestos						
<b>B00F - R0039 - Duplicating Workroom</b>						
No Asbestos						
<b>B00F - R0040 - Security Store</b>						
No Asbestos						
<b>B00F - R0041 - Movement</b>						
No Asbestos						
<b>B00F - R0042 - Movement</b>						
No Asbestos						
<b>B00F - R0043 - Cleaning Distributed Store</b>						
No Asbestos						
<b>B00F - R0044 - Staff Toilet</b>						
No Asbestos						
<b>B00F - R0045 - Staff Toilet</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

**B00F - R0046 - Staff Toilet**

No Asbestos

**B00F - R0047 - Movement**

No Asbestos

**B00F - R0048 - Stairs**

No Asbestos

**B00F - R0049 - Garden Store**

Ceiling Structures/Linings	Flat AC Sheeting	13m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	------	--------------	--------------------	---------	--------------------

4051/B00F/R0030/Ceiling Structures/Linings/S18

**Chrysotile (white asbestos) , Amosite (brown asbestos)**

**B00F - R0050 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	30m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	------	--------------	--------------------	---------	--------------------

4051/B00F/R0030/Ceiling Structures/Linings/S18

**Chrysotile (white asbestos) , Amosite (brown asbestos)**

**B00F - R0051 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	57m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	------	--------------	--------------------	---------	--------------------

4051/B00F/R0030/Ceiling Structures/Linings/S18

**Chrysotile (white asbestos) , Amosite (brown asbestos)**

**B00F - R9001 - Sports Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - Communal Facilities/Pupil Facilities - 1957 - Brick/Block (Brick/Block)**

**Exterior**

Wall Cladding	Flat AC Sheeting 4051/B00H/Wall Cladding/S1					No Asbestos Detected
Ceiling Voids	Non Accessible Area - No asbestos was found.					
Underfloor Voids	No Asbestos Found					

**Interior**

**B00H - R0001 - Toilets - Girls**

Partition Walls (Cubicles)	Compressed AC Sheet 4051/B00H/R0001/Partition Walls (Cubicles)/S2					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting 4051/B00H/R0001/Wall Linings Internal/S3					No Asbestos Detected

**B00H - R0002 - Shower/Change**

Partition Walls (Cubicles)	Compressed AC Sheet 4051/B00H/R0001/Partition Walls (Cubicles)/S2					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting 4051/B00H/R0001/Wall Linings Internal/S3					No Asbestos Detected

**B00H - R0003 - Plant**

Wall Linings Internal	Flat AC Sheeting 4051/B00H/R0001/Wall Linings Internal/S3					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting 4051/B00H/R0003/Ceiling Structures/Linings/S29					No Asbestos Detected

**B00H - R0004 - Cleaning Distributed Store**

Wall Linings Internal	Flat AC Sheeting 4051/B00H/R0001/Wall Linings Internal/S3					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting 4051/B00H/R0003/Ceiling Structures/Linings/S29					No Asbestos Detected

**B00H - R0005 - Movement**

No Asbestos

**B00H - R0006 - External Movement**

No Asbestos

**B00H - R0007 - Movement**

Wall Linings Internal	Flat AC Sheeting 4051/B00H/R0001/Wall Linings Internal/S3					No Asbestos Detected
-----------------------	--	--	--	--	--	----------------------

**B00H - R0008 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00H - R0009 - Shower/Change**

Partition Walls (Cubicles)	Compressed AC Sheet 4051/B00H/R0001/Partition Walls (Cubicles)/S2					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting 4051/B00H/R0001/Wall Linings Internal/S3					No Asbestos Detected

**B00H - R0010 - Toilets - Boys**

Partition Walls (Cubicles)	Compressed AC Sheet 4051/B00H/R0001/Partition Walls (Cubicles)/S2					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting 4051/B00H/R0001/Wall Linings Internal/S3					No Asbestos Detected

**B00H - R0011 - Raised Platform**

No Asbestos

**B00H - R0012 - Hall Chair Store**

No Asbestos

**B00H - R0013 - External Movement**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00H - R0014 - Disabled Toilet</b>						
No Asbestos						
<b>B00H - R0015 - Sports Store</b>						
No Asbestos						
<b>B00H - R0016 - Canteen Office/Store</b>						
No Asbestos						
<b>B00H - R0017 - Canteen Office/Store</b>						
No Asbestos						
<b>B00H - R0018 - Canteen</b>						
No Asbestos						
<b>B00H - R0019 - Uniform Shop</b>						
No Asbestos						
<b>B00H - R0020 - Communal Space</b>						
No Asbestos						
<b>B00H - R0021 - Hall Chair Store</b>						
No Asbestos						
<b>B00H - R0022 - External Movement</b>						
No Asbestos						
<b>B00H - R0023 - Stairs</b>						
No Asbestos						
<b>B00H - R0024 - Stairs</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00J - Pupil Facilities - 1957 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00J - R0001 - Drinking Facilities**

No Asbestos

**B00J - R0002 - Toilets - Girls**

No Asbestos

**B00J - R0003 - Sports Store**

No Asbestos

**B00J - R0004 - Toilets - Boys**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00K - General Learning - 2010 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00K - R0001 - Home Base**

No Asbestos

**B00K - R0002 - General Storeroom**

No Asbestos

**B00K - R0003 - Practical Activities**

No Asbestos

**B00K - R0004 - Withdrawal Space - 2hb**

No Asbestos

**B00K - R0005 - Home Base**

No Asbestos

**B00K - R0006 - Home Base Store - P**

No Asbestos

**B00K - R0007 - Practical Activities**

No Asbestos

**B00K - R0008 - External Movement**

No Asbestos

**B00K - R0009 - Home Base**

No Asbestos

**B00K - R0010 - Home Base Store**

No Asbestos

**B00K - R0011 - Practical Activities**

No Asbestos

**B00K - R0012 - Withdrawal Space - 2hb**

No Asbestos

**B00K - R0013 - Home Base**

No Asbestos

**B00K - R0014 - Home Base Store**

No Asbestos

**B00K - R0015 - Practical Activities**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Listing of Electronic Attachments as of 22/03/2017***

**Available Asbestos Related Electronic Files**

4051\_ASB\_210813\_AMP.pdf

\* Note : Refer to AMS for details of the attachment(s).

2017