

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Padstow North Public School (4088)
Region : South Western Sydney
State Electorate : East Hills
Local Government Area : Bankstown

Initial Survey : Noel Arnold & Associates : 29 - Mar - 2008
Reviewed By : Parsons Brinckerhoff : 25 - Nov - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Library - 1959 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4088/B00A/Eaves Linings/S6				Chrysotile (white asbestos)	
Gable Verge Lining	Flat AC Sheeting	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4088/B00A/Gable Verge Lining/S7				Chrysotile (white asbestos)	
Underfloor Voids	AC Fragments/Debris	2m2	South	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4088/B00A/Underfloor Voids/S8				Chrysotile (white asbestos)	

Interior

B00A - R0002 - Entry Vestibule

No Asbestos

B00A - R0003 - Library Office/Workroom

No Asbestos

B00A - R0004 - Communications Room

No Asbestos

B00A - R0005 - Reading Area

No Asbestos

B00A - R0006 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4088/B00D/R0001/Ceiling Structures/Linings/S1				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00A - R0007 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4088/B00D/R0001/Ceiling Structures/Linings/S1				Chrysotile (white asbestos) , Amosite (brown asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Administration/Communal Facilities - 1957 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	80m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4088/B00B/Eaves Linings/S9				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4088/B00B/Gable Verge Lining/S23				Chrysotile (white asbestos)	
Underfloor Voids	AC Fragments/Debris	1m2	West	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4088/B00B/Underfloor Voids/S10				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	

Interior

B00B - R0001 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4088/B00D/R0001/Ceiling Structures/Linings/S1				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00B - R0002 - Clerical Office

No Asbestos

B00B - R0003 - General Storeroom

No Asbestos

B00B - R0004 - Staff Toilet

No Asbestos

B00B - R0005 - Principal

No Asbestos

B00B - R0006 - Plant

No Asbestos

B00B - R0007 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00B - R0008 - Duplicating Workroom

Floor Coverings Res/Textile	Vinyl Tiles	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4088/B00B/R0008/Floor Coverings Res/Textile/S3				Chrysotile (white asbestos)	

B00B - R0009 - Sick Bay

No Asbestos

B00B - R0010 - Community Clinic

No Asbestos

B00B - R0013 - Movement

No Asbestos

B00B - R0014 - General Storeroom

No Asbestos

B00B - R0015 - Deputy Principal

No Asbestos

B00B - R0016 - Security Store

No Asbestos

B00B - R0017 - Movement

No Asbestos

B00B - R0019 - General Storeroom

No Asbestos

B00B - R0020 - Hall Chair Store

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Sheet					
	4088/B00D/R0003/Floor Coverings Res/Textile/S2					No Asbestos Detected
B00B - R0021 - General Storeroom						
No Asbestos						
B00B - R0022 - Interview						
No Asbestos						
B00B - R0023 - Communal/Performance Store						
No Asbestos						
B00B - R0024 - Uniform Shop						
Floor Coverings Res/Textile	Vinyl Sheet					
	4088/B00D/R0003/Floor Coverings Res/Textile/S2					No Asbestos Detected
B00B - R0025 - Movement						
Floor Coverings Res/Textile	Vinyl Sheet					
	4088/B00D/R0003/Floor Coverings Res/Textile/S2					No Asbestos Detected
B00B - R0027 - Music Store						
No Asbestos						
B00B - R0028 - Sports Store						
No Asbestos						
B00B - R0029 - P.E. Store						
No Asbestos						
B00B - R0030 - Movement						
Floor Coverings Res/Textile	Vinyl Sheet					
	4088/B00D/R0003/Floor Coverings Res/Textile/S2					No Asbestos Detected
B00B - R0031 - General Storeroom						
No Asbestos						
B00B - R0032 - Movement						
Floor Coverings Res/Textile	Vinyl Sheet					
	4088/B00D/R0003/Floor Coverings Res/Textile/S2					No Asbestos Detected
B00B - R0033 - External Movement						
Ceiling Structures/Linings	Flat AC Sheeting	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4088/B00D/R0001/Ceiling Structures/Linings/S1					Chrysotile (white asbestos) , Amosite (brown asbestos)
B00B - R0034 - External Movement						
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4088/B00D/R0001/Ceiling Structures/Linings/S1					Chrysotile (white asbestos) , Amosite (brown asbestos)
B00B - R0035 - External Movement						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4088/B00D/R0001/Ceiling Structures/Linings/S1					Chrysotile (white asbestos) , Amosite (brown asbestos)
B00B - R0038 - Movement						
No Asbestos						
B00B - R0039 - Staff Room						
No Asbestos						
B00B - R0040 - Home Base						
No Asbestos						
B00B - R0041 - Home Base						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00B - R0042 - Toilet - Lobby						
No Asbestos						
B00B - R0043 - Staff Toilet						
No Asbestos						
B00B - R0044 - Toilet - Lobby						
No Asbestos						
B00B - R0045 - Staff Toilet						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning - 1959 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	60m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4088/B00C/Eaves Linings/S11			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
Gable Verge Lining	Flat AC Sheeting	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4088/B00C/Gable Verge Lining/S12			Chrysotile (white asbestos)		
Underfloor Voids	No Asbestos Found					

Interior

B00C - R0001 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4088/B00D/R0001/Ceiling Structures/Linings/S1			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00C - R0002 - Cleaning Supplies

No Asbestos

B00C - R0003 - Craft Store

No Asbestos

B00C - R0004 - Movement

Floor Coverings Res/Textile	Vinyl Sheet				
	4088/B00D/R0003/Floor Coverings Res/Textile/S2				No Asbestos Detected

B00C - R0005 - Personal Effects Storage

Floor Coverings Res/Textile	Vinyl Sheet				
	4088/B00D/R0003/Floor Coverings Res/Textile/S2				No Asbestos Detected

B00C - R0006 - Home Base

No Asbestos

B00C - R0007 - Home Base Store

No Asbestos

B00C - R0008 - Home Base

No Asbestos

B00C - R0009 - Home Base Store

No Asbestos

B00C - R0010 - Movement

Floor Coverings Res/Textile	Vinyl Sheet				
	4088/B00D/R0003/Floor Coverings Res/Textile/S2				No Asbestos Detected

B00C - R0011 - Personal Effects Storage

Floor Coverings Res/Textile	Vinyl Sheet				
	4088/B00D/R0003/Floor Coverings Res/Textile/S2				No Asbestos Detected

B00C - R0012 - Home Base

No Asbestos

B00C - R0013 - Home Base Store

No Asbestos

B00C - R0014 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4088/B00D/R0001/Ceiling Structures/Linings/S1			Chrysotile (white asbestos) , Amosite (brown asbestos)		

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning - 1959 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	25m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4088/B00D/Eaves Linings/S13			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
Gable Verge Lining	Flat AC Sheeting	10m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4088/B00D/Gable Verge Lining/S14			Chrysotile (white asbestos)		
Underfloor Voids	Flat AC Sheeting					No Asbestos Detected
	4088/B00D/Underfloor Voids/S15					

Interior

B00D - R0001 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4088/B00D/R0001/Ceiling Structures/Linings/S1			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00D - R0002 - Movement

Floor Coverings Res/Textile	Vinyl Sheet					No Asbestos Detected
	4088/B00D/R0003/Floor Coverings Res/Textile/S2					

B00D - R0003 - Personal Effects Storage

Floor Coverings Res/Textile	Vinyl Sheet					No Asbestos Detected
	4088/B00D/R0003/Floor Coverings Res/Textile/S2					

B00D - R0004 - Special Programs Room

No Asbestos

B00D - R0005 - Home Base Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning - 1959 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	25m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4088/B00E/Eaves Linings/S16			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4088/B00E/Gable Verge Lining/S17			Chrysotile (white asbestos)		
Underfloor Voids	Packers on piers	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4088/B00E/Underfloor Voids/S18			Chrysotile (white asbestos)		

Interior

B00E - R0001 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4088/B00D/R0001/Ceiling Structures/Linings/S1			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00E - R0002 - Home Base

No Asbestos

B00E - R0003 - Home Base Store

No Asbestos

B00E - R0004 - Movement

No Asbestos

B00E - R0005 - Personal Effects Storage

No Asbestos

B00E - R0006 - Home Base

No Asbestos

B00E - R0007 - Home Base Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Pupil Facilities - 1959 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - No Voids					
Ceiling Voids - Raked Ceiling	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	30m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4088/B00F/Eaves Linings/S19			Chrysotile (white asbestos) , Amosite (brown asbestos)		

Interior

B00F - R0001 - Movement	No Asbestos					
B00F - R0002 - General Storeroom	No Asbestos					
B00F - R0003 - General Storeroom	No Asbestos					
B00F - R0004 - Canteen	No Asbestos					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning - 1959 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00G - R0001 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4088/B00D/R0001/Ceiling Structures/Linings/S1				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00G - R0002 - Personal Effects Storage

No Asbestos

B00G - R0003 - Home Base

No Asbestos

B00G - R0004 - Home Base Store

No Asbestos

B00G - R0005 - Toilets - Boys/Girls

Wall Linings Internal	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4088/B00G/R0005/Wall Linings Internal/S4				Chrysotile (white asbestos) , Amosite (brown asbestos)		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - General Learning/Administration - 1959 - Timber (Timber)**Exterior**

Ceiling Voids - Raked Ceiling	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	50m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4088/B00H/Eaves Linings/S22					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4088/B00H/Gable Verge Lining/S21					Chrysotile (white asbestos)
Underfloor Voids	Flat AC Sheeting	2m2	Under R0002	Good Condition (1)	Low (1)	Low Priority (2-3)
	4088/B00H/Underfloor Voids/S20					Chrysotile (white asbestos)
Underfloor Voids	Packers on piers	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4088/B00H/Underfloor Voids/S25					Chrysotile (white asbestos)

Interior**B00H - R0001 - Home Base**

Wall Linings Internal	Flat AC Sheeting	2m2	Behind Heater	Good Condition (1)	Low (1)	Low Priority (2-3)
	4088/B00H/R0001/Wall Linings Internal/S5					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00H - R0002 - Home Base

Wall Linings Internal	Flat AC Sheeting	2m2	Behind Heater	Good Condition (1)	Low (1)	Low Priority (2-3)
	4088/B00H/R0001/Wall Linings Internal/S5					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00H - R0003 - Home Base

Wall Linings Internal	Flat AC Sheeting	2m2	Behind Heater	Good Condition (1)	Low (1)	Low Priority (2-3)
	4088/B00H/R0001/Wall Linings Internal/S5					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00H - R0004 - General Storeroom

No Asbestos

B00H - R0005 - Staff Toilet

No Asbestos

B00H - R0006 - Staff Kitchen

No Asbestos

B00H - R0007 - Movement

No Asbestos

B00H - R0008 - Staff Room

Wall Linings Internal	Flat AC Sheeting	2m2	Behind Heater	Good Condition (1)	Low (1)	Low Priority (2-3)
	4088/B00H/R0001/Wall Linings Internal/S5					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00H - R0009 - Home Base

Wall Linings Internal	Flat AC Sheeting	2m2	Behind Heater	Good Condition (1)	Low (1)	Low Priority (2-3)
	4088/B00H/R0001/Wall Linings Internal/S5					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00H - R0010 - Clerical Office

No Asbestos

B00H - R0011 - Clerical Office/Workroom

No Asbestos

B00H - R0012 - Home Base

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Wall Linings Internal	Flat AC Sheeting	2m2	Behind Heater	Good Condition (1)	Low (1)	Low Priority (2-3)
4088/B00H/R0001/Wall Linings Internal/S5				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00H - R0013 - Home Base						
Wall Linings Internal	Flat AC Sheeting	2m2	Behind Heater	Good Condition (1)	Low (1)	Low Priority (2-3)
4088/B00H/R0001/Wall Linings Internal/S5				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00H - R0014 - Sports Store						
No Asbestos						
B00H - R0015 - Cleaning Distributed Store						
No Asbestos						
B00H - R0016 - Personal Effects Storage						
No Asbestos						
B00H - R0017 - External Movement						
Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4088/B00H/R0017/Ceiling Structures/Linings/S24				Chrysotile (white asbestos) , Crocidolite (blue asbestos)		
B00H - R0018 - Personal Effects Storage						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Pupil Facilities - 1959 - Timber (Timber)

Exterior

Underfloor Voids - Slab on Ground Non Accessible Area
 - No Voids

Ceiling Voids - Raked Ceiling No Asbestos Found

Interior

B00J - R0001 - Drinking Facilities

No Asbestos

B00J - R0002 - Drinking Facilities

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Pupil Facilities - 1959 - Timber (Timber)

Exterior

Underfloor Voids - Slab on Ground Non Accessible Area
 - No Voids

Ceiling Voids - Raked Ceiling No Asbestos Found

Interior

B00K - R0001 - Toilets - Girls

No Asbestos

B00K - R0002 - Cleaning Distributed Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Pupil Facilities - 1959 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found
Underfloor Voids - Slab on Ground	Non Accessible Area - No Voids

Interior

B00L - R0001 - Drinking Facilities

No Asbestos

B00L - R0002 - Toilets - Boys

No Asbestos

B00L - R0003 - Cleaning Distributed Store

No Asbestos

B00L - R0004 - Drinking Facilities

No Asbestos

B00L - R0005 - Toilets - Girls

No Asbestos

B00L - R0006 - Cleaning Distributed Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - Other - 2007 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - No Voids
Ceiling Voids	No Asbestos Found

Interior

B00M - R0001 - Movement

No Asbestos

B00M - R0002 - Movement

No Asbestos

B00M - R0003 - Toilets - Boys

No Asbestos

B00M - R0004 - Toilets - Girls

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00N - Communal Facilities - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - No Voids
Ceiling Voids	No Asbestos Found

Interior

B00N - R0001 - Communal Space

No Asbestos

B00N - R0002 - Raised Platform

No Asbestos

B00N - R0003 - Hall Chair Store

No Asbestos

B00N - R0004 - Communal/Performance Store

No Asbestos

B00N - R0005 - P.E. Store

No Asbestos

B00N - R0006 - Toilet - Lobby

No Asbestos

B00N - R0007 - Toilets - Girls

No Asbestos

B00N - R0008 - Sound Cupboard

No Asbestos

B00N - R0009 - Toilet - Lobby

No Asbestos

B00N - R0010 - Toilets - Boys

No Asbestos

B00N - R0011 - Cleaning Distributed Store

No Asbestos

B00N - R0012 - General Storeroom

No Asbestos

B00N - R0013 - Main Switch Board

No Asbestos

B00N - R0014 - Access Shower/Toilet/Change

No Asbestos

B00N - R0015 - Covered Outdoor Learning Area

No Asbestos

B00N - R0016 - Movement

No Asbestos

B00N - R0017 - Movement

No Asbestos

B00N - R0018 - Ramp

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D15767 - Learning Unit - Standard With P.A.A. : Placement Date - 24/12/2014

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos		1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos		1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos		11.52 m2

Interior

R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos		70 m2
---------	---------------	------------------	--	-------

R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		3 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

Available Asbestos Related Electronic Files

4088_ASB_010713_AMP.pdf

* Note : Refer to AMS for details of the attachment(s).

2017